



A Textron Company

## **ALERT SERVICE BULLETIN**

**205-96-67**

1 May 1996  
Revision A, 12 October 2018

**MODEL AFFECTED:** 205A/205A-1

**SUBJECT:** MAIN ROTOR BLADE 204-011-250-001, -005, -009, -113 AND, -117, INTRODUCTION OF DAILY WIPE-DOWN INSPECTION AND SPECIAL 25-HOUR INSPECTION.

**HELICOPTERS AFFECTED:** Serial numbers 30001 through 30332.

**COMPLIANCE:** Part I: At the next daily inspection and every daily inspection thereafter.

Part II: Within the next 25 flight hours and every 25 flight hours thereafter.

**DESCRIPTION:**

This ASB has been revised in its entirety.

Bell has recently been informed of two main rotor blades P/N 204-011-250-113 with chordwise cracks originating from the extreme trailing edge outside of the current inspection area between blade station 190 and 210. Consequently, the existing Daily and Special Inspection introduced by the original release of ASB 205-96-67 are being revised to extend the inspection area and change the procedure. This ASB introduces the revised inspection area and the change in the procedure. Applicability of this bulletin to any spare part shall be determined prior to its installation on an affected helicopter.

**APPROVAL:**

The engineering design aspects of this bulletin are FAA approved for FAA certified helicopters as listed in the applicable Type Certificate Data Sheet. For non FAA certified helicopters, the engineering design aspects of this bulletin are Bell Engineering approved.

**CONTACT INFO:**

For any questions regarding this bulletin, please contact:

Bell Product Support Engineering - Medium Helicopters  
Tel: 450-437-6201 / 1-800-363-8028 / psemedium@bellflight.com

**MANPOWER:**

Approximately 0.3 man-hour is required to complete Part 1 of this bulletin.  
Approximately 0.5 man-hour is required to complete Part 2 of this bulletin.

This estimate is based on hands-on time and may vary with personnel and facilities available.

**WARRANTY:**

There is no warranty credit applicable for parts or labor associated with this bulletin.

**MATERIAL:**

**Required Material:**

The following material is required for the accomplishment of this bulletin and may be obtained through your Bell Supply Center.

<u>Part Number</u>	<u>Nomenclature</u>	<u>Qty (Note)</u>
204-011-250-001	Blade Assy	A/R (1)
204-011-250-113	Blade Assy	A/R (1)
204-011-250-117	Blade Assy	A/R (1)

**NOTE 1:** Only required if Blade Assy is found unserviceable.

**Consumable Material:**

The following material is required to accomplish this bulletin, but may not require ordering, depending on the operator's consumable material stock levels. This material may be obtained through your Bell Supply Center.

<u>Part Number</u>	<u>Nomenclature</u>	<u>Qty (Note)</u>	<u>Reference *</u>
Commercial	Cheesecloth, Cotton	A/R	C-486
2100-06673-00	Isopropyl Alcohol	1 Gallon	C-385
5300-61653-01	WD-40	12oz	C-125
5060-60154-00	Abrasive Cloth or Paper	A/R	C-406

\* C-XXX numbers refer to the consumables list in the BHT-ALL-SPM, Standard Practices Manual

**SPECIAL TOOLS:**

None required.

**WEIGHT AND BALANCE:**

Not affected

**ELECTRICAL LOAD DATA:**

Not affected.

**REFERENCES:**

BHT-205A-1-IPB Illustrated Parts Breakdown  
 BHT-205A1-MM Maintenance Manual

**PUBLICATIONS AFFECTED:**

BHT-205A1-MM

**ACCOMPLISHMENT INSTRUCTIONS:**

**Part I: Daily Inspection**

1. Prepare the helicopter for maintenance.
2. Wipe the upper and lower skin surfaces of the blades between blade station 100 to 215 with cheesecloth (C-486)

-NOTE-

Inspection of the lower surface of the blade will require supporting (lifting) the tip to remove any bow.

3. Inspect the area in accordance with the BHT-205A1-MM paying attention to the trailing edge and any blade surface which may have snagged the cheesecloth or caused it to fray.
4. All areas that may have snagged or frayed the cheesecloth require further investigation. It may be an indication of a crack or paint chip which could lead to corrosion resulting in blade cracking.
5. If no snag/fraying is detected, proceed to step 9.
6. In areas where the cheesecloth snagged or frayed, remove paint from the affected area by hand sanding in a spanwise direction only with an abrasive cloth or paper (C-406) 220 grit or smoother.
7. Carry out one of the following inspections of the affected area as follows:
  - a. Visually inspect the affected area using a 10X magnifying glass with a strong light source applied at an oblique angle and perpendicular to the crack orientation.
  - b. Inspect using Eddy Current method with surface probe (BHT-ALL-SPM)
8. If any cracks are found, remove blade from service and contact Bell Product Support.
9. Make an entry in the helicopter logbook and historical service records indicating compliance with Part I of this Alert Service Bulletin.

## **Part II: Recurring 25-hour Special Inspection**

1. Prepare the helicopter for maintenance.
2. Inspect the upper and lower skin surfaces of the main rotor blades as follows:
  - a. Wipe the last 4 inches of the trailing edge between blade station 100 and 215 (shaded area) with an alcohol-soaked cloth (C-385) and wipe dry with a clean cloth. (Figure 1)

-NOTE-

Carry out the following step immediately after completing the above alcohol wipe procedure. (Inspection of the lower side of the blade will require supporting (lifting) the tip to remove any bow).

- b. Using a strong light source at an oblique angle, check for evidence of a dark line. A dark line represents excess alcohol bleeding out of possible cracks or edge voids. (If no defects are found during the inspection, proceed to step 2.f).

- c. Any crack in the surface finish must be investigated further by removing paint in the affected area. Remove paint by hand sanding the affected area in a spanwise direction only, with an abrasive cloth or paper (C-406) 220 grit or smoother to determine if the crack is in the skin. (Any crack in the surface finish may be indicative of a skin crack).
  - d. The main rotor blade must be removed from service if any skin cracks are detected. Contact Bell Product Support if any skin cracks are found during the inspection.
  - e. If no skin cracks are found, touch-up and refinish the affected area. (BHT-205A1-MM, Chapter 65).
  - f. Carry out main rotor blade preventive maintenance. (BHT-205-MM, Para 65-22).
3. Make an entry in the helicopter logbook and historical service records indicating findings and compliance with Part II of this Alert Service Bulletin.




Figure 1 – 204-011-250 Series Main Rotor Blade