

INFORMATION LETTER

505-22-18

7 April 2022

TO: All owners and operators of Model 505 helicopters

SUBJECT: 505 GARMIN FLIGHT CONTROL (GFC) 600H PEDAL OSCILLATION OBSERVED UNDER GUSTY/TURBULENT AIR CONDITIONS

This Information Letter is issued to ensure complete distribution of the attached Garmin Service Alert No: 22032 rev A GFC 600H Pedal Oscillation Observed Under Gusty / Turbulent Air Conditions.

Some 505 helicopters with the GFC 600H autopilot version V403100, and optional yaw axis installed, may exhibit pedal oscillations during certain turbulent and/or gusty wind conditions. The pedal oscillations may be exacerbated at or above 120 Knots Indicated Airspeed (KIAS).

Owners/operators of the affected models 505 are advised to follow the actions recommended in the Garmin Service Alert (attached).

For any questions regarding this letter, please contact:

Bell Product Support Engineering

Tel: 1-450-437-2862 / 1-800-363-8023 / productsupport@bellflight.com

or

Garmin Aviation Customer Support
<u>Tel: 913-397-8200</u> / <u>1-866-739-5687</u>
http://explore.garmin.com/en-US/general-aviation/



1200 E. 151st Street Olathe, KS 66062 913-397-8200

SERVICE ALERT

NO.: 22032 Rev A

TO: Owners/Operators of Bell 505 rotorcraft with a GFC 600H

DATE: March 18, 2022

SUBJECT: GFC 600H Pedal Oscillation Observed Under Gusty / Turbulent Air Conditions

PRODUCTS AFFECTED

Garmin GFC 600H Helicopter Flight Control installed in the Bell 505 with the following are affected:

- GFC 600H software version v403100 installed
- · Optional yaw axis installed

ISSUE

Some Bell 505 installations of the GFC 600H autopilot system may exhibit pedal oscillations during certain turbulent and/or gusty wind conditions. The pedal oscillations may be exacerbated at or above 120kts KIAS.

ACTION

If the condition is observed do the following:

- 1. PLACE FEET ON PEDALS to reduce/prevent pedal movement.
- 2. DISENGAGE YAW using the YAW ON/OFF switch mounted on the collective.
- 3. REDUCE SPEED to 100KIAS or less if continued use of yaw is desired.
- 4. At pilot discretion ENGAGE YAW using the YAW ON/OFF switch.

If condition persists, DISENGAGE YAW.

RESOLUTION

This issue will be corrected in an update to GFC 600H STC SR01961WI.

© 2022 Garmin Ltd. or its subsidiaries.

This work is licensed under a

Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License.

Service Alert 22032 Page 1-1
March 18, 2022 Revision A