



INFORMATION LETTER

206-14-104

206L-14-98

22 April 2014

TO: All owners and operators of Model 206A/B/L helicopters

**SUBJECT: INTRODUCTION OF TAIL ROTOR GEAR BOX CAP ASSEMBLY P/N
206-040-437-101**

Bell Helicopter has received infrequent reports of damaged tail rotor gearbox output seal lips and the wear sleeve.

This information letter is issued to notify operators that a new cap assembly has been developed. The new cap assembly adds an internal oil passage to improve lubrication to the seal area. This cap assembly is a direct replacement for cap assembly 206-040-437-001.

Due to the dimensional differences of the castings, cap assembly 206-040-437-001 cannot be modified.

Information pertaining to the new cap assembly will be added in a future revision of the BHT-206A/B-SERIES-IPB and BHT-206L-SERIES-IPB.

For any questions regarding this letter, please contact:

Bell Helicopter Product Support Engineering - Light Helicopters
Tel: 450-437-2862 / 1-800-363-8023 / pselight@bh.com