

ALERT SERVICE BULLETIN



NO. 427-09-27
DATE Sep 01, 2009
PAGE 1 of 3

DATE
REV

MODEL AFFECTED: 427

SUBJECT: BHT 427 MM, Chapter 4, Correction of

HELICOPTERS AFFECTED: Model 427 helicopters serial number 56001 and subsequent and 58001 and subsequent

COMPLIANCE: Immediately upon receipt of this bulletin.

DESCRIPTION:

At revision 10 of BHT-427-MM, dated 28 August 2008, mistakes were reported in the Chapter 4, Table 4-2, Airworthiness Limitations Schedule. The retirement life of certain crosstubes was incorrectly listed.

This bulletin introduces a revision of the applicable maintenance manual.

APPROVAL:

The engineering design aspects of this bulletin are Transport Canada Civil Aviation (TCCA) approved.

MANPOWER:

Not applicable.

WARRANTY:

Not applicable

MATERIAL:

Required Material:

The following material is required for the accomplishment of this bulletin and may be obtained through your Bell Helicopter Textron Supply Center.

None required

Consumable Material:

The following material is required to accomplish this bulletin, but may not require ordering, depending on the operator's consumable material stock levels. This material may be obtained through your Bell Helicopter Textron Supply Center.

None required

SPECIAL TOOLS:

None required

WEIGHT AND BALANCE:

Not affected

ELECTRICAL LOAD DATA:

Not affected

REFERENCES:

BHT-427-MM

PUBLICATIONS AFFECTED:

BHT-427-MM

ACCOMPLISHMENT INSTRUCTIONS:

1. Insert BHT-427-MM Revision 11 dated 18 August 2009 in the maintenance manual.
2. Verify that all parts/components are within the retirement life listed in Chapter 4 of the latest maintenance manual revision.
3. Make an entry in the helicopter records indicating compliance with this bulletin.