



# **ALERT SERVICE BULLETIN INDEX**

## **NOTE**

THIS INDEX IS A LIST OF ALERT SERVICE BULLETINS ISSUED. THIS INDEX DOES NOT IDENTIFY WHICH ALERT BULLETINS ARE ACTIVE OR INACTIVE.

THE ATA/CHAP. REF. COLUMN INDICATES THE MAINTENANCE AND/OR OVERHAUL MANUAL CHAPTER/S AFFECTED BY THE RESPECTIVE BULLETIN; OR, THE BULLETIN IS APPLICABLE TO A SERVICE INSTRUCTION (S.I.).

## **PROPRIETARY RIGHTS NOTICE**

These data are proprietary to Bell Helicopter Textron, Inc. Disclosure, reproduction, or use of these data for any purpose other than helicopter operation is forbidden without prior written authorization from Bell Helicopter Textron, Inc.

Newly released Alert Service Bulletins can be viewed and printed by accessing our Service Directives website at [www.bellcustomer.com](http://www.bellcustomer.com). This publication supersedes BHT-205A1-ASB INDEX dated 1 January 2007 in its entirety.

COPYRIGHT NOTICE  
COPYRIGHT 2008  
BELL® HELICOPTER TEXTRON INC.  
AND BELL HELICOPTER TEXTRON  
CANADA LTD.  
ALL RIGHTS RESERVED

**Bell Helicopter**  
A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

**1 JANUARY 2008**



**205A1 ALERT SERVICE BULLETIN INDEX**

STATUS CODE

A = Active

A- ( ) = Active — (Additional Information)

└────────── P = Incorporated in Parts Catalog  
 R = Referenced in Maintenance Manual

I = Inactive

I- ( ) = Inactive — (Reason)

└────────── I = Incorporated in Maintenance Manual  
 P = Incorporated in Parts Catalog  
 S = Superseded (New Bulletin Number)  
 R = Referenced in Maintenance Manual

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
205A-1	Basic	9-18-68		26	Relocation of Fire Detector Unit
205A-2	Basic	2-5-69		27	Removal of Lower Irreversible Pilot Valve Plugs in the 205A/ 205A-1 Cyclic Cylinders, P/N 205-076-035-1
205A-3	Basic Rev B	4-2-69 8-3-70		4	Assignment of 1000 Hour Retirement Life for Model 204B Float Gear Aft Cross Tube, P/N 204-706-053-5 and 205A/A-1; Float Gear Cross Tubes (Fwd P/N 205-050-114-3) (Aft 205-050-114-1)
205A-4	Basic	12-15-69		32	Inspection of 205A/A-1 Forward and Aft Cross Tubes, P/N 205-050-114-1, -3, and -5
205A-5	Basic	11-20-70		27	Inspection of 205A/A-1 Anti-Torque Pitch Change Chains, P/N's 205-001-721-1 and 205-001-748-1
205A-6	Basic Rev A	5-11-71 6-14-71		53	Inspection and Modification of 205A/A-1 Tailboom Vertical Forward Spar, P/N 205-032-851

**BHT-205A1-ASB INDEX****205A1 ALERT SERVICE BULLETIN INDEX**

<b>NUMBER</b>	<b>ISSUE</b>	<b>DATE</b>	<b>STATUS</b>	<b>ATA/CHAP</b>	
				<b>REF.</b>	<b>SUBJECT</b>
205A-7	Basic	6-5-72		65	Inspection of Tail Rotor Hub and Blade Assy, P/N's 204-011-701-1, -5, -9, and -15; 204-011-800-5, -7, -15, and -17
205-02-73-1	Basic Rev A	2-16-73 4-11-73		S.I.	Float Kit Installation, P/N 205-706-050-1, Inspection of Forward and Aft Float Cross Tubes, P/N 205-050-114-7 and -9, and Installation of Friction Damper Assys, P/N 205-050-127-3 and -5
205-04-73-1	Basic Rev A	11-13-73 11-5-75		66	Grease, Part Number 204-040-755-3, Dated After July, 1973
205-(04-1)-73-1	Basic Rev A	7-31-73 8-3-73		65	Inspection of Main Rotor Blades, P/N 204-011-250 (All Dash Numbers)
205-05-73-1	Basic	5-23-73		65	Inspection of Tail Rotor Hub and Blade Assemblies, P/N 204-011-800-7, -15, -17, and -25
205-05-73-2	Basic	6-4-73		65	(A) Modification to Marvel Model 7HEL075 Kit - Tail Rotor Balancing (B) A One-Time Tail Rotor Balancing and Track Inspection Requirement
205-05-73-3	Basic Rev A	6-15-73 6-18-73		65	Tail Rotor Blade Retention Bearing Inspection, Hub and Blade Assembly, P/N 212-010-701-17
205-05-73-4	Basic Rev A	7-18-73 7-25-73		4	Mandatory Replacement Interval for Tail Rotor Grip Assy, P/N 204-011-728, is Reduced to 500 Hours
205-05-73-5	Basic	8-23-73		65	Inspection of Tail Rotor Hub Assembly P/N 212-010-701
205-05-73-6	Basic Rev C	12-6-73 3-21-74		65	Cancelling of Inspection of Tail Rotor Yoke, P/N 212-010-744-1
205-06-73-1	Basic	11-2-73		29	Installation of Temperature Indicators on the Hydraulic Reservoirs

## 205A1 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
205-11-73-1	Basic Rev A	6-26-73 7-24-73		27	Inspection of Anti-Torque Silent Chain Assemblies, P/N 205-001-721-1 and P/N 205-001-748-1
205-04-74-1	Basic	2-5-74		66	Inspection of Main Driveshaft Boot, P/N 205-040-176-3
205-(04-2)-74-1	Basic	9-3-74		65	Inspection of Swashplate Scissors Level Bolts, P/N 464-P8-90 or P/N 212-010-411-1
205-05-74-1	Basic Rev A	3-1-74 6-24-74		27	Revised Tail Rotor Rigging Procedures
205-05-74-2	Basic	11-11-74		65	Inspection of Tail Rotor Assembly, P/N 212-010-701 (All Dash Numbers), for Interference
205-75-1	Basic	3-14-75		11	One Time Inspection of Emergency Exit Decals
205-75-2	Basic	4-1-75		S.I.	Internal Rescue Hoist Assembly, P/N 205-706-030-5, -15, or -21
205-75-3	Basic	4-18-75		66	Inspection of Transmission Assembly Oil System
205-75-4	Basic Rev A	9-18-75 10-14-75		27	Inspection of Anti-Torque Pitch Change Control Assembly, P/N 205-012-721-1 or 204-010-740-5, and Pitch Change Rod, P/N 205-012-722-1
205-75-5	Basic Rev C	9-12-75 4-25-79		65	Inspection, Sealing, and Refinishing of Main Rotor Blade, P/N 204-011-250 (All Dash Numbers)
205-75-6	Basic Rev A	8-8-75 8-22-75		11	Replacement of Emergency Exit Decals and Escape Release Handle Covers
205-75-7	Basic Rev B	11-5-75 3-5-76		26	Inspection of Fire Extinguisher Cartridges
205-75-8	Basic	12-12-75		S.I.	Replacement of the Float Damper Clevis Fitting, P/N 205-050-123-005, With A Float Damper Fitting, P/N 205-050-130-001

**BHT-205A1-ASB INDEX****205A1 ALERT SERVICE BULLETIN INDEX**

<b>NUMBER</b>	<b>ISSUE</b>	<b>DATE</b>	<b>STATUS</b>	<b>ATA/CHAP</b>	<b>SUBJECT</b>
				<b>REF.</b>	
205-75-9	Basic	12-16-75		27	Inspection of Anti-Torque Control Chain, P/N 204-001-739-3
205-76-1	Basic	2-17-76		65	One Time Inspection of Main Rotor Blade Bolt Washer, P/N 204-011-152-1
205-76-2	Basic	3-5-76		4	Assignment of 500 Hour Service Life to Float Gear Cross Tubes
205-76-3	Basic	3-17-76		65	Inspection of Stabilizer Bar Outer Tube
205-76-4	Basic	5-17-76		65	Stabilizer Bar Tube
205-76-5	Basic Rev B	5-17-76 10-28-76		27	Synchronized Elevator
205-76-6	Basic Rev A	8-24-76 8-30-76		27	Anti-Torque Controls Fairleads
205-76-7	Basic	9-9-76		27	Hydraulic Actuator Moisture Seal Installation
205-76-8	Basic Rev A	9-10-76 9-23-78		27	Flight Control Tubes and Bellcrank
205-76-9	Basic Rev A	9-9-76 10-28-76		66	Engine to Transmission Driveshaft Alignment (Superseded by SB 205-77-10)
205-76-10	Basic	9-16-76		65	Swashplate Support
205-76-11	Basic Rev A	9-27-76 9-28-76		28	Removal of Screen From S2490 Fitting
205-76-12	Basic	9-29-76		52	Inspection and Adjustment of Latch System
205-76-13	Basic Rev B	9-29-76 12-9-76		65	Replacement of NAS Bolts With Bell Standard Bolts
205-76-14	Basic	10-1-76		28	One Time Inspection of Fuel Boost Pumps
205-76-15	Basic	10-26-76		66	Replacement of Tail Rotor Hanger Bearings
205-76-16	Basic	11-15-76		S.I.	Rotor Brake Quill, P/N 205-040-300-1

## 205A1 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	SUBJECT
				REF.	
205-76-17	Basic	12-1-76		66	Replacement of Coupling Seals on Main Driveshaft Assy, P/N 205-040-004-17
205-76-18	Basic Rev A	12-22-76 1-3-77		65	Inspection of Steel Grip Pad on Main Rotor Blade, P/N 204-011-250
205-77-1	Basic Rev A	1-10-77 2-1-77		5	1000 Hour Special Inspection Req. for Main Rotor Hub Fitting Assy, P/N 204-012-102-5; Pins, P/N 204-012-104-5; and Strap Assemblies, P/N 204-012-112-5
205-77-2	Basic	1-19-77		27	Hydraulic Actuators, P/N 205-076-036
205-77-3	Basic	2-16-77		4	Assignment of a 750 Hr Service Life to the Rotor Brake Quill, P/N 204-040-424-1
205-77-4	Basic Rev A	3-11-77 6-13-79		4	Limit Service Life of the Upper Left Hand Tailboom Longeron Assy to 3000 Flight Hours
205-77-5	Basic	3-11-77		65	Tail Rotor Pitch Change Horn, P/N 212-010-716
205-77-6	Basic	3-22-77		52	Adding Additional Inspection Holes in the L/H & R/H Passenger Door Assemblies
205-77-7	Basic	4-11-77		27	Tail Rotor Chain Guard Assembly, P/N 205-012-725-1
205-77-8	Basic	5-12-77		71	Inspection of Engine Driveshaft Adapter Bolt P/N 204-040-813-1 For Loss of Torque
205-77-9	Basic	6-6-77		52	Replacement of Spacers Attaching the Emergency Escape Release Handle Covers
205-77-10	Basic	6-9-77		66	Engine to Transmission Driveshaft Alignment

**BHT-205A1-ASB INDEX****205A1 ALERT SERVICE BULLETIN INDEX**

<b>NUMBER</b>	<b>ISSUE</b>	<b>DATE</b>	<b>STATUS</b>	<b>ATA/CHAP</b>	
				<b>REF.</b>	<b>SUBJECT</b>
205-77-11	Basic	6-9-77		66	Inspection of Tail Rotor Driveshafts and Removal of Anti-Chafing Tape from the Tail Rotor Driveshaft Cover and the Fin Cover Door Assemblies
205-77-12	Basic Rev A	6-15-77 2-20-79		66	Replacement of the Coupling Seals on the Main Driveshaft Assembly, P/N 205-040-004-17
205-77-13	Basic	6-27-77		27	Replacement of Tail Rotor Chain Guard P/N 205-010-747-3
205-77-14	Basic	7-22-77		27	Inspection of Hydraulic Actuators, P/N 212-076-005-9
205-78-1	Basic	2-21-78		S.I.	External Cargo Suspension Kit, Decrease of Load Rating
205-78-2	Basic	4-19-78		4	Main Rotor Hub Strap Assemblies, P/N 204-012-112-5, Reduction of Service Life
205-78-3	Basic	4-19-78		4	Main Rotor Hub Inboard Fitting, P/N 204-012-102-5, Reduction of Service Life
205-78-4	Basic Rev A	5-11-78 5-11-78		S.I.	Replacement of External Cargo Hook Link Assembly, P/N 205-070-944-1 or -5, With New Link Assembly, P/N 205-070-944-7
205-78-5	Basic	5-16-78		27	Mandatory Installation of Tail Rotor Push-Pull Control System
205-78-6	Basic	10-13-78		4	M/R Hub Strap Pin, P/N 204-021-104-5, Reduction of Service Life
205-79-7	Basic Rev A	3-7-79 4-25-79		27	Control Installation, P/N 205-001-020-001, -005, -007, Inspection of Cyclic Control Cylinder Assys, P/N 205-076-36-007, -009, -011, Replacement of Piston
205-79-8	Basic	5-22-79		65	Main Rotor Hub Assembly, P/N 204-012-101 (All Dash Numbers), Corrosion Protection of

## 205A1 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	SUBJECT
				REF.	
205-79-9	Basic Rev A	8-7-79 4-28-80		66	Inspection and Replacement of Transmission Aluminum Oil Tubes, P/N's 205-040-214-1, 205-040-213-1, and Quick Disconnect Coupling Halves, P/N 375200-12 and P/N 375504-12
205-79-10	NEVER ISSUED				
205-79-11	Basic	10-19-79		27	Hydraulic Cylinder Assemblies, P/N 212-076-005-001, -005, -007, -009, and -011, Inspection and Rework of Spanner Link Assy, P/N 41000517
205-80-12	Basic	5-13-80		4	Reduction of Retro-fit Life of Tension/Torsion Straps, P/N 204-012-122-001/-005
205-80-13	Basic Rev A	8-20-80 9-12-80		4	Float Landing Gear Crosstube, P/N's 205-050-114-001, -003, -005, -007, -009, -011, -013, and 205-706-050-005, -009, and -013, Mandatory Retirement and Mandatory Relocation of Forward Friction Damper
205-80-14	Basic Rev A	12-8-80 3-25-81		66	Oil and Fuel Filter, P/N 204-040-760, V-Band Clamp T-Bolt, Replacement of
205-81-15	Basic	2-3-81		66	Zinc Chromate, Thermal Limit Indicator, Addition of
205-81-16	Basic	6-22-81		4	Main Rotor Yoke, P/N 204-011-102 (All Dash Numbers), Retirement Life of
205-81-17	Basic	10-26-81		65	Swashplate Support Assembly, P/N 204-011-404-121, Inspection of
205-81-18	Basic	10-28-81		27	Main Hydraulic Cylinder Assembly, P/N 212-076-005-101, Inspection of the Lower Servo Housing for Blocked Bypass Passage
205-82-19	Basic	4-5-82		S.I.	Rotor Brake Master Cylinder, Maximum Pressure, Inspection of

**BHT-205A1-ASB INDEX****205A1 ALERT SERVICE BULLETIN INDEX**

<b>NUMBER</b>	<b>ISSUE</b>	<b>DATE</b>	<b>STATUS</b>	<b>ATA/CHAP</b>	
				<b>REF.</b>	<b>SUBJECT</b>
205-82-20	Basic	7-26-82		S.I.	Internal Hoist, P/N 214-070-300-1, Western Gear Corp. P/N 42277R1, Inspection and Modification of
205-84-21	Basic	11-2-84		27	Elevators, P/N 205-030-856-091 and -093, and Prior Dash Numbers to Horn Assembly, P/N 205-001-914-027, Attachment, Modification of
205-85-22	Basic Rev A	1-17-85 1-23-85		65	Main Rotor Grip/Blade Bolt Interference on Repaired Grips, P/N 204-011-121 Series, Inspection of
205-86-23	Basic Rev A	6-26-86 10-14-86		53	Fin Spar Assembly, P/N 212-030-121-005 and -007, Spar Cap Assembly, P/N 212-030-447-001 and -101, Inspection and Repair of
205-86-24	Basic Rev A	6-27-86 7-23-86		65	Tail Rotor Trunnion Bearing Housing, P/N 212-011-716-001, Inspection of
205-87-25	Basic	3-23-87		65	Main Rotor Pillow Block to Yoke Attachment Washer, P/N AN 960-816, Replacement of
205-87-26	Basic Rev A	8-4-87 8-21-87		66	Main Rotor Mast, P/N 204-011-450 Series, and Main Rotor Trunnion, P/N 204-011-105-001, Assignment of Retirement Life
205-87-27	Basic	11-12-87		32	Ground Handling Wheel Gear Assembly, P/N 212-050-200-005 and -101, Cradle Assembly, P/N 214-050-011-001, Pin Replacement of
205-87-28	Basic	12-15-87		65	Main Rotor Yoke, P/N 204-011-102, (All Dash Numbers), Inspection of

## 205A1 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	SUBJECT
				REF.	
205-88-29	Basic	5-4-88		27	Flight Control Cylinder Assemblies, P/N 212-076-005 (All Dash Numbers) and 212-076-004 (All Dash Numbers), Cleaning of
205-88-30	Basic	6-1-88		27	Flight Control Cylinder Assemblies, P/N 205-076-029 (All Dash Numbers), 205-076-031 (All Dash Numbers) and 205-076-036 (All Dash Numbers), Cleaning of
205-88-31	Basic	7-28-88		32	Ground Handling Wheel Gear Assembly, P/N 204-050-200-005 and -15 Forward Support Pin, Replacement of
205-89-32	Basic	4-6-89		66	Spiral Bevel Gear P/N 204-040-701-103, Inspection of
205-89-33	Basic Rev A	8-29-89 8-29-89		65	Strap Assembly, Main Rotor, Tension-Torsion P/N 204-012-122-5 and P/N 204-310-101-101, Removal From Service
205-89-34	Basic Rev A	9-8-89 10-27-92		65	Main Rotor Flight Control System Bolts, Inspection of
205-89-35	Basic Rev A	10-25-89 3-8-90		S.I.	Cargo Hook P/N SP7109-11, Warning Plate, Addition of
205-90-36	Basic Rev A	3-23-90 8-31-90		65	Main Rotor Yoke P/N 204-011-102 (All Dash Numbers) Inspection of
205-90-37	Basic	3-26-90		65	Swashplate Outer Ring P/N 204-011-403-001, S/N SC-000014, Removal From Service
205-90-38	Basic Rev A	6-26-90 10-11-90		65	Main Rotor Pillow Block Attachment Bolt 204-011-171-003, Washer 140-007-33S28-3 and Nut EB080, One Time Use of
205-90-39	Basic	9-18-90		53	Tailboom Upper Longeron Splice Inspection Provisions

**BHT-205A1-ASB INDEX****205A1 ALERT SERVICE BULLETIN INDEX**

<b>NUMBER</b>	<b>ISSUE</b>	<b>DATE</b>	<b>STATUS</b>	<b>ATA/CHAP</b>	<b>SUBJECT</b>
				<b>REF.</b>	
205-90-40	Basic Rev A	10-2-90 3-21-91		4	Method of Calculating Retirement Life On Subject Parts and Assignment of Retirement Lives 1) Main Rotor Mast P/N 204-011-450-All Dash Numbers 2) Main Rotor Trunnion 204-011-105-001
205-90-41	Basic	12-5-90		52	Crew Door Hinge Pins (Jettison Pins) P/N 204-030-790-011/-013
205-91-42	Basic	9-26-91			Tension-Torsion Strap Retention Pins P/N 204-012-104-005
205-91-43	Basic Rev B	10-4-91 11-21-91			Tail Rotor Driveshaft Hanger Bearing P/N 204-040-623-003/-005
205-91-44	Basic	11-21-94			Tail Rotor Driveshaft Hanger Bearing P/N 204-040-623-003/-005
205-91-45	Basic	12-13-91			Swashplate Support P/N 204-011-404-125
205-92-46	Basic	2-6-92			Scissors Link to Swashplate Attachment Bolt, Inspection of
205-92-47	Basic	5-6-92			Oil Level Indicators P/N 204-040-508-005/-007/-013
205-92-48	Basic	8-5-92			Tail Rotor Yoke 212-010-704-005/-007
205-92-49	Basic	10-5-92			Tail Rotor Driveshaft Inspection of
205-92-50	Basic Rev A	10-23-92 11-11-92			Lower Planetary Spider Gear P/N 204-040-785-003 Magnetic Particle Inspection, All Transmission Assemblies Of All Part and Dash Numbers
205-92-51	Basic	10-23-92			Main Rotor Yoke P/N 204-011-102 All Dash Numbers, Removal From Service
205-92-52	Basic	11-6-92			Main Beam Cap P/N 205-030-164-095
205-92-53	Basic Rev A	2-1-93 6-1-93			Rotor Brake Quill P/N 205-040-300-001, Removal From Service

205A1 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
205-93-54	Basic	6-18-93			Lower Spider P/N 412-040-785-101, Assignment of Retirement Life
205-93-55	Basic Rev A	6-21-93 6-20-94			Cargo Hooks, Breeze Eastern Customer Advisory Bulletin No. CAB-100-41, Customer Service Bulletin No. CSB-129 and CSB-142
205-93-56	Basic Rev A	6-21-93 7-1-94			Tailboom Doubler P/N 212-030-099-089/-129
205-93-57	Basic	11-10-93			Tail Rotor Driveshaft Hanger Bearing P/N 204-040-623-005 One Time Inspection of
205-93-58	Basic Rev A	12-7-93 3-4-94			Main Driveshaft and Tail Rotor Drive System Grease Lubricated Couplings, Over-temperature Indicators, Installation of
205-94-59	Basic Rev B	5-23-94 8-17-95			Blade Bolt P/N 204-011-151-001, Removal From Service Of Specific Serial Numbers
205-94-60	Basic	11-28-94			Main Rotor Yoke P/N 212-011-102-105 Inspection of:  Main Rotor Hub Pitch Change Bearings P/N 212-011-111-103, and P/N 212-011-112-103: Removal of Inner Races From Service  Introduction of New Inner Races P/N 212-311-009-101 and P/N 212-311-010-101 Into Service
205-95-61	Basic	2-13-95			Introduction of New Scheduled Inspection Overhaul and Conditional Inspection Requirements: Main Rotor Grip P/N 204-011-121-005, -117 and Part Number Grips With Modified Suffix Characters

**BHT-205A1-ASB INDEX****205A1 ALERT SERVICE BULLETIN INDEX**

<b>NUMBER</b>	<b>ISSUE</b>	<b>DATE</b>	<b>STATUS</b>	<b>ATA/CHAP REF.</b>	<b>SUBJECT</b>
205-95-62	Basic Rev A	7-3-95 2-12-96			Powertrain Modification on Model 205A-1
205-95-63	Basic Rev C	5-8-95 10-9-95			Tail Rotor Hanger Bearings P/N 204-040-623-003/-005, Application of Witness Mark
205-95-64	Basic	6-5-95			Elbow P/N 212-076-146-001, Removal From Service
205-95-65	Basic Rev A	7-24-95 2-12-96			Main Rotor Mast 204-011-450- 007/-105, and Main Rotor Trunnion 204-011-105-001, Change of Retirement Life and Method of Determination
205-95-66	Basic	12-11-95			Main Rotor Hydraulic Servo Actuators 212-076-005-011/-101, One Time Inspection of Shoulder Bolts
205-96-67	Basic	5-1-96			Main Rotor Blade P/N 204-011- 250-ALL: Introduction of Daily Wipe-down Inspection and Special 25 Hour Inspection
205-96-68	Basic Rev A	8-1-96 5-18-98			Tail Rotor Yoke Assemblies P/N 212-010-704-All and P/N 212- 010-744-All Inspection of; and Trunnion Assemblies P/N 212- 010-738-001 Inspection of, and Trunnion Assemblies P/N 205- 012-716-001 and P/N 212-010- 703-001 Removal from Service
205-96-69	Basic	9-3-96			Tail Rotor Yoke P/N 212-011-702- All Inspection of, and Tail Rotor Flapping Stop/ Yield Indicator P/N 212-011-713-103 Installation of
205-98-70	Basic Rev A	2-27-98 9-21-98			Fin Spar Cap, Inspection of
205-98-71	Basic Rev A	5-15-98 9-21-98			Fin Spar, Inspection of
205-98-72	Basic Rev B	8-3-98 10-22-98			HR Textron Safety Bulletin, Inspection for Bogus Actuators

## 205A1 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
205-98-73	Basic Rev B	10-9-98 2-28-00			Fin Spar Cap, Replacement of
205-99-74	Basic	1-8-99			High Landing Gear Aft Crosstube, Assignment of Retirement Life
205-99-75	Basic	3-19-99			BL-4807 Swivel Hook Reliability Improvement
205-00-76	Basic Rev B	4-24-00 8-4-00			Main Rotor (M/R) Mast, P/N 204- 011-450- 007/-105, Inspection and Retirement Index Number (RIN) Life Reduction
205-00-77	Basic Rev A	5-26-00 9-13-00			Tail Rotor Counterweight Bellcrank Retention Nut MS14145L6 and MS17826-6, Installation and One Time Use Of
205-00-78	Basic Rev A	8-1-00 9-9-02			Cargo Hook, Onboard Systems P/N 528-002-00
205-00-79	Basic	10-19-00			Main Hydraulic Servo Actuator Rod End Lock Washer, Inspection and Replacement of
205-00-80	Basic Rev D	11-10-00 3-18-05			Tail Rotor (T/R) Blade 212-010- 750-009/-011/-105/-107, Tip Block Retention Modification
205-01-81	Basic	1-19-01			Magnetic Brake P/N 204-001-376- 003, One Time Inspection of
205-01-82	Basic	3-30-01			Chip Detector Assy, Tedeco B3703
205-01-83	Basic	4-19-01			Clutch Assembly P/N X134296, Assignment of Retirement Life
205-01-84	Basic Rev A	7-26-01 7-30-01			Pillow Block P/N 204-011-108-113, Tube Assembly P/N 212-010-404- 005, Strap Fitting P/N 204-012- 102-009, Inspection and Recall of Specific Serial Number Part
205-01-85	Basic	10-18-01			Main Rotor Head Inboard Fitting 204-012-102-009, Inspection of Specific Serial Numbers

**BHT-205A1-ASB INDEX****205A1 ALERT SERVICE BULLETIN INDEX**

<b>NUMBER</b>	<b>ISSUE</b>	<b>DATE</b>	<b>STATUS</b>	<b>ATA/CHAP REF.</b>	<b>SUBJECT</b>
205-02-86	Basic	6-20-02			1200 Hour Special Inspection Requirements for Main Rotor Hub Pins P/N 204-012-104-003/-005
205-02-87	Basic	11-22-02			Tail Rotor Blade Assemblies P/N 212-010-750-011/-113/-115, Inspection and Rework of
205-02-88	Basic	11-26-02			Main Rotor Grips 204-011-121-117, Ultrasonic Inspection of
205-04-89	Basic	12-3-04			Tail Rotor Pitch Horn Assembly P/N 212-011-708-105, Replacement of
205-05-90	Basic	2-18-05			Crosshead P/N 212-010-775-001, Inspection and Recall of Specific Serial Number Part
205-05-91	Basic	4-30-05			Tail Rotor Blade P/N 212-010-750-009 through -129, Inspection and Rework of
205-07-92	Basic	3-6-07			Aeronautical Accessories, Inc. ASB No. AA-06107 for PC Safety Valve™: Valve Stem Over Torque
205-07-93	Basic	6-11-07			Assignment of a 100-hour Retirement Life for Stabilizer Bar Mixing Lever Bearings P/N KP6A, AN201KP6A, MS20201KP6A, MS27641-6, and Scissors Assembly Pivot Bearings P/N KP8A, AN201KP8A, MS20201KP8A, MS27641-8
205-07-94	Basic	6-11-07			Starter/Generator Power Cable Upgrade
205-07-95	Basic Rev A	9-11-07 9-19-07			Tail Rotor Blade Assembly, Inspection of
205-07-96	Basic	11-27-07			Cyclic Flight Control Bearing, P/N MS27643-4 One Time Inspection and Replacement of

NOTICE

The following blank pages are provided for entry of additional bulletins when distributed. These additional bulletins will be included in this index at next revision.

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
--------	-------	------	--------	------------------	---------

# BHT-205A1-ASB INDEX

## NOTICE

The following blank pages are provided for entry of additional bulletins when distributed. These additional bulletins will be included in this index at next revision.

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
--------	-------	------	--------	------------------	---------