



ALERT SERVICE BULLETIN INDEX

NOTE

THIS INDEX IS A LIST OF ALERT SERVICE BULLETINS ISSUED. THIS INDEX DOES NOT IDENTIFY WHICH ALERT BULLETINS ARE ACTIVE OR INACTIVE.

THE ATA/CHAP. REF. COLUMN INDICATES THE MAINTENANCE AND/OR OVERHAUL MANUAL CHAPTER/S AFFECTED BY THE RESPECTIVE BULLETIN; OR, THE BULLETIN IS APPLICABLE TO A SERVICE INSTRUCTION (S.I.).

PROPRIETARY RIGHTS NOTICE

These data are proprietary to Bell Helicopter Textron, Inc. Disclosure, reproduction, or use of these data for any purpose other than helicopter operation is forbidden without prior written authorization from Bell Helicopter Textron, Inc.

Newly released Alert Service Bulletins can be viewed and printed by accessing our Service Directives website at www.bellcustomer.com. This publication supersedes BHT-222/B-ASB INDEX dated 1 January 2007 in its entirety.

COPYRIGHT NOTICE
COPYRIGHT 2008
BELL® HELICOPTER TEXTRON INC.
AND BELL HELICOPTER TEXTRON
CANADA LTD.
ALL RIGHTS RESERVED

Bell Helicopter
A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

1 JANUARY 2008

222/B ALERT SERVICE BULLETIN INDEX

STATUS CODE

A = Active

A- () = Active — (Additional Information)

└────────────────── P = Incorporated in Parts Catalog
R = Referenced in Maintenance Manual

I = Inactive

I- () = Inactive — (Reason)

└────────────────── I = Incorporated in Maintenance Manual
P = Incorporated in Parts Catalog
S = Superseded (New Bulletin Number)
R = Referenced in Maintenance Manual

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
222-80-1	Basic	10-21-80		96	Overhead Console Electrical Installation, Modification of
222-80-2	Basic Rev A	12-17-80 3-30-81		65	Drive Hub Assembly, P/N 222-010-417-009, Inspection and Modification of
222-81-3	Basic	2-4-81		66	Zinc Chromate Primer, Thermal Indicator, Addition of
222-81-4	Basic	3-5-81		96	Battery Temperature Sensors for 17AH Battery, P/N GE43B010RB03, Wiring Change, Termination of
222-81-5	Basic	4-9-81		26	Engine Fire Extinguisher Installation, P/N 222-069-910-101, Squib Discharge Valve, Identification and Wiring, Clarification of
222-81-6	Basic	4-27-81		66	Tail Rotor Driveshaft Hanger Bearing, P/N 222-344-606-003, Alignment of
222-81-7	NEVER ISSUED				
222-81-8	Basic	9-15-81		96	Rework of Electrical Cable Assemblies to Prevent Chafing

BHT-222/B-ASB INDEX

222/B ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	SUBJECT
				REF.	
222-81-9	Basic	9-28-81		25	Rescue Hoist and Provision Kit, P/N 222-899-110-101, -103, and Heavy Duty Rescue Hoist Installation, P/N 222-899-184-101, Addition of Electrical Ground to Hoist
222-81-10	Basic	10-21-81		65	Collective Lever Assembly, P/N 222-010-497-101, Inspection of
222-82-11	Basic	4-29-82		53	Tailboom P/N 222-035-100-103, Inspection, Repair, and Modification of
222-82-12	Basic	5-18-82		65	Swashplate Drive Link Assemblies, P/N 222-010-460-101, Inspection and Replacement of
222-82-13	Basic	5-18-82		65	Aluminum Swashplate Drive Link Assemblies, P/N 222-010-460-101, Inspection and Replacement of
222-82-14	Basic Rev A	4-30-82 5-28-87		65	Swashplate Drive Assembly, P/N 222-010-417-009, and Spline Plate, P/N 222-310-418-105/-107, Inspection of
222-82-15	Basic Rev A	4-30-82 8-24-82		65	Main Rotor Blade, P/N 222-015-500-101, Center Spar Doubler, Inspection, Sealing, and Protection of
222-82-16	Basic	6-22-82		27	Servo Actuator, P/N 222-382-001-101, Inspection of
222-82-17	Basic Rev A	10-18-82 2-28-83		65	Main Rotor Trunnion, P/N 222-010-154-101, and Mast Assembly, Torquemeter, P/N 222-040-002-103, Mandatory Life Reduction
222-83-18	Basic	1-26-83		65	Walking Beam Assembly, P/N 222-010-415, Inspection of
222-83-19	Basic	3-28-83		65	Walking Beam Assembly, P/N 222-010-415-005 and -009, Modification

222/B ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
222-83-20	Basic	4-5-83		53	Nodal Beam Left Side Aft Support Fitting, P/N 222-031-520-105, Airworthiness Life (Hours), Assignment of
222-83-21	Basic	4-11-83		27	Synchro Transmitter Arm Retaining Clip, P/N 222-001-455-101, Installation of
222-83-22	Basic Rev A	4-27-83 5-4-83		65	Idler Link Assembly and Collective Lever Connecting Bolt, P/N 20-057-10-45D, Inspection and Retorque of
222-83-23	Basic Rev A	8-30-83 8-30-83		25	Rescue Hoist Installation, P/N 222-899-110-101/-103, Hoist, P/N BL-16600 (All Dash Numbers), Conversion and Inspection of
222-83-24	Basic	9-28-83		S.I.	Switch Guard, P/N 51380-C, On Float Arm Switch, P/N 106488H1-19, Modification of
222-83-25	Basic	11-7-83		32	Nose Gear Trunnion Assembly, P/N 3965001-3, Inspection of
222-84-26	Basic	7-16-84		S.I.	Emergency Flotation Reservoir, P/N 222-325-021-101, Decal (WARNING), P/N 31-023-8B, and Decal (CAUTION), P/N 31-023-9B, Installation of
222-85-27	Basic	2-13-85		S.I.	Dual Controls Auxiliary Equipment Kit, P/N 222-706-084-101/-103, Installation of Spring Pin Assembly
222-85-28	Basic	3-21-85		53	Tailboom, P/N 222-035-150-103, Inspection, Repair, and Modification of
222-85-29	Basic	4-12-85		26	Fire Detector Element Ground Strap, Addition of
222-85-30	Basic	6-13-85		96	Instrument Current Limiter, P/N 531-1 Reconfiguration of
222-85-31	Basic Rev A	6-27-85 11-1-85		71	Engine, Lycoming LTS-101-650C-2/-3 and 101-750C-1, Ng Operating Speed Restrictions

BHT-222/B-ASB INDEX**222/B ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	SUBJECT
				REF.	
222-85-32	Basic Rev A	9-5-85 11-3-86		27	Directional Hydraulic Actuator, P/N 222-382-002-101, Inspection of Rod End
222-85-33	Basic	8-13-85		27	Directional Hydraulic Actuator, P/N 222-382-002-101, and Main Rotor Control Dual Servo Actuator, P/N 222-382-001-101, Inspection of Control Linkage Rivets
222-85-34	Basic Rev B	9-30-85 10-13-86		25	Rescue Hoist Installation, Conversion of Hoist, P/N BL-16600-80, to P/N BL-16600-110
222-85-35	Basic	11-20-85		53	Fin Assembly, P/N 222-035-220, Modification and Installation of
222-86-36	Basic	6-27-86		S.I.	Emergency Floatation System, and Squib Valve Assembly, P/N 212-073-912-(All), Inspection and Modification of
222-86-37	Basic	8-29-86		96	Rewiring of Engine Chip Detectors to Provide Early Warning of a No. 2 or No. 3 Bearing Failure (222B)
222-86-38	Basic	10-28-86		25	Rescue Hoist Cable Cutter Circuit, Rewiring of in Accordance with Breeze Manufacturing Preferred Method
222-86-39	Basic Rev A	10-31-86 1-14-87		65	Flapping Bearing, P/N 222-310-114-003/-105, Rework of
222-87-40	Basic	1-26-87		65	Swashplate Pins, P/N 222-010-455-003, Inspection of
222-87-41	Basic	2-18-87		S.I.	Emergency Floatation System, Modification of, and Squib Valve Assembly, P/N 212-073-912-(All), Replacement of
222-87-42	Basic Rev B	3-2-88 7-18-88		96	Daily and Periodic Inspection of Engine Oil System Chip Detectors, Installation of the LTS 101-650 Series Engine #2 and #3 Bearings Scavenge Debris Monitor Kit, Wiring of the #2 and #3 Scavenge Debris Monitor to a Dedicated Red Warning Light Segment, Addition of a "Warning" Note to the Flight Manual (222)

222/B ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	SUBJECT
				REF.	
222-87-43	Basic	6-22-87		S.I.	Auxiliary Equipment Kit Emergency Flotation, P/N 222-706-093-101, -107, -111, -115, -119, and -121, Modification of
222-87-44	Basic	10-12-87		52	Aft Passenger Windows (Emergency Exit), Replacement of
222-87-45	Basic	11-19-87		65	Swashplate Drive Assembly, Modification to Incorporate P/N 222-010-471-101 Drive Hub Assembly
222-88-46	Basic	1-4-88		65	Main Rotor Yoke, P/N 222-011-102-101, Inspection of
222-88-47	Basic	3-2-88		96	Daily and Periodic Inspection of Engine Oil System Chip Detectors, Addition of a "Warning" Note to the Flight Manual and Modification of the Chip Detector Electrical System (222B)
222-88-48	Basic Rev A	7-26-88 8-26-88		-	External Hoist, P/N BL-16600-(All Dash Numbers), and Heavy Duty Hoist, P/N BL-20200-1, Inspection of Load Cable and Hook/Bumper Stowage
222-88-49	Basic	9-1-88		53	Bulkhead P/N 222-031-309-101 Web to Angle Attach Rivets One Time Inspection of
222-88-50	Basic	9-1-88		53	Stabilizer Assembly, P/N 222-035-250-101, -103, -105, Inspection of
222-88-51	Basic	11-14-88		65	Main Rotor Yoke Assembly, P/N 222-011-102-101, Modification of
222-89-52	Basic Rev A	1-10-89 8-1-89		79	Aeroquip 601 Hose Assemblies, One-Time Inspection and Replacement
222-89-53	Basic Rev A	3-20-89 5-23-89		53	Stabilizer Assembly, P/N 222-035-250-101, -103, -105 Inspection and Replacement of
222-89-54	Basic Rev A	8-9-89 9-27-89		65	Main Rotor Flight Control Bolts, Inspection of

BHT-222/B-ASB INDEX**222/B ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
222-89-55	Basic	8-24-89		53	Tail Rotor Boost Cylinder Support Bracket, P/N 222-031-471-001, Inspection and Replacement of
222-90-56	Basic	1-15-90		S.I.	Breeze-Eastern Cargo Hook P/N 17172-1 Warning Plate, Addition of
222-90-57	Basic	12-21-90		95	Engine, Lycoming LTS 101-650/-750 Series Power Turbine Speed Restriction for Cast Turbine Wheels
222-91-58	Basic	9-17-91		25	Crew Seat Restraint Assembly 222-320-823-101, -105, -107, -115, Improvement of
222-92-59	Basic Rev A	1-8-92 10-13-92		S.I.	Engine Overspeed Control System (OCS) Kit, Installation of
222-92-60	Basic	12-16-92			Flapping Bearing, P/N 222-310-114-003/-105/-107/-109
222-93-61	Basic Rev A	4-21-93 4-24-96			Engine Air Intake Duct Assembly, P/N 222-062-211, Inspection of
222-93-62	Basic	6-2-93			Lycoming LT 101 Engine, Power Turbine Rotor Assembly P/N 4-141-290-01/-03, One Time Inspection of
222-93-63	Basic Rev B	6-2-93 10-19-93			Lycoming LT 101 Engine, Power Turbine Rotor Assembly P/N 4-141-290-01/-03, Special Inspection of
222-93-64	Basic Rev A	6-21-93 6-20-94			Cargo Hooks, Breeze Eastern Customer Advisory Bulletin No. CAB-100-41, Customer Service Bulletin No. CSB-147
222-93-65	Basic	8-30-93			Flapping Bearings, P/N 222-310-114-003/-105/-107/-109, Replacement of
222-93-66	Basic	10-19-93			Lycoming LT 101 Engine, Gas Producer Rotor Discs P/N 4-111-015-04/-09/-14, One Time Inspection of

222/B ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	SUBJECT
				REF.	
222-93-67	Basic Rev A	12-7-93 3-4-94			Main and Tail Rotor Driveshaft Grease Lubricated Couplings, Over-Temperature Indicators, Installation of
222-94-68	Basic	4-4-94			Lycoming LT 101 Engine, Removal of No. 2 Winged Bearing, P/N 4-301-362-101, S/N 3-740 Thru 3-839, S/N 3-1288 Thru 3-1361 and S/N 4-534 Thru 4-680
222-94-69	Basic	8-12-94			Driveshaft P/N 222-044-645-103 and 222-044-685-101, Inspection of
222-94-70	Basic	9-6-94			Pedal Assembly P/N 222-001-760-001/-003, Modification of
222-94-71	Basic	9-12-94			Nose Wheel Assemblies P/N 222-336-004-001 and P/N 222-336-004-101, One Time Inspection and Replacement of
222-94-72	Basic	10-31-94			Emergency Exit, Passenger Door Windows
222-94-73	Basic	11-14-94			Flapping Spring P/N 222-310-117-103, Inspection of
222-95-74	Basic	1-18-95			Shaft Assembly P/N 222-044-685-101, Recall and Replacement of
222-95-75	Basic	9-25-95			Engine Fire Extinguisher System
222-95-76	Basic Rev B	10-9-95 4-22-96			Tail Rotor Blades P/N 222-016-001-101/-107/-111/-113/-115 and -119
222-95-77	Basic	10-16-95			Tail Rotor Pitch Link, P/N 222-312-702-101, Replacement of
222-95-78	Basic	12-4-95			Main Rotor Hub P/N 222-012-101-103/-107, Grip Retaining Bolt P/N 222-310-127-101, Re-Torque and Inspection of
222-96-79	Basic	11-13-96			Tail Rotor Blade P/N 222-016-001-101/-107/-111/-113/-115 and -119, Removal From Service
222-98-80	Basic	3-23-98			Power Trim Check Procedure
222-98-81	Basic	4-23-98			Main Rotor Hub Grip and Flapping Bearing Bolt Torque Check

BHT-222/B-ASB INDEX**222/B ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
222-98-82	Basic	4-30-98			Vertical Fin Assembly Installation, Inspection of
222-98-83	Basic	10-12-98			Main Rotor Hub Trunnion Bolt, Inspection of
222-99-84	Basic	2-15-99			Swashplate Assembly Drive Pins, Inspection of
222-99-85	Basic	12-16-99			Tail Rotor (T/R) Pitch Change Bearings P/N 222-312-753-103, Inspection of; and Tail Rotor Blade Attaching Hardware, Replacement of
222-01-86	Basic	5-19-00			Hydraulic Actuator Support P/N 222-040-125-001, Inspection of
222-01-87	Basic	1-19-01			Magnetic Brake P/N 204-001-376- 105 and -107, One Time Inspection of
222-01-88	Basic	1-16-01			Rescue Hoist, BL-16600 Series, Breeze Eastern Customer Alert Bulletin CAB-100-58
222-01-89	Basic	2-7-01			Upper Fuel Enclosure, Right Side Addition of Drain Provision
222-01-90	Basic Rev A	5-18-01 10-26-05			Rotating Ring Assembly P/N 222- 010-403-005, -113 and -117, Inspection of
222-01-91	Basic	5-18-01			Main Rotor Pendulum Weight Support P/N 222-011-114-103, Replacement of
222-02-92	Basic	3-28-02			Main Rotor Pendulum Weight Support P/N 222-011-114-101 and -103, Rework of
222-02-93	Basic Rev A	4-1-02 3-3-03			Main Rotor Hub Assemblies P/N 222-011-101-103/-105/-107/ -109 and P/N 222-012-101-103/ -107, Inspection of
222-02-94	Basic	4-9-02			Fuel System Check and Relief Valve P/N 222-366-687-101, Replacement of

222/B ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
222-03-95	Basic	6-26-03			Honeywell LTS 101 Engine, Inspection of Fuel Pump Internal Drive Splines
222-03-96	Basic	6-26-03			Honeywell LTS 101 Engine, Replacement of Fuel System Power Turbine Governor Spool Bearing Part No. 2523973
222-03-97	Basic	9-23-03			Main Rotor Hub P/N 222-011-101-ALL and 222-012-101-ALL, Inspection of
222-04-98	Basic	6-8-04			Honeywell LTS 101 Engine Removal and Replacement of Fuel Control Spool Bearing P/N 2523973 Rev. M
222-04-99	Basic Rev C	8-9-04 2-16-06			Tail Rotor Counterweight Bellcrank P/N 222-012-727-003, Removal from Service
222-04-100	Basic Rev A	8-27-04 8-28-06			Tail Rotor Blade P/N 222-016-001-123, -127, -131 and -135, Inspection of
222-04-101	Basic Rev B	10-12-04 3-15-06			Tail Rotor Counterweight Bellcrank P/N 222-012-727-105, Inspection of
222-06-102	Basic	2-17-06			Float Inflation Valve Squib P/N 29022968, Misidentification of
222-06-103	Basic	11-21-06			Engine — Gearbox — Removal and Replacement of Locking Cup Part No. 4-082-094-01
222-07-104	Basic	1-9-07			Tail Rotor Pitch Change Mechanism, Revised Rigging Procedures
222-07-105	Basic	3-28-07			Disc Assembly P/N 36300-1 and 37855-1, Inspection of
222-07-106	Basic Rev C	9-11-07 9-20-07			Tail Rotor Blade Assembly, Inspection of

NOTICE

The following blank pages are provided for entry of additional bulletins when distributed. These additional bulletins will be included in this index at next revision.

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
---------------	--------------	-------------	---------------	--------------------------	----------------

BHT-222/B-ASB INDEX

NOTICE

The following blank pages are provided for entry of additional bulletins when distributed. These additional bulletins will be included in this index at next revision.

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
--------	-------	------	--------	------------------	---------