

# **Bell Helicopter** **TEXTRON**

A Subsidiary of Textron, Inc.

October 15, 2003

## **INFORMATION LETTER 212-03-52 412-03-51**

**TO: All Owners/Operators of Bell 212,412 and 412EP Helicopters**

**SUBJECT: INTER TURBINE TEMPERATURE INDICATORS**

Bell Helicopter has been made aware that certain operators are experiencing problems with Inter Turbine Temperature (ITT) indicators. In high temperature and humid environments the pointer could stick to the pointer stop. This Info Letter is to advise of the availability of a design modification that incorporates an improved pointer stop. In order to have the modification incorporated the unit must be returned to Bell Helicopter Customer Property Return (CPR).

Refer to the table below for the applicable part numbers.

<b>Bell Helicopter P/N</b>	<b>AMETEK P/N</b>	<b>Bell Helicopter P/N</b>	<b>AMETEK P/N</b>
212-075-067-109	SEL-OC19EJ	212-075-067-119	10355N04T00
212-075-067-113	10355N01T00	212-075-067-121	10355N06T00
212-075-067-115	10355N02T00	212-075-067-123	10355N07T00
212-075-067-117	10355N03T00	212-075-067-125	SEL-OC19EJ
212-075-067-117	10355N05T00	212-075-067-127	10355N08T00

### **Address:**

Bell Helicopter Textron Inc.  
Customer Property Return, Plant 8  
3000 South Norwood and Trinity Blvd.  
Hurst, Texas 76053