



April 13, 2009

INFORMATION LETTER 206-09-98

TO: All Owners/Operators of Bell 206A/B Series Helicopters

SUBJECT: SUSPECT FLAP RESTRAINT SUPPORT 206-010-191-001



Bell Helicopter has received two reports of flap restraint supports 206-010-191-001 that were not manufactured to Bell Helicopter specifications. These supports have two raised areas on the lower surface that contacts the main rotor trunnion as shown on page two. This condition is not considered detrimental to the normal operation of the helicopter however if discrepant parts are found, contact Product Support Engineering for further instructions.

E-mail: pselight@bellhelicopter.textron.com

Fax: (450) 433-0272

Phone: (450) 437-2862 / (450) 971-6407

U.S./Canada: (800) 243-6407



Raised material

Figure 1. Discrepant Flap Restraint Support 206-010-191-001.