



TECHNICAL BULLETIN INDEX

THE ATA/CHAP. REF. COLUMN INDICATES THE MAINTENANCE AND/OR OVERHAUL MANUAL CHAPTER/S AFFECTED BY THE RESPECTIVE BULLETIN; OR, THE BULLETIN IS APPLICABLE TO A SERVICE INSTRUCTION (S.I.).

PROPRIETARY RIGHTS NOTICE

These data are proprietary to Bell Helicopter Textron, Inc. Disclosure, reproduction, or use of these data for any purpose other than helicopter operation is forbidden without prior written authorization from Bell Helicopter Textron, Inc.

Newly released Technical Bulletins can be viewed and printed by accessing our Service Directives website at www.bellcustomer.com. This publication supersedes BHT-214ST-TB INDEX dated 1 January 2007 in its entirety.

COPYRIGHT NOTICE
COPYRIGHT 2008
BELL® HELICOPTER TEXTRON INC.
AND BELL HELICOPTER TEXTRON
CANADA LTD.
ALL RIGHTS RESERVED

Bell Helicopter
A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

1 JANUARY 2008

214ST TECHNICAL BULLETIN INDEX

STATUS CODE

A = Active

A- () = Active — (Additional Information)

└────────────────── P = Incorporated in Parts Catalog
 R = Referenced in Maintenance Manual

I = Inactive

I- () = Inactive — (Reason)

└────────────────── I = Incorporated in Maintenance Manual
 P = Incorporated in Parts Catalog
 S = Superseded (New Bulletin Number)
 R = Referenced in Maintenance Manual

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP | |
|------------|-------|---------|--------|----------|---|
| | | | | REF. | SUBJECT |
| 214ST-82-1 | Basic | 12-7-82 | A | 53 | Addition of a Doubler to the Tailboom Fin Upper Rib, P/N 214-021-214-119 |
| 214ST-83-2 | Basic | 1-17-83 | I-P | 67 | Hydraulic Servo Actuators, P/N 214-076-161-101, Install Boot, P/N 214-076-297-101 |
| 214ST-83-3 | Basic | 2-28-83 | A | S.I. | Cargo Mirror Kit, P/N 214-706-041-101, Provision, Location of |
| 214ST-83-4 | Basic | 2-24-83 | A | 25 | Passenger Steps, Pneumatic Lines, Boot Seal Addition of |
| 214ST-83-5 | Basic | 2-24-83 | I-P | 32 | Float Switch Shields, P/N 214-073-950-101, Replacement of |
| 214ST-83-6 | Basic | 2-24-83 | A | 71 | Engine Air Inlet Duct Assy, P/N 214-062-256-103, and -104, Modification of |
| 214ST-83-7 | Basic | 2-28-83 | I-I | 67 | Fly-By-Wire (FBW) Elevator Control System, Improved Elevator Horn to Spar Attachment |
| 214ST-83-8 | Basic | 3-16-83 | A | 53 | Air Barrier, P/N 214-031-641, on Number One Hanger Bearing Beam, P/N 214-031-716, Installation of |

BHT-214ST-TB INDEX

214ST TECHNICAL BULLETIN INDEX

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP | |
|-------------|----------------|--------------------|--------|----------|--|
| | | | | REF. | SUBJECT |
| 214ST-83-9 | Basic | 3-17-83 | A | 32 | Landing Gear Forward and Aft Crosstube Assemblies, P/N 214-052-002-101 or, -103 or 214-052-052-101, Inspection and Rework of |
| 214ST-83-10 | Basic | 3-29-83 | A | 63 | Elastomeric Spring, (Helper Spring) P/N 214-031-617-107, Modification of |
| 214ST-83-11 | Basic Rev B | 3-31-83 7-24-95 | A | 52 | Upper door Track, P/N 214-031-277-119, -121, -129, -131 and FS 255.20 Bulkhead Cap, P/N 214-031-252-127, -128, -179, -180, Repair/Modification |
| 214ST-83-12 | Basic | 4-26-83 | A | 53 | Aft Engine Tailpipe Fairing, P/N 214-061-866-267, Modification of |
| 214ST-83-13 | Basic | 5-16-83 | A | S.I. | Modification - Seat Installation Aux. Fuel Seat Belt Attach Point, Provisions for |
| 214ST-83-14 | Basic | 6-1-83 | I | 67 | Tailboom Elevator Assemblies, P/N 214-021-100-103 and-104, Modification of |
| 214ST-83-15 | Basic | 6-6-83 | I-P | 96 | Copilot Control Annunciator Dimming Resistor, Replacement of |
| 214ST-83-16 | Basic | 6-15-83 | A | 53 | Forward Fuselage Assembly, P/N 214-031-002-107, Addition of Drain Holes and Seals |
| 214ST-83-17 | Basic | 6-20-83 | I-P | 30 | Windshield Wiper Motor Converter, P/N 214-073-932-105 and -107, Replacement of |
| 214ST-83-18 | Basic | 8-4-83 | I-I | 67 | Main Rotor Hydraulic Actuator, P/N 214-076-161-101/-103, Mount Bearing, Friction Adjustment of |
| 214ST-83-19 | Basic | 8-29-83 | A | 53 | Cockpit Area Access Step P/N 214-031-840-103/-104, Installation of |
| 214ST-83-20 | Basic | 10-25-83 | I-I | 76 | Engine Rigging and Load Demand Spindle (LDS) Marking, Change to |

214ST TECHNICAL BULLETIN INDEX

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP | |
|-------------|----------------|--------------------|--------|----------|--|
| | | | | REF. | SUBJECT |
| 214ST-83-21 | Basic | 10-25-83 | I-I | 64 | Tail Rotor Retrofit Kit, P/N 214-704-071-101, Installation of |
| 214ST-83-22 | Basic | 11-11-83 | A | 62 | Thrust Ring, P/N 214-010-559-101, and Idler Pin, P/N 214-010-422-101, Modification of |
| 214ST-83-23 | Basic | 10-30-83 | A | 33 | Park Brake Light, Disabling of |
| 214ST-84-24 | Basic | 1-25-84 | A | 32 | Emergency Float System, P/N 214-706-120-105, Modification of |
| 214ST-84-25 | Basic | 3-15-84 | I-P | 25 | Passenger Step Actuators, P/N 214-001-423-105, Replacement of |
| 214ST-84-26 | Basic | 3-15-84 | A | 53 | Tail Rotor Driveshaft Cover Assemblies, P/N 214-031-319-105 and 214-061-866-215, Modification of, and Center Support Assy, P/N 214-031-318-103, Replacement of |
| 214ST-84-27 | Basic | 3-15-84 | A | 52 | Passenger Door Bumper, Modification of |
| 214ST-84-28 | Basic | 3-16-84 | A | 62 | Main Rotor Blade Tie-Down, Provisions for |
| 214ST-84-29 | Basic | 4-4-84 | A | 67 | Number One Engine Throttle Grip Replacement of |
| 214ST-84-30 | Basic | 5-29-84 | A | 25 | Extended Flights Over Water Food Ration Bag Assemblies, P/N 214-706-044-103/-104, Installation and Provisions for |
| 214ST-84-31 | Basic Rev B | 5-31-84 6-25-85 | I-I | 62 | Main Rotor Outboard Strap Fitting Assembly, P/N 214-010-115-001, Replacement of |
| 214ST-84-32 | Basic | 6-1-84 | A | 25 | Life Raft Painter Line Kit, Provisions for |
| 214ST-84-33 | Basic | 6-12-84 | A | 53 | Seals to the Access Panels on the Forward Fuselage Assembly, P/N 214-031-002-107, Replacement and Addition of |

BHT-214ST-TB INDEX

214ST TECHNICAL BULLETIN INDEX

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP | SUBJECT |
|-------------|----------------|--------------------|--------|----------|---|
| | | | | REF. | |
| 214ST-84-34 | Basic | 6-15-84 | A | 53 | Hinged Door Interior Panel Assembly, P/N 214-070-567-101/-102, Modification of |
| 214ST-84-35 | Basic | 9-13-84 | A | 98 | Flight Director Kit, P/N 214-705-001-109, Wiring Modification of |
| 214ST-84-36 | Basic | 9-10-84 | A | 64 | Tail Rotor Flapping Stop, P/N 214-001-809-101, Rework of |
| 214ST-84-37 | Basic Rev A | 9-27-84 1-30-86 | A | 67 | Main Rotor Hydraulic Actuator, P/N 214-076-161-101/-103, Piston Seals and Cylinder Assemblies, Replacement of |
| 214ST-84-38 | Basic | 9-28-84 | A | 21 | Cabin Vent System, P/N 214-073-102-101, Modification of |
| 214ST-84-39 | Basic | 10-11-84 | A | 32 | Emergency Float Bottle Brackets, P/N 214-031-305-123 and 214-031-925-121, Replacement of |
| 214ST-84-40 | Basic | 11-7-84 | A | 95 | Access for On Ship Adjustments of Elevator Position Indicator, Provisions for |
| 214ST-84-41 | Basic | 11-20-84 | A | 95 | Engine Governor Control Panel, P/N 214-175-385-103, RF Interference of |
| 214ST-84-42 | Basic | 11-27-84 | A | 53 | Tailboom Fin, P/N 214-021-002-103, Modification of |
| 214ST-85-43 | Basic Rev A | 1-9-85 2-1-88 | A | 67 | M/R Hydraulic Actuator Bearing Housing Assembly, P/N 214-076-166-001, Modification of |
| 214ST-85-44 | Basic | 1-9-85 | A | 67 | Throttle Rack Dust Cap, P/N 214-001-250-101, Modification of |
| 214ST-85-45 | Basic | 2-14-85 | I-P | 71 | Improved Bleed Air Tube Assembly, P/N 214-060-069-127, Installation of |
| 214ST-85-46 | Basic | 2-14-85 | I-I | 98 | Electrical Fuel Sump Drain Valve, P/N 214-066-328-101, Installation of |
| 214ST-85-47 | Basic | 3-14-85 | A | 29 | Rotor Brake Master Cylinder Detent, Increase of |

214ST TECHNICAL BULLETIN INDEX

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP | |
|---|----------------|---------------------|--------|----------|--|
| | | | | REF. | SUBJECT |
| 214ST-85-48 | Basic | 3-18-85 | A | 32 | Nose Wheel Landing Gear, P/N 214-052-121-105, Modification of |
| 214ST-85-49 | Basic | 3-11-85 | A | 25 | Liferaft Assemblies, P/N 214-070-943-103, -104, -107, -108, -109, and -110, (Vendor: Sargent Industries, Pico Division, P/Ns 100103-205, -206, -305, and -306 and 100102-701 and -702) Modification of |
| 214ST-85-50 | Basic | 4-26-85 | I-I | 4 | Retirement Life for Main Rotor Grip, P/N 214-010-104-121 |
| 214ST-85-51 | Basic | 5-2-85 | I-P | 63 | Improved Oil Pressure Transmitter, P/N 222-375-077-111, Introduction of |
| 214ST-85-52 | Basic | 5-10-85 | A | 98 | Flight Director Kit, P/N 214-705-001-109, Altitude Sensor, Wiring Modifications of |
| 214ST-85-53 | Basic | 5-23-85 | A | 63 | Combining Gearbox Assembly, P/N 214-040-013-109, Installation of |
| 214ST-85-54 | Basic | 6-18-85 | I-P | 11 | Engine Fire Extinguisher Decal, P/N 214-069-936-101, Addition of |
| 214ST-85-55 | Basic | 6-18-85 | I-P | 28 | Hose Assembly, P/N AE3908K0226-065 Installation of |
| 214ST-85-56 (See ASB 214ST-89-49) | Basic | 6-18-85 | I-S | 63 | Improved Transmission Oil Filter Support Bracket, P/N 214-040-599-111, Installation of |
| 214ST-85-57 | Basic | 8-12-85 | A | 98 | AARS Tachometer Excitation External Bias Resistor, Addition of |
| 214ST-85-58 | Basic | 8-15-85 | A | 29 | Hydraulic Motor, P/N 214-076-333-101, Modification to New Configuration |
| 214ST-85-59 | Basic | 9-4-85 | A | 21 | Air Conditioning Installation, P/N 214-889-199-101/-103 and P/N 214-899-285-101/-103/-105, Installation of Caution Decal |
| 214ST-85-60 | Basic Rev A | 10-8-85 10-29-85 | I-P | 11 | Fuel Quantity Decal, P/N 214-175-274-101, Replacement of |

BHT-214ST-TB INDEX

214ST TECHNICAL BULLETIN INDEX

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP | |
|-------------|----------------|-------------------|--------|----------|--|
| | | | | REF. | SUBJECT |
| 214ST-85-61 | Basic | 10-15-85 | A | 67 | Cyclic Control Tube, P/N 214-001-088-101, Inspection and Replacement of |
| 214ST-85-62 | Basic | 10-15-85 | I-P | 34 | Airspeed Data Computer Retrofit, P/N 214-704-073-101 |
| 214ST-85-63 | Basic | 11-1-85 | I-I | 64 | Tail Rotor Blade, P/N 214-015-700-111, Improved Visibility Paint Scheme |
| 214ST-86-64 | Basic Rev A | 2-4-86 9-28-87 | A | 63 | Nodal Beam Assembly, P/N 214-031-601-101, -109, -111, Modification of |
| 214ST-86-65 | Basic | 3-26-86 | I-I | 52 | Retainer Secured (Push Out) Passenger Compartment Windows |
| 214ST-86-66 | Basic | 5-21-86 | A | 29 | Hydraulic System Installation, PCI, PCII, and Utility, Replacement of 2014/2024 Aluminum Alloy Flareless Tube Fittings |
| 214ST-86-67 | Basic | 6-19-86 | A | 29 | Hydraulically Driven Fan, P/N 214-040-860-103 and -105, Replacement of Washer |
| 214ST-86-68 | Basic | 7-30-86 | A | 67 | Main Rotor Hydraulic Actuator, P/N 214-076-161-101/-103 and -105, Piston Seals and Upper Cylinder, Replacement of |
| 214ST-86-69 | Basic | 10-3-86 | I-P | 29 | Hydraulic Pump, P/N 214-076-033-001 (Abex Model AP1V-105, P/N 63074), Replacement of External Driveshaft |
| 214ST-87-70 | Basic | 1-14-87 | I-P | 62 | Collective Lever Assembly, P/N 214-010-492-105 and 214-010-250-105, Introduction of |
| 214ST-87-71 | Basic | 1-27-87 | A | S.I. | Center Headliner, P/N 214-070-527-101, Modification of |
| 214ST-87-72 | Basic | 1-27-87 | A | 71 | Environmental/EMI Protected Engine Compartment Harnesses, P/N 214-075-083-101/-103, Addition of |

214ST TECHNICAL BULLETIN INDEX

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP | |
|-------------|----------------|---------------------|--------|----------|---|
| | | | | REF. | SUBJECT |
| 214ST-87-73 | Basic | 1-28-87 | I-P | 29 | PC2 Hydraulic System Module, Installation of Fill Port Elbow |
| 214ST-87-74 | Basic | 4-21-87 | A | 53 | Support, P/N 214-031-716-115, Modification to Improve Water Drainage from Aft Engine Deck, P/N 214-031-712-101 |
| 214ST-87-75 | Basic Rev A | 6-1-87 3-7-88 | A | 32 | Landing Gear Strap Assemblies, P/N 214-031-839-101/-102, Rework of |
| 214ST-87-76 | Basic | 6-10-87 | A | 25 | Passenger Step Assembly, P/N 214-031-791-101/-102, Attachment, Replacement of |
| 214ST-87-77 | Basic | 8-18-87 | I-P | 11 | Markings Installation, P/N 214-070-515-101/-103/-105/-107/-109/-113/-115, Tail Rotor Hazard Warnings Decals, Addition of |
| 214ST-87-78 | Basic | 10-26-87 | A | 21 | Heat Sensor Access Panel for Helicopters with Air Conditioning |
| 214ST-88-79 | Basic | 1-14-88 | A | 67 | Inspection and Corrosion Protection of Directional Control Bellcrank Support to Tail Rotor Gearbox Faying Surface |
| 214ST-88-80 | Basic | 2-8-88 | A | 11 | Addition of Identification Decal to Aircraft Exterior |
| 214ST-88-81 | Basic | 4-8-88 | A | 53 | Nose Frame Assembly, P/N 214-031-123-115 and -116, Repair of |
| 214ST-88-82 | Basic | 4-8-88 | A | 53 | Roof Door Track, P/N 214-031-512-101, Repair of |
| 214ST-88-83 | Basic Rev A | 4-28-88 5-12-88 | A | 53 | Fuel Cell Panel Assembly, P/N 214-031-709-103, Repair of |
| 214ST-88-84 | Basic | 5-2-88 | A | 71 | Aft Engine Tailpipe, Fairing P/N 214-061-866-267, Modification and/or Replacement of |
| 214ST-88-85 | Basic Rev A | 5-17-88 10-17-88 | A | 53 | Lower Center, Left and Right Side Skins, P/N 214-031-703-107 and -109, 214-031-704-103 and -105, and 214-031-705-103, Modification of |

BHT-214ST-TB INDEX

214ST TECHNICAL BULLETIN INDEX

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP | |
|-------------|-------|----------|--------|----------|---|
| | | | | REF. | SUBJECT |
| 214ST-88-86 | Basic | 6-28-88 | I-I | 63 | Rotor Brake Assembly, Modification of |
| 214ST-88-87 | Basic | 9-12-88 | I-I | 63 | Transmission Oil Cooler Blower Bleed Air Shutoff and Line Check Valve, P/N 209-072-433-107, Installation of |
| 214ST-88-88 | Basic | 9-16-88 | A | 71 | Firewalls Installation, P/N 214-061-870-105/-107/-109/-111, Repair of |
| 214ST-88-89 | Basic | 9-26-88 | I-P | 71 | Engine Bleed Air Shutoff and Line Check Valves, P/N 209-072-433-105, Installation of |
| 214ST-88-90 | Basic | 9-28-88 | A | 53 | Left Hand Panel Assembly, P/N 214-021-211, Lower Vertical Tailboom Fin, Cracked |
| 214ST-88-91 | Basic | 10-6-88 | A | 53 | Tailboom Attachment at Fuselage Longeron Forgings, Spot Facing of Forward Surfaces |
| 214ST-88-92 | Basic | 10-27-88 | A | 53 | Clevis Assembly, P/N 214-031-817-102, Modification of |
| 214ST-89-93 | Basic | 1-5-89 | I-P | 62 | Collective Hub, P/N 214-010-505-109 and Hub Nut, P/N 214-010-417-103, With Left Hand Threads, Introduction of |
| 214ST-89-94 | Basic | 1-6-89 | A | 63 | Nodal Beam Support Weight Attachment Bolts, Increase Torque and Replacement of |
| 214ST-89-95 | Basic | 1-26-89 | A | 53 | Left Pylon Cover Plate and Seal Tape, Replacement of |
| 214ST-89-96 | Basic | 1-30-89 | A | 53 | Baggage and Electrical Compartment Seal Tape P/N 4516, Addition of |
| 214ST-89-97 | Basic | 2-9-89 | A | 67 | Hydraulic Flight Control Cylinders, P/N 214-076-161-101/-103/-105 and 214-076-294-101, Bypass Indicator Switch Replacement and Adjustment Procedure |
| 214ST-89-98 | Basic | 2-22-89 | I-P | 29 | Utility Hydraulic System, Modification of |

214ST TECHNICAL BULLETIN INDEX

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP | |
|--|----------------|---------------------|--------|----------|--|
| | | | | REF. | SUBJECT |
| 214ST-89-99 | Basic | 2-23-89 | I-P | 29 | Oil Cooler System, P/N 214-040-018-103 and -105, Replacement of Hydraulic Motor and Tube Assemblies |
| 214ST-89-100 | Basic | 4-13-89 | A | 21 | Air Conditioning Expansion Valve, Providing Additional Clearance to Nodal Beam Assy |
| 214ST-89-101 | Basic | 5-18-89 | A | 28 | 85 Gallon Auxiliary Fuel Kit, P/N 214-706-600, Modification of |
| 214ST-89-102 | Basic | 5-18-89 | A | 53 | FWD Cabin Roof Assy/Door Post Joint P/N 214-031-500-103, -107, -155, -159, Modification of |
| 214ST-89-103 | Basic | 6-8-89 | A | 65 | Tail Rotor Gearbox Assembly P/N 214-040-011, Configuration Change and Upgrade |
| 214ST-89-104 (See ASB 214ST-92-57) | Basic | 7-28-89 | I-S | 64 | Tail Rotor Crosshead P/N 214-010-806-105, Introduction of |
| 214ST-89-105 | Basic | 9-28-89 | A | 53 | Left and Right Side Upper Aft Cabin Rain Gutter, P/N 214-031-525-117/-118, Modification of |
| 214ST-89-106 | Basic | 11-7-89 | A | 53 | Tailboom Assembly, P/N 214-031-003- Prior to -111, Modification of |
| 214ST-89-107 | Basic | 11-8-89 | A | 65 | Intermediate Gearbox Assembly, P/N 214-040-011, Configuration Change and Upgrade |
| 214ST-89-108 | Basic Rev A | 11-15-89 2-17-95 | A | 62 | Scissors and Sleeve Assembly, P/N 214-010-501, Configuration Change and Upgrade |
| 214ST-90-109 | Basic Rev A | 1-15-90 11-12-90 | A | 62 | Mast Assembly P/N 214-040-003-105 and -107, Configuration Change and Upgrade |
| 214ST-90-110 | Basic Rev C | 2-16-90 12-22-00 | A | 63 | Combining Gearbox Assembly P/N 214-040-013, Configuration Change and Upgrade |
| 214ST-90-111 | Basic | 3-6-90 | A | 53 | Main Rotor Blade Tiedown, P/N 214-070-081-147 Rework, to, P/N 214-070-081-171 and Add Attachment Bracket to Tailboom |

BHT-214ST-TB INDEX

214ST TECHNICAL BULLETIN INDEX

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP | |
|--------------|----------------|--------------------|--------|----------|--|
| | | | | REF. | SUBJECT |
| 214ST-90-112 | Basic | 3-16-90 | A | 53 | Roof Frame P/N 214-031-516-131, -132, -139, and -140 Repair/Modification of |
| 214ST-90-113 | Basic | 10-3-90 | A | 63 | 3 Micron Transmission External Oil Filter Assembly, P/N 214-040-760-101, Installation of |
| 214ST-90-114 | Basic | 10-8-90 | I-P | 63 | 3 Micron Combining Gearbox External Oil Filter Assembly P/N 214-040-760-101, Installation of |
| 214ST-90-115 | Basic | 10-17-90 | A | 65 | Tail Rotor Driveshaft Hanger Assembly P/N 214-040-600, Configuration Change and Upgrade |
| 214ST-90-116 | Basic | 11-9-90 | A | 67 | Voltage Transient Suppression Diode Assembly For Yaw Magnetic Brake, Installation of |
| 214ST-90-117 | Basic | 11-9-90 | A | 96 | AFCS SCAS Actuator P/N's 214-001-540-107; -113 (Roll), 214-001-540-109; -115 (Pitch), 214-001-540-111; -117 (Yaw), Repair and Overhaul |
| 214ST-91-118 | Basic | 1-9-91 | A | 96 | AFCS Fly by Wire Elevator Actuator P/N's 214-001-970-107/-111, Overhaul of |
| 214ST-91-119 | Basic Rev A | 1-16-91 9-25-00 | A | 63 | Main Transmission Assembly P/N 214-040-002, Configuration Change and Upgrade |
| 214ST-91-120 | Basic | 1-30-91 | A | 96 | Improved Anti-Collision Light Installation |
| 214ST-91-121 | Basic | 2-13-91 | A | 62 | Swashplate and Support Assembly P/N 214-010-500, Configuration Change and Upgrade |
| 214ST-91-122 | Basic | 2-19-91 | A | 63 | Introduction of New Oil Sight Glass for Combining Gearbox |
| 214ST-91-123 | Basic | 5-7-91 | A | 5 | Main and Tail Rotor Driveshaft Splined Coupling and Hangers, Revision to the Special Inspection and Overhaul Requirements |

214ST TECHNICAL BULLETIN INDEX

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP | |
|--|-------|----------|--------|----------|---|
| | | | | REF. | SUBJECT |
| 214ST-91-124 | Basic | 6-27-91 | A | 67 | Main Rotor Hydraulic Actuator, P/N 214-076-161-101/-103/-105 and -107, Piston Seals and Rod Seals, Replacement of |
| 214ST-91-125 | Basic | 8-1-91 | A | 96 | Passenger and Sliding Door Lock Switches, Replacement of |
| 214ST-91-126 | Basic | 10-22-91 | A | 96 | Non-Essential Bus, Improved Operational Logic of |
| 214ST-92-127 (See ASB 214ST-93-60) | Basic | 2-13-92 | I-S | 63 | Improved Rotor Brake Quill, P/N 209-040-173-103, Introduction of |
| 214ST-93-128 | Basic | 3-17-93 | A | 64 | Tail Rotor Hub Assembly, P/N 214-011-801-109, Bonding of Trunnion Bearing Housings in Yoke |
| 214ST-93-129 | Basic | 8-27-93 | A | 5 | Main Rotor Spindle Special Inspection Deletion |
| 214ST-93-130 | Basic | 10-20-93 | A | 65 | Tail Rotor Gearbox Inspection Change |
| 214ST-93-131 | Basic | 12-3-93 | I-I | 4 | Forward Main (Wheel) Landing Gear Support Fitting, P/N 214-031-438-101, -102, -103 and -104, Retirement Life, Increase of |
| 214ST-93-132 | Basic | 12-15-93 | A | 96 | AFCS Actuator, Attitude (AARS) P/N's 214-001-370-101/-103, Functional Test |
| 214ST-94-133 | Basic | 1-19-94 | I-I | 4 | Main (Wheel) Landing Gear Beam Assembly, P/N 214-052-102-103, -104, -105, and -106, Retirement Life, Increase of |
| 214ST-94-134 | Basic | 1-19-94 | I-I | 5 | Left Hand Upper Fuselage Longerons, P/N 214-031-431-101, -105, Maintenance Manual Inspection Revision |
| 214ST-94-135 | Basic | 7-26-94 | I | 4 | Main Rotor Mast Assembly, P/N 214-040-090-109 and -121, Retirement Life, Increase of |
| 214ST-94-136 | Basic | 7-29-94 | I-I | 5 | TBO Increase for Generator P/N 214-175-150-105 |

BHT-214ST-TB INDEX**214ST TECHNICAL BULLETIN INDEX**

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP | |
|--|----------------|--------------------|---------------|-----------------|---|
| | | | | REF. | SUBJECT |
| 214ST-94-137 | Basic | 8-18-94 | A | 53 | Upper Door Track P/N 214-031-512-103, -104, -105 and -106 and Roof Skin P/N 214-031-500-115/-116 Repair/Modification |
| 214ST-94-138 | Basic | 9-6-94 | A | 96 | AFCS SCAS Actuator P/N 214-001-540-107, -113 (Roll); -109, -115 (Pitch); and -111, -117 (Yaw), Rework When Solenoid P/N 214-001-570-103 is Installed |
| 214ST-94-139 | Basic Rev A | 9-30-94 2-17-95 | A | 25 | Crew Seat Attenuators P/N 222-020-840-117/-119, Verification and Rework of |
| 214ST-94-140 | Basic | 11-28-94 | A | 29 | Aircraft Braking Systems Service Bulletin: Introduction of Stainless Steel Piston 5011934 |
| 214ST-94-141 | Basic | 11-28-94 | A | 52 | 214ST Relocation and Replacement of, "Door Lock" Sliding and Hinge Cargo Door Switches and Addition of Baggage Compartment Isolation Switch |
| 214ST-95-142 | Basic | 2-14-95 | A | 62 | Scissors and Sleeve Assembly, P/N 214-010-501-103, -107, -109, -113 and -115, Drive Plate Attachment Bolt and Washer Replacement |
| 214ST-95-143 | Basic | 2-17-95 | A | S.I. | Lucas Western Service Bulletins: High Performance Rescue Hoist Assembly Washer Interference |
| 214ST-95-144 (See ASB 214ST-95-72) | Basic | 3-13-95 | I-S | 53 | Tailboom Assembly P/N 214-031-003-111, Inspection and Modification |
| 214ST-95-145 | Basic Rev A | 5-26-95 6-1-95 | I-I | 63 | Introduction of Improved Spider P/N 214-040-357-101 |
| 214ST-95-146 | Basic | 6-15-95 | A | 4 | Main Rotor Blade Assembly, P/N 214-015-300-105 and -107, Retirement Life, Increase of |
| 214ST-95-147 | Basic | 8-14-95 | A | 29 | HR Textron Service Bulletin 41002810-67-02: Replacement of Upper End Cap on Dual Hydraulic Servo Actuator Assembly 41002810 (BHT P/N 214-076-161-ALL) |

214ST TECHNICAL BULLETIN INDEX

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP | |
|--|----------------|---------------------|--------|----------|--|
| | | | | REF. | SUBJECT |
| 214ST-95-148 | Basic | 10-2-95 | A | 63 | Engine to Transmission Driveshaft Assembly P/N 214-040-014, Configuration Change and Upgrade |
| 214ST-95-149 (See ASB 214ST-96-74) | Basic | 10-9-95 | I-S | 32 | Introduction of New Emergency Float Inflation Solenoid Valve, P/N 214-073-929-105 and Solenoid Valve Assembly, P/N 214-073-940-103 |
| 214ST-97-150 | Basic | 1-8-97 | A | 25 | Introduction of New Life Raft Ejection Bag Reservoir Bottle, P/N 44000-1 |
| 214ST-97-151 | Basic | 1-31-97 | A | 63 | Combining Gearbox Assembly, P/N 214-040-013-115, Installation of |
| 214ST-97-152 | Basic | 3-21-97 | A | 62 | Introduction of New Main Rotor Pitch Change Bearing Assembly, Inner Race P/N 214-310-001-101, and Bearing, P/N 214-310-002-101 |
| 214ST-97-153 | Basic | 7-11-97 | A | 67 | Modification of Collective Actuator Balance Spring Installation |
| 214ST-97-154 | Basic | 7-31-97 | A | 62 | Main Rotor Hub Assembly, P/N 214-010-100-183 and Subsequent, Configuration Change and Upgrade |
| 214ST-97-155 | Basic | 8-27-97 | A | 62 | Modification of P/N 214-015-300, Main Rotor Blades to P/N 214-015-300-129 By Application of a High Visibility Paint Scheme |
| 214ST-98-156 | Basic Rev A | 4-30-98 11-16-98 | A | 96/98 | Bellmouth Heater Circuit, Modification of |
| 214ST-98-157 | Basic Rev A | 6-16-98 10-22-98 | A | 32 | Forward and Aft Cross Tube Assemblies, P/N 214-052-002-103 and 214-052-052-101, Maintenance Manual Revision, Inspection, Data Plate Removal, and Re-identification |

BHT-214ST-TB INDEX**214ST TECHNICAL BULLETIN INDEX**

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP | |
|---------------|----------------|-------------------|---------------|-----------------|--|
| | | | | REF. | SUBJECT |
| 214ST-98-158 | Basic Rev A | 9-9-98 8-11-99 | A | 4/5 | Dual Hydraulic Servo Actuator Assembly, P/N 214-076-161-ALL: Change in Retirement Life and Establishment of TBO Interval |
| 214ST-98-159 | Basic | 10-27-98 | A | - | Keith Products, Inc., Service Bulletin SB-98002, Modification of ES73171-4 Blower Assembly |
| 214ST-99-160 | Basic | 1-26-99 | A | 96 | Starter Motor Clutch Assembly, P/N 36B510954G2, Cleaning/ Overhaul Procedure |
| 214ST-99-161 | Basic | 5-2-99 | A | 97 | Speaker Mount Bracket Assembly, Replacement of |
| 214ST-99-162 | Basic | 11-19-99 | A | 63 | Introduction of P/N 214-030-626-103 Clevis and P/N 214-031-601-129 Restraint Assembly, and Modification of P/N 214-030-626-101 Clevis |
| 214ST-00-163 | Basic | 6-14-00 | A | 63 | Introduction of New Transmission Ring Gear Case Assembly, P/N 214-040-361-101 |
| 214ST-00-164 | Basic | 11-27-00 | A | 63 | Introduction of New Combining Gearbox Assembly Generator Pad Seal, P/N 209-340-265-103 |
| 214ST-01-165 | Basic | 4-2-01 | A | 53 | BL 14.0 Left and Right Hand Main Beam Assemblies, FS 227.10 Center Bulkhead Assembly, and FS 255.20 Aft Cabin Bulkhead Assembly, Additional Maintenance Manual Inspection Requirements |
| 214ST-02-166 | Basic | 1-25-02 | A | 64 | Tail Rotor Hub Assembly Blade Pitch Change Bearing Bolts, Additional Maintenance Manual and Component Repair and Overhaul Manual Inspection and Assembly Requirements |
| 214ST-02-167 | Basic | 5-31-02 | A | 53 | Tailboom Station (BS) 293.50 Bulkhead Installation and Vertical Fin Assembly Splices, Additional Maintenance Manual Inspection Requirements |

214ST TECHNICAL BULLETIN INDEX

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP | |
|--------------|----------------|-------------------|--------|----------|--|
| | | | | REF. | SUBJECT |
| 214ST-02-168 | Basic | 6-11-02 | A | 67 | Introduction of P/N 214-001-133-103 Collar and Modification of Existing P/N 214-001-133-001 Collar |
| 214ST-02-169 | Basic | 8-30-02 | A | 62 | Main Rotor Hub Assembly Spindle Assembly, P/N 214-010-103, Revision of Inspection and Overhaul Requirements |
| 214ST-02-170 | Basic | 8-30-02 | A | 96 | Introduction of P/N 214-060-056-109 Electric Starter Motor |
| 214ST-02-171 | Basic | 11-4-02 | A | 64 | Introduction of New Tail Rotor Blade Retaining Bolt and Washer Hardware |
| 214ST-02-172 | Basic | 11-8-02 | A | 96 | Replacement of P/N 214-175-380-101 Nickel-Cadmium Battery |
| 214ST-03-173 | Basic | 3-14-03 | A | 65 | Intermediate Gearbox Mounting Hardware Change |
| 214ST-04-174 | Basic Rev A | 3-8-04 6-26-06 | A | 62 | Scissors and Sleeve Assembly, Sleeve Upper Nut, P/N 214-010-418-001, Additional Maintenance Manual Inspection Requirements |
| 214ST-06-175 | Basic | 8-28-06 | A | 67 | Support Plates on the Fly By Wire (FBW) 214-001-970-107/-111 Actuators, Installation of |

NOTICE

The following blank pages are provided for entry of additional bulletins when distributed. These additional bulletins will be included in this index at next revision.

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP REF. | SUBJECT |
|---------------|--------------|-------------|---------------|--------------------------|----------------|
|---------------|--------------|-------------|---------------|--------------------------|----------------|

BHT-214ST-TB INDEX

NOTICE

The following blank pages are provided for entry of additional bulletins when distributed. These additional bulletins will be included in this index at next revision.

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP REF. | SUBJECT |
|--------|-------|------|--------|------------------|---------|
|--------|-------|------|--------|------------------|---------|