



**OPERATIONS
SAFETY
NOTICE INDEX**

COPYRIGHT NOTICE

COPYRIGHT 2011
BELL © HELICOPTER TEXTRON INC.
AND BELL HELICOPTER TEXTRON
CANADA LTD.
ALL RIGHTS RESERVED

Bell *helicopter*

A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

19 SEPTEMBER 2011

205A1 OPERATIONS SAFETY NOTICE INDEX

NUMERICAL INDEX

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
OSN 205A1-75-1	Basic	6-Nov-75	25 Hour Inspection of 204-001-739-3 Tail Rotor Chain
OSN 205-77-1	Rev A	20-May-77	Installation of Auxiliary Fuel Tank Kits, P/N 205-706-044 and P/N 205-706-045 Equipped With Connection Adapter, P/N AE98148N
OSN 205-78-1	Basic	24-Feb-78	Service Bulletin 205-77-4
OSN 205-79-1	Basic	4-Jan-79	An Alert Follow-up Concerning the Need to Incorporate, BHT S. B. 205-78-5 Which Requires Replacement of the Tail Rotor Chain, Etc.
OSN 205-80-2	Basic	29-Jul-80	Inspection and Maintenance of Float Landing GearKit, P/N 205-706-050, Service Instruction 205-24
OSN 205-80-3	Basic	15-Sep-80	Inspection of Drag Brace Assembly, P/N 204-011-140-001 and -005
OSN 205-80-4	Basic	27-Oct-80	Removal and Installation of Trunnion Bearings, P/N 204-011-451-001 on Swashplate Assemblies, P/N 204-011-400 Series
OSN 205-81-5	Basic	7-Nov-81	Main Transmission Bevel Gear Tooth Damage
OSN 205-84-6	Basic	1-May-84	Main Rotor Blade Repair
OSN 205-84-7	Basic	25-Sep-84	Flight Control Cylinder, P/N 212-076-005-101, and All Previous Dash Numbers Modified per Technical Bulletins 205-80-38 or 212-80-45
OSN 205-85-8	Basic	8-Oct-85	Inspection for Defective Universals, P/N 204-011-128-001, Vendor P/N DW-6ZZ Main Rotor Pitch Link Assemblies
OSN 205-85-9	Basic	14-Nov-85	Cracked Main Rotor Blade Grip, P/N 204-011-121-009
OSN 205-86-10	Basic	6-Jun-86	Airworthiness Directive: 86-09-05 Applicable to Avco Lycoming Division T5313B and T5317A Turboshaft Engines
OSN 205-87-11	Basic	21-Apr-87	Ground Handling Wheels Kits, P/N 214-706-104-001 and -103, and Gear Assemblies, P/N 212-050-200-001, -003, and -005, Inspection
OSN 205-87-12	Basic	2-Sep-87	Suspect Bogus Non-FAA Certified Tail Rotor Grip, P/N 205-011-711-101
OSN 205-87-13	Basic	6-Nov-87	Crew Seat, P/N 205-070-798-001, Lap Belt, P/N 541119651, Attachment, Inspection of
OSN 205-88-14	Basic	9-Mar-88	Availability of a Wire Strike Protection System for Bell Helicopters
OSN 205-88-15	Basic	18-Mar-88	Flight Control System Checks Before Flight
OSN 205-89-16	Rev A	6-Apr-89	Failure of Main Transmission Spiral Bevel Gear
OSN 205-89-17	Basic	1-Aug-89	Defective Universals, P/N 204-011-128-001, Vendor Code 10083, Main Rotor Pitch Link Assemblies
OSN 205-90-18	Basic	23-Feb-90	Failure of Main Rotor Yoke P/N 204-011-102-125
OSN 205-90-19	Basic	3-Mar-90	Investigation of Failed Main Rotor Yoke P/N 204-011-102-125

205A1 OPERATIONS SAFETY NOTICE INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
OSN 205-90-20	Basic	9-Oct-90	Stress Corrosion Cracking of Main Rotor Grip Assemblies P/N 204-011-121 Series
OSN 205-90-21	Basic	6-Nov-90	Investigation of Crack in Tail Rotor Blade
OSN 205-91-22	Basic	30-Jan-91	Main Rotor Blade Doubler Cracks
OSN 205-91-23	Basic	3-Sep-91	Installation of Tail Rotor Driveshaft Hanger Assemblies P/N 204-040-600 and 212-040-600
OSN 205-91-24	Basic	12-Sep-91	Failure of Tail Rotor Driveshaft Hanger Bearing P/N 204-040-623-003
OSN 205-91-25	Basic	20-Sep-91	Failure of Tail Rotor Driveshaft Hanger Bearing P/N 204-040-623-003
OSN 205-91-26	Rev A	10-Nov-91	Tail Rotor Driveshaft Hanger Bearing Lubrication P/N 212-040-600-005, 412-040-600-101, 412-040-601-103
OSN 205-91-27	Basic	31-Oct-91	Investigation of Tail Rotor Driveshaft Hanger Bearing P/N 204-040-623-003 Failure
OSN 205-91-28	Basic	31-Oct-91	Failure of Main Rotor Mast P/N 204-011-450-105
OSN 205A-93-29	Basic	30-Apr-93	Main Rotor Blade Skin Cracks
OSN 205-93-30	Basic	27-Aug-93	Cargo Door Emergency Escape Panel
OSN 205-93-31	Basic	8-Dec-93	Excessive Tail Rotor Drive System Use Caused by Repeated Heavy Lift Operations
OSN 205-94-32	Basic	16-May-94	Flight Limitations
OSN 205-96-33	Basic	17-May-96	Tail Rotor Yoke -- Static/Dynamic Damage
OSN 205-98-34	Rev A	2-Jun-98	AlliedSignal T53 Engine Spur Gear Failure
OSN 205-00-35	Basic	24-Mar-00	Main Rotor Mast 204-011-450-ALL Retirement Index Number Calculation and Bell Helicopter Request for Information
OSN 205A1-00-36	Basic	20-Apr-00	Main Servo Actuator 212-076-005-ALL, Lower Rod— End Bearing
OSN 205-02-37	Basic	27-Aug-02	Tail Rotor Blades 212-010-750-ALL, Inspection of
OSN 205-03-38	Basic	4-Sep-03	Drive Link P/N 204-011-407-101, Inspection of
OSN 205-04-39	Basic	23-Feb-04	205A1/212/412/412CF Tail Rotor Pitch Link Inspection
OSN 205-05-40	Basic	22-Feb-05	Main Rotor Blades 204-012-001-ALL and 212-015-501-ALL Inspection of
OSN 205-06-41	Basic	10-Jan-06	Rod End Bearing Assembly P/N 212-010-123-101: Inspection of
OSN 205-07-42	Basic	26-Mar-07	FAA Unapproved Parts Notification 2006-00097
OSN 205-07-43	Basic	5-Jul-07	FAA Unapproved Parts Notification 2007-00089
OSN 205-10-44	Basic	14-Jun-10	Tailboom Longerons Inspection Requirements

GENERAL OPERATIONS SAFETY NOTICE INDEX

NUMERICAL INDEX

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
OSN GEN-76-1	Basic	21-Jan-76	Use of Life Vests During Over-water Operations
OSN GEN-76-2	Basic	23-Jan-76	Helicopter Accidents Caused by Ground Handling Errors
OSN GEN-76-3	Basic	24-Sep-76	Use of Standard Hardware
OSN GEN-76-4	Basic	13-Sep-76	Heavy Lift, Aft Center of Gravity, Prolonged Hover, Cyclic Control Abuse
OSN GEN-76-5	Basic	13-Sep-76	Fuel Contamination
OSN GEN-76-6	Basic	18-Oct-76	Collective Minimum Friction
OSN GEN-76-7			NOT USED
OSN GEN-76-8	Basic	22-Dec-76	Operation of Helicopters in Salt Laden Atmosphere
OSN GEN-77-1	Rev A	3-Nov-77	Airworthiness of Aircraft Parts
OSN GEN-78-1	Basic	10-Jan-78	Maintenance of the Main Rotor Blade Inspection System (B.I.S.)
OSN GEN-78-2	Basic	5-May-78	Cracked Main Rotor Yoke P/N 204-011-102
OSN GEN-78-3	Basic	13-Sep-78	Chadwick C-47 Electronic Weighing System, Load Cell Link P/N 47-40200-19
OSN GEN-78-4	Basic	11-Dec-78	Chaffed Oil Lines
OSN GEN-79-1	Basic	2-May-79	Cracked Main Rotor Yoke P/N 204-011-102
OSN GEN-79-2	Basic	26-Nov-79	Cracked Main Rotor Yoke P/N 204-011-102
OSN GEN-80-3	Basic	13-Feb-80	Cracked Main Rotor Blade, P/N 204-011-250 Series
OSN GEN-80-4	Basic	19-Jun-80	Rotating Control Bolts
OSN GEN-80-5	Basic	27-Jun-80	Enhancement of Crew and Passenger Safety During High Impact Landings
OSN GEN-80-6	Basic	27-Jun-80	Daily Inspection of Main Input Driveshafts
OSN GEN-80-7	Basic	24-Jul-80	Transporting Flammable Cargo
OSN GEN-81-8	Basic	22-Sep-81	Inspection of Tail Rotor Pitch Links
OSN GEN-82-9	Basic	6-Oct-82	Tail Rotor Driveshaft Curvic Couplings, Inspection, Maintenance
OSN GEN-83-10	Basic	1-Sep-83	Engine Compressor Washing
OSN GEN-85-11	Basic	6-Nov-85	Beware of "Certificate of Manufacture, Inspection and Conformance"
OSN GEN-87-12	Basic	13-May-87	FAA Airworthiness Directive 87-06-09 (Mechanical Products, Inc.)
OSN GEN-88-13	Reissue	5-May-92	Lines Extending from the Helicopter
OSN GEN-89-14	Basic	6-Dec-89	Bogus P/N 212-073-905-1 Pressure Gage, Emergency Floats
OSN GEN-91-15	Basic	29-Jul-91	Electromagnetic Compatibility (EMC) of Aircraft Wiring with Pyrotechnic Device and Cargo Hooks
OSN GEN-91-16	Basic	21-Aug-91	Airframe Structural Repair
OSN GEN-91-17	Basic	1-Oct-91	Main Driveshaft Assembly, Inspection of
OSN GEN-92-18	Basic	19-Mar-92	Proper Stowage of Miscellaneous Items in and Around the Flight Crew Compartment
OSN GEN-92-19	Basic	5-May-92	MS21042 Series Nuts Approved Vendors
OSN GEN-92-20	Basic	25-Jun-92	Use of Non-Conforming Floatbag Assemblies
OSN GEN-92-21	Basic	25-Jun-92	Lubricant P/N 204-040-755-005

GENERAL OPERATIONS SAFETY NOTICE INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
OSN GEN-93-22	Basic	29-Jan-93	Main Rotor Vibration; Emphasis on Timely Investigation
OSN GEN-93-23	Basic	29-Jan-93	Maintenance/Overhaul Procedures
OSN GEN-93-24	Basic	1-Mar-93	Parts Authenticity and Traceability
OSN GEN-93-25	Basic	15-Dec-93	"Slingshot" Maneuvers in Heavy Lift Operations
OSN GEN-95-26	Basic	19-Jan-95	Aircraft Cleaning
OSN GEN-95-27	Basic	24-Mar-95	Tail Rotor Yoke (Flexure Style) Failure
OSN GEN-96-28	Basic	21-May-96	Transmission Spiral Bevel Gear Cracks
OSN GEN-96-29	Basic	18-Oct-96	Unapproved Tail Rotor Driveshaft Hanger Bearings
OSN GEN-97-30	Basic	27-Jan-97	Breeze-Eastern Customer Advisory Bulletin Number CAB-100-54
OSN GEN-97-31	Basic	1-May-97	Tail Rotor Hanger Bearings Maintenance
OSN GEN-02-32	Basic	2-May-02	Bogus Parts Tail Rotor Grips
OSN GEN-02-33	Basic	10-Oct-02	Maintenance/Overhaul Procedures
OSN GEN-02-34	Basic	22-Nov-02	Correct Procedure for Torquing Fasteners
OSN GEN-04-35	Basic	21-Sep-04	Cyclic Stick Grip Assembly
OSN GEN-06-36	Basic	17-Apr-06	Paint Application on Helicopter Faying Surfaces
OSN GEN-06-37	Basic	20-Jul-06	NAS 1291-7 and -8 Nut, Confirmation of Condition Upon Installation
OSN GEN-09-38	Basic	7-Apr-09	Bearings in Flight Controls
OSN GEN-09-39			RESERVED
OSN GEN-09-40	Basic	16-Nov-09	Onboard Systems International Alert Service Letter Document no. 159-027-00.
OSN GEN-10-41	Basic	18-Jan-10	Honeywell Bendix/King Discrepant Databases for KLN35A/KLN 88/KLN 89/KLN 89B/KLN 90/KLN 90A/KLN90B/KLN 94/KLX 100/KLX 135/KLX 135A/KLN 900
OSN GEN-10-42	Basic	13-Dec-10	Use of Specified Hardware
OSN GEN-11-43	Rev A	16-Sep-11	NAS1291 Nuts and NAS626 Bolts
OSN GEN-11-44	Basic	10-May-11	Defective Grease Fittings NAS516-1A

NOTICE

The following blank pages are provided for entry of additional notices when distributed. These additional notices will be included in this index at next revision

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
--------------------	-----------------------	-------------	----------------