

BHT-222/B-ASB-INDEX

**Bell** *MODEL* **222/222B**

**ALERT  
SERVICE  
BULLETIN  
INDEX**

**COPYRIGHT NOTICE**

COPYRIGHT 2011  
BELL © HELICOPTER TEXTRON INC.  
AND BELL HELICOPTER TEXTRON  
CANADA LTD.  
ALL RIGHTS RESERVED

**Bell** *helicopter*  
A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

**13 DECEMBER 2011**



## 222/B ALERT SERVICE BULLETIN INDEX

## NUMERICAL INDEX

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
ASB 222-80-1	Basic	21-Oct-80	Overhead Console Electrical Installation, Modification of
ASB 222-80-2	Rev A	30-Mar-81	Drive Hub Assembly, P/N 222-010-417-009, Inspection and Modification of
ASB 222-81-3	Basic	4-Feb-81	Zinc Chromate Primer, Thermal Indicator, Addition of
ASB 222-81-4	Basic	25-Mar-81	Battery Temperature Sensors for 17AH Battery, P/N GE43B010RB03, Wiring Change, Termination of
ASB 222-81-5	Basic	9-Apr-81	Engine Fire Extinguisher Installation, P/N 222-069-910-101, Squib Discharge Valve, Identification and Wiring, Clarification of
ASB 222-81-6	Basic	27-Apr-81	Tail Rotor Driveshaft Hanger Bearing, P/N 222-344-606-003, Alignment of
ASB 222-81-7			NEVER ISSUED
ASB 222-81-8	Basic	15-Sep-81	Rework of Electrical Cable Assemblies to Prevent Chafing
ASB 222-81-9	Basic	28-Sep-81	Rescue Hoist and Provision Kit, P/N 222-899-110-101, -103, and Heavy Duty Rescue Hoist Installation, P/N 222-899-184-101, Addition of Electrical Ground to Hoist
ASB 222-81-10	Basic	21-Oct-81	Collective Lever Assembly, P/N 222-010-497-101, Inspection of
ASB 222-82-11	Basic	29-Apr-82	Tailboom P/N 222-035-100-103, Inspection, Repair, and Modification of
ASB 222-82-12	Basic	18-May-82	Swashplate Drive Link Assemblies, P/N 222-010-460-101, Inspection and Replacement of
ASB 222-82-13	Basic	18-May-82	Aluminum Swashplate Drive Link Assemblies, P/N 222-010-460-101, Inspection and Replacement of
ASB 222-82-14	Rev A	28-May-87	Swashplate Drive Assembly, P/N 222-010-417-009, and Spline Plate, P/N 222-310-418-105/-107, Inspection of
ASB 222-82-15	Rev A	24-Aug-82	Main Rotor Blade, P/N 222-015-500-101, Center Spar Doubler, Inspection, Sealing, and Protection of
ASB 222-82-16	Basic	22-Jun-82	Servo Actuator, P/N 222-382-001-101, Inspection of
ASB 222-82-17	Rev A	28-Feb-83	Main Rotor Trunnion, P/N 222-010-154-101, and Mast Assembly, Torquemeter, P/N 222-040-002-103, Mandatory Life Reduction
ASB 222-83-18	Basic	26-Jan-83	Walking Beam Assembly, P/N 222-010-415, Inspection of
ASB 222-83-19	Basic	28-Mar-83	Walking Beam Assembly, P/N 222-010-415-005 and -009, Modification
ASB 222-83-20	Basic	5-Apr-83	Nodal Beam Left Side Aft Support Fitting, P/N 222-031-520-105, Airworthiness Life (Hours), Assignment of
ASB 222-83-21	Basic	11-Apr-83	Synchro Transmitter Arm Retaining Clip, P/N 222-001-455-101, Installation of
ASB 222-83-22	Rev A	4-May-83	Idler Link Assembly and Collective Lever Connecting Bolt, P/N 20-057-10-45D, Inspection and Retorque of

## 222/B ALERT SERVICE BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
ASB 222-83-23	Rev A	30-Aug-83	Rescue Hoist Installation, P/N 222-899-110-101/-103, Hoist, P/N BL-16600 (All Dash Numbers), Conversion and Inspection of
ASB 222-83-24	Basic	21-Sep-83	Switch Guard, P/N 51380-C, On Float Arm Switch, P/N 106488H1-19, Modification of
ASB 222-83-25	Basic	7-Nov-83	Nose Gear Trunnion Assembly, P/N 3965001-3, Inspection of
ASB 222-84-26	Basic	16-Jul-84	Emergency Flotation Reservoir, P/N 222-325-021-101, Decal (WARNING), P/N 31-023-8B, and Decal (CAUTION), P/N 31-023-9B, Installation of
ASB 222-85-27	Basic	13-Feb-85	Dual Controls Auxiliary Equipment Kit, P/N 222-706-084-101/-103, Installation of Spring Pin Assembly
ASB 222-85-28	Basic	21-Mar-85	Tailboom, P/N 222-035-150-103, Inspection, Repair, and Modification of
ASB 222-85-29	Basic	12-Apr-85	Fire Detector Element Ground Strap, Addition of
ASB 222-85-30	Basic	13-Jun-85	Instrument Current Limiter, P/N 531-1 Reconfiguration of
ASB 222-85-31	Rev A	1-Nov-85	Engine, Lycoming LTS-101-650C-2/-3 and 101-750C-1, Ng Operating Speed Restrictions
ASB 222-85-32	Rev A	3-Nov-86	Directional Hydraulic Actuator, P/N 222-382-002-101, Inspection of Rod End
ASB 222-85-33	Basic	13-Aug-85	Directional Hydraulic Actuator, P/N 222-382-002-101, and Main Rotor Control Dual Servo Actuator, P/N 222-382-001-101, Inspection of Control Linkage Rivets
ASB 222-85-34	Rev B	13-Oct-86	Rescue Hoist Installation, Conversion of Hoist, P/N BL-16600-80, to P/N BL-16600-110
ASB 222-85-35	Basic	20-Nov-85	Fin Assembly, P/N 222-035-220, Modification and Installation of
ASB 222-86-36	Basic	27-Jun-86	Emergency Flotation System, and Squib Valve Assembly, P/N 212-073-912-(All), Inspection and Modification of
ASB 222-86-37	Basic	29-Aug-86	Rewiring of Engine Chip Detectors to Provide Early Warning of a No. 2 or No. 3 Bearing Failure (222B)
ASB 222-86-38	Basic	28-Oct-86	Rescue Hoist Cable Cutter Circuit, Rewiring of in Accordance with Breeze Manufacturing Preferred Method
ASB 222-86-39	Rev A	14-Jan-87	Flapping Bearing, P/N 222-310-114-003/-105, Rework of
ASB 222-87-40	Basic	26-Jan-87	Swashplate Pins, P/N 222-010-455-003, Inspection of
ASB 222-87-41	Basic	18-Feb-87	Emergency Flotation System, Modification of, and Squib Valve Assembly, P/N 212-073-912-(All), Replacement of
ASB 222-87-42	Rev B	18-Jul-88	Daily and Periodic Inspection of Engine Oil System Chip Detectors, Installation of the LTS 101-650 Series Engine #2 and #3 Bearings Scavenge Debris Monitor Kit, Wiring of the #2 and #3 Scavenge Debris Monitor to a Dedicated Red Warning Light Segment, Addition of a "Warning" Note to the Flight Manual (222)

## 222/B ALERT SERVICE BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
ASB 222-87-43	Basic	22-Jun-87	Auxiliary Equipment Kit Emergency Flotation, P/N 222-706-093-101, -107, -111, -115, -119, and -121, Modification of
ASB 222-87-44	Basic	12-Oct-87	Aft Passenger Windows (Emergency Exit), Replacement of
ASB 222-87-45	Basic	19-Nov-87	Swashplate Drive Assembly, Modification to Incorporate P/N 222-010-471-101 Drive Hub Assembly
ASB 222-88-46	Basic	14-Jan-88	Main Rotor Yoke, P/N 222-011-102-101, Inspection of
ASB 222-88-47	Basic	2-Mar-88	Daily and Periodic Inspection of Engine Oil System Chip Detectors, Addition of a "Warning" Note to the Flight Manual and Modification of the Chip Detector Electrical System (222B)
ASB 222-88-48	Rev A	26-Aug-88	External Hoist, P/N BL-16600-(All Dash Numbers), and Heavy Duty Hoist, P/N BL-20200-1, Inspection of Load Cable and Hook/Bumper Stowage
ASB 222-88-49	Basic	1-Sep-88	Bulkhead P/N 222-031-309-101 Web to Angle Attach Rivets One Time Inspection of
ASB 222-88-50	Basic	1-Sep-88	Stabilizer Assembly, P/N 222-035-250-101, -103, -105, Inspection of
ASB 222-88-51	Basic	14-Nov-88	Main Rotor Yoke Assembly, P/N 222-011-102-101, Modification of
ASB 222-89-52	Rev A	1-Aug-89	Aeroquip 601 Hose Assemblies, One-Time Inspection and Replacement
ASB 222-89-53	Rev A	23-May-89	Stabilizer Assembly, P/N 222-035-250-101, -103, -105 Inspection and Replacement of
ASB 222-89-54	Rev A	27-Sep-89	Main Rotor Flight Control Bolts, Inspection of
ASB 222-89-55	Basic	24-Aug-89	Tail Rotor Boost Cylinder Support Bracket, P/N 222-031-471-001, Inspection and Replacement of
ASB 222-90-56	Basic	15-Jan-90	Breeze-Eastern Cargo Hook P/N 17172-1 Warning Plate, Addition of
ASB 222-90-57	Basic	21-Dec-90	Engine, Lycoming LTS 101-650/ -750 Series Power Turbine Speed Restriction for Cast Turbine Wheels
ASB 222-91-58	Basic	17-Sep-91	Crew Seat Restraint Assembly 222-320-823-101, -105, -107, -115, Improvement of
ASB 222-92-59	Rev A	13-Oct-92	Engine Overspeed Control System (OCS) Kit, Installation of
ASB 222-92-60	Basic	16-Dec-92	Flapping Bearing, P/N 222-310-114-003/-105/-107/-109
ASB 222-93-61	Rev A	24-Apr-96	Engine Air Intake Duct Assembly, P/N 222-062-211, Inspection of
ASB 222-93-62	Basic	2-Jun-93	Lycoming LT 101 Engine, Power Turbine Rotor Assembly P/N 4-141-290-01/-03, One Time Inspection of
ASB 222-93-63	Rev B	19-Oct-93	Lycoming LT 101 Engine, Power Turbine Rotor Assembly P/N 4-141-290-01/-03, Special Inspection of

## 222/B ALERT SERVICE BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
ASB 222-93-64	Rev A	20-Jun-94	Cargo Hooks, Breeze Eastern Customer Advisory Bulletin No. CAB-100-41, Customer Service Bulletin No. CSB-147
ASB 222-93-65	Basic	30-Aug-93	Flapping Bearings, P/N 222-310-114-003/-105/-107/-109, Replacement of
ASB 222-93-66	Basic	19-Oct-93	Lycoming LT 101 Engine, Gas Producer Rotor Discs P/N 4-111-015-04/-09/-14, One Time Inspection of
ASB 222-93-67	Rev A	4-Mar-94	Main and Tail Rotor Driveshaft Grease Lubricated Couplings, Over-Temperature Indicators, Installation of
ASB 222-94-68	Basic	4-Apr-94	Lycoming LT 101 Engine, Removal of No. 2 Winged Bearing, P/N 4-301-362-101, S/N 3-740 Thru 3-839, S/N 3-1288 Thru 3-1361 and S/N 4-534 Thru 4-680
ASB 222-94-69	Basic	12-Aug-94	Driveshaft P/N 222-044-645-103 and 222-044-685-101, Inspection of
ASB 222-94-70	Basic	6-Sep-94	Pedal Assembly P/N 222-001-760-001/-003, Modification of
ASB 222-94-71	Basic	12-Sep-94	Nose Wheel Assemblies P/N 222-336-004-001 and P/N 222-336-004-101, One Time Inspection and Replacement of
ASB 222-94-72	Basic	31-Oct-94	Emergency Exit, Passenger Door Windows
ASB 222-94-73	Basic	14-Nov-94	Flapping Spring P/N 222-310-117-103, Inspection of
ASB 222-95-74	Basic	18-Jan-95	Shaft Assembly P/N 222-044-685-101, Recall and Replacement of
ASB 222-95-75	Basic	25-Sep-95	Engine Fire Extinguisher System
ASB 222-95-76	Rev B	22-Apr-96	Tail Rotor Blades P/N 222-016-001-101/-107/-111/-113/-115 and -119
ASB 222-95-77	Basic	16-Oct-95	Tail Rotor Pitch Link, P/N 222-312-702-101, Replacement of
ASB 222-95-78	Basic	4-Dec-95	Main Rotor Hub P/N 222-012-101-103/-107, Grip Retaining Bolt P/N 222-310-127-101, Re-Torque and Inspection of
ASB 222-96-79	Basic	13-Nov-96	Tail Rotor Blade P/N 222-016-001-101/-107/-111/-113/ -115 and -119, Removal From Service
ASB 222-98-80	Basic	23-Mar-98	Power Trim Check Procedure
ASB 222-98-81	Basic	23-Apr-98	Main Rotor Hub Grip and Flapping Bearing Bolt Torque Check
ASB 222-98-82	Rev A	9-Jun-98	Vertical Fin Assembly Installation, Inspection of
ASB 222-98-83	Basic	12-Oct-98	Main Rotor Hub Trunnion Bolt, Inspection of
ASB 222-99-84	Basic	15-Feb-99	Swashplate Assembly Drive Pins, Inspection of
ASB 222-99-85	Basic	16-Dec-99	Tail Rotor (T/R) Pitch Change Bearings P/N 222-312-753-103, Inspection of; and Tail Rotor Blade Attaching Hardware, Replacement of
ASB 222-00-86	Basic	19-May-00	Hydraulic Actuator Support P/N 222-040-125-001, Inspection of
ASB 222-01-87	Basic	19-Jan-01	Magnetic Brake P/N 204-001-376-105 and -107, One Time Inspection of
ASB 222-01-88	Basic	16-Jan-01	Rescue Hoist, BL-16600 Series, Breeze Eastern Customer Alert Bulletin CAB-100-58

## 222/B ALERT SERVICE BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
ASB 222-01-89	Basic	7-Feb-01	Upper Fuel Enclosure, Right Side Addition of Drain Provision
ASB 222-01-90	Rev A	26-Oct-05	Rotating Ring Assembly P/N 222-010-403-005, -113 and -117, Inspection of
ASB 222-01-91	Basic	18-May-01	Main Rotor Pendulum Weight Support P/N 222-011-114-103, Replacement of
ASB 222-02-92	Basic	28-Mar-02	Main Rotor Pendulum Weight Support P/N 222-011-114-101 and -103, Rework of
ASB 222-02-93	Rev A	3-Mar-03	Main Rotor Hub Assemblies P/N 222-011-101-103/-105/-107/-109 and P/N 222-012-101-103/ -107, Inspection of
ASB 222-02-94	Basic	9-Apr-02	Fuel System Check and Relief Valve P/N 222-366-687-101, Replacement of
ASB 222-03-95	Basic	26-Jun-03	Honeywell LTS 101 Engine, Inspection of Fuel Pump Internal Drive Splines
ASB 222-03-96	Basic	26-Jun-03	Honeywell LTS 101 Engine, Replacement of Fuel System Power Turbine Governor Spool Bearing Part No. 2523973
ASB 222-03-97	Basic	23-Sep-03	Main Rotor Hub P/N 222-011-101-ALL and 222-012-101-ALL, Inspection of
ASB 222-04-98	Basic	8-Jun-04	Honeywell LTS 101 Engine Removal and Replacement of Fuel Control Spool Bearing P/N 2523973 Rev. M
ASB 222-04-99	Rev C	16-Feb-06	Tail Rotor Counterweight Bellcrank P/N 222-012-727-003, Removal from Service
ASB 222-04-100	Rev B	31-Mar-08	Tail Rotor Blade P/N 222-016-001-123, -127, -131 and -135, Inspection of
ASB 222-04-101	Rev B	15-Mar-06	Tail Rotor Counterweight Bellcrank P/N 222-012-727-105, Inspection of
ASB 222-06-102	Basic	17-Feb-06	Float Inflation Valve Squib P/N 29022968, Misidentification of
ASB 222-06-103	Basic	21-Nov-06	Engine - Gearbox - Removal and Replacement of Locking Cup Part No. 4-082-094-01
ASB 222-07-104	Basic	9-Jan-07	Tail Rotor Pitch Change Mechanism, Revised Rigging Procedures
ASB 222-07-105	Basic	28-Mar-07	Disc Assembly P/N 36300-1 and 37855-1 Inspection of
ASB 222-07-106	Rev D	29-Nov-10	Tail Rotor Blade Assembly, Inspection of
ASB 222-09-107	Basic	7-Apr-09	Staked Bearings, One Time Inspection of
ASB 222-09-108	Basic	10-Nov-09	Main Rotor Pendulum Weight Support P/N 222-011-114-101 and -103 Removal from Service
ASB 222-10-109	Rev A	30-Aug-11	Hydraulic Servoactuator P/N 222-382-001-107 Manufactured by Woodward HRT, Inspection of
ASB 222-10-110	Rev A	15-Dec-10	Directional Flight Control Bearing P/N MS27643-4; Inspection and Replacement of
ASB 222-11-111	Basic	9-Dec-11	Overhaul of Hydraulic Servo Actuator P/N 222-382-001-107 and Introduction of Servo Actuator P/N 222-382-001-111





## BHT-222/B-ASB-INDEX

### NOTICE

The following blank pages are provided for entry of additional notices when distributed. These additional notices will be included in this index at next revision

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
-------------	---------------	------	---------