



INFORMATION LETTER INDEX

COPYRIGHT NOTICE

COPYRIGHT 2011
BELL © HELICOPTER TEXTRON INC.
AND BELL HELICOPTER TEXTRON
CANADA LTD.
ALL RIGHTS RESERVED

Bell *helicopter*

A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

04 OCTOBER 2011

205B INFORMATION LETTER INDEX

NUMERICAL INDEX

| PUBLICATION | ISSUE/ REV | DATE | SUBJECT |
|---------------|---------------|-----------|--|
| IL 205B-96-15 | Basic | 26-Feb-96 | "Look-alike" Transmission Accessory Components |
| IL 205B-97-01 | Basic | 28-Aug-97 | Retaining Rings Part Number RS675L, P/N M27426-3233C and Deflectors P/N 204-040-378-001, P/N 204-040-378-101: Use Of |
| IL 205B-00-02 | Basic | 20-Apr-00 | Main Rotor Mast 204-011-450-001/-007/-105/-113/-119; Inspection and Retirement Index Number (RIN) life Reduction |
| IL 205B-00-03 | Basic | 2-Jun-00 | Main Rotor Grip 204-011-121-121 |
| IL 205B-00-04 | Basic | 3-Aug-00 | Federal Aviation Administration (FAA) AD 2000-15-52 |
| IL 205B-00-05 | Rev A | 7-Aug-00 | Federal Aviation Administration (FAA) AD 2000-15-52 Alternate Means of Compliance (AMOC) Statement for Trunnions 204-011-105-001 and 204-011-105-103 |
| IL 205B-00-06 | Basic | 18-Aug-00 | Status Report on Medium Mast ASB |
| IL 205B-00-07 | Basic | 1-Sep-00 | Status Report on Medium Mast ASB |
| IL 205B-01-08 | Basic | 20-Mar-01 | Status Report on Medium Mast ASB |
| IL 205B-01-09 | Basic | 20-Apr-01 | Torque on Flight Control Bolts |
| IL 205B-01-10 | Basic | 20-Jun-01 | Improved Bearing with Silver-plated Steel Cage, Introduction of |
| IL 205B-01-11 | Basic | 29-Nov-01 | Status Report on Medium Helicopter Mast ASB |
| IL 205B-02-12 | Basic | 24-Jan-02 | 204-011-121-009/-121 M/R Grip Ultrasonic Inspection Of |
| IL 205B-02-13 | Basic | 18-Mar-02 | 204-011-121-009/-121 M/R Grip Ultrasonic Inspection Of |
| IL 205B-02-14 | Basic | 9-Apr-02 | 204-011-121-009/-121 M/R Grip Ultrasonic Inspection Of |
| IL 205B-02-15 | Basic | 10-Dec-02 | Improved Wiper Motors P/N 204-070-907-103/104 |
| IL 205B-03-16 | Basic | 30-Sep-03 | Main Rotor Grip 204-011-121-005/-009/-117/-121 Ultrasonic Inspection Courses |
| IL 205B-04-17 | Basic | 12-Jul-04 | Main Rotor Grips 204-011-121-009, 117 and 121 |
| IL 205B-04-18 | Rev B | 14-Sep-10 | BLR FastFin and Strake Installation on All Bell 204, 205, 205B, and 212 Model Helicopters |
| IL 205B-05-19 | Rev A | 13-Dec-06 | Change to Recommended Intervals for Planned Maintenance of Breeze-Eastern Rescue Hoists and Cargo Winches |
| IL 205B-05-20 | Basic | 29-Mar-05 | Main Rotor Drag Brace P/N 204-011-140-ALL |
| IL 205B-08-21 | Rev A | 23-Jul-08 | Grip Assembly P/N 204-011-121-125, Introduction of |

GENERAL INFORMATION LETTER INDEX

NUMERICAL INDEX

| PUBLICATION | ISSUE/ REV | DATE | SUBJECT |
|------------------------|---------------|-----------|--|
| IL GEN-35:COA:ms-8833 | Basic | 6-Oct-77 | Replacement of Grease P/N 204-040-755-3 (ANDEROL L786 OR R-508) with Grease P/N 204-040-755-5 (SYN TECH 3913-G1) |
| IL GEN-35:AJS:ms-9146 | Basic | 30-Jan-78 | Cracked Main Rotor Yoke P/N 204-011-102 |
| IL GEN-35:EAM:ms-9227 | Basic | 4-Mar-78 | Inter Turbine Temperature Indicator Modification |
| IL GEN-35:GEH:ms-9379 | Basic | 17-Apr-78 | AL-T3 Torque Ctrl Exchange Program |
| IL GEN-35:GEH:ms-9599 | Basic | 12-Jun-78 | Idle Gear Failures |
| IL GEN-35:TKF:ms-9628 | Basic | 29-Jun-78 | Gear Failure (-701) Referred to in OSN 212-78-1 |
| IL GEN-35:COA:ms-9801 | Basic | 5-Oct-78 | New Mast Bearing P/N 212-040-136-1 |
| IL GEN-35:GAZ:oab-2102 | Basic | 11-Dec-78 | New Bell Helicopter Textron Warranty for New Helicopters and Spares Delivered January 1, 1979 and Subsequent |
| IL GEN-35:COA:ms-9950 | Basic | 13-Dec-78 | Inspection of Metal Contaminated Transmissions |
| IL GEN-35:CFB:ms-9963 | Basic | 20-Dec-78 | (Idle Gear) |
| IL GEN-79-1 | Basic | 9-Feb-79 | Agenda for 1979 Management, Flight & Maint Conf |
| IL GEN-79-2 | Basic | 29-Mar-79 | Revised Main Rotor Hub Overhaul Procedures |
| IL GEN-79-3 | Basic | 14-May-79 | Models 206, 206L, 212 Availability of Trial Micro-Fiche Publications |
| IL GEN-79-4 | Basic | 1-Jun-79 | CANCELED |
| IL GEN-79-5 | Basic | 23-Jul-79 | Lord Kinematics Refurbished Parts |
| IL GEN-79-6 | Basic | 20-Aug-79 | Undersize 205-040-176-101 and 212-040-176-7 Boots |
| IL GEN-79-7 | Basic | 22-Aug-79 | Lubrication Frequency (Superseded by GEN-79-9) |
| IL GEN-79-8 | Basic | 10-Sep-79 | Imminent Bearing Shortages |
| IL GEN-79-9 | Basic | 9-Nov-79 | Lubrication Frequency (Supersedes GEN-79-7) |
| IL GEN-79-10 | Basic | 13-Nov-79 | Stabilizer Bar Assy Component Overhaul Schedule |
| IL GEN-80-11 | Basic | 21-Apr-80 | New Discrepancy/Malfunction Report Form |
| IL GEN-80-12 | Basic | 23-Apr-80 | Care and Handling of Electrical Wire and Cable |
| IL GEN-80-13 | Basic | 23-May-80 | Dust Ingestion and Sulfur Contamination |
| IL GEN-80-14 | Basic | 16-Jun-80 | Termination of the Trial Micro Fiche Publications Program |
| IL GEN-80-15 | Basic | 3-Oct-80 | Terminal Junction System |
| IL GEN-80-16 | Basic | 16-Dec-80 | New Location & Teletype Numbers for Product Supt Dept |
| IL GEN-81-17 | Basic | 21-Apr-81 | Chadwick-Helmuth Rotor Balancer |
| IL GEN-81-18 | Basic | 5-Aug-81 | Repair of Tailrotor driveshafts with Missing Weights |
| IL GEN-81-19 | Basic | 11-Aug-81 | CSR Effectiveness Questionnaire |
| IL GEN-81-20 | Basic | 14-Aug-81 | Use of Alternate Parts in 204/205/212 XMSNs |
| IL GEN-81-21 | Basic | 1-Sep-81 | Compressor Wash - All Model Turbine Engines |
| IL GEN-81-22 | Basic | 29-Sep-81 | BHT Announces New Round of M&O Conferences |
| IL GEN-81-23 | Basic | 9-Dec-81 | Bell Helicopter Textron Announces the Continuance of Maintenance & Operations Conferences |
| IL GEN-81-24 | Basic | 14-Dec-81 | Grease P/N 204-040-755-5 (SYN Tech 3913-G1) Shelf Life |
| IL GEN-82-25 | Basic | 7-Apr-82 | The Discrepancy/Malfunction Rpt (D/MR) |

GENERAL INFORMATION LETTER INDEX

NUMERICAL INDEX (Cont)

| PUBLICATION | ISSUE/ REV | DATE | SUBJECT |
|--------------|---------------|-----------|---|
| IL GEN-82-26 | Basic | 15-Jan-82 | Availability of Wire Strike Protection for Bell Helicopters |
| IL GEN-82-27 | Basic | 17-Mar-82 | Bell Helicopter Textron, Inc. Training Center Telephone Number Changes |
| IL GEN-82-28 | Basic | 15-Nov-82 | Trend Monitoring Vibrations |
| IL GEN-83-29 | Basic | 26-May-83 | Daily Inspections/Airworthiness Checks |
| IL GEN-84-30 | Rev A | 31-May-84 | Royal Lubricants Co., Royco Turbine Oil 500 Usage Of |
| IL GEN-84-31 | Rev B | 17-Nov-92 | Inspection Rqmts for Reservoirs & Valve Operating Squibs Used in Emergency Float & Fire Extinguisher Systems (Superseded by IL GEN-93-52) |
| IL GEN-84-32 | Basic | 12-Jun-84 | Driveshaft Coupling Lubricant, P/N 204-040-755-005 |
| IL GEN-84-33 | Basic | 24-Jul-84 | Electric ARC Etching, Unauthorized Procedure |
| IL GEN-84-34 | Basic | 9-Aug-84 | Grease P/N 204-040-755-5 (SYN Tech 3913-G1) Unauthorized Sources |
| IL GEN-84-35 | Basic | 9-Aug-84 | Failure of Main Rotor Pitch Change Link Clevis, P/N 204-011-136-001 |
| IL GEN-84-36 | Basic | 28-Nov-84 | Use of Pressing Tool (Work Aid) when Inst. 205-040-301-001 Pinion in 204-040-424-001 Dup. Brg. Of Rotor BK Quill |
| IL GEN-84-37 | Basic | 28-Nov-84 | Use of Pressing Plug & Sleeve when Installing 204-040-102-017 Pin in Duplex BRG. Of Gen. Drive Quill |
| IL GEN-84-38 | Basic | 6-Dec-84 | High Density Terminal Junction Modules |
| IL GEN-85-39 | Basic | 10-Jan-85 | Simmonds Precision Information Letter No. 84-01 Describing Deterioration of Rubber in Fuel Transmitters |
| IL GEN-85-40 | Rev A | 9-Jan-86 | Protection of Elastomeric Components with Silicone Elastomers |
| IL GEN-86-41 | Basic | 5-Feb-86 | Availability of Alternate Cable Cutter Cartridge |
| IL GEN-86-42 | Basic | 17-Mar-86 | 1986 MF&M Conference (Avis) |
| IL GEN-86-43 | Basic | 10-Jun-86 | New Rotor Brake Linings |
| IL GEN-87-44 | Basic | 18-Feb-87 | Lord Corporation Refurbishment/Exchange Parts Program |
| IL GEN-87-45 | Basic | 7-Apr-87 | Plastic Media Blasting (PMB) |
| IL GEN-87-46 | Rev A | 4-Jan-88 | Use of Illustrated Parts Catalogs |
| IL GEN-88-47 | Rev B | 22-Apr-92 | MS21042 Series Nuts, Approved Vendors for |
| IL GEN-90-48 | Basic | 8-Oct-90 | Accelerometer Minimum Specifications for Main Rotor Balancing Applications |
| IL GEN-91-49 | Basic | 9-Oct-91 | Refurbishment of Parts Manufactured with K1001 (BLUE) Epoxy Resin Coating |
| IL GEN-92-50 | Basic | 20-Jan-92 | Lord Corporation Remanufactured/Exchange Parts Program |
| IL GEN-92-51 | Basic | 4-Dec-92 | Magnolia Magnobond 6392 Adhesive |

GENERAL INFORMATION LETTER INDEX

NUMERICAL INDEX (Cont)

| PUBLICATION | ISSUE/ REV | DATE | SUBJECT |
|--------------|---------------|-----------|--|
| IL GEN-93-52 | Basic | 21-Jun-93 | Insp Rqmts for Res. & Valve Operating Squibbs Used in Emergency Float & Eng. Fire Ext. Sys & for Rescue Hoist Cable Cutter Squibbs |
| IL GEN-94-53 | Basic | 4-Mar-94 | Powertrain Component Corrosion Prevention |
| IL GEN-94-54 | Basic | 15-Apr-94 | Retirement Index Number (RIN) for Cycle Lived Components (Superseded by IL GEN-03-94) |
| IL GEN-96-55 | Rev A | 19-Oct-99 | Improved Tail Rotor 90/42 Degree Gearbox Oil Filler Caps |
| IL GEN-97-56 | Basic | 10-Mar-97 | Bell Helicopter Part Numbering System |
| IL GEN-97-57 | Basic | 24-Mar-97 | Use of Noise Cancelling Headsets in Bell Helicopters |
| IL GEN-97-58 | Basic | 13-Nov-97 | Castrol Aero 5734 |
| IL GEN-98-59 | Rev A | 8-May-98 | Folding Step Electrical Actuators P/N 212-075-418-107 |
| IL GEN-98-60 | Basic | 1-Jun-98 | RADS-AT User Training |
| IL GEN-98-61 | Basic | 12-Jun-98 | A/C Modification & New E-Mail Addresses for Bell Helicopter Textron Canada |
| IL GEN-98-62 | Basic | 16-Nov-98 | Flexure Style Main Rotor & Tail Rotor Yokes |
| IL GEN-99-63 | Basic | 13-Jan-99 | Pressure Vessels, used as Nitrogen Reservoirs for Emergency Floatation Systems, Service Life Of |
| IL GEN-99-64 | Basic | 18-Jan-99 | Airframe Damage Descriptions |
| IL GEN-99-65 | Rev A | 2-Jun-06 | Interchangeability of Agusta & Bell Manufactured Parts |
| IL GEN-99-66 | Basic | 21-Jan-99 | RADS-AT User Training |
| IL GEN-99-67 | Basic | 19-Mar-99 | RADS-AT Y2K Problems |
| IL GEN-99-68 | Basic | 7-Sep-99 | Access to Commercial Helicopter Service Directives |
| IL GEN-99-69 | Basic | 17-Nov-99 | Gimbal Arm Corrosion and Maximum Service Life of SX-16 Nightsun or SX-5 Starburst Searchlight |
| IL GEN-00-70 | Basic | 25-Jan-00 | Damage to Aluminum Rigid Lines Caused by Identification Tape |
| IL GEN-00-71 | Basic | 26-May-00 | Technical Publications Revision Status Website |
| IL GEN-00-72 | Basic | 18-Jul-00 | Cold Expansion Tools and Sleeves |
| IL GEN-00-73 | Basic | 8-Sep-00 | Breeze Eastern 300 LBS Rescue Hoist P/N BL-16600-110 and BL-16600-170, and Aeronautical Accessories Inc (AAI) 300 LBS Rescue Hoist P/N 407-979-100 |
| IL GEN-00-74 | Basic | 13-Nov-00 | Post Wiring Inspection After Customizing Modification |
| IL GEN-00-75 | Basic | 16-Nov-00 | Rotor Analysis and Diagnostic Systems (RADS-AT) Training Course |
| IL GEN-01-76 | Basic | 20-Mar-01 | Procedure for Requesting BHT-Approved Structural Repair |
| IL GEN-01-77 | Basic | 26-Apr-01 | Fuel Cell Shelf Life & Storage |
| IL GEN-01-78 | Basic | 26-Apr-01 | Helicopter External Noise Levels |
| IL GEN-01-79 | Basic | 19-Jun-01 | Turnbuckle Part Number 204-011-137-001 (Pitch Link Barrel) |
| IL GEN-01-80 | Basic | 25-Jun-01 | Replacement of Exxon Turbine Oils by Air BP Oils |

GENERAL INFORMATION LETTER INDEX

NUMERICAL INDEX (Cont)

| PUBLICATION | ISSUE/ REV | DATE | SUBJECT |
|---------------|---------------|-----------|--|
| IL GEN-01-81 | Basic | 5-Jul-01 | Rotor Analysis and Diagnostic Systems (RADS-AT) Training Course |
| IL GEN-01-82 | Basic | 28-Aug-01 | Use of Unapproved Parts from Surplus Military Inventory |
| IL GEN-01-83 | Basic | 8-Oct-01 | Type MA-6/8 Inertia Reel Assemblies |
| IL GEN-01-84 | Basic | 11-Oct-01 | Primer on Rotor Brake Disc Friction Surfaces |
| IL GEN-02-85 | Basic | 6-Mar-02 | Rotor Analysis and Diagnostic Systems (RADS-AT) Manufacturing/Support Changes and Upcoming Training Course |
| IL GEN-02-86 | Basic | 4-Apr-02 | New Internet Service Provided to Bell Customers |
| IL GEN-02-87 | Basic | 5-Sep-02 | RADS-AT Training |
| IL GEN-03-88 | Basic | 31-Jan-03 | Defective NAS516-1A Grease Fittings |
| IL GEN-03-89 | Basic | 28-Feb-03 | Inspection and Surface Protection of Steel Parts |
| IL GEN-03-90 | Basic | 4-Mar-03 | New Repair Angle Standard |
| IL GEN-03-91 | Rev A | 8-Apr-09 | Receipt of Service Directives On-line |
| IL GEN-03-92 | Basic | 8-Aug-03 | Expansion of Product Support Engineering Service |
| IL GEN-03-93 | Basic | 13-Aug-03 | Bearing Grease Lubricant |
| IL GEN-03-94 | Basic | 10-Oct-03 | Expanded Use of Retirement Index Numbers (RIN) |
| IL GEN-03-95 | Basic | 21-Nov-03 | Use of High-pressure Washer Around Helicopters |
| IL GEN-04-96 | Basic | 6-Jan-04 | Procedure for Requesting BHT-Approved Structural Repairs |
| IL GEN-04-97 | Basic | 14-Jun-04 | Hand Held Fire Extinguisher, Replacement of |
| IL GEN-04-98 | Rev C | 3-Mar-11 | Changes to BHT Customer Property Return (CPR) Process |
| IL GEN-04-99 | Basic | 3-Aug-04 | Superseded Rivets |
| IL GEN-04-100 | Basic | 1-Dec-04 | Information Regarding the Handling and Testing of Cartridges |
| IL GEN-04-101 | Basic | 20-Dec-04 | Rolls-Royce Technical Publications Delivered with New Production Helicopters |
| IL GEN-05-102 | Basic | 7-Feb-05 | Wet Installation Primer Application |
| IL GEN-05-103 | Basic | 28-Feb-05 | Seat Belt and Shoulder Restraint Webbing, Inspection Guidelines |
| IL GEN-05-104 | Basic | 15-Dec-05 | Temperature Indicator "TEMP-PLATE" Sealer, Introduction of |
| IL GEN-06-105 | Basic | 12-Jan-06 | 2006 Maintenance & Operations (M&O) Conferences |
| IL GEN-06-106 | Reissue | 11-Jan-10 | Availability of Electronic Publications |
| IL GEN-06-107 | Basic | 23-Aug-06 | Procedure for Providing Customer/Contact Information |
| IL GEN-07-108 | Basic | 15-Jan-07 | Clarification of Proper Assembly Torque Technique When Using Conical Seal Washers on Flared End Fittings |
| IL GEN-07-109 | Basic | 9-Feb-07 | Clarification on Part Numbers Identification |
| IL GEN-07-110 | Basic | 16-Feb-07 | Continuing Qualification and Maintenance of Pressure Cylinders and Squibs |

GENERAL INFORMATION LETTER INDEX

NUMERICAL INDEX (Cont)

| PUBLICATION | ISSUE/ REV | DATE | SUBJECT |
|--------------------|-----------------------|-------------|--|
| IL GEN-07-111 | Basic | 20-Apr-07 | Risk of FOD of Fluid and Pneumatic Systems Malfunction Due to Cap Plugs |
| IL GEN-07-112 | Basic | 20-Apr-07 | Shelf Life of Temp-Plates P/N 6000-1, 6000-2 and 6000-3 |
| IL GEN-07-113 | Basic | 17-Jul-07 | Compatibility of Newly Installed Equipment |
| IL GEN-08-114 | Basic | 25-Feb-08 | Artex Service Bulletins SN019 and SN020 |
| IL GEN-08-115 | Basic | 16-Jun-08 | Aircraft Model Designations and Applicability to Bulletins |
| IL GEN-09-116 | Basic | 16-Feb-09 | SkyBOOKS Electronic Log Books, Introduction of |
| IL GEN-09-117 | Basic | 17-Nov-09 | psemil214@bellhelicopter.textron.com E-mail Address, Inactivation of |
| IL GEN-10-118 | Basic | 12-Aug-10 | Breeze-Eastern Cargo Hook Maintenance Concept |
| IL GEN-10-119 | Basic | 12-Aug-10 | Applicability of Bulletins After Incorporation into the Maintenance Manual |
| IL GEN-10-120 | Basic | 22-Dec-10 | New Bulletin Format |
| IL GEN-11-121 | Basic | 4-Oct-11 | Operation of Bell Aircraft Near Volcanic Activity |

BHT-ALL-IL-INDEX

NOTICE

The following blank pages are provided for entry of additional notices when distributed. These additional notices will be included in this index at next revision

| PUBLICATION | ISSUE/ REV | DATE | SUBJECT |
|--------------------|-----------------------|-------------|----------------|
|--------------------|-----------------------|-------------|----------------|