



# TECHNICAL BULLETIN INDEX

**COPYRIGHT NOTICE**

COPYRIGHT 2011  
BELL © HELICOPTER TEXTRON INC.  
AND BELL HELICOPTER TEXTRON  
CANADA LTD.  
ALL RIGHTS RESERVED



POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

**15 SEPTEMBER 2011**



## 212 TECHNICAL BULLETIN INDEX

## NUMERICAL INDEX

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 212-02-73-1	Basic	22-Jun-73	Passenger Power Step
TB 212-03-73-1	Basic	30-Jan-73	Engine Mount - Allowable Rod End Bearing Wear Limits
TB 212-03-73-2	Basic	26-Apr-73	Airframe Engine Installation Modifications Required for PT6T3 Engine Design Improvements
TB 212-03-73-3	Basic	25-May-73	Exhaust Duct, P/N 212-061-202-5 and -6, Installation of Additional Retaining Bolts
TB 212-03-73-4	Basic	6-Aug-73	Procedure for the Replacement of the Bearings in the P/N 209-062-502-9 Oil Cooler Blower
TB 212-04-73-1	Basic	27-Apr-73	90 Gearbox Input Quill Seal Replacement
TB 212-04-73-2	Basic	10-Sep-73	Increase Torque of the Mast Lower Bearing Retainer Nut, P/N 204-040-309-1
TB 212-04-73-3	Basic	10-Sep-73	Special Tool, P/N T101586, Pusher Set
TB 212-(04-2)-73-1	Basic	11-May-73	Stabilizer Bar Damper Overhaul and/or Exchange, P/N 204-010-937-9
TB 212-06-73-1	Basic	16-May-73	Installation of Hydraulic Cylinder Assembly, P/N 212-076-005-7
TB 212-09-73-1	Basic	20-Mar-73	Addition of ARC Suppression Diodes Across Heater Switch Terminals
TB 212-09-73-2	Basic	3-Aug-73	Modification of the IMC System to Provide "Fly Thru" Capability
TB 212-09-73-3	Basic	3-Aug-73	Change Source of ARU Trim Power to Eliminate Interconnection of Pitch and Roll Channel D.C. Power
TB 212-09-73-4	Basic	3-Aug-73	Modification of the Yaw Sensor Amplifier Module Assembly
TB 212-09-73-5	Basic	8-Oct-73	Modification of AC Bus No. 2
TB 212-09-73-6	Basic	8-Oct-73	Tarsyn 444, 3 Axis Gyro, Disabling of Pitch Erection Cutoff (PECO)
TB 212-10-73-1	Basic	29-Jan-73	Installation of Fuel Filter Screen in Fitting, P/N S2490
TB 212-11-73-1	Basic	19-Sep-73	Availability of Bearing Staking Tool Kit, P/N T101886-1, for Improved Universal Assembly, P/N 205-076-381-1
TB 212-13-73-1	Basic	2-Jan-73	Issuance of Technical Bulletins Will Replace Service Letter Publication Effective January 1973
TB 212-13-73-2	Basic	7-Feb-73	Installation of Ballast on the Tail Skid for Weight and Balance Control
TB 212-13-73-3	Rev A	1-May-73	Component Exchange
TB 212-13-73-4			NEVER ISSUED
TB 212-13-73-5	Basic	27-Mar-73	Inspection of Airframe Dynamic Components
TB 212-13-73-6	Basic	18-Sep-73	Fluorescent Penetrant Inspection
TB 212-50-73-1	Basic	8-Jan-73	Rotor Brake Assemblies (Goodyear)
TB 212-50-73-2	Basic	11-May-73	Auxiliary Equipment Kit, Winterization Heater - Addition of Compensation Drain Port, P/N 212-706-008-1
TB 212-01-74-1	Rev A	19-May-75	Installation Instructions for Support Assemblies, P/N 205-030-341-1 and -2 and 205-030-342-1 and -2

## 212 TECHNICAL BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 212-01-74-2	Basic	22-Jul-74	Installation of Pylon Friction Damper Mount Retrofit, Kit, P/N 205-704-029-3
TB 212-03-74-1	Basic	12-Feb-74	Replacement of Bolts which Secure Engine Bleed Air Elbows
TB 212-03-74-2	Basic	26-Aug-74	Replacement of Engine Mount Bolts
TB 212-04-74-1	Basic	29-Apr-74	Modification of Transmission Oil System
TB 212-(04-1)-74-1	Basic	27-Aug-74	Main Rotor Yoke Assembly, P/N 204-011-102-17, Spindle Replacement Dimension Change
TB 212-(04-2)-74-1	Basic	12-Feb-74	Improved Stabilizer Bar Lever Assembly, P/N 212-010-302-1, and Swashplate Scissor Lever Assembly, P/N 212-010-407-1
TB 212-(04-2)-74-2	Basic	29-May-74	Rotating Control Bolt Kit, P/N 212-704-092-1
TB 212-05-74-1	Basic	10-Oct-74	Inspection of Inner Grip Plate Area, Tail Rotor Blade, P/N 212-010-750 (All Dash Numbers)
TB 212-09-74-1	Rev A	12-Feb-75	Reterminate Ground SensingLeads from DC Control Units
TB 212-09-74-2	Basic	30-Jan-74	Identification of the Three Axis Gyro, Tarsyn 444
TB 212-09-74-3	Basic	13-Nov-74	Drain Holes for Direct Current Control Unit, Lear Siegler Model 51509-001R and 51509-002R
TB 212-09-74-4	Rev A	10-Jan-75	Fuse Identification for AutomaticFlight Control System (AFCS) Components
TB 212-10-74-1	Basic	14-Nov-74	Replacement of Fuel Decal
TB 212-13-74-1	Basic	23-Jan-74	Reissue of Flight Manuals for Model 212 Helicopters
TB 212-13-74-2	Rev A	19-Sep-74	Component Exchange
TB 212-75-1	Basic	24-Jan-75	Improved Control Rod Guide for the Anti-Torque and Synchronized Elevator Control System
TB 212-75-2	Basic	16-Apr-75	Installation of Fast Erection Command for the Sperry Three Axis Reference System Tarsyn, P/N 2593996-333 and -444
TB 212-75-3	Basic	13-Mar-75	Ground Handling Gear Hydraulic Pump Repair Kit, P/N KH 9000
TB 212-75-4	Basic	13-Mar-75	Clamping Requirement for Hydraulic Hose on No. 2 System
TB 212-75-5	Basic	16-Apr-75	Reroute Pitot Tubing to Eliminate Water Trap
TB 212-75-6	Basic	2-May-75	Relocation of the No. 1 AC Sensing Relay
TB 212-75-7	Basic	9-Jun-75	New Refurbish Kit, P/N 212-073-922-1, for Emergency Float Kit, P/N 212-706-042-1
TB 212-75-8	Rev A	21-Jul-75	Fabrication and Installation of Temporary Cover for the Three (3) Axis Sensor, P/N 2593996-333/-444
TB 212-75-9	Basic	13-Nov-75	Installation of Alternate Hydraulic Pump, P/N PV3-044-8, for Pump, P/N 212-076-010-1, on No. 1 Hydraulic System Model 212 Helicopter
TB 212-76-1	Basic	13-Jan-76	Modification of Transmission, P/N 212-040-001-15
TB 212-76-2	Basic	21-Jan-76	Transmission Case Exchange Program
TB 212-76-3	Basic	13-Feb-76	Addition of a Blocking Diode to Prevent Damage to the RPM Limit Warning Box

## 212 TECHNICAL BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 212-76-4	Basic	13-Feb-76	Repair of Electric Sump Drain Valve, P/N AF11C-9
TB 212-76-5	Basic	13-Feb-76	Service and Warranty Policy - Kratos Instruments
TB 212-76-6	Basic	5-Mar-76	Component Exchange
TB 212-76-7	Rev A	29-Nov-76	Modification - Main Driveshaft Assembly, P/N 212-040-005-3 and -7
TB 212-76-8	Basic	17-Mar-76	Rework of Emergency Float Kit Temperature Vs Pressure Placard
TB 212-76-9	Rev A	16-Nov-76	Transmission Oil Pump, P/N 212-040-184-1 (Vendor P/N GC 2778)
TB 212-76-10	Basic	7-Apr-76	Warranty Claim Procedure and Return of Parts
TB 212-76-11	Basic	15-Apr-76	Inspection and Rework of "J" Stringers Aft of Tailboom Baggage Compartment
TB 212-76-12	Rev A	13-Feb-78	Inspection and Repair of Main Beam Cap Extrusion, P/N 212-030-190-5 and -7
TB 212-76-13	Rev A	9-Jun-76	Flight Control Hydraulic Actuators
TB 212-76-14	Basic	7-Jul-76	Main Input Driveshaft Assembly, P/N 212-040-005
TB 212-76-15	Basic	8-Jul-76	Flight Control Tubes and Bellcranks
TB 212-76-16	Basic	16-Aug-76	Removal of Decal, P/N 212-070-663-1
TB 212-76-17	Basic	30-Sep-76	Skid Landing Gear Spares Replacement Part Number Change
TB 212-76-18	Basic	27-Oct-76	Repair/Replacement Instructions Model 212 Helicopter Lift Beam Assembly, P/N 205-030-845-208, -255, and -359
TB 212-76-19	Basic	1-Dec-76	Starter/Generator Harness Assembly
TB 212-77-1	Basic	4-Jan-77	I.T.T. Indicating System on 212 Model Helicopters Prior to S/N 30554 (Non IFR-IMC)
TB 212-77-2	Rev B	24-Jan-78	Conversion of Emergency Flotation Inflation Cylinder Assembly, P/N 212-073-810-1, into a Cylinder Assembly, P/N 212-073-920-3, Configuration
TB 212-77-3	Basic	7-Mar-77	Clamping Requirement for Hydraulic Hose on No. 2 System
TB 212-77-4	Basic	7-Mar-77	Functional Test of the Gyro-magnetic Compass Annunciator
TB 212-77-5	Basic	16-Mar-77	Revised Synchronized Elevator Control System Rigging
TB 212-77-6	Rev A	21-Jun-77	Main Rotor Blade Splice Cover Assembly, P/N 204-015-011-1
TB 212-77-7	Basic	12-Aug-77	Fiberglass Belted Main Rotor Blade, P/N 212-015-501-5
TB 212-77-8	Basic	13-Sep-77	One Time Inspection of Forward Crosstube Assemblies, P/N 205-050-400-5, -13, -37, -39, -701, and -703, Which have Attained 1000 Hours Service Time
TB 212-77-9	Basic	6-Oct-77	Transmission, 42 and 90 Gearbox Assembly Electrical Chip Detectors, P/N B752G, B3703, and B7669B
TB 212-77-10	Rev A	24-Jan-78	Replacement of Existing Emergency Inflation Cylinder Assembly, P/N 212-073-812-1, with Cylinder Assembly, P/N 212-073-920-3

## 212 TECHNICAL BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 212-77-11	Rev A	21-Jul-78	Rework Instructions for CargoHook Bumper Casting, P/N 204-072-901-1
TB 212-77-12	Basic	24-Oct-77	Installation of Bushing Containment Washers on the Hydraulic Actuator Spanner Link Input Lever in Accordance with Hydraulic Research Textron Service Bulletin FMTC 236
TB 212-77-13	Basic	25-Oct-77	Installation of Bushing Containment Washers on the Hydraulic Actuator Spanner Link Input Lever and Replacement of Shoulder Bolts in Accordance with Hydraulic Research Textron Service Bulletin FMTC 237
TB 212-77-14	Basic	25-Oct-77	Time-Between-Overhaul (TBO) Intervals of the Power Plant Combining Gearbox, P/N 3017480
TB 212-77-15	Basic	2-Nov-77	Installation Instructions for P/N 212-075-692 Five Volt D.C. Power Supply
TB 212-78-1	Basic	24-Feb-78	Relocation of the Forward Friction Dampers, Fixed Floats Landing Gear
TB 212-78-2	Basic	28-Feb-78	Inspection and Maintenance of Emergency Exits
TB 212-78-3	Basic	16-Mar-78	Hydraulic Line, P/N 70034M310W144, One Time Inspection
TB 212-78-4	Basic	16-Mar-78	Flight Control Hydraulic Actuators, P/N 212-076-005-7, -9, and -11
TB 212-78-5	Rev A	27-Sep-78	Main Rotor Blades, P/N 204-012-001-23/-33 and 212-015-501-5, Removal and Repair of Blade Inspection System (BIS) Skin Ground
TB 212-78-6	Rev A	3-May-78	Directional Control Motion Transducer Attaching Hardware Reinstallation
TB 212-78-7	Basic	18-Apr-78	Modification to the 5 Vdc Power Supply Circuit
TB 212-78-8	Basic	19-Apr-78	Replacement of Cargo Door Sliders, P/N 204-030-220-1
TB 212-78-9	Rev A	11-Aug-78	Installation of Diodes to the Engine Control Panel Fuel Switches to Correct the Engine Fuel Valve Caution Light
TB 212-78-10	Basic	15-May-78	Announcement of Increase in Time-Between-Overhaul of Main Rotor Hub Assembly
TB 212-78-11	Basic	17-May-78	Main Rotor Hub Assembly, P/N 204-012-101, Pillow Block Assembly Procedure
TB 212-78-12	Basic	19-May-78	Replacement of the Transmission Bevel Gear Attachment Bolts, P/N AN107607
TB 212-78-13	Basic	31-May-78	Tail Rotor Driveshaft Hanger Assembly, P/N 212-040-600-1, Modification to the Greasable Hanger Assembly, P/N 212-040-600-5
TB 212-78-14	Basic	21-Jun-78	Main Rotor Blades, P/N 212-015-501-5, Announcement of Inspection Requirement Changes and Deletion of Blade Inspection System

## 212 TECHNICAL BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 212-78-15	Rev B	12-May-06	Repair of the Engine Service Deck Center Panel, P/N 212-030-009-7, and -97
TB 212-78-16	Rev B	9-Mar-79	Skid Landing Gear Aft Crosstube Assembly, P/N 205-050-400-63, Procedure for Installation of Model 212 Helicopters
TB 212-78-17	Basic	31-Oct-78	Main Driveshaft Assembly, P/N 212-040-005 Series, Retrofit with Newly Developed Boot Assembly, P/N 212-040-176-007
TB 212-78-18	Basic	7-Nov-78	Repair of Baggage Compartment Top Honeycomb Panel, P/N 205-030-812
TB 212-78-19	Basic	27-Nov-78	Model 212 Emergency Flotation Inflation Cylinder, Special Filling Instructions
TB 212-79-20	Rev B	22-Jun-79	Rework of the Baggage Compartment Forward Bulkhead, P/N 212-030-144
TB 212-79-21	Basic	23-Jan-79	Cylinder and Support Assembly, Anti-Torque Control, P/N 212-001-720-1, -3, or -5, Rework of Clevis, P/N 209-001-719-1
TB 212-79-22	Basic	12-Feb-79	Installation of Pulsation Damper, P/N 214-076-153-1, in Pressure Line of Number Two Hydraulic System
TB 212-79-23	Basic	16-Feb-79	Hydraulic Cylinder Assembly, P/N 212-076-004-003, -005, 212-076-005-007, -009, and -011
TB 212-79-24	Basic	26-Mar-79	Repair of Baggage Compartment Side Honeycomb Panels, Right Side, P/N 205-032-811, and Left Side, P/N 205-032-813
TB 212-79-25	Basic	26-Mar-79	Landing Gear Forward And Aft Crosstube Assemblies, P/N 205-050-400-53, -55, and -63, Inspection and Rework
TB 212-79-26	Basic	26-Mar-79	High Skid Gear Forward and Aft Crosstube Assemblies, P/N 205-050-403-31 Fwd of -33 Aft, Inspection and Rework
TB 212-79-27	Basic	26-Mar-79	Inspection and Repair of Fixed Floats Forward and Aft Crosstube Assemblies, P/N 205-050-114-23 and -25
TB 212-79-28	Basic	29-Mar-79	Structural Repair to Cabin Windshield, Upper Longeron and Door Post, P/N 205-030-619
TB 212-79-29	Rev B	24-Jun-87	Staking Tool for Bearing Installed in Lift Link, P/N 212-030-104-005/-101
TB 212-79-30	Rev A	18-Oct-83	Installation of Wear Sleeves on Flight Control Tube Assemblies in Anti-Torque Control Installations, P/N 212-001-002-003, P/N 212-001-009-003, and Synchronized Elevator Control Installation, P/N 212-001-005-003
TB 212-79-31	Basic	30-Apr-79	Emergency Flotation Equipment Float Bag Pressure Relief Valve, P/N 780-RPA-5.0, Field Inspection, Cleaning, and Lubrication of
TB 212-79-32	Basic	22-Jun-79	Main Rotor Mast Assembly, P/N 204-040-366-015, -017, -019, and -021, TBO Increase, Mast Bearing, P/N 212-040-136-001, 1000 Hour Retirement Deletion

## 212 TECHNICAL BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 212-79-33	Basic	22-Aug-79	Power Plant Combining Gearbox Time-Between-Overhaul, Increase of
TB 212-79-34	Basic	24-Oct-79	Addition of Grounds to Prevent Circuit Failure Due to Loss of Single Ground Connection
TB 212-80-35	Basic	3-Mar-80	Transmission, P/N 212-040-001-131 (Mod A), with TBO of 1500 Hours, and P/N 212-040-001-059 (Mod B), with TBO of 2500 Hours, Conversion to
TB 212-80-36	Basic	19-Feb-80	Improved Fuel Impending Bypass Indicating System
TB 212-80-37	Basic	18-Feb-80	Swashplate Support Assembly, P/N 204-011-404-017, and Inner Ring Assembly, P/N 204-011-402-021, Installation of
TB 212-80-38	Basic	11-Mar-80	Screen, P/N 212-060-536-001, Installation
TB 212-80-39	Basic	15-May-80	Gearbox Assembly, 42, Tail Rotor Drive, P/N 212-040-003, Gearbox Assembly, 90, Tail Rotor Drive, P/N 212-040-004, Time-Between-Overhaul (TBO), Increase of
TB 212-80-40	Basic	2-Jun-80	Cyclic, Collective, and Tail Rotor Control Installations, Damage and Repair Limits of Bellcrank, Lever, and Support Assemblies Under the Cabin Floor Area
TB 212-80-41	Basic	1-Aug-80	Oil Cooler Blowers, P/N 209-062-502, Inspection and Rework of
TB 212-80-42	Basic	7-Aug-80	Emergency Flotation Kits, P/N 212-706-021-001, -003, 212-706-032-001, -003, 212-706-042-001, and -003, Inflation System, Replacement of Aluminum Parts with Stainless Steel Parts
TB 212-80-43	Basic	5-Sep-80	Hydraulic System Installation, Number 1, P/N 212-076-002, and Number 2, P/N 212-076-001, Installation of Check Valves in the Integrated Valve and Filter Assemblies and the Addition of Clamps on Two Hydraulic Lines
TB 212-80-44	Rev A	9-Feb-81	Collective Yaw Coupling, AFCS with IFR or IMC Controls, Modification of
TB 212-80-45	Basic	3-Oct-80	Modification of Hydraulic Cylinder Assemblies, P/N 212-076-005-007, -009, and -011 FMTC 247
TB 212-81-46	Basic	20-Jan-81	Bellcrank Assemblies, P/N 212-001-712-001, Rework to Allow Replacement of Bearing, P/N DSRP-4
TB 212-81-47	Basic	20-Jan-81	Hydraulic Pumps, P/N 212-076-010-001 (ABEX P/N AP2V-82) and P/N 212-076-011-001 (ABEX P/N AP2V-81), Modification of
TB 212-81-48	Rev C	23-Mar-09	Engine, PT6T-3/-3B, Power Section, Mixing and Use of
TB 212-81-49	Basic	6-Mar-81	Hydraulic System, P/N 212-076-001, Replacement of Hose Assembly, P/N 124038-6D0136, with Hose Assembly, P/N 70-012V000G146



## 212 TECHNICAL BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 212-81-50	Basic	18-Mar-81	Inspection and Rework of the Vertical Fin Forward Spar and the Installation of a Doubler on the Upper Left Side Skin of Vertical Fin
TB 212-81-51	Rev A	13-Apr-81	Swashplate and Support Assy,P/N 204-011-400-127, Introduction of
TB 212-81-52	Rev C	24-Oct-89	Relocation of Torque Transmitters
TB 212-81-53	Basic	29-Apr-81	New Passenger Doors with Push-Out Emergency Egress Windows, P/N 205-032-669-173 and -174, Approval of
TB 212-81-54	Basic	6-May-81	PT6T-3B Engine, Installation of
TB 212-81-55	Basic	7-May-81	Cargo Release Relay, Electrical Grounding of
TB 212-81-56	Rev A	17-Sep-81	Main Rotor Hub Assembly,P/N 204-012-101-(All Dash Numbers), Modifications to Grease Lubrication
TB 212-81-57	Basic	10-Sep-81	Support Case, P/N 212-040-054-013, and Lift Link Fitting, P/N 212-040-106-001, Interference Between
TB 212-82-58	Rev B	20-Jul-92	Ground Handling of Model 212Helicopters Tire, P/N 12 1-2X4 1-2, Tube, P/N 12 1-2X4 1-2, Replacement Skid Tube, P/N 205-050-400, Modification for Ground Handling at Helicopters Weights Above 8,000 Pounds Aft Crosstube of Skid Gear, Strap for Ground Handling at High Gross Weights
TB 212-82-59	Basic	6-Jan-82	Check Valve, P/N 60478, in Emergency Float Kit, P/N 212-706-042-(All), 212-706-032-(All), and 212-706-021-(All), Removal or Modification of
TB 212-82-60	Basic	4-Feb-82	Hydraulic Cylinder Assemblies, P/N 212-076-005-001. -005, -007, -009, -011, Rework of Mounting Bracket, P/N 212-076-116-001, -003, and Bearing Nut, P/N 212-076-118-001
TB 212-82-61	Basic	19-Jul-82	Suspension Assembly - Cargo, P/N 204-072-915-101 and Prior, Modification of
TB 212-82-62	Basic	30-Mar-82	Dual Torque Indicator, Replacement of
TB 212-82-63	Basic	16-Aug-82	Replacement of Upper Honeycomb Panel, Tailboom Baggage Compartment, with Sheetmetal Skin
TB 212-82-64	Basic	2-Sep-82	Baffle, Tope Engine Cowl, P/N 212-060-823-101, Modification of
TB 212-82-65	Basic	14-Sep-82	Engine Fuel Switch, Inspection of
TB 212-82-66	Basic	29-Sep-82	Directional Hydraulic Servo Actuator, P/N 212-076-004-003, -005, Change of Overhaul Interval
TB 212-83-67	Basic	17-Jan-83	Pylon Access Covers, P/N 212-030-163-93 or -333 and 212-030-164-165 or -289. and Panels, P/N 212-030-219-005, or -101 and 212-030-244-001 or -101, Modification of
TB 212-83-68	Basic	17-Jan-83	Hydraulic System Installation, P/N 212-961-102, 212-961-128, and 212-076-196, Installation of Check Valve at the Number 2 System Integrated Valve and Filter Assembly

## 212 TECHNICAL BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 212-83-69	Basic	23-Feb-83	AFCS 5 Volt Power Supply, Addition of a Reference Resistor to Control Line
TB 212-83-70	Basic	1-Mar-83	Eliminate Capability of Aft Cabin Interphone Stations to Transmit on Air Traffic Control COMM Radios
TB 212-83-71	Basic	6-Apr-83	Main Input Driveshaft, P/N 212-040-005, Dynamic Balancing of
TB 212-83-72	Basic	4-Aug-83	Hydraulic Pumps, P/N 212-076-010-001, (ABEX Model AP2V-82, P/N 66007) and P/N 212-076-011-001 (ABEX Model AP2V-81, P/N 66005), Seal Retainer Gasket, Installation of
TB 212-83-73	Basic	16-Aug-83	Hydraulic Oil Temperature Switch, P/N 83154, Replacement of
TB 212-83-74	Basic	12-Sep-83	Matrix High Density Grounding Modules, Inspection/Replacement of
TB 212-83-75	Basic	30-Sep-83	Latch Installation, Crew Door. P/N 204-030-500-005/-006, Modification of
TB 212-83-76	Basic	12-Oct-83	Horizontal Stabilizer Ribs, P/N 205-030-856-095 and -097, Modification of
TB 212-83-77	Basic	21-Nov-83	Flight Control Cylinder, P/N 212-076-005-7, -11, -101, Input Lever Assembly, Replacement of FMTC 258
TB 212-83-78	Basic	1-Dec-83	3 Micron Transmission Oil Filter, P/N 204-040-760-105, Installation of
TB 212-84-79	Basic	8-Feb-84	Crew Door Hinge, P/N 204-031-837-011/-012 (Upper Fixed), 204-031-658-1/-2 (Upper Movable), 204-031-467-011/-012 (Lower Fixed) and 204-031-468-1/-2 (Lower Movable), Bushing of
TB 212-84-80	Rev A	13-Sep-85	Mast Assembly, P/N 204-040-366-021, Increase in Time-Between-Overhaul (TBO)
TB 212-84-81	Basic	16-Feb-84	Transmission Assembly, P/N 212-040-001-059 and -141, Increase in Time-Between-Overhaul (TBO)
TB 212-84-82	Basic	16-Feb-84	Gearbox Assembly, 42 Degree, P/N 212-040-003-023, Increase in Time-Between-Overhaul (TBO)
TB 212-84-83	Basic	16-Feb-84	Gearbox Assembly, 90 Degree, P/N 212-040-004-009, Increase in Time-Between-Overhaul (TBO)
TB 212-84-84	Basic	29-Feb-84	Flight Control Cylinder, P/N 212-076-005-7, -11, -101, Piston Head Seals, Replacement of FMTC 260
TB 212-84-85	Basic	20-Mar-84	Emergency Floats, P/N 212-030-411-1, -2, -3, and -4 and P/N 212-050-207-9, -10, -11, and -12, Testing of
TB 212-84-86	Basic	28-Nov-84	Cargo Release Relay, Rewriting of
TB 212-85-87	Basic	23-Jan-85	Door Assembly, Upper Cabin Nose, P/N 212-030-348-003, Modification for Watertightness
TB 212-85-88	Basic	28-Jan-85	Flight Control Cylinder, P/N 212-076-005-7 and -9, Installation of Bushing Containment Washers in Accordance with HR Textron Service Bulletin PMTC 236

## 212 TECHNICAL BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 212-85-89	Basic	1-Feb-85	Main Transmission Input Quill Carbon Magnetic Seal, P/N 412-040-111-103, Installation of
TB 212-85-90	Basic	1-Nov-85	Tail Rotor Blade, P/N 212-010-750 (All Dash Numbers), Improved Visibility Paint Scheme
TB 212-85-91	Basic	22-Nov-85	Universal Assembly, P/N 412-076-620-101, Replacement of Bearings
TB 212-86-92	Basic	12-Feb-86	Fin Spar Cap, P/N 212-030-447-101, Installation of
TB 212-86-93	Basic	26-Mar-86	Retainer Secured (Push Out) Passenger Compartment Windows
TB 212-86-94	Basic	27-Mar-86	Main Rotor Grip Seal, P/N S12561-341, Replacement of
TB 212-86-95	Basic	28-Jul-86	Hydraulic Pumps, P/N 212-076-010-001, (ABEX Model AP2V-82, P/N 66007) and P/N 212-076-011-001, (ABEX Model AP2V-81, P/N 66005), Replacement of External Driveshaft
TB 212-86-96	Basic	29-Sep-86	Generator Control Unit, P/N 51539-002N, Inspection and Modification of
TB 212-87-97	Basic	19-Jun-87	Tail Rotor Driveshaft, P/N 204-040-620-011, Modification of
TB 212-87-98	Basic	14-Aug-87	Pilot Collective Stick Tube, P/N 212-001-181-001, and Copilot Collective Stick Tube, P/N 212-001-170-001, Inspection of
TB 212-87-99	Basic	17-Aug-87	Markings Installation, P/N 212-070-600-1/-3/-5/-7/-9/-101/-111/-115/-119, Tail Rotor Hazard Warning Decals, Addition of
TB 212-87-100	Basic	28-Sep-87	Rotor Brake Assembly, Modification of
TB 212-87-101	Basic	16-Oct-87	Hydraulic Pump, P/N PV3-044-8A, Installation of
TB 212-88-102	Basic	8-Feb-88	Addition of Identification Decal on Aircraft Exterior
TB 212-88-103	Basic	13-Apr-88	Tail Rotor Counterweight Bellcrank Assembly, P/N 212-011-705-001, Inspection of
TB 212-88-104	Rev A	13-Jun-89	Fin, P/N 212-030-099-103, Modification of
TB 212-88-105	Rev C	19-Jan-06	Tailboom Assemblies, P/N 212-030-100-005 through 212-030-100-115, Modification for Use on All Model 212 Helicopters
TB 212-88-106	Rev A	7-Apr-05	Main Beam Cap P/N 205-030-186-005 Inspection and Replacement with Main Beam Cap P/N 205-030-186-101
TB 212-88-107	Rev A	9-Jan-89	External Power Circuit, Modification of
TB 212-88-108	Basic	23-Nov-88	Plumb Bob Support Installation, P/N 205-030-147-009, Inspection of
TB 212-88-109	Basic	19-Dec-88	Hydraulic System Installation, PCI and PCII, Replacement of 2014/2024 Aluminum Alloy Flareless Tube Fittings
TB 212-89-110	Basic	6-Jan-89	Addition of Diode Assemblies, P/N 30-126-5AA To The Battery Bus Circuit
TB 212-89-111	Basic	13-Mar-89	Tail Rotor Gearbox Assembly P/N 212-040-004-005, Conversion to the 212-040-004-009 Configuration

## 212 TECHNICAL BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 212-89-112	Basic	13-Mar-89	Intermediate Gearbox Assembly P/N 212-040-003-007, Conversion to the 212-040-003-023 Configuration
TB 212-89-113	Basic	31-May-89	Improved Corrosion Resistant Fire Extinguisher Discharge Outlet Fittings
TB 212-89-114	Basic	6-Jun-89	Mast Assembly P/N 204-040-366-015, -017, Configuration Change and Upgrade
TB 212-89-115	Basic	6-Jun-89	Tail Rotor Driveshaft Hanger Assembly P/N 212-040-600-001 and -009, Configuration Change and Upgrade
TB 212-89-116	Rev A	27-Sep-89	Lift Link Fitting P/N 212-040-106-001 and -101, Inspection of
TB 212-89-117	Rev B	5-Mar-91	Main Transmission Assembly, P/N 212-040-001-059, -141, -149, and -169, Configuration Change and Upgrade
TB 212-89-118	Basic	7-Aug-89	Linear Actuator Interference with Bulkhead
TB 212-89-119	Rev A	19-Jun-90	Airborne Canister Type Fuel Boost Pump Assembly P/N 206-062-687-101, Installation of
TB 212-89-120	Basic	18-Oct-89	Increase in Time-Between-Overhaul (TBO) Interval of the PT6T-3/-3B Power Plant Combining (Reduction) Gearbox
TB 212-89-121	Basic	27-Oct-89	Introduction of New Step Actuator P/N 212-075-418-103
TB 212-89-122	Basic	6-Nov-89	Swashplate and Support Assembly P/N 204-011-400, Configuration Change and Upgrade
TB 212-89-123	Basic	6-Nov-89	Tail Rotor Hub and Blade Assy, P/N 212-010-701 and 212-011-701 Series, Configuration Change and Upgrade
TB 212-90-124	Rev A	19-Aug-92	Engine Overboard Fuel Drains, Reroute to Fuel Tanks
TB 212-90-125	Rev A	3-Aug-90	MRC Duplex Bearings P/N 204-040-424-001, Inspection and Recall
TB 212-90-126	Basic	3-Aug-90	Mid Firewall and Induction Baffle Assembly Replacement of Blind Rivets (NAS1398C) with Solid Rivets (MS20615)
TB 212-90-127	Basic	10-Oct-90	Transmission Assembly P/N 212-040-001-059, -137, -141, -149, -165, -169, -179, and -191, Increase in Time-Between-Overhaul (TBO)
TB 212-90-128	Rev B	18-Dec-02	Main Rotor Hub Assembly P/N 204-012-101, Configuration Change and Upgrade
TB 212-91-129	Basic	11-Jan-91	Scissors and Sleeve Assembly P/N 204-011-401, Configuration Change and Upgrade
TB 212-91-130	Basic	5-Feb-91	Stabilizer Bar Assembly P/N 204-011-326 and P/N 212-010-300, Configuration Change and Upgrade
TB 212-91-131	Basic	5-Mar-91	Main Transmission Full Flow Debris Monitor, Installation of
TB 212-91-132	Rev A	6-Oct-92	Introduction of Lift Link Fitting P/N 212-030-154-101 and Bolt P/N 412-030-224-101, Which Supersedes Lift Link Fitting P/N 212-030-154-001, and Bolt P/N 212-030-155-001
TB 212-91-133	Basic	9-Apr-91	Number 1 Hydraulic System Tube Assembly P/N 212-076-348-001

## 212 TECHNICAL BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 212-91-134	Rev A	19-Mar-92	Tail Rotor Pitch Change Tube Assembly P/N 209-011-710-ALL, Electro Chemical Metallizing
TB 212-91-135	Rev A	26-Sep-91	Improved Inspection Access Doors on Engine Oil Cooler Support Cowling
TB 212-91-136	Basic	20-Jun-91	Hydraulic Pumps P/N PV3-044-8 (Sperry-Vickers) Replacement of Driveshaft
TB 212-91-137	Basic	26-Jun-91	Transmission Oil Pump Key P/N 38-56007-1003-2 and MS35756-3 Which were Supplied as Spares, Replacement of
TB 212-91-138	Rev C	15-May-03	Increased 5 Minute Takeoff Horsepower Rating
TB 212-92-139	Rev A	7-Apr-92	Installation of Improved Rotor Brake Quill P/N 412-040-123-101
TB 212-92-140	Basic	3-Mar-92	Sump Case Assembly P/N 204-040-355-005 and -017, Rework Procedure to Reduce The Size of the Chip Detector Boss Entry-Countersink
TB 212-92-141	Basic	10-Mar-92	Alternate Skid Tube Installation and Operational Requirements for Ground Handling at High Gross Weights
TB 212-92-142	Rev A	18-Jan-95	Main Flight Control Servo Cylinders P/N 212-076-005-007/-009/-011/-101/-103/-105
TB 212-92-143	Basic	12-Nov-92	Pilot Collective Control Panel Assembly
TB 212-93-144	Basic	24-Jun-93	Rotor Brake Quill P/N 412-040-123-101, One Time (External) Inspection
TB 212-93-145	Basic	24-Nov-93	Engine #2 Governor Trim Actuator
TB 212-93-146	Basic	30-Aug-93	Lower Planetary Spider P/N 412-040-785-103, Introduction of
TB 212-94-147	Basic	27-Jan-94	Modification to Tailboom Assembly P/N 212-030-100-005, -049, -057, -063, -069, -089, -097, -103 and -115
TB 212-94-148	Rev A	7-May-94	Baggage Compartment Lower Skin Doubler
TB 212-94-149	Basic	7-May-94	Case Assembly, Bevel Gear P/N 212-040-053-009
TB 212-94-150	Basic	15-Jun-94	Doubler, Installation on L/H Side of Tailboom Fin
TB 212-94-151	Basic	26-Sep-94	IFR Fin Removal
TB 212-94-152	Basic	28-Nov-94	Rotor Brake Assembly, Introduction of Stainless Steel Piston
TB 212-95-153	Basic	5-Apr-95	Lucas Western Service Bulletins, High Performance Rescue Hoist Assembly Washer Interference
TB 212-95-154	Basic	12-May-95	Aft Position Light Shock Mount
TB 212-95-155	Basic	17-Jul-95	Tail Rotor Hub Assembly P/N 212-011-701-003, Conversion to -125 Configuration
TB 212-95-156	Basic	18-Sep-95	Pillow Block Bushing P/N 204-011-135-105, Increase In Retirement Life
TB 212-96-157	Basic	22-Jul-96	Improved Fuel Lines, Installation of
TB 212-96-158	Basic	22-Jul-96	Aft Oil Cooler Scoop (Cowling) Latch, Replacement of
TB 212-96-159			NEVER ISSUED
TB 212-96-160	Basic	16-Dec-96	Seal P/N 212-340-113-101 and Wear Sleeve P/N 214-040-867-101, Introduction of

## 212 TECHNICAL BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 212-97-161	Basic	30-Jan-97	Engine/Rotor Tachometer Generator, Replacement of
TB 212-97-162	Basic	8-Aug-97	Introduction of Mast Assembly P/N 212-540-002-111 for Use in 212 Increased Take-off Power Kit 212-704-153-101
TB 212-97-163	Basic	2-Sep-97	Exhaust Duct Assembly 212-061-202-009, Exchange or Rework of
TB 212-97-164	Basic	15-Sep-97	Gas Producer RPM Increase
TB 212-98-165	Basic	10-Sep-98	Breeze-Eastern A60LT Cargo Hooks
TB 212-98-166	Basic	29-Sep-98	Introduction of Pylon Support Brackets
TB 212-98-167	Basic	26-Oct-98	Transmission Oil Cooler Line Clamping, Improvement of
TB 212-99-168	Basic	20-Jan-99	Heated P3 Airline, Introduction of
TB 212-99-169	Basic	10-Feb-99	Crew Seat Height Adjustment Tube, Modification of
TB 212-99-170	Basic	10-Feb-99	Improved Pitch Horn to Main Rotor Grip Attachment Hardware
TB 212-99-171	Basic	15-Feb-99	Engine Upper Cowling Main Drive Shaft Inspection Door, Modification
TB 212-99-172	Basic	22-Feb-99	New Door Rollers and Sliders
TB 212-99-173	Basic	19-Mar-99	Tail Rotor Gearbox Speedi-Sleeve, Addition of
TB 212-99-174	Basic	19-Mar-99	Guide, Crew Seat Shoulder Strap, Rework of
TB 212-99-175	Basic	19-Mar-99	Throttle Bellcrank Mount, Improvement of
TB 212-99-176	Basic	7-May-99	New Fire Extinguisher Bracket
TB 212-99-177	Basic	7-May-99	Bellcrank Assembly, Rework of
TB 212-99-178	Basic	7-May-99	New Sliding Door Latch Guard
TB 212-99-179	Basic	20-Aug-99	Pilot and Co-pilot Collective Stick No. 1 Throttle Grip, Modification of
TB 212-99-180	Basic	26-Nov-99	Hinged Panel Assembly, Improvement of
TB 212-99-181	Rev A	3-Apr-09	Fuel Pump Larger Diameter Drain Lines, Introduction of
TB 212-00-182	Basic	30-Jun-00	Cyclic and Collective Jackshafts, Inspection and Modification of
TB 212-00-183	Basic	4-Aug-00	Forward Crosstube, Modification of
TB 212-00-184	Rev A	23-Apr-01	Fin Spar Cap 212-030-125-001 & 212-030-447-001/-101, Replacement of
TB 212-01-185	Basic	31-Jan-01	Improved Tail Rotor Pitch Links
TB 212-01-186	Basic	16-Apr-01	Engine Power Turbine Governor Lever Re-Indexing, Introduction of
TB 212-01-187	Basic	7-Sep-01	Improved Engine Torque Transmitting System Benz Model 800-0001, Introduction of
TB 212-02-188	Basic	13-Dec-02	Transmission Oil Cooler Lines P/N 412-040-243-101 and 412-040-244-101, Introduction of
TB 212-03-189	Rev A	23-Apr-03	Replacement of Landing Light Mechanical Relay Assembly with a Solid-State Switch Mounted on a Printed Wiring Board
TB 212-03-190	Basic	26-Mar-03	Lower Nose Doors P/N 212-030-217-011 and 212-030-205-001 and Seal Replacement

## 212 TECHNICAL BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
TB 212-03-191	Basic	16-May-03	Transmission Debris Collector Assembly P/N 212-040-146-001 to -101 FM, Modification of
TB 212-03-192	Basic	27-Aug-03	Transmission Oil Filter Assembly P/N 204-040-760-113, Introduction of
TB 212-03-193	Basic	20-Oct-03	Swashplate and Support Assembly, Bolt 204-011-463-107, Introduction of
TB 212-04-194	Basic	28-Jan-04	AFCS Indicators, Replacement for Spares
TB 212-04-195	Basic	16-Feb-04	Oil Drain Valve P/N 209-062-010-001, Powerplant Accessory Gearbox, Improved Security of Screws
TB 212-04-196	Basic	15-Jun-04	Intake Screen Improvements
TB 212-04-197	Basic	28-Jun-04	Transmission Oil Pump 212-040-184-001, Modification of
TB 212-04-198	Basic	25-Aug-04	Heated Windshield Indicators, Replacement for Spares
TB 212-04-199	Basic	13-Sep-04	New Chip Detector Interface Problem with the Master Caution Panel
TB 212-05-200	Basic	11-May-05	Bearing and Liner Assemblies P/N 204-010-433-001 and P/N 204-011-443-001: Installation Improvements
TB 212-05-201	Rev A	14-Dec-07	Tailboom Bulkhead Reinforcement
TB 212-06-202	Rev A	22-Jun-07	Improved Baggage Compartment Door Seal
TB 212-06-203	Basic	13-Jun-06	Installation of Missing Rigging Rivets
TB 212-06-204	Basic	21-Jul-06	Vertical Fin Cover Hinge Pin Improved Installation
TB 212-06-205	Basic	18-Oct-06	Center Engine Deck Modification for Use on Other Aircraft
TB 212-07-206	Basic	8-Mar-07	Power Section Case Drain Fitting Standardization
TB 212-08-207	Basic	26-Feb-08	Upper Crew Door Hinge Structure, Reinforcement of
TB 212-08-208	Basic	5-Mar-08	Replacement of Blind Rivets on Tailboom
TB 212-08-209	Basic	13-May-08	Fuel Overflow Deflector Upgrade
TB 212-09-210	Basic	28-Apr-09	Tail Rotor Gearbox Excluder Housing Leak: Prevention of
TB 212-11-211	Basic	21-Mar-11	Number One Engine Jackshaft Support Inspection and Modification of
TB 212-11-212	Basic	6-Apr-11	Generator Grounding, Improvement of





# BHT-212-TB-INDEX

## NOTICE

The following blank pages are provided for entry of additional notices when distributed. These additional notices will be included in this index at next revision

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
-------------	---------------	------	---------