A Textron Company

OPERATION SAFETY NOTICE

AA-23011
28 November 2023

TO: **All owners and operators of helicopters with one of the following STC's installed: SR00513AT, SR01447AT, SR01844AT.**

SUBJECT: Expandable Pins Assembly in Tail Rotor Pedal Lockout Kit, P/N 206-928-110 a subassembly of P/N 206-928-200.

Operators have reported experiencing a shearing, fracture, or failure of Expandable Pins/Bolts within the threaded portion of the pin. This condition results from improper installation of the expandable pin. Proper installation/inspection must be completed as follows:

PERFORM DAILY/PREFLIGHT VISUAL INSPECTION

Reference Section 4.0, Maintenance Instructions, 4.1.1, Tail Rotor Pedals Locked Out, in the Instructions for Continued Airworthiness Report No. AA-99032 to perform the required Daily/Preflight Inspection. If adjustments are found to be necessary, refer to Section 4.5 of Instructions for Continued Airworthiness, Report No. AA-99032.



All questions or issues regarding this Operation Safety Notice should be addressed to:

Aeronautical Accessories
450 Industrial Park Rd.
Piney Flats, TN 37686-4419
Toll free: 1-800-251-7094
Email: techsupport@aero-access.com

Approved for public release.