



INFORMATION LETTER

IL 206-13-103

IL 206L-13-96

14 October 2013

TO: All owners and operators of Model 206A/B/L and TH-67

SUBJECT: REPLACEMENT OF TAIL ROTOR BLADES P/N 206-016-201-131 and 206-016-201-135 BY VAN HORN COMPOSITE TAIL ROTOR BLADES P/N 2062200-301.

This Information Letter is issued to notify operators regarding the introduction of the Van Horn composite Tail Rotor Blades as future spares replacement for Bell Helicopter models 206B3, 206L series, TH-67 and 206A/B with SI-112 incorporated.

The current Bell Helicopter manufactured Tail Rotor Blades will be available until depletion of stock. Thereafter, replacement Tail Rotor Blades will have to be procured through **Aeronautical Accessories** under FAA STC SR02249LA, Transport Canada STC SH10-22, EASA STC 10039278 or Brazilian STC 2012S09-07.

**Aeronautical Accessories,
P.O. Box 3689
Bristol, Tennessee 37625**

**Phone: 800-251-7094
423-538-5151
sales@aero-access.com**

The Van Horn Tail Rotor Blades are a direct replacement for Tail Rotor Blades P/N 206-016-201-131 and P/N 206-016-201-135 (long blades). At this time, Bell Helicopter continues to support Tail Rotor Blades P/N 206-016-201-133 and P/N 206-016-201-137 (short blades) through our spares system.

Instructions for Continued Airworthiness (ICA) and technical support regarding the Van Horn Blades will be provided directly by **Van Horn Aviation**.

**Van Horn Aviation, L.L.C.
1510 W. Drake Drive
Tempe, Arizona 85283**

**Phone: 480-483-4202
Fax: 480-446-0321
www.vanhornaviation.com**

For any questions regarding this letter, please contact:

Bell Helicopter Product Support Engineering - Light Helicopters
Tel: 450-437-2862 / 1-800-363-8023 / pselight@bh.com