

**BHT-214B/B1-ASB-INDEX**

**Bell** *MODEL* **214B** *SERIES*

**ALERT  
SERVICE  
BULLETIN  
INDEX**

**COPYRIGHT NOTICE**

COPYRIGHT 2011  
BELL © HELICOPTER TEXTRON INC.  
AND BELL HELICOPTER TEXTRON  
CANADA LTD.  
ALL RIGHTS RESERVED

**Bell** *helicopter*  
A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

**10 JANUARY 2012**



## 214B/B1 ALERT SERVICE BULLETIN INDEX

## NUMERICAL INDEX

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
ASB 214-76-1	Rev A	16-Jul-76	Hydraulic Installation, Flight Control System
ASB 214-76-2	Basic	24-Aug-76	Hydraulic Hose Installation, Flight Control System
ASB 214-76-3	Rev A	1-Nov-76	Inspection and Rework of Engine Service Deck Support U Channel, 214-030-710-45
ASB 214-76-4	Basic	29-Sep-76	Inspection and Adjustment of Latch System, Passenger Door Emergency Escape Panel
ASB 214-76-5	Basic	29-Oct-76	Main Rotor Spindle, P/N 214-010-103-1
ASB 214-76-6	Basic	1-Nov-76	Rework of Main Beam Vertical Splice Fitting, P/N 214-030-463-1
ASB 214-76-7	Basic	19-Nov-76	Installation of Main Rotor Blade Inspection System Kit, P/N 214-704-116-1, on Main Rotor Blade, P/N 214-015-001-5
ASB 214-76-8	Basic	16-Dec-76	Tail Rotor Control Rigging
ASB 214-77-1	Basic	23-Feb-77	Replacement of Spacers and Screws Attaching the Emergency Escape Release Handle Covers
ASB 214-77-2	Basic	23-Feb-77	Inspection and Rework of the Main Beam Upper Cap Beam, P/N 214-030-455-5
ASB 214-77-3	Basic	8-Mar-77	Inspection and Rework of Fuselage Tailboom Attach Bulkhead Flanges
ASB 214-77-4	Basic	28-Mar-77	Adding Inspection Holes in the Passenger Door Assemblies
ASB 214-77-5	Basic	7-Apr-77	Modification of VHF AM Communication System - KTR 905 Power Source
ASB 214-77-6	Basic	29-Apr-77	Daily Inspection of Scissors and Sleeve Assembly Collective Hub Lock Plate, P/N 214-010-451-1
ASB 214-77-7	Basic	2-May-77	Inspection of Tail Rotor Drive Shaft and Removal of Anti-Chafing Tape From the Tail Rotor Driveshaft Covers and the 42 degree Gearbox Cover and the Fin Cover Door Assemblies
ASB 214-77-8	Rev A	30-Nov-77	Inspection of Tailboom Vertical Fin Forward Spar Area
ASB 214-77-9	Basic	13-Sep-77	Mandatory Replacement of Elevator Control Tube Assemblies, P/N 214-001-025-1, -7 and P/N 214-001-038-1
ASB 214-77-10	Rev A	24-Jul-78	Inspection Requirements, Main Rotor Blades, P/N 214-015-001-5 and -11 (See ASB 214-93-50)
ASB 214-78-1	Basic	24-Jan-78	Tailboom Vertical Fin, Modification of
ASB 214-78-2	Basic	27-Feb-78	T5508D Engine Operating Speed, Temporary Restriction
ASB 214-78-3	Basic	8-Mar-78	PART I: Assignment of a P/N 214-040-021-1 to the Freewheeling Clutch Assembly Installed in the 214-040-026-1, -5, -7, -11, and -13 Input Quill Assemblies - PART II: Assignment of a 600 Hour Overhaul Inspection Period to the Transmission Freewheeling Clutch Assembly, P/N 214-040-021-1

## 214B/B1 ALERT SERVICE BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
ASB 214-78-4	Basic	18-Apr-78	Retirement Life Reduction of Collective Lever Idler Link Assembly, P/N 214-010-409-5 and Assignment of Retirement Life to Idler Link Pivot Bolt, P/N 20-057-10-118D
ASB 214-78-5	Basic	19-Apr-78	Main Rotor Hub Strap Assemblies, P/N 214-010-116-1, Reduction of Service Life
ASB 214-78-6	Basic	23-Oct-78	Engine Compressor Stall
ASB 214-79-7	Rev A	13-Aug-79	Main Rotor Trunnions P/N 214-010-106-1 and 214-010-226-1, Reduction of Service Life
ASB 214-79-8	Basic	12-Dec-79	Sprag Clutch, P/N 214-040-808-1, 600 Hour Retirement Life (See ASB 214-80-11)
ASB 214-80-9	Basic	10-Mar-80	Tail Rotor Flapping Bearing Wear Indicator, Installation of (See ASB 214-80-15)
ASB 214-80-10	Basic	13-May-80	Reduction of Retirement Life of Tension/Torsion Straps, P/N 214-010-179-001/-003
ASB 214-80-11	Basic	4-Jun-80	Freewheeling Clutch Assembly, P/N 214-040-021-001, Overhaul of Sprag Clutch Assembly, P/N 214-040-808-001, Retirement Life, Change of (See ASB 214-80-13)
ASB 214-80-12	Basic	29-Aug-80	Main Hydraulic Servo Actuators, P/N 214-076-146-001, Seal Inspection of the Upper and Lower Piston Head Seals
ASB 214-80-13	Basic	22-Aug-80	Freewheeling Clutch Assembly, P/N 214-040-021-103, Installation of
ASB 214-80-14	Basic	28-Aug-80	Main Rotor Trunnion Replacement of P/N 214-010-106-001, P/N 214-010-226-001 or -103, by Trunnion, P/N 214-010-230-101
ASB 214-80-15	Basic	22-Dec-80	Tail Rotor Flapping Bearing Wear Indicator, P/N 214-010-775-101, Replacement by P/N 214-010-778-101
ASB 214-81-16	Basic	3-Feb-81	Zinc Chromate, Thermal Limit Indicator, Addition of (See ASB 214-93-51)
ASB 214-81-17	Basic	25-Mar-81	PART I: Main Rotor Spindle Bolt, P/N EWB26-10H90, Inspection of - PART II: Main Rotor Spindle Bolt, P/N WEB26-10H90, Retirement Life, Reduction of
ASB 214-81-18	Basic	14-Sep-81	Yoke, Tail Rotor, P/N 214-010-702-001, -105, and -107, Inspection of
ASB 214-82-19	Basic	26-Jul-82	Internal Hoist, P/N 214-070-300-1, Western Gear Corp. P/N 42277R1 Inspection and Modification of
ASB 214-82-20	Basic	15-Dec-82	Tail Rotor Counterweight and Crosshead Assembly Nut, P/N MS17826-8, Replacement of
ASB 214-83-21	Basic	12-Sep-83	Main Rotor Spindle, P/N 214-010-103 (All Dash Numbers), Inspection of
ASB 214-83-22	Basic	26-Sep-83	Battery Temperature Sensor, Rewiring of

## 214B/B1 ALERT SERVICE BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
ASB 214-83-23	Rev A	14-Dec-83	Main Rotor Grips, P/N 214-010-104-113, Serial Numbers OJ 010, OJ 012, OJ 014, OJ 020, OJ 023, and OJ 025, Verification of (See ASB 214-83-25)
ASB 214-83-24	Basic	9-Nov-83	Freewheeling Clutch, Borg Warner P/N X139223, BHTI P/N 214-040-866-101, 600 Hour Retirement Life, Assignment of
ASB 214-83-25	Basic	28-Nov-83	Main Rotor Grip Assembly, P/N 214-010-104-009/-113, Retirement Life, Reduction of
ASB 214-84-26	Basic	12-Mar-84	Collective Sleeve, P/N 214-010-411-001, With Serial Number A-19 Prefix, Inspection of (See ASB 214-85-29)
ASB 214-84-27	Rev A	11-Jan-85	Elevators, P/N 214-020-100-009, -010, -013, and -014, and Prior Dash Numbers to Horn Assembly, P/N 214-001-920-007, Attachment, Modification of
ASB 214-85-28	Basic	3-Sep-85	Drag Brace Assembly, P/N 214-010-113-001/-003, Inspection of
ASB 214-85-29	Basic	7-Nov-85	Collective Sleeve, P/N 214-010-411-001/-003, with Serial Number A-19 Prefix and A-1 thru A-10, Reinspection of
ASB 214-85-30	Basic	7-Nov-85	Main Rotor Pitch Link Assembly, P/N 214-010-410 (All Dash Numbers), Inspection of
ASB 214-86-31	Basic	3-Feb-86	Main Rotor Spindle Bolt, P/N 214-010-183-101, Inspection of
ASB 214-86-32	Basic	20-Feb-86	Collective Sleeve Assembly, P/N 214-010-411-001/-003, Replacement of
ASB 214-86-33	Basic	2-Jun-86	Drag Brace Assembly, P/N 214-010-113-001/-003, Replacement of
ASB 214-86-34	Rev C	8-Oct-87	Tail Rotor Retrofit Kit, P/N 214-704-072-101, Installation of
ASB 214-86-35	Basic	14-Jul-86	Inspection Interval of Locking Plate, P/N 214-010-232-101, for Condition and Proper Installation, and Torque Check of Collective Hub Nut, P/N 214-010-417-001 (See ASB 214-86-36)
ASB 214-86-36	Basic	8-Oct-86	Scissors and Sleeve Locking Plates, P/N 214-010-231-101 and P/N 214-010-232-101, Replacement of
ASB 214-87-37	Rev A	10-Sep-87	Main Rotor Yoke, P/N 214-010-105-001, Reduction of Retirement Life from 5000 Hours to 3750 Hours, the Addition of a 1200 Hour Inspection, and a New Airspeed vs Altitude Restriction
ASB 214-87-38	Basic	8-Oct-87	Engine Fuel Valve Electrical Connector, P/N MS3456W14S-5S, One Time Inspection
ASB 214-87-39	Basic	11-Nov-87	Ground Handling Wheel Gear Kit, P/N 214-706-104-001, Cradle Assembly, P/N 214-050-011-001, Pin, Replacement of
ASB 214-88-40	Basic	6-Apr-88	Drag Brace Assembly, P/N 214-010-113-107, Inspection of
ASB 214-89-41	Basic	17-Oct-89	Main Rotor Flight Control System Bolts, Inspection of
ASB 214-90-42	Basic	15-Jan-90	Breeze-Eastern Cargo Hooks P/N 17138-1 and -3, Warning Plate, Addition of (See ASB 214-93-49)

## 214B/B1 ALERT SERVICE BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
ASB 214-90-43	Basic	4-Apr-90	Main Rotor Trunnion P/N 214-010-230-101, and Main Rotor Mast P/N 214-040-090-105/-117, Elimination of Calendar Retirement
ASB 214-90-44	Basic	5-Dec-90	Crew Door Hinge Pins (Jettison Pins) P/N 204-030-790-011/-013
ASB 214-91-45	Basic	1-Aug-91	Carrier Assembly, P/N 214-040-077-007 and -101, Increase in Retirement Life, a Method of Calculating Retirement Life and Alternate Method of Compliance (See ASB 214-94-52)
ASB 214-91-46	Rev A	8-Oct-92	Pillow Block Bearing Bolts, P/N 20-057-12-48D and -50D, Increase in Retirement Life, a Method of Calculating Retirement Life and Alternate Method of Compliance (See ASB 214-94-54)
ASB 214-92-47	Rev B	19-May-93	Spider, P/N 214-040-080-101, Establishment of a Retirement Life, and Method of Determination (See ASB 214-94-53)
ASB 214-93-48	Rev A	21-Apr-93	Improved Rotor Brake Quill, P/N 209-040-173-103, Installation of
ASB 214-93-49	Rev A	24-May-94	Breeze-Eastern Cargo Hook Customer Advisory Bulletin No. CAB-100-41 and Customer Service Bulletin No. CSB-148
ASB 214-93-50	Basic	21-Sep-93	Main Rotor Blade P/N 214-015-001-5 and -11, Inspection for Accomplishment of "Mod A"
ASB 214-93-51	Rev A	4-Mar-94	Main Driveshaft and Tail Rotor Drive System Grease Lubricated Couplings, Over-temperature Indicators, Installation of
ASB 214-94-52	Basic	7-Nov-94	Upper Planetary Carrier, P/N 214-040-077-007 and -101, Change in Retirement Life and Method of Determination
ASB 214-94-53	Basic	7-Nov-94	Spider, P/N 214-040-080-001, and -101, Change in Retirement Life and Method of Determination
ASB 214-94-54	Basic	7-Nov-94	Pillow Block Bearing Bolts, P/N 20-057-12-48D, Change in Retirement Life and Method of Determination
ASB 214-94-55	Basic	7-Nov-94	Trunnion, P/N 214-010-230-101, Change in Retirement Life and Establishment of a Method of Determination
ASB 214-95-56	Rev A	23-Oct-95	P/N 214-015-001-ALL (Metal) Main Rotor Blade Spar Corrosion
ASB 214-96-57	Basic	26-Aug-96	Tail Rotor Yoke Assembly P/N 214-011-802-105 and -111 Inspection and Installation of Tail Rotor Flapping Stop P/N 214-011-809-109
ASB 214-97-58	Basic	20-May-97	Swashplate Duplex Bearing, P/N 214-310-400-101, One Time Inspection
ASB 214-97-59	Basic	17-Jul-97	Self-locking Barrel Nut, P/N NAS577B-10A, One Time Inspection
ASB 214-97-60	Rev A	24-Feb-98	Tail Rotor Blade, P/N 214-015-750-005, -109, and -113, Crack Inspection
ASB 214-99-61	Basic	5-Jul-99	Main Rotor Strap Pin, P/N 214-010-117-001, Recall

## 214B/B1 ALERT SERVICE BULLETIN INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
ASB 214-00-62	Basic	2-Jun-00	214-010-185-107 Strap Fitting Assembly, Establishment of 2500 Hour Airworthiness Life
ASB 214-00-63	Basic	21-Aug-00	Honeywell Service Bulletin T5508D-0042: Engine-Accessory Drive Gearbox - One Time Inspection - Accessory Gearbox Cover Assembly P/N 2-080-010-15/-18/-20/ -23/-24
ASB 214-00-64	Rev A	14-Sep-00	P/N 214-015-001-ALL (Metal) Main Rotor Blade Lower Skin Inspection
ASB 214-02-65	Basic	15-Feb-02	Honeywell Service Bulletin T5508D-0043: Engine Accessory Drive Gearbox - One Time Replacement - Accessory Drive Spur Gear Part No. 2-080-016-02/-04
ASB 214-03-66	Basic	12-Mar-03	Tail Rotor Blade, P/N214-015-750-005,-109 and -113, Tip Closure Inspection
ASB 214-05-67	Basic	10-Oct-05	Honeywell Service Bulletin T5508D-0046: Engine - Accessory Drive Carrier Assembly - Removal from Service of Accessory Drive Inner Bevel Gear Part No. 2-070-024-01
ASB 214-06-68	Basic	11-Aug-06	Tail Rotor Driveshaft Hanger Assembly Bearing,P/N 214-040-606-101, One Time Inspection
ASB 214-07-69	Basic	18-Oct-07	Cyclic Flight Control Bearing, P/N MS27643-4, One Time Inspection and Replacement Of
ASB 214-08-70	Rev C	14-Apr-09	P/N 214-030-606-005 Pylon Support Spindle Assembly, Establishment of a Retirement Life and Method of Determination
ASB 214-10-71	Basic	10-Dec-10	Elevator and Directional Flight Control Bearings P/N MS27643-4; Inspection and Replacement of
ASB 214-12-72	Basic	6-Jan-12	Engine - Fuel System - Incorrectly Maintained Fuel Controls





# BHT-214B/B1-ASB-INDEX

## NOTICE

The following blank pages are provided for entry of additional notices when distributed. These additional notices will be included in this index at next revision

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
-------------	---------------	------	---------