



A Textron Company

INFORMATION LETTER

222-11-23  
28 February 2011

**TO: All owners and operators of Model 222 and 222B helicopters**

**SUBJECT: HYDRAULIC SERVOACTUATOR P/N 222-382-001-107  
MANUFACTURED BY WOODWARD HRT**

This information letter is issued to inform our worldwide 222 and 222B customers on Bell's progress towards preparation for the upcoming overhaul of subject actuators.

Following the one time inspection of the actuator piston rod introduced by Alert Service Bulletin 222-10-109, hydraulic actuators P/N 222-382-001-107 were returned to service until the established overhaul requirement of 1 year/ 1200 hours or 2 years/2400 hours is reached.

Currently, Bell Helicopter and WHRT are not yet ready to accept/receive actuators for overhaul.

Bell Engineering and Senior Management are working with WHRT on a plan to better support the overhaul of these actuators.

As soon as a working plan is in place, we will inform you when and where to ship the actuators for overhaul.

For any questions regarding this letter, please contact:

Bell Helicopter Product Support Engineering - Intermediate Helicopters  
Tel: 450-437-2077 / 1-800-463-3036 / pseinter@bellhelicopter.textron.com