



OPERATIONS SAFETY NOTICE INDEX

COPYRIGHT NOTICE

COPYRIGHT 2011
BELL © HELICOPTER TEXTRON INC.
AND BELL HELICOPTER TEXTRON
CANADA LTD.
ALL RIGHTS RESERVED

Bell *helicopter*

A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

19 SEPTEMBER 2011

206A/B/B3 OPERATIONS SAFETY NOTICE INDEX

NUMERICAL INDEX

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
OSN 206-75-1	Basic	15-Oct-75	Cracked Main Rotor Hub Yoke
OSN 206-75-2	Basic	4-Nov-75	Daily Inspection of 206-010-200-29 Main Rotor Blades
OSN 206-76-1	Basic	14-Oct-76	Deterioration of Engine Inlet Screen Assembly
OSN 206-77-1	Basic	21-Jan-77	Engine Shut Down Procedure
OSN 206-77-2	Basic	2-Mar-77	Inspection and Maintenance
OSN 206-77-3	Basic	23-Aug-77	Main Rotor Pitch Change Links
OSN 206-77-4	Basic	3-Oct-77	Fuel Boost Pumps Inoperative/Unusable Fuel Quantity
OSN 206-78-1	Basic	26-Jan-78	Landing Gear Installation
OSN 206-78-2	Basic	15-Feb-78	N2 Operating Speed Restriction
OSN 206-78-3	Basic	22-Aug-78	Tooth Failures, Main Bevel Gear P/N 206-040-021
OSN 206-78-4	Basic	19-Sep-78	Tail Rotor Blades, P/N 206-010-750 Series
OSN 206-79-1	Basic	30-Jan-79	Cracked Main Rotor Yokes
OSN 206-79-2	Basic	26-Feb-79	Draining of Airframe Fuel Filter During Pilot Preflight Inspection
OSN 206-79-3	Basic	15-May-79	600 Hour Inspection and Lubrication of Main Driveshaft P/N 206-040-100
OSN 206-79-4	Basic	19-Sep-79	Cracked Main Rotor Grip P/N 206-010-102-009
OSN 206-79-5	Basic	4-Dec-79	Tail Rotor Blades, P/N 206-010-750-007 (Aluminum)
OSN 206-80-6	Basic	11-Mar-80	Proper Installation of the 20-057-5-18D Bolt Securing the Lower End of the 206-001-099-001 Control Tube to the 206-001-526-003 Bellcrank
OSN 206-80-7	Basic	16-May-80	External Hoist Kit, P/N 206-706-126-001
OSN 206-82-8	Basic	28-May-82	FAA Airworthiness Directive 82-07-03(Janitrol Aero Division Combustion Heaters)
OSN 206-82-9	Basic	27-Jul-82	Engine-Out Audio Warning Horn, Disabling of
OSN 206-83-10	Basic	31-Oct-83	Supplemental Operating & Emergency Procedures
OSN 206-84-11	Basic	16-Mar-84	Main Rotor Blade Repair
OSN 206-84-12	Basic	17-Jul-84	Dual Control-Quick Disconnect Kit, P/N 206-706-127 (All Dash Numbers) Service Instructions 206-67 and 206-2024
OSN 206-84-13	Basic	13-Sep-84	Skin Compression Wrinkles in Tailboom
OSN 206-84-14	Basic	19-Nov-84	Inspection of Tail Rotor Blade Tip Block and Tail Rotor Gearbox for Security of Attachment
OSN 206-85-15	Basic	19-Apr-85	206B Series External Hoist Kit, P/N 206-706-126 (All Dash Numbers), 206L Series External Hoist Kit, P/N 206-899-861 (All Dash Numbers)
OSN 206-86-16	Basic	18-Mar-86	Landing Gear Installation
OSN 206-86-17	Basic	31-Jul-86	Allison Model 250-C20/C28 Series Gas Producer Rotor Contamination
OSN 206-86-18	Basic	7-Aug-86	Inspection of Cap, P/N 32652, for Thread Damage
OSN 206-86-19	Rev A	22-Sep-86	Examination of Float Inflation Valve, P/N 206-073-915-101
OSN 206-87-20	Basic	23-Sep-87	A.S.B. 206-87-37 and A.S.B. 206L-87-44, Main Rotor Mast Return for Metallurgical Evaluation

206A/B/B3 OPERATIONS SAFETY NOTICE INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
OSN 206-87-21	Basic	18-Jan-88	Light Reflected Into Cockpit
OSN 206-87-22	Basic	22-Jan-88	Wedge Windows Can Cause Doors to Open In Flight
OSN 206-88-23	Basic	1-Mar-88	Cyclic Control System Rigging
OSN 206-88-24	Basic	9-Mar-88	Availability of a Wire Strike Protection System for Bell Helicopters
OSN 206-89-25	Basic	13-Jan-89	Investigation of Cracks in the Main Rotor Blade Trailing Edge Extrusion
OSN 206-89-26	Basic	26-Sep-89	Cargo Hook Electrical Release Wiring
OSN 206-91-27	Basic	10-Oct-91	Engine Mount Leg, Clamshell Dampers
OSN 206-92-28	Basic	18-May-92	FAA/PMA Float Bags Manufactured by Air Float Systems
OSN 206-92-29	Basic	25-Jun-92	OSN 206-89-25/OSN 206L-89-25; Investigation of Cracks in the Main Rotor Blade Trailing Edge Extrusion
OSN 206-92-30	Basic	23-Nov-92	FAA/PMA Float Bags Manufactured by SMR Technologies
OSN 206-93-31	Basic	10-Mar-93	Pilot's Run-up Check
OSN 206-93-32	Basic	31-Mar-93	Tail Rotor Blades, Check/Inspection of
OSN 206-93-33	Basic	24-Nov-93	Dual Controls Quick-disconnect, Removal of
OSN 206-98-34	Basic	2-Nov-98	Flight Controls Rigging
OSN 206-99-35	Rev B	9-Mar-07	Repairs or Alterations Not Approved by Bell Helicopter
OSN 206-99-36	Basic	19-Aug-99	ASB 206-87-39, Dated 9-17-87, Tail Rotor Pitch Link P/N 206-010-793-101, Inspection of
OSN 206-02-37	Basic	31-May-02	Tail Rotor Disc Pack Coupling P/N 32721-1, Attaching Hardware Torque Check of
OSN 206-03-38	Basic	3-Jan-03	Tail Rotor Blades 206-016-201-XXX, Periodic Inspection of
OSN 206-10-39	Basic	11-May-10	206-001-397-XXX Cyclic Support Assembly; Maintenance and Inspection of

GENERAL OPERATIONS SAFETY NOTICE INDEX

NUMERICAL INDEX

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
OSN GEN-76-1	Basic	21-Jan-76	Use of Life Vests During Over-water Operations
OSN GEN-76-2	Basic	23-Jan-76	Helicopter Accidents Caused by Ground Handling Errors
OSN GEN-76-3	Basic	24-Sep-76	Use of Standard Hardware
OSN GEN-76-4	Basic	13-Sep-76	Heavy Lift, Aft Center of Gravity, Prolonged Hover, Cyclic Control Abuse
OSN GEN-76-5	Basic	13-Sep-76	Fuel Contamination
OSN GEN-76-6	Basic	18-Oct-76	Collective Minimum Friction
OSN GEN-76-7			NOT USED
OSN GEN-76-8	Basic	22-Dec-76	Operation of Helicopters in Salt Laden Atmosphere
OSN GEN-77-1	Rev A	3-Nov-77	Airworthiness of Aircraft Parts
OSN GEN-78-1	Basic	10-Jan-78	Maintenance of the Main Rotor Blade Inspection System (B.I.S.)
OSN GEN-78-2	Basic	5-May-78	Cracked Main Rotor Yoke P/N 204-011-102
OSN GEN-78-3	Basic	13-Sep-78	Chadwick C-47 Electronic Weighing System, Load Cell Link P/N 47-40200-19
OSN GEN-78-4	Basic	11-Dec-78	Chaffed Oil Lines
OSN GEN-79-1	Basic	2-May-79	Cracked Main Rotor Yoke P/N 204-011-102
OSN GEN-79-2	Basic	26-Nov-79	Cracked Main Rotor Yoke P/N 204-011-102
OSN GEN-80-3	Basic	13-Feb-80	Cracked Main Rotor Blade, P/N 204-011-250 Series
OSN GEN-80-4	Basic	19-Jun-80	Rotating Control Bolts
OSN GEN-80-5	Basic	27-Jun-80	Enhancement of Crew and Passenger Safety During High Impact Landings
OSN GEN-80-6	Basic	27-Jun-80	Daily Inspection of Main Input Driveshafts
OSN GEN-80-7	Basic	24-Jul-80	Transporting Flammable Cargo
OSN GEN-81-8	Basic	22-Sep-81	Inspection of Tail Rotor Pitch Links
OSN GEN-82-9	Basic	6-Oct-82	Tail Rotor Driveshaft Curvic Couplings, Inspection, Maintenance
OSN GEN-83-10	Basic	1-Sep-83	Engine Compressor Washing
OSN GEN-85-11	Basic	6-Nov-85	Beware of "Certificate of Manufacture, Inspection and Conformance"
OSN GEN-87-12	Basic	13-May-87	FAA Airworthiness Directive 87-06-09 (Mechanical Products, Inc.)
OSN GEN-88-13	Reissue	5-May-92	Lines Extending from the Helicopter
OSN GEN-89-14	Basic	6-Dec-89	Bogus P/N 212-073-905-1 Pressure Gage, Emergency Floats
OSN GEN-91-15	Basic	29-Jul-91	Electromagnetic Compatibility (EMC) of Aircraft Wiring with Pyrotechnic Device and Cargo Hooks
OSN GEN-91-16	Basic	21-Aug-91	Airframe Structural Repair
OSN GEN-91-17	Basic	1-Oct-91	Main Driveshaft Assembly, Inspection of
OSN GEN-92-18	Basic	19-Mar-92	Proper Stowage of Miscellaneous Items in and Around the Flight Crew Compartment
OSN GEN-92-19	Basic	5-May-92	MS21042 Series Nuts Approved Vendors
OSN GEN-92-20	Basic	25-Jun-92	Use of Non-Conforming Floatbag Assemblies
OSN GEN-92-21	Basic	25-Jun-92	Lubricant P/N 204-040-755-005

GENERAL OPERATIONS SAFETY NOTICE INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
OSN GEN-93-22	Basic	29-Jan-93	Main Rotor Vibration; Emphasis on Timely Investigation
OSN GEN-93-23	Basic	29-Jan-93	Maintenance/Overhaul Procedures
OSN GEN-93-24	Basic	1-Mar-93	Parts Authenticity and Traceability
OSN GEN-93-25	Basic	15-Dec-93	"Slingshot" Maneuvers in Heavy Lift Operations
OSN GEN-95-26	Basic	19-Jan-95	Aircraft Cleaning
OSN GEN-95-27	Basic	24-Mar-95	Tail Rotor Yoke (Flexure Style) Failure
OSN GEN-96-28	Basic	21-May-96	Transmission Spiral Bevel Gear Cracks
OSN GEN-96-29	Basic	18-Oct-96	Unapproved Tail Rotor Driveshaft Hanger Bearings
OSN GEN-97-30	Basic	27-Jan-97	Breeze-Eastern Customer Advisory Bulletin Number CAB-100-54
OSN GEN-97-31	Basic	1-May-97	Tail Rotor Hanger Bearings Maintenance
OSN GEN-02-32	Basic	2-May-02	Bogus Parts Tail Rotor Grips
OSN GEN-02-33	Basic	10-Oct-02	Maintenance/Overhaul Procedures
OSN GEN-02-34	Basic	22-Nov-02	Correct Procedure for Torquing Fasteners
OSN GEN-04-35	Basic	21-Sep-04	Cyclic Stick Grip Assembly
OSN GEN-06-36	Basic	17-Apr-06	Paint Application on Helicopter Faying Surfaces
OSN GEN-06-37	Basic	20-Jul-06	NAS 1291-7 and -8 Nut, Confirmation of Condition Upon Installation
OSN GEN-09-38	Basic	7-Apr-09	Bearings in Flight Controls
OSN GEN-09-39			RESERVED
OSN GEN-09-40	Basic	16-Nov-09	Onboard Systems International Alert Service Letter Document no. 159-027-00.
OSN GEN-10-41	Basic	18-Jan-10	Honeywell Bendix/King Discrepant Databases for KLN35A/KLN 88/KLN 89/KLN 89B/KLN 90/KLN 90A/KLN90B/KLN 94/KLX 100/KLX 135/KLX 135A/KLN 900
OSN GEN-10-42	Basic	13-Dec-10	Use of Specified Hardware
OSN GEN-11-43	Rev A	16-Sep-11	NAS1291 Nuts and NAS626 Bolts
OSN GEN-11-44	Basic	10-May-11	Defective Grease Fittings NAS516-1A

NOTICE

The following blank pages are provided for entry of additional notices when distributed. These additional notices will be included in this index at next revision

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
--------------------	-----------------------	-------------	----------------