

ALERT SERVICE BULLETIN

REVISION NOTICE

Bell Helicopter **TEXTRON**

A Subsidiary of Textron Inc.

DATE 10-25-01

TO: **All Bell 407 Helicopters Owners/Operators**

SUBJECT: **REVISION "A" TO ALERT SERVICE BULLETIN 407-98-23: (OIL COOLER BLOWER FAN HANGER BEARING 407-340-339-101/103 AND ROYCO 13 PER MIL-G-25013, INTRODUCTION OF)**

Alert Service Bulletin 407-98-23 is cancelled and superseded by Alert Service Bulletin 407-01-44 Revision A.

7651 60046 REV 1198

AN APPROPRIATE ENTRY SHOULD BE MADE IN THE AIRCRAFT LOG BOOK UPON ACCOMPLISHMENT
IF OWNERSHIP OF AIRCRAFT HAS CHANGED PLEASE FORWARD TO NEW OWNER

ALERT SERVICE BULLETIN

Bell Helicopter **TEXTRON**
A Subsidiary of Textron Inc.

NO. 407-98-23
DATE 12-11-98
PAGE 1 of 1

DATE	10-25-01
REV	"A"

MODEL AFFECTED: 407

SUBJECT: OIL COOLER BLOWER FAN HANGER BEARING
407-340-339-101/-103 AND ROYCO 13 PER MIL-
G-25013, INTRODUCTION OF.

HELICOPTERS AFFECTED: All model 407 helicopters

COMPLIANCE: Effective immediately

DESCRIPTION:

Alert Service Bulletin 407-98-23 is cancelled and superceded by Alert Service Bulletin 407-01-44 Revision A.

A.

7851 55192 REV 1198

AN APPROPRIATE ENTRY SHOULD BE MADE IN THE AIRCRAFT LOG BOOK UPON ACCOMPLISHMENT
IF OWNERSHIP OF AIRCRAFT HAS CHANGED PLEASE FORWARD TO NEW OWNER