

ALERT SERVICE BULLETIN
REVISION NOTICE

DATE Sep 21, 2009



TO: All Owners/Operators of Bell 205 / 205A-1 Helicopters

**SUBJECT: REVISION "A" TO ALERT SERVICE BULLETIN 205-09-100:
HIGH LANDING GEAR FWD CROSSTUBE P/N 212-321-103**

Revision "A" of this bulletin is re-formatted to include all High Fwd Crosstubes P/N 212-321-103 installed in production or as a Bell direct replacement part.

AN APPROPRIATE ENTRY SHOULD BE MADE IN THE AIRCRAFT LOGBOOK UPON ACCOMPLISHMENT
IF OWNERSHIP OF AIRCRAFT HAS CHANGED PLEASE FORWARD TO NEW OWNER

ALERT SERVICE BULLETIN



NO. 205-09-100

DATE Sep 21, 2009

PAGE 1 of 2

DATE 09-21-09

REV A

MODEL AFFECTED: 205 / 205A-1

SUBJECT: HIGH LANDING GEAR FWD CROSSTUBES P/N
212-321-103

HELICOPTERS AFFECTED: All Model 205A and 205A-1 helicopters serial number 30001 through 30039. S/N 30050 through 30052, 30057 through 30067, S/N 30078 through 30127 and S/N 30128 through 30332.

COMPLIANCE: Vendor Alert Service Bulletin AA-08055 Rev. B must be carried out on all High Fwd Crosstube P/N 212-321-103 either installed in production or as a Bell direct replacement part. Vendor ASB was previously provided with the initial release of this bulletin

DESCRIPTION:

The purpose of this bulletin is to carry out the intent of Vendor bulletin AA-08055 Rev B. It applies to all High Fwd Crosstubes P/N 212-321-103.

Aeronautical Accessories crosstube part number 212-321-103 is a Bell-approved replacement for Crosstube Assembly part number 205-050-403-007/-031 and 412-050-046-101.

APPROVAL:

The engineering design aspects of this bulletin are FAA/ODA approved.

MANPOWER:

Approximately 29.0 man-hours are required to complete this bulletin. Man-hours are based on hands-on time, and may vary with personnel and facilities available.

AN APPROPRIATE ENTRY SHOULD BE MADE IN THE AIRCRAFT LOGBOOK UPON ACCOMPLISHMENT
IF OWNERSHIP OF AIRCRAFT HAS CHANGED PLEASE FORWARD TO NEW OWNER

WARRANTY:

There is no warranty provided for this bulletin.

MATERIAL:

See Vendor Bulletin AA-08055 Rev B

SPECIAL TOOLS:

None required

WEIGHT AND BALANCE:

Not affected.

ELECTRICAL LOAD DATA:

Not affected

REFERENCES:

Aeronautical Accessories Alert Service Bulletin AA-08055 Rev B (Available from Aeronautical Accessories, Inc., P.O. Box 3689 Bristol, Tn., 37625-3689 USA, Phone 800-251-7094 or 423-538-8469)

BHT-412-IPB Illustrated Parts Breakdown

BHT-412-MM Maintenance Manual

PUBLICATIONS AFFECTED:

None affected

ACCOMPLISHMENT INSTRUCTIONS:

Accomplish instructions as per Vendor Bulletin AA-08055 Rev B.