

**ALERT SERVICE BULLETIN**  
REVISION NOTICE

DATE Sep 21, 2009



**TO: All Owners/Operators of Bell 212 Helicopters**

**SUBJECT: REVISION "A" TO ALERT SERVICE BULLETIN 212-09-132:  
HIGH LANDING GEAR FWD CROSSTUBE P/N 212-321-103**

Revision "A" of this bulletin is re-formatted to include all High Fwd Crosstubes P/N 212-321-103 installed in production or as a Bell direct replacement part.

AN APPROPRIATE ENTRY SHOULD BE MADE IN THE AIRCRAFT LOGBOOK UPON ACCOMPLISHMENT  
IF OWNERSHIP OF AIRCRAFT HAS CHANGED PLEASE FORWARD TO NEW OWNER

# ALERT SERVICE BULLETIN



NO. 212-09-132

DATE Sep 21, 2009

PAGE 1 of 2

DATE 09-21-09

REV A

**MODEL AFFECTED:** 212

**SUBJECT:** HIGH LANDING GEAR FWD CROSSTUBES P/N 212-321-103

**HELICOPTERS AFFECTED:** All Model 212 helicopters serial number 30501 through 30999, 31101 through 31311, 32101 through 32142 and, 35001 through 35103.

**COMPLIANCE:** Vendor Alert Service Bulletin AA-08055 Rev. B must be carried out on all High Fwd Crosstube P/N 212-321-103 either installed in production or as a Bell direct replacement part. Vendor ASB was previously provided with the initial release of this bulletin.

## DESCRIPTION:

The purpose of this bulletin is to carry out the intent of Vendor bulletin AA-08055 Rev B. It applies to all High Fwd Crosstubes P/N 212-321-103.

Aeronautical Accessories crosstube part number 212-321-103 is a Bell-approved replacement for Crosstube Assembly part number 205-050-403-007/-031 and 412-050-046-101.

## APPROVAL:

The engineering design aspects of this bulletin are FAA/ODA approved.

## MANPOWER:

Approximately 29.0 man-hours are required to complete this bulletin. Man-hours are based on hands-on time, and may vary with personnel and facilities available.

**WARRANTY:**

There is no warranty provided for this bulletin.

**MATERIAL:**

See Vendor Bulletin AA-08055 Rev B.

**SPECIAL TOOLS:**

None required.

**WEIGHT AND BALANCE:**

Not affected.

**ELECTRICAL LOAD DATA:**

Not affected.

**REFERENCES:**

Aeronautical Accessories Alert Service Bulletin AA-08055 Rev B (Available from Aeronautical Accessories, Inc., P.O. Box 3689 Bristol, Tn., 37625-3689 USA, Phone 800-251-7094 or 423-538-8469)  
BHT-412-IPB Illustrated Parts Breakdown  
BHT-412-MM Maintenance Manual

**PUBLICATIONS AFFECTED:**

None affected.

**ACCOMPLISHMENT INSTRUCTIONS:**

Accomplish instructions as per Vendor Bulletin AA-08055 Rev B.