



ALERT SERVICE BULLETIN INDEX

NOTE

THIS INDEX IS A LIST OF ALERT SERVICE BULLETINS ISSUED. THIS INDEX DOES NOT IDENTIFY WHICH ALERT BULLETINS ARE ACTIVE OR INACTIVE.

THE ATA/CHAP. REF. COLUMN INDICATES THE MAINTENANCE AND/OR OVERHAUL MANUAL CHAPTER/S AFFECTED BY THE RESPECTIVE BULLETIN; OR, THE BULLETIN IS APPLICABLE TO A SERVICE INSTRUCTION (S.I.).

PROPRIETARY RIGHTS NOTICE

These data are proprietary to Bell Helicopter Textron, Inc. Disclosure, reproduction, or use of these data for any purpose other than helicopter operation is forbidden without prior written authorization from Bell Helicopter Textron, Inc.

Newly released Alert Service Bulletins can be viewed and printed by accessing our Service Directives website at www.bellcustomer.com. This publication supersedes BHT-204B-ASB INDEX dated 1 January 2007 in its entirety.

COPYRIGHT NOTICE
COPYRIGHT 2008
BELL® HELICOPTER TEXTRON INC.
AND BELL HELICOPTER TEXTRON
CANADA LTD.
ALL RIGHTS RESERVED

Bell Helicopter
A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

1 JANUARY 2008

204B ALERT SERVICE BULLETIN INDEX

STATUS CODE

A = Active

A- () = Active — (Additional Information)

└────────────────── P = Incorporated in Parts Catalog
R = Referenced in Maintenance Manual

I = Inactive

I- () = Inactive — (Reason)

└────────────────── I = Incorporated in Maintenance Manual
P = Incorporated in Parts Catalog
S = Superseded (New Bulletin Number)
R = Referenced in Maintenance Manual

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP REF. | SUBJECT |
|--------|----------------|------------------|--------|------------------|--|
| 204B-1 | Basic | 12-21-66 | | VI | Balancing and Track Requirements For Tail Rotor Hub and Blade Assembly, P/N 204-011-701-9 or 204-011-701-15 |
| 204B-2 | Basic | 6-5-67 | | VI | One-Time Inspection of Tail Rotor Yoke, P/N's 204-010-781-5 or -9 |
| 204B-3 | Basic | 8-15-67 | | VI | One-Time Inspection of Tail Rotor Slider Assembly, P/N 204-010-720-3 |
| 204B-4 | Basic | 11-8-67 | | III | One-Time Inspection of Swashplate and Support Assembly P/N 204-011-400, With 200 Hours or Less Component Operating Time |
| 204B-5 | Basic Rev B | 4-2-69 8-3-70 | | I | Assignment of 1000 Hour Retirement Life for Model 204B Float Gear Aft Cross Tube, P/N 204-706-053-5, and 205A/A-1 Float Gear Cross Tube (Aft P/N 205-050-114-1), (FWD P/N 205-050-114-3) |

BHT-204B-ASB INDEX**204B ALERT SERVICE BULLETIN INDEX**

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP | SUBJECT |
|-----------------|----------------|---------------------|---------------|-----------------|---|
| | | | | REF. | |
| 204B-6 | Basic | 6-5-72 | | VI | Inspection of Tail Rotor Hub and Blade Assemblies, P/N 204-011-701-1, -5, -9, and -15; 204-011-800-5, -7, -15, and -17 |
| 204-06-73-1 | Basic | 5-17-73 | | VII | 1000 Hour Inspection of the Irreversible Valve Assembly, P/N 204-076-055-1 |
| 204-04-73-1 | Basic Rev A | 11-13-73 11-5-75 | | IV | Grease, P/N 204-040-755-3, Dated After July, 1973 |
| 204-(04-1)-73-1 | Basic Rev A | 7-31-73 8-3-73 | | II | Inspection of Main Rotor Blades, P/N 204-011-250 (All Dash Numbers) |
| 204-05-73-1 | Basic | 5-23-73 | | VI | Inspection of Tail Rotor Hub and Blade Assemblies, P/N's 204-011-701-1, -5, -9, and -15; P/N 204-011-800-5, -17, and -25 |
| 204-05-73-2 | Basic Rev A | 7-18-73 7-25-73 | | I | Mandatory Replacement Interval for Tail Rotor Grip Assemblies, P/N 204-011-706 and P/N 204-011-728, Is Reduced to 500 Hours |
| 24-11-73-1 | Basic | 7-13-73 | | VI | Inspection of Anti-Torque Silent Chain Assy, P/N 205-001-721-1 |
| 204-04-74-1 | Basic | 2-5-74 | | IV | Inspection of Main Drive Shaft Boot, P/N 205-040-176-3 |
| 204-(04-2)-74-1 | Basic | 9-3-74 | | III | Inspection of Swashplate Scissors Lever Bolts, P/N NAS 464-P8-90 or P/N 212-010-411-1 |
| 204-75-1 | Basic Rev C | 9-12-75 4-25-79 | | II | Inspection, Sealing and Refinishing of Main Rotor Blades, P/N 204-011-250 (All Dash Numbers) |
| 204-75-2 | Basic Rev A | 9-16-75 8-13-76 | | X | Replacement of Emergency Exit Decals, and Escape Release Handle Covers |

204B ALERT SERVICE BULLETIN INDEX

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP | |
|---------------|----------------|--------------------|---------------|-----------------|--|
| | | | | REF. | SUBJECT |
| 204-75-3 | Basic | 9-23-75 | | VII | Inspection of Anti-Torque Pitch Change Control Assembly, P/N 204-010-740-5, Pitch Change Rod, 204-010-742-9 |
| 204-75-4 | Basic | 12-16-75 | | VII | Inspection of Anti-Torque Control Chain, P/N 204-001-739-3 |
| 204-76-1 | Basic | 2-17-76 | | II | One Time Inspection of Main Rotor Blade Bolt Washer, P/N 204-011-152-1 |
| 204-76-2 | Basic | 3-17-76 | | II | Inspection of Stabilizer Bar Outer Tube, P/N 204-011-328-1/-11 |
| 204-76-3 | Basic | 5-17-76 | | II | Stabilizer Bar Tube Assembly, P/N 204-011-328-1 |
| 204-76-4 | Basic | 8-24-76 | | VII | Anti-Torque Controls Fairleads, P/N 204-011-820-1 and P/N 204-001-856-1 |
| 204-76-5 | Basic Rev A | 9-9-76 9-23-78 | | VII | Flight Control Tubes and Bellcranks |
| 204-76-6 | Basic | 9-16-76 | | III | Swashplate Support Assembly, P/N 204-011-404-9 |
| 204-76-7 | Basic Rev B | 9-29-76 12-9-76 | | III | Replacement of NAS Rotating Control Bolts with Bell Standard Bolts |
| 204-76-8 | Basic | 12-13-76 | | VI | Replacement of Tail Rotor Hanger Bearings, P/N 204-040-623-1, With 204-040-623-5 |
| 204-76-9 | Basic Rev A | 12-22-76 1-3-77 | | II | Inspection of Steel Grip Pad on Main Rotor Blade, P/N 204-011-250 (All Dash Numbers) |
| 204-77-1 | Basic Rev A | 1-10-77 2-1-77 | | I | 1000 Hour Special Inspection Requirements for Main Rotor Hub Fitting Assemblies, P/N 204-012-102-5; Pins, P/N 204-012-104-5; and Strap Assemblies, P/N 204-012-112-5 |

BHT-204B-ASB INDEX**204B ALERT SERVICE BULLETIN INDEX**

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP | SUBJECT |
|---------------|----------------|---------------------|---------------|-----------------|--|
| | | | | REF. | |
| 204-77-2 | Basic | 3-8-77 | | X | Replacement of Spacers and Screws Attaching the Emergency Escape Release Handle Covers |
| 204-77-3 | Basic | 6-15-77 | | VI | Inspection of Tail Rotor Driveshafts and Removal of Anti-Chafing Tape From the Tail Rotor Driveshaft Cover and the Fin Cover Door Assemblies |
| 204-77-4 | Basic | 6-27-77 | | VII | Replacement of Tail Rotor Chain Guard, P/N 204-010-747-3 |
| 204-77-5 | Basic | 8-8-77 | | X | Adding Inspection Holes in the L/H and R/H Passenger Door Assemblies |
| 204-77-6 | Basic | 9-30-77 | | V | Inspection of Engine Driveshaft Adapter Bolts, P/N 204-040-813-001, for Loss of Torque |
| 204-78-1 | Basic | 2-21-78 | | S.I. | External Cargo Suspension Kit, Decrease of Load Rating |
| 204-78-2 | Basic | 4-19-78 | | I | Main Rotor Hub Inboard Fitting, P/N 204-012-102-5, Reduction of Service Life |
| 204-78-3 | Basic | 4-19-78 | | II | Main Rotor Hub Strap Assemblies, P/N 204-012-112-5, Reduction of Service Life |
| 204-78-4 | Basic | 5-11-78 | | S.I. | Replacement of External Cargo Hook Link Assembly, P/N 205-070-944-1 or -5, With New Link Assy, P/N 205-070-944-7 |
| 204-78-5 | Basic Rev A | 10-13-78 5-13-80 | | I | Main Rotor Hub Strap Pin, P/N 204-012-104-5, Reduction of Service Life |
| 204-79-6 | Basic | 5-22-79 | | II | Main Rotor Hub Assy, P/N 204-012-101 (All Dash Numbers), Corrosion Protection of |
| 204-79-7 | Basic | 8-21-79 | | VII | T/R Cable and Chain Damper Kit, P/N 204-706-130-101, Installation of |

204B ALERT SERVICE BULLETIN INDEX

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP | |
|-----------|----------------|--------------------|--------|----------|--|
| | | | | REF. | SUBJECT |
| 204-80-8 | Basic | 5-13-80 | | I | Reduction of Retirement Life of Tension/Torsion Straps, P/N 204-012-122-001/-005 |
| 204-80-9 | Basic Rev A | 11-5-80 3-25-81 | | V | Oil and Fuel Filter, P/N 204-040-760, V-Band Clamp T-Bolt, Inspection of |
| 204-81-10 | Basic | 2-3-81 | | IV | Zinc Chromate, Thermal Limit Indicator, Addition of |
| 204-81-11 | Basic | 6-22-81 | | I | Main Rotor Yoke, P/N 204-011-102 (All Dash Numbers), Retirement Life of |
| 204-81-12 | Basic | 10-26-81 | | III | Swashplate Support Assembly, P/N 204-011-404-121, Inspection of |
| 204-85-13 | Basic Rev A | 1-17-85 1-23-85 | | II | Main Rotor Grip/Blade Bolt Interference on Repaired Grips, P/N 204-011-121 Series, Inspection and Rework of |
| 204-87-14 | Basic | 3-23-87 | | II | Main Rotor Pillow Block Yoke Attachment Washer, P/N ANA960-816, Replacement of |
| 204-87-15 | Basic Rev A | 8-4-87 8-21-87 | | III | Main Rotor Mast, P/N 204-011-450-007/-105, and Main Rotor Trunnion, P/N 204-011-105-001, Assignment of Retirement Life |
| 204-87-16 | Basic | 12-15-87 | | II | Main Rotor Yoke, P/N 204-011-102 (All Dash Numbers), Inspection of |
| 204-88-17 | Basic | 1-29-88 | | VI | Tail Rotor Grip, P/N 204-011-728 (All Dash Numbers), Reduction in Retirement Life |
| 204-88-18 | Basic | 7-28-88 | | I | Ground Handling Wheel Gear Assembly, P/N 204-050-200-005 and -15 Forward Support Pin, Replacement of |

BHT-204B-ASB INDEX**204B ALERT SERVICE BULLETIN INDEX**

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP | |
|---------------|----------------|---------------------|---------------|-----------------|--|
| | | | | REF. | SUBJECT |
| 204-89-19 | Basic | 4-6-89 | | IV | Spiral Bevel Gear P/N 204-040-701-103, Inspection of |
| 204-89-20 | Basic Rev A | 8-29-89 8-29-89 | | I | Strap Assembly, Main Rotor, Tension - Torsion P/N 204-012-122-5 and P/N 204-310-101-101, Removal From Service |
| 204-89-21 | Basic | 8-29-89 | | VI | Tail Rotor Hub Assembly P/N 204-011-801-121, Removal From Service |
| 204-89-22 | Basic Rev A | 9-7-89 10-10-89 | | VI | Tail Rotor Gearbox (90 Deg.) Duplex Bearing Set P/N 204-040-424-001, Replacement |
| 204-90-23 | Basic | 9-8-89 | | | Main Rotor Flight Control System Bolts, Inspection of |
| 204-90-24 | Basic Rev A | 10-25-89 3-8-90 | | | Cargo Hook P/N SP7109-11, Warning Plate, Addition of |
| 204-90-25 | Basic Rev A | 3-23-90 | | | Main Rotor Yoke P/N 204-011-102-All, Inspection of |
| 204-90-26 | Basic | 3-26-90 | | | Swashplate Outer Ring P/N 204-011-403-001, S/N SC-000014, Removal From Service |
| 204-90-27 | Basic Rev A | 6-26-90 10-11-90 | | | Main Rotor Pillow Block Attachment Bolt 204-011-171-003, Washer 140-007-33S28-3 and Nut EB080, One Time Use of |
| 204-90-28 | Basic | 12-5-90 | | | Crew Door Hinge Pins (Jettison Pins) P/N 204-030-790-011/-113 |
| 204-91-29 | Basic | 9-26-91 | | | Tension Torque Strap Retention Pins P/N 204-012-104-005 |
| 204-91-30 | Basic Rev A | 10-4-91 11-10-91 | | | Tail Rotor Driveshaft Hanger Bearing P/N 204-040-623-005 |
| 204-91-31 | Basic | 11-21-91 | | | Tail Rotor Driveshaft Hanger Bearing P/N 204-040-623-005 |
| 204-91-32 | Basic | 12-13-91 | | | Swashplate Support P/N 204-011-404-125 |

204B ALERT SERVICE BULLETIN INDEX

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP REF. | SUBJECT |
|---------------|----------------|--------------------|---------------|--------------------------|--|
| 204-92-33 | Basic | 2-6-92 | | | Scissor Link to Swashplate Attachment Bolt, Inspection of |
| 204-92-34 | Basic | 5-6-92 | | | Oil/Hydraulic Level Indicators P/N 204-040-508-001/-003/-005/-007/-009 |
| 204-92-35 | Basic | 10-23-92 | | | Lower Planetary Spider Gear P/N 204-040-785-003 Magnetic Particle Inspection, All Transmission Assemblies of All Part and Dash Numbers |
| 204-92-36 | Basic | 10-23-92 | | | Main Rotor Yoke P/N 204-011-102, All Dash Numbers, Removal From Service |
| 204-93-37 | Basic Rev A | 6-21-93 6-20-94 | | | Cargo Hooks, Breeze Eastern Customer Advisory Bulletin No. CAB-100-41, Customer Service Bulletin No. CSB-129 and CSB-142 |
| 204-93-38 | Basic | 11-10-93 | | | Tail Rotor Driveshaft Hanger Bearing, P/N 204-040-623-005 One Time Inspection of |
| 204-93-39 | Basic Rev A | 12-7-93 3-4-94 | | | Main Driveshaft and Tail Rotor Drive System Grease Lubricated Couplings, Over-Temperature Indicators, Installation of |
| 204-93-40 | Basic | 12-7-93 | | | Tail Rotor Slider P/N 204-010-720-003 |
| 204-94-41 | Basic | 5-9-94 | | | Tail Rotor Blade P/N 204-011-702-All, Removal From Service of Affected Serial Numbers, Inspection of |
| 204-94-42 | Basic Rev B | 5-23-94 8-17-95 | | | Blade Bolt P/N 204-011-151-001, Removal From Service of Specific Serial Numbers |
| 204-94-43 | Basic | 11-28-94 | | | Main Rotor Yoke P/N 212-011-102-105 Inspection of |

BHT-204B-ASB INDEX**204B ALERT SERVICE BULLETIN INDEX**

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP REF. | SUBJECT |
|---------------|----------------|--------------------|---------------|--------------------------|---|
| 204-95-44 | Basic | 3-13-95 | | | Introduction of New Scheduled Inspection and Conditional Inspection Requirements: Main Rotor Grip P/N 204-011-121-001/-005/-117 and P/N Grips with Modified Suffix Characters |
| 204-95-45 | Basic | 7-3-95 | | | Powertrain Modification on 204B |
| 204-95-46 | Basic Rev C | 5-8-95 10-9-95 | | | Tail Rotor Hanger Bearings P/N 204-040-623-005, Application of Witness Mark |
| 204-95-47 | Basic | 7-24-95 | | | Main Rotor Mast 204-011-450-001/-007/-105, and Main Rotor Trunnion 204-011-105-001, Change of Retirement Life and Method of Determination |
| 204-96-48 | Basic Rev A | 1-29-96 2-12-96 | | | Tail Rotor Blades, P/N 204-011-702-015/-121, Inspection of |
| 204-96-49 | Basic | 5-1-96 | | | Main Rotor Blade P/N 204-011-250-ALL: Introduction of Daily Wipe Down Inspection and Special 25 Hour Inspection |
| 204B-98-50 | Basic | 10-22-98 | | | Fin Spar 205-030-899-001 / 089, 205-030-846-001/-003/-047/-049, 204-030-825-063/-065 Inspection |
| 204-00-51 | Basic Rev A | 4-24-00 6-16-00 | | | Main Rotor (M/R) Mast, P/N 204-011-450-001/-007/-105, Inspection and Retirement Index Number (RIN) Life Reduction |
| 204-00-52 | Basic Rev A | 8-1-00 9-9-02 | | | Cargo Hook, Onboard Systems P/N 528-002-00 |
| 204-01-53 | Basic | 1-19-01 | | | Magnetic Brake P/N 204-001-376 003, One Time Inspection of |
| 204B-01-54 | Basic | 4-19-01 | | | Clutch Assembly P/N X134296, Assignment of Retirement Life |

204B ALERT SERVICE BULLETIN INDEX

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP REF. | SUBJECT |
|---------------|----------------|--------------------|---------------|--------------------------|---|
| 204B-01-55 | Basic | 7-26-01 | | | Pillow Block P/N 204-011-108-113, Tube Assembly P/N 212-010-404-005, Strap Fitting P/N 204-012-102-009, Inspection and Recall of Specific Serial Number Part |
| 204B-01-56 | Basic | 10-18-01 | | | Main Rotor Head Inboard Fitting 204-012-102-009, Inspection of Specific Serial Numbers |
| 204B-02-57 | Basic | 6-20-02 | | | 1200 Hour Special Inspection Requirements for Main Rotor Hub Pins P/N 204-012-104-001/-003/-005 |
| 204-02-58 | Basic | 11-26-02 | | | Main Rotor Grips 204-011-121-117, Ultrasonic Inspection of |
| 204-07-59 | Basic | 3-6-07 | | | Aeronautical Accessories, Inc. ASB No. AA-06107 for PC Safety Valve™: Valve Stem Over Torque |
| 204-07-60 | Basic | 6-11-07 | | | Assignment of a 100-hour Retirement Life for Stabilizer Bar Mixing Lever Bearings P/N KP6A, AN201KP6A, MS20201KP6A, MS27641-6, and Scissors Assembly Pivot Bearings P/N KP8A, AN201KP8A, MS20201KP8A, MS27641-8 |
| 204-07-61 | Basic Rev A | 9-11-07 9-19-07 | | | Tail Rotor Blade Assembly, Inspection of |
| 204-07-62 | Basic | 11-27-07 | | | Cyclic Flight Control Bearing, P/N MS27643-4 One Time Inspection and Replacement of |

NOTICE

The following blank pages are provided for entry of additional bulletins when distributed. These additional bulletins will be included in this index at next revision.

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP REF. | SUBJECT |
|---------------|--------------|-------------|---------------|--------------------------|----------------|
|---------------|--------------|-------------|---------------|--------------------------|----------------|

BHT-204B-ASB INDEX

NOTICE

The following blank pages are provided for entry of additional bulletins when distributed. These additional bulletins will be included in this index at next revision.

| NUMBER | ISSUE | DATE | STATUS | ATA/CHAP REF. | SUBJECT |
|--------|-------|------|--------|------------------|---------|
|--------|-------|------|--------|------------------|---------|