



ALERT SERVICE BULLETIN INDEX

NOTE

THIS INDEX IS A LIST OF ALERT SERVICE BULLETINS ISSUED. THIS INDEX DOES NOT IDENTIFY WHICH ALERT BULLETINS ARE ACTIVE OR INACTIVE.

THE ATA/CHAP. REF. COLUMN INDICATES THE MAINTENANCE AND/OR OVERHAUL MANUAL CHAPTER/S AFFECTED BY THE RESPECTIVE BULLETIN; OR, THE BULLETIN IS APPLICABLE TO A SERVICE INSTRUCTION (S.I.).

PROPRIETARY RIGHTS NOTICE

These data are proprietary to Bell Helicopter Textron, Inc. Disclosure, reproduction, or use of these data for any purpose other than helicopter operation is forbidden without prior written authorization from Bell Helicopter Textron, Inc.

Newly released Alert Service Bulletins can be viewed and printed by accessing our Service Directives website at www.bellcustomer.com. This publication supersedes BHT-205B-ASB INDEX dated 1 January 2007 in its entirety.

COPYRIGHT NOTICE
COPYRIGHT 2008
BELL® HELICOPTER TEXTRON INC.
AND BELL HELICOPTER TEXTRON
CANADA LTD.
ALL RIGHTS RESERVED

Bell Helicopter
A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

1 JANUARY 2008

205B ALERT SERVICE BULLETIN INDEX

STATUS CODE

A = Active

A- () = Active — (Additional Information)

└────────────────── P = Incorporated in Parts Catalog
R = Referenced in Maintenance Manual

I = Inactive

I- () = Inactive — (Reason)

└────────────────── I = Incorporated in Maintenance Manual
P = Incorporated in Parts Catalog
S = Superseded (New Bulletin Number)
R = Referenced in Maintenance Manual

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
205B-90-1	Basic Rev A	10-17-90 3-21-91			Method of Calculating Retirement Life on Subject Parts and Assignment of Retirement Lives 1) Main Rotor Yoke P/N 204-011-102-ALL 2) Main Rotor Mast, P/N 204-011-450-ALL 3) Main Rotor Trunnion, P/N 204-011-105-001
205B-90-2	Basic	10-30-90			Drag Brace Assembly, P/N 204-011-140-001, Magnetic Particle Inspection
205B-90-3	Basic	10-30-90			Main Rotor Yoke P/N 204-011-102-125 and Subsequent, Inspection of
205B-90-4	Basic	10-30-90			Main Rotor Pillow Block Attachment Bolt P/N 204-011-171-003, Washer 140-007-33S28-3 and Nut EB080 or 42FLW-820, One Time Use of
205B-90-5	Basic	12-5-90			Crew Door Hinge Pins (Jettison Pins) P/N 204-030-790-011/-013

BHT-205B-ASB INDEX

205B ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	SUBJECT
				REF.	
205B-91-6	Basic Rev A	6-12-91 6-27-91			Lower Planetary Spider Gear, P/N 204-040-785-003, Assignment of a Special Inspection
205B-91-7	Basic	9-26-91			Tension Torsion Strap Retention Pins P/N 204-012-104-005
205B-91-8	Basic Rev B	10-4-91 11-21-91			Tail Rotor Driveshaft Hanger Bearing P/N 204-040-623-003
205B-91-9	Basic	11-21-91			Tail Rotor Driveshaft Hanger Bearing P/N 204-040-623-003
205B-91-10	Basic	12-13-91			Swashplate Support P/N 204-011- 404-125
205B-92-11	Basic	2-6-92			Scissors Link to Swashplate Attachment Bolt, Inspection of
205B-92-12	Basic	5-6-92			Oil Level Indicators P/N 204-040- 508-005/-007/-013
205B-92-13	Basic	10-5-92			Tail Rotor Driveshaft Inspection of
205B-92-14	Basic	10-23-92			Main Rotor Yoke P/N 204-011- 102-All, Removal from Service
205B-93-15	Basic Rev A	2-1-93 6-1-93			Rotor Brake Quill P/N 205-040- 300-001 Removal from Service
205B-93-16	Basic	6-18-93			Lower Spider P/N 412-040-785- 101, Assignment of Retirement Life
205B-93-17	Basic Rev A	6-21-93 6-20-94			Cargo Hooks, Breeze Eastern Customer Advisory Bulletin No. CAB-100-41, Customer Service Bulletin No. CSB-129 and CSB- 142
2058-93-18	Basic Rev A	6-21-93 7-1-94			Tailboom Doubler P/N 212-030- 099-089/-129
205B-93-19	Basic Rev B	12-7-93 3-4-94			Tailrotor Drive System Grease Lubricated Couplings, Overtemperature Indicators, Installation of

205B ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
205B-94-20	Basic	11-28-94			Main Rotor Yoke P/N 212-011-102-105 Inspection of
205B-95-21	Basic	3-13-95			Introduction of New Scheduled Inspection and Conditional Inspection Requirements: Main Rotor Grip P/N 204-011-121-121 and P/N Grips With Modified Suffix Characters
205B-95-22	Basic Rev B	5-8-95 10-9-95			Tail Rotor Hanger Bearings P/N 204-040-623-003/-005, Application of Witness Mark
2058-95-23	Basic	6-5-95			Elbow P/N 212-076-146-001, Removal From Service
205B-95-24	Basic	6-30-95			Main Rotor Mast P/N 204-011-450-007/-105, and Main Rotor Trunnion 204-011-105-001, Charge of Retirement Life and Method of Determination (RIN)
205B-96-25	Basic	9-3-96			Tail Rotor Yoke P/N 212-011-702-All, Inspection of, and Tail Rotor Flapping Stop/ Yield Indicator P/N 212-011-713-103 Installation of
205B-98-26	Basic Rev A	2-27-98 9-21-98			Fin Spar Cap, Inspection of
205B-98-27	Basic	6-1-98			Tail Rotor Blade, Reduction in Service Life
205B-98-28	Basic Rev B	8-2-98 10-22-98			HR Textron Safety Bulletin, Inspection for Bogus Actuators
205B-99-29	Basic	1-8-99			High Landing Gear Aft Crosstube, Assignment of Retirement Life
205B-00-30	Basic Rev B	4-24-00 8-4-00			Main Rotor (M/R) Mast, P/N 204-011-450-007/-105, Inspection and Retirement Index Number (RIN) Life Reduction

BHT-205B-ASB INDEX

205B ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
205B-00-31	Basic Rev A	5-26-00 9-13-00			Tail Rotor Counterweight Bellcrank Retention Nut MS14145L6 and MS17826-6, Installation and One Time Use of
205B-00-32	Basic Rev A	8-1-00 9-9-02			Cargo Hook, Onboard Systems P/N 528-002-00
205B-00-33	Basic	10-19-00			Main Hydraulic Servo Actuator Rod End Lock Washer, Inspection and Replacement of
205B-00-34	Basic Rev D	11-10-00 3-18-05			Tail Rotor (T/R) Blade P/N 212-010-750-109/-111, Tip Block Retention Modification
205B-01-35	Basic	1-19-01			Magnetic Brake P/N 204-001-376-003, One Time Inspection of
205B-01-36	Basic	3-30-01			Chip Detector Assembly, Tedeco B3703
205B-01-37	Basic	3-19-01			Clutch Assembly P/N X134296, Assignment of Retirement Life
205B-01-38	Basic	7-26-01			Pillow Block P/N 204-011-108-113, Tube Assembly P/N 212-010-404-005, Inspection and Recall of Specific Serial Number Part
205B-02-39	Basic Rev B	5-3-02 11-22-02			Main Rotor Grips 204-011-121-005, -009, -113, -117 and -121, Ultrasonic, Inspection of
205B-02-40	Basic	6-20-02			1200 Hour Special Inspection Requirements for Main Rotor Hub Pins P/N 204-012-104-003/-005
205B-02-41	Basic	11-22-02			Tail Rotor Blade Assemblies P/N 212-010-750-117, Inspection and Rework of
205B-04-42	Basic	12-3-04			Tail Rotor Pitch Horn Assembly P/N 212-011-708-105, Replacement of
205B-05-43	Basic	2-18-05			Crosshead P/N 212-010-775-001, Inspection and Recall of Specific Serial Number Part

205B ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
205B-05-44	Basic	4-30-05			Tail Rotor Blade P/N 212-010-750-009 through -129, Inspection and Rework of
205B-07-45	Basic	3-6-07			Aeronautical Accessories, Inc. ASB No. AA-06107 for PC Safety Valve™: Valve Stem Over Torque
205B-07-46	Basic Rev A	9-11-07 9-19-07			Tail Rotor Blade Assembly, Inspection of
205B-07-47	Basic				Cyclic Flight Control Bearing, P/N MS27643-4 One Time Inspection and Replacement of

NOTICE

The following blank pages are provided for entry of additional bulletins when distributed. These additional bulletins will be included in this index at next revision.

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
---------------	--------------	-------------	---------------	--------------------------	----------------

BHT-205B-ASB INDEX

NOTICE

The following blank pages are provided for entry of additional bulletins when distributed. These additional bulletins will be included in this index at next revision.

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
--------	-------	------	--------	------------------	---------