



ALERT SERVICE BULLETIN INDEX

NOTE

THIS INDEX IS A LIST OF ALERT SERVICE BULLETINS ISSUED. THIS INDEX DOES NOT IDENTIFY WHICH ALERT BULLETINS ARE ACTIVE OR INACTIVE.

THE ATA/CHAP. REF. COLUMN INDICATES THE MAINTENANCE AND/OR OVERHAUL MANUAL CHAPTER/S AFFECTED BY THE RESPECTIVE BULLETIN; OR, THE BULLETIN IS APPLICABLE TO A SERVICE INSTRUCTION (S.I.).

PROPRIETARY RIGHTS NOTICE

These data are proprietary to Bell Helicopter Textron, Inc. Disclosure, reproduction, or use of these data for any purpose other than helicopter operation is forbidden without prior written authorization from Bell Helicopter Textron, Inc.

Newly released Alert Service Bulletins can be viewed and printed by accessing our Service Directives website at www.bellcustomer.com. This publication supersedes BHT-206L/L1/L3/L4-ASB INDEX dated 1 January 2007 in its entirety.

COPYRIGHT NOTICE
COPYRIGHT 2008
BELL © HELICOPTER TEXTRON INC.
AND BELL HELICOPTER TEXTRON
CANADA LTD.
ALL RIGHTS RESERVED

Bell Helicopter
A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

1 JANUARY 2008

206L/L1/L3/L4 ALERT SERVICE BULLETIN INDEX

STATUS CODE

A = Active

A- () = Active — (Additional Information)

└────────────────── P = Incorporated in Parts Catalog
R = Referenced in Maintenance Manual

I = Inactive

I- () = Inactive — (Reason)

└────────────────── I = Incorporated in Maintenance Manual
P = Incorporated in Parts Catalog
S = Superseded (New Bulletin Number)
R = Referenced in Maintenance Manual

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
206L-75-1	Basic	12-18-75		53	Inspection of Cabin Roof Beam
206L-75-2	Basic	12-23-75		28	Addition of a Back-Up Ring, P/N MS29513-325, On Fuel Interconnect Tube
206L-76-1	Basic	3-8-76		71	Temporary Change of Engine Shutdown Procedures
206L-76-2	Basic	4-2-76		28	Replacement of Fuel Valve, P/N 206-063-640-1, With Fuel Valve, P/N 206-063-640-3
206L-76-3	Basic	8-13-76		4	Reduction of Service Life, Tension/Torsion Straps, P/N 206-011-127-1
206L-76-4	Basic	7-23-76		66	Increase Service Life of T/R Gearbox Duplex Bearing, P/N 206-040-410-3
206L-76-5	Basic	8-13-76		5	Increase Inspection Interval of Transmission Sun Gear, P/N 206-040-122-5
206L-76-6	Basic	9-13-76		65	Inspection of Nuts, P/N F52NTE242, Used on M/R Blade Retention Bolts
206L-76-7	Basic Rev. A	10 -14-76 10-27-76		27	Flight Control System Hydraulic Reservoir, P/N 206-076-032-7

BHT-206L/L1/L3/L4-ASB INDEX**206L/L1/L3/L4 ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
206L-76-8	Basic Rev. A	11-1-76 12-15-76		28	Fuel Quantity Probes, P/N 206-063-657-3 and 204-063-658-3
206L-76-9	Basic	11-9-76		53	Installation of Improved Handling Qualities Kit, P/N 206-704-133-1
206L-76-10	Basic	12-10-76		53	Addition of Rivets In Splice Area Between Lower Aft Shell, P/N 206-033-099-1, and Lower Forward Shell, P/N 206-033-100-1, At Waterline 25.25 and Station 117.44 to 125.44 R/H and L/H Sides
206L-77-1	Basic	1-28-77		66	Inspection of Oil Cooler Blower Impeller, P/N 206-061-432-11
206L-77-2	Basic	2-22-77		28	Installation of Fuel Ejector Pump Filters, P/N 206-063-693-1
206L-77-3	Basic Rev. A	3-7-77 3-11-77		5	Increase Inspection Interval of Transmission Sun Gear, P/N 206-040-122-5
206L-77-4	Basic	3-22-77		S.I.	Rotor Brake Kit- Replacement of Lining Retention Screws in Kit, P/N 206-706-042-1
206L-77-5	Basic	3-25-77		28	Inspection of Fuel Transfer Check Valves, P/N 206-063-687-3
206L-77-6	Basic	4-6-77		4	Reduction of Calendar Life, Tension/Torsion Straps, P/N 206-011-127-1
206L-77-7	Basic	4-22-77		S.I.	Emergency Floatation Kit Inflation System Squib Valve Assy, P/N 206-073-915-1
206L-77-8	Basic	5-25-77		66	Increase Service Life of T/R Gearbox Duplex Bearings, P/N 206-040-410-3
206L-77-9	Basic	6-20-77		71	N2 Operating Speed Restriction
206L-77-10	Basic	10-20-77		66	Inspection of Oil Cooler Blower Impeller, P/N 206-061-432-11

206L/L1/L3/L4 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
206L-77-11	Basic	10-24-77		4	Retirement Time and Calendar Life, Tension/Torsion Straps, P/N 206-011-127-1 and 206-011-147-3
206L-77-12	Basic Rev. A	12-8-77 2-21-78		66	Replacement of Oil Cooler Blower Impeller, P/N 206-061-432-11, With Impeller, P/N 206-061-432-31
206L-78-1	Basic	4-14-78		4	M/R Hub Tension/Torsion Straps, P/N 206-011-127-1, Retirement Life of
206L-78-2	Basic	7-21-78		65	Latch Bolt, P/N 206-011-122-1 and -3, Retirement Life of
206L-78-3	Basic	10-23-78		53	Horizontal Stabilizer, P/N 206-023-119, Inspection of
206L-78-4	Basic	12-18-78		66	Freewheeling Outer Race Shaft, P/N 206-040-221-3, Inspection of
206L-79-5	Basic	4-3-79		4	Main Rotor Yoke, P/N 206-011-101-001 and -005, Retirement life of
206L-79-6	Basic	5-23-79		97	VOR Antenna, P/N CI-159 and CI-159A
206L-79-7	Basic	10-25-79		28	Replacement of Fuel Feed Tube Assembly, Union to Firewall, P/N 206-063-666-001, and Fuel Vent Tube Assy Tee to Union, Outboard, P/N 206-063-668-001
206L-80-8	Basic Rev. A	2-22-80 6-3-80		65	Tail Rotor Blade, P/N 206-010-750-005 and -007, Inspection and Retirement of
206L-80-9	Basic Rev. C	2-26-80 8-10-01		65	Main Rotor Trunnion, P/N 206-011-120-001, Magnetic Particle Inspection Requirements and Replacement of
206L-80-10	Basic	4-11-80		27	Anti-Torque Control System Rigging Procedures

BHT-206L/L1/L3/L4-ASB INDEX**206L/L1/L3/L4 ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
206L-80-11	Basic	5-1-80		4	Main Rotor Yoke, P/N 206-011-101-001 and -005, Retirement Life of
206L-80-12	Basic	6-2-80		4	Addition of Calendar Life Retirement on TT straps, P/N 206-011-147-003, and P/N 206-011-147-007
206L-80-13	Basic	6-17-80		71	Engine Fuel Filter, Associated Fuel Hoses and Freewheeling Oil Hose, Modification of
206L-80-14	Basic	6-27-80		S.I.	External Hoist Kit, P/N 206-899-861, Mod and Inspection of (Inspect and Modify as Described in the Attached Breeze Corporation Bulletin, No. BEB162-8.)
206L-80-15	Basic	7-29-80		4	Reduction of Service Life of Main Rotor Grips, P/N 206-011-132-009 (Selected Serial Numbers)
206L-80-16	Basic	11-17-80		53	Horizontal Stabilizer Assembly, P/N 206-023-119 (All Dash Numbers), Inspection of
206L-81-17	Basic	2-3-81		66	Zinc Chromate Primer, Thermal Indicator, Addition of
206L-81-18	Basic Rev. A	2-20-81 3-19-81		96	Battery Relay Diode Assembly, P/N 30-037-13, Replacement of
206L-81-19	Basic	2-24-81		71	Hose Assembly, Freewheeling Aft Oil Vent, P/N 124F001ABB0311SS, Replacement of
206L-81-20	Basic Rev. B	4-24-81 3-10-82		96	Engine Starter, and Electrical Cables, Replacement of
206L-81-21	Basic	5-7-81		S.I.	Emergency Floatation Equipment Kit, P/N 206-706-067-1, -3, -5, -101, and 206-706-210-101 and -103, Inspection of the Valve Assembly, P/N 206-073-915-5

206L/L1/L3/L4 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
206L-81-22	Basic	8-10-81		71	Engine, Allison 250-C20/C20B, N1 and N2 Operation Speed Restrictions
206L-81-23	Basic Rev. A	7-10-81 10-23-81		53	Horizontal Stabilizer Assembly, Modification or Retirement of
206L-81-24	Basic	9-11-81		76	250-C28B Engine (Electronic) N2 Overspeed Control System, Disarmed
206L-81-25	Basic	10-12-81		S.I.	Rescue Hoist Provisions and Hoist Installation, P/N 206-899-861-101, Addition of Electrical Ground to Hoist Assembly
206L-82-26	Basic	5-19-82		65	Tail Rotor Blade, P/N 206-016-201-001, Check and Repair of
206L-82-27	Basic	7-19-82		28	Fuel Shutoff Valve, Provision for Thermal Relief
206L-82-28	Basic	11-15-82		66	Tail Rotor Gearbox, P/N 206-040-402-003, Inspection of
206L-83-29	Basic Rev. A	8-30-83 -		S.I.	Rescue Hoist Installation, P/N 206-899-861-101, Hoist, P/N BL-16600 All Dash Numbers, Conversion and Inspection of
206L-83-30	Basic Rev. A	12-22-83 2-29-84		66	Mast Assembly, Main Rotor, P/N 206-040-535, Inspection and Processing of
206L-84-31	Basic	1-4-84		28	Fuel Supply Tube Assembly, P/N 206-061-454-101, Replacement of
206L-84-32	Basic	8-30-84		S.I.	Reservoir, Emergency Flotation, P/N 1269556-4, Installation of Decal (WARNING), P/N 31-023-8B, and Decal (CAUTION), P/N 31-023-9B, On
206L-85-33	Basic Rev. A	2-13-85 3-15-85		S.I.	Quick Disconnect Dual Controls, P/N 206-706-127-5 and -103, Installation of Spring Pin Assembly

BHT-206L/L1/L3/L4-ASB INDEX**206L/L1/L3/L4 ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
206L-85-34	Basic Rev. B	3-7-85 6-21-85		65	Tail Rotor Blade, P/N 206-016-201-001/-107, Check and Rivet Replacement
206L-85-35	Basic Rev. A	2-26-85 4-18-85		65	Main Rotor Blade, P/N 206-015-001-001, -103, Inboard Trim Tab, P/N 206-015-516-101, Removal, Blade Inspection and Repair
206L-85-36	Basic	6-21-85		27	Cyclic Control Stick Assembly, P/N 206-001-344-001 and -101, Inspection of
206L-85-37	Basic Rev. B	9-30-85 10-13-86		S.I.	Rescue Hoist Installation, Conversion of Hoist, P/N BL-16600-80, to P/N BL-16600-110
206L-85-38	Basic	11-25-85		71	Engine, Turbine Assembly, Turbine to Compressor Coupling Shaft, Replace
206L-86-39	Basic	6-23-86		71	Engine, Turbine Assembly, Installation of No. 8 Bearing Scavenge Line Air/Oil Separator Assembly
206L-86-40	Basic	8-13-86		66	Oil Cooler Blower Impeller, P/N 206-061-432-031, Inspection of
206L-86-41	Basic	9-30-86		28	Airframe Fuel Filter Assembly P/N 222-336-621-003, Modification of
206L-86-42	Basic Rev. A	12-2-86 1-9-87		28	Fuel Boost Pump Retainer, P/N 206-064-621-101, Modification of
206L-87-43	Basic	1-19-87		S.I.	Reservoir Assemblies, P/N 206-073-800-001/-003, 206-073-839-001/-101/-105, and 206-073-848-101/-107/-111, Valve Assembly, P/N 206-073-915-005/-101, Cap Replacement
206L-87-44	Basic	4-23-87		66	Main Rotor Mast, P/N 206-040-535-105, Return for Metallurgical Evaluation

206L/L1/L3/L4 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
206L-87-45	Basic	5-26-87		53	Wire Strike Protection System, Inspection and Rework of
206L-87-46	Basic	6-18-87		S.I.	Rescue Hoist Cable Cutter Circuit, Rewiring of, in Accordance with Breeze Manufacturing Preferred Method
206L-87-47	Basic Rev. C	8-12-87 10-23-89		53	Tailboom, P/N 206-033-004-All, Inspection of
206L-87-48	Basic	9-17-87		65	Tail Rotor Pitch Link(s), P/N 206-010-793-101 and P/N 206-010-792-105, Inspection of
206L-87-49	Basic	10-8-87		28	Engine Fuel Valve Electrical Connector, P/N MS3456W14S-5S, One Time Inspection of
206L-88-50	Basic	1-18-88		96	Battery Relay Bus Bar, P/N 206-075-689-101, Inspection and Relocation of
206L-88-51	Basic	1-18-88		65	Tail Rotor Yoke, P/N 206-011-819-101, Inspection and Rework
206L-88-52	Basic	6-10-88		28	Fuel System Flow Switches, P/N 206-063-635-001, 206-064-601-001, -003, -101 and -103, Replacement of
206L-88-53	Basic	7-18-88		28	Low Fuel Warning Switch, P/N 206-063-613-003, Installation of
206L-88-54	Basic Rev. A	7-18-88 9-16-88		48	RPM Warning Horn Muting System, Installation of
206L-88-55	Basic Rev. A	7-26-88 8-26-88		S.I.	External Hoist, P/N BL-16600-(All Dash Numbers), Inspection of Load Cable and Hook/Bumper Stowage
206L-89-56	Basic Rev. B	1-10-89 11-21-89		79	Aeroquip 601 Hose Assemblies, One-Time Inspection and Replacement
206L-89-57	Basic	3-21-89		71	Pc Air Filter Housing Assembly, Replacement of

BHT-206L/L1/L3/L4-ASB INDEX**206L/L1/L3/L4 ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
206L-89-58	Basic Rev. B	4-12-89 7-28-92		71	Bendix Power Turbine Governor Py Port, Inspection of
206L-89-59	Basic Rev. A	8-2-89 8-29-89		65	Tail Rotor Hub Assembly P/N 206- 011-810-015 and Tail Rotor Yoke P/N 206-011-811-009, Removal From Service
206L-89-60	Basic	8-29-89		65	Strap Assembly, Main Rotor Tension/ Torsion P/N 206-011-147- 7, Removal From Service
206L-89-61	Basic Rev. A	9-21-89 11-30-89		65	Main Rotor Flight Control System Bolts, Inspection of
206L-89-62	Basic	10-6-89		53	Horizontal Stabilizer Assembly P/N 206-023-119-All, Inspection For Conformity
206L-89-63	Basic	10-10-89		S.I.	Emergency Float Bag Inflation Valve Restrictors-Installation of, (Service Instruction 206-2033)
206L-89-64	Basic Rev. A	10-25-89 11-29-89		65	Main Rotor Blade P/N 206-015- 001-001/-103/-105, Removal From Service
206L-89-65	Basic	10-25-89		S.I.	Breeze-Eastern Cargo Hooks P/N 17149-2, Warning Plate, Addition of
206L-90-66	Basic	5-15-90		97	VOR Antenna P/N CI-259D Coded D/M 8930 to D/M 9015 Inclusive
206L-90-67	Basic Rev. A	5-31-90 8-5-91		98	Fuel Valve Switch Guard, Installation of
206L-90-68	Basic Rev. A	6-12-90 7-16-90		71	Turbine Spline Adapter, Replacement of
206L-90-69	Basic Rev. A	6-21-90 1-15-91		66	Sungear P/N 206-040-662-101, of by Serial Number
206L-90-70	Basic	6-27-90		65	Tail Rotor Blade P/N 206-016-201- 113 and 206-016-201-127, Inspection of
206L-90-71	Basic Rev. A	9-18-90 10-31-90		65	Tail Rotor Blade 206-016-201-127, Removal From Service

206L/L1/L3/L4 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
206L-91-72	Basic	1-30-91		66	Bearing Hanger, 206-040-346 One Time Inspection
206L-91-73	Basic	9-10-91		25	Shoulder Harness Inertia Reel Support, Replacement of
206L-91-74	Basic	9-13-91		66	Driveshaft Seal Assembly 206-040-272-101, Replacement of
206L-91-75	Basic	9-19-91		25	Restraint Assembly 222-320-823-109, -113, Improvement of
206L-91-76	Basic Rev. A	10-10-91 10-31-91		76	Possible Incorrect Max Fuel Flow Setting on Certain Bendix Fuel Controls
206L-91-77	Basic	11-12-91		27	Collective Bellcrank Support 206-001-555-001, One Time Inspection and Rework
206L-91-78	Basic	11-26-91		71	Engine Bleed Valve, Removal From Service
206L-92-79	Basic	5-5-92			Main Rotor Pillow Block Retention Hardware, Replacement of Bolt MS21250-04018.
206L-92-80	Basic	5-7-92			Tail Rotor Gearbox Oil Level Indicators 204-040-508-011
206L-92-81	Basic	6-22-92			Engine Pan Drain, One-Time Inspection For Obstruction
206L-92-82	Basic Rev. A	7-31-92 8-6-92			Allison 250C30, Fuel Control
206L-92-83	Basic	8-5-92			Flap Restraint 206-011-117-003
206L-92-84	Rev. A	2-27-95			Bracket, Bearing Support 206-033-412-001/-003/-005/-007 and -009, One Time Inspection
206L-92-85	Basic	11-12-92			206L Series External Hoist Kit, P/N 206-899-861 (All Dash Numbers) Inspection of
206L-92-86	Basic	12-3-92			Main Rotor Latch Bolt 206-011-260-101, Removal of Unapproved Bolts From Service

BHT-206L/L1/L3/L4-ASB INDEX

206L/L1/L3/L4 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
206L-92-87	Basic	1-8-93			Allison 250-C28/C30 Engine Fuel Controls
206L-93-88	Basic Rev. A	6-21-93 6-20-94			Cargo Hooks, Breeze Eastern Customer Advisory Bulletin No. CAB-100-41 and Customer Service Bulletin No. CSB-146.
206L-93-89	Basic Rev. B	9-7-93 4-4-94			Swashplate Support Assembly, Inspection of
206L-93-90	Basic Rev. A	10-19-93 11-9-93			Trunnion 206-011-120-103 Master Spline Mislocation of
206L-93-91	Basic Rev. B	12-7-93 12-30-94			Main Driveshaft Outer Coupling Indicators, Installation of
206L-93-92	Basic	11-17-93			Main Rotor Blade 206-015-001-107, Inspection and Rework
206L-94-93	Basic	4-4-94			Landing Gear Assembly Improvement; Crosstube Assemblies, P/N 206-053-109-all Dash Numbers (High Skid Landing Gear Kit and Emergency Lightweight Float Kit) and P/N 206-053-119-all Dash Numbers (Standard Landing Gear), Replacement of
206L-94-94	Basic Rev. A	4-27-94 7-11-94			Turbine Outlet Temperature Indicator, Replacement of Kratos Indicators P/N 124.444-6 and 124.444-20 With Indicators 206-075-680-105 Or 206-375-006-101
206L-94-95	Basic	5-5-94			Tail Rotor Pitch Horn 206-011-809-107/-109, Looseness Check of
206L-94-96	Basic Rev. A	8-15-94 9-26-94			Transmission Restraint Assembly 206-033-506-103, Configuration For Use In Prior 206L Series
206L-94-97	Basic	8-17-94			Landing Gear Assembly Improvement; Fixed Floats Kit P/N 206-706-065, Crosstube Assemblies, P/N 206-050-169-013 and -011, Replacement Of

206L/L1/L3/L4 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
206L-94-98	Basic	9-26-94			Landing Gear Assembly Improvement; Emergency Float System Kit P/N 206-706-067, Crosstube Assemblies P/N 206-053-129-009, -011, -101 and -103, Replacement of
206L-94-99	Basic Rev. B	9-19-94 10-8-01			Trunnion 206-011-120-103, and Mast 206-040-535-001/-005/-101/-105, Assignment of Retirement Index Number (RIN) To
206L-95-100	Basic	9-5-95			Main Drive Shaft 206-040-015-011/-015 Inner Coupling to Shaft Attachment Hardware, One Time Inspection of
206L-95-101	Basic Rev. B	9-11-95 12-18-95			Tail Rotor Driveshaft Hanger of
206L-95-102	Basic	12-26-95			Allison 240-C28 Series, Turbine Wheel
206L-96-103	Basic Rev. A	2-12-96 3-25-96			Fuel Pump Seal and Starter Generator Seal Drain Tubes P/N 206-064-228-001 and 206-064-229-001, Modification of
206L-96-104	Basic Rev. B	8-19-96 7-24-98			Tail Rotor Yoke Assembly P/N and Stop P/N 206-011-752-101 Installation of
206L-96-105	Basic	12-2-96			Tailboom Horizontal Stabilizer Lower Supports 206-023-100-109/-110, Modification of
206L-96-106	Basic	12-11-96			Transmission Main Case Assembly P/N 206-040-530-101 Oil Transfer Passage, Inspection of
206L-97-107	Basic Rev. A	9-4-97 2-4-98			Tailboom, Modification of, Inspection of
206L-97-108	Basic	6-20-97			Main Rotor Hub Pillow Block, Change in Retention Hardware

BHT-206L/L1/L3/L4-ASB INDEX**206L/L1/L3/L4 ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
206L-97-109	Basic	10-10-97			Engine Driven Fuel Pump (CECO), Internal Drive Spline, Inspection of
206L-98-110	Basic	5-6-98			Collective Idler Link, Modification of Limitations Schedule
206L-98-111	Basic	7-24-98			Replacement of Hydraulic Relief Valve
206L-98-112	Basic Rev. A	10-14-98 10-10-02			Engine Fuel Control, Internal Spring Replacement
206L-98-113	Basic	11-18-98			Main Rotor Blades, P/N 206-015-001-107, -109, -111 and -113, Delamination of Tip Cap Assembly, Replacement of
206L-98-114	Basic Rev. B	11-25-98 12-6-00			Tailboom, Inspection of Horizontal Stabilizer for Cracks
206L-99-115	Basic Rev. F	5-21-99 4-14-01			Tailbooms 206-033-004-ALL, Inspection and Modification Of
206L-00-116	Basic	3-30-00			Collective Lever Assembly 206-010-467-001, Modification and New Collective Lever Assembly/-105, Introduction of
206L-00-117	Basic	10-30-00			Rolls-Royce 250-C30P Engine, Replacement of Compressor Scroll 23066737 and 23072848
206L-01-118	Basic	3-6-01			Rescue Hoist, BL-16600 Series, Breeze Eastern Customer Alert Bulletin CAB-100-58
206L-01-119	Basic Rev. A	3-30-01 5-7-01			Chip Detector Assembly, Tedeco B4093 and B3188B
206L-01-120	Basic	7-26-01			Tail Rotor Output Shaft 206-040-949-101 by Serial Number Recall of
206L-01-121	Basic	9-17-01			Rolls Royce Engine, Turbine Assembly - Third Stage Turbine Wheels with Limited Life

206L/L1/L3/L4 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
206L-01-122	Basic	10-3-01			Magnetic Brake P/N 204-001-376-003 - One Time Inspection of
206L-01-123	Basic Rev. A	10-12-01 2-22-06			Engine-To-Transmission Driveshaft 206-340-003-105, Inspection of
206L-01-124	Basic	10-11-01			Rolls Royce Engine, Gearbox Assembly - Inspection of Helical Torquemeter Gearshaft Assembly
206L-03-125	Basic	1-21-03			Main Rotor Blades 206-015-001-ALL, Inspection and Rework of
206L-03-126	Basic	11-21-03			Rolls-Royce 250-C30 Engine, Turbine Assembly – Inspection of 4th Stage Turbine Wheels (23066744)
206L-04-127	Basic Rev. C	13-12-04 3-5-05			Tail Rotor Blades 206-016-201-131, Check/Inspection of
206L-04-128	Basic	5-17-04			Engine, Turbine Assembly — Third Stage Turbine Wheel Replacement, Specific Serial Numbers
206L-04-129	Basic Rev. A	7-19-04 12-1-04			Freewheel Aft Bearing Cap 406-040-509-101, Inspection and Recall of
206L-04-130	Basic	7-26-04			Power Turbine RPM (N ₂) Steady State Operation Avoidance, Introduction of
206L-04-131	Basic	9-13-04			Tail Rotor Blade 206-016-201-131, Check and Removal from Service of
206L-04-132	Basic Rev. A	9-2-04 4-10-04			Low Level Detector Switch Unit P/N 206-063-613-003, Removal from Service of
206L-05-133	Basic	5-17-05			Torque Indicator, P/N 206-075-739-123, Recall of

BHT-206L/L1/L3/L4-ASB INDEX**206L/L1/L3/L4 ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
206L-05-134	Basic Rev. A	6-8-05 4-9-07			New Transient Limit and Power Turbine RPM (N _P) Steady State Operation Avoidance, Introduction of
206L-05-135	Basic	6-30-05			Rolls-Royce 250-C30P Engine Gearbox Assembly — Inspection and Rework of Gearbox Housing
206L-05-136	Basic Rev. A	10-17-05 11-10-05			Clevis Assembly — Hydraulic Servo Assembly, Part Number 41001520
206L-05-137	Basic	11-8-05			Tail Rotor Trunnion Housing Seal 535642 Installation, One Time Inspection of
206L-06-138	Basic	2-17-06			Float Inflation Valve Squib P/N 29022968, Misidentification of
206L-06-139	Basic	7-8-06			Aeronautical Accessories, Inc. Flat Crew Window P/N 206-202-103 and 206-202-104, STC SH5773SW
206L-06-140	Basic	9-7-06			Upper Left-hand Tailboom Attachment Hardware, Inspection of
206L-06-141	Basic	9-12-06			Horizontal Stabilizer 206-023-119-167, Inspection and Replacement of
206L-06-142	Basic	10-12-06			Engine, Turbine Assembly — Power Turbine Outer Shaft
206L-07-143	Basic	3-9-07			Aeronautical Accessories, Inc. PC Safety Valve™ Stem Over Torque STC SE00057AT
206L-07-144	Basic	3-23-07			Cargo Hook Stress Corrosion Cracks
206L-07-145	Basic	3-28-07			Disc Assembly P/N 32721-1, Inspection of
206L-07-146	Basic	5-21-07			Power Turbine RPM (N ₂) Steady State Operation Avoidance, Introduction of

206L/L1/L3/L4 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
206L-07-147	Basic	7-19-07			Freewheel Aft Seal P/N 209-340-265-103 Installation Procedures, Improvement of
206L-07-148	Basic	9-11-07			Tail Rotor Blade Assembly, Inspection of
	Rev. A	9-19-07			

NOTICE

The following blank pages are provided for entry of additional bulletins when distributed. These additional bulletins will be included in this index at next revision.

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
---------------	--------------	-------------	---------------	--------------------------	----------------

BHT-206L/L1/L3/L4-ASB INDEX

NOTICE

The following blank pages are provided for entry of additional bulletins when distributed. These additional bulletins will be included in this index at next revision.

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
--------	-------	------	--------	------------------	---------