



ALERT SERVICE BULLETIN INDEX

NOTE

THIS INDEX IS A LIST OF ALERT SERVICE BULLETINS ISSUED. THIS INDEX DOES NOT IDENTIFY WHICH ALERT BULLETINS ARE ACTIVE OR INACTIVE.

THE ATA/CHAP. REF. COLUMN INDICATES THE MAINTENANCE AND/OR OVERHAUL MANUAL CHAPTER/S AFFECTED BY THE RESPECTIVE BULLETIN; OR, THE BULLETIN IS APPLICABLE TO A SERVICE INSTRUCTION (S.I.).

PROPRIETARY RIGHTS NOTICE

These data are proprietary to Bell Helicopter Textron, Inc. Disclosure, reproduction, or use of these data for any purpose other than helicopter operation is forbidden without prior written authorization from Bell Helicopter Textron, Inc.

Newly released Alert Service Bulletins can be viewed and printed by accessing our Service Directives website at www.bellcustomer.com. This publication supersedes BHT-212-ASB INDEX dated 1 January 2007 in its entirety.

COPYRIGHT NOTICE
COPYRIGHT 2008
BELL® HELICOPTER TEXTRON INC.
AND BELL HELICOPTER TEXTRON
CANADA LTD.
ALL RIGHTS RESERVED

Bell Helicopter
A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

1 JANUARY 2008

212 ALERT SERVICE BULLETIN INDEX

STATUS CODE

A = Active

A - () = Active — (Additional Information)

└────────────────── P = Incorporated in Parts Catalog
R = Referenced in Maintenance Manual

I = Inactive

I - () = Inactive — (Reason)

└────────────────── I = Incorporated in Maintenance Manual
P = Incorporated in Parts Catalog
S = Superseded (New Bulletin Number)
R = Referenced in Maintenance Manual

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
212-1	Basic	8-3-71	I	63	One-Time Inspection of Transmission Oil Cooler Flex Hose, P/N 71-01OK000T334 and P/N 70-010K000A320
212-2	Basic	8-9-71	I	64	Modification of Tail Rotor Pitch Horn, P/N 212-010-716-5
212-3	Basic	9-20-71	I - (P)	63	Shield, P/N 212-062-015-1, Installation of
212-4	Basic	11-29-71	I	53	Inspection of Model 212 Lift Beam Assembly, P/N 205-030-845-255
212-5	Basic	11-4-71	I - (S)	64	Inspection, Replacement, and Installation of Tail Rotor Pitch Change Shaft Bearing, P/N 212-010-762-1
212-6	Basic Rev. A	1-26-72 2-8-72	I	71	Oil Cooler Fan Blower, P/N 209-062-502-7, Shear Pin Replacement Procedure
212-7	Basic	3-15-72	I - (I)	4	Assignment of 100-Hour Retirement Life for Stabilizer Bar Mixing Lever Bearings, P/N KP6A and Scissors Assembly Pivot Bearings, P/N KP8A

BHT-212-ASB INDEX

212 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
212-8	NEVER ISSUED				
212-9	Basic	9-18-72	I	53	Installation of Kit, P/N 212-704-077-1, for Modification of Engine Mount Beam Panels, P/N 212-030-169 and 212-030-719, at Station 172.0
212-10	Basic	10-23-72	I	96	Functional Test of Model 212 D.C. Electrical Power Generating System
212-11	Basic	12-4-72	I - (I)	63	Retorque of Engine to Driveshaft Adapter Nut, P/N 212-040-631-1
212-01-73-1	Basic Rev. B	5-18-73 10-9-73	I - (P)	53	Inspection and Modification/Repair of Model 212 Tailboom, P/N 212-030-100 (All Dash Numbers)
212-01-73-2	Basic	10-8-73	I - (S)	53	Inspection of Synchronized Elevators, P/N 205-030-856 (All Dash Numbers)
212-03-73-1	Basic	6-11-73	I - (S)	53	Installation of Improved Engine Oil Cooler Cowl Latches
212-03-73-2	Basic	11-5-73	I - (S)	96	Inspection of Electrical Terminal Block on Starter/Generator
212-04-73-1	Basic	12-10-73	I - (S)	63	Installation of Transmission Internal Oil Filter Gaskets, P/N 205-040-187-1 and -3
212-04-73-2	Basic Rev. A	11-13-73 11-5-75	I	63	Grease, P/N 204-040-755-3, Dated After July, 1973
212-(04-1)-73-1	Basic	8-3-73	I - (S)	62	Inspection of Main Rotor Blades, P/N 204-011-250 (All Dash Numbers)
212-(04-2)-73-1	Basic Rev. A	6-21-73 9-18-73	I - (R)	62	Inspection of 204-011-451-1 Trunnion Bearings Installed In the Swashplate Rotating Ring Assembly, P/N 204-011-403-1
212-(04-2)-73-2	Basic	8-21-73	I - (R)	62	Inspection of the Swashplate and Support Assy, P/N 204-010-400

212 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
212-05-73-1	Basic Rev. A	4-13-73 6-15-73	I - (R)	64	Increased Torque Value on Tail Rotor Retaining Nut, P/N 212-010-706-1
212-05-73-2	Basic	5-30-73	I - (R)	64	Inspection, Replacement, and Installation of Tail Rotor Pitch Change Shaft Bearing, P/N 212-010-762-1
212-05-73-3	Basic	5-31-73	I	64	Modification to Marvel Model 7HEL075 Kit - Tail Rotor Balancing and a One-Time Tail Rotor Balancing and Track Inspection Requirement
212-05-73-4	Basic	8-20-73	I	64	Inspection of Tail Rotor Hub Assembly, P/N 212-010-701
212-05-73-5	Basic Rev. C	12-6-73 3-21-74	I	64	Inspection of Tail Rotor Hub Assembly P/N 212-010-701-3
212-10-73-1	Basic Rev. A	6-28-73 7-24-73	I - (R)	28	Removal of Fuel Filter Screen from Fitting, P/N S2490
212-11-73-1	Basic	10-17-73	I - (R)	67	Inspection of the Anti-Torque Control Tubes, P/N's 212-001-053-5, 212-001-052-1, and 212-001-055-1
212-11-73-2	Basic	12-3-73	I	67	Modification of the Lateral Cyclic Control Bellcrank, P/N 212-001-070-3, Installed in (FAA) I.F.R. Configured Helicopters
212-01-74-1	Basic	1-11-74	I	53	Sealing of Left Hand, Aft Fuel Cell Bulkhead Panel Assembly P/N 205-030-401
212-01-74-2	Basic Rev. B	3-27-74 12-17-74	I	53	Inspection, Repair, and Modification of Synchronized Elevators, P/N 205-030-856-49 and -51
212-01-74-3	Basic	10-7-74	I - (P)	53	One Time Inspection of Upper Right Hand Tail Boom Attachment Bolt, P/N NAS628-26

BHT-212-ASB INDEX

212 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	SUBJECT
				REF.	
212-03-74-1	Basic	2-12-74	I - (R)	96	Repositioning Electrical Terminal Block on Starter/Generator
212-03-74-2	Basic Rev. A	3-26-74 3-29-74	I	71	Installation of Improved Engine Oil Cooler Cowl Latches
212-03-74-3	Basic	11-14-74	I	71	Replacement of Engine Cowl Latches
212-03-74-4	Basic	11-27-74	I	71	Inspection of Engine Chip Detectors (Canceled. Perform Inspection Per U.A.C.L. Inspection Letter dtd 2 December 1974.)
212-04-74-1	Basic	2-19-74	I	63	Inspection of Main Driveshaft Boot, P/N 212-040-176-3
212-04-74-2	Basic Rev. B	3-22-74 5-21-75	I - (R/P)	63	Modification of Transmission Oil System
212-(04-2)-74-1	Basic	2-20-74	I	62	One Time Inspection of Scissors and Sleeve Assemblies P/N 204-011-401-17 and -19
212-(04-2)-74-2	Basic	9-3-74	I	62	Inspection of Swashplate Scissors Lever Bolts, P/N NAS464-P8-90 or P/N 212-010-411-1
212-05-74-1	Basic	11-11-74	I - (R)	64	Inspection of Tail Rotor Assembly, P/N 212-010-701 (All Dash Numbers), for Interference
212-08-74-1	Basic Rev. A	10-11-74 10-16-74	I - (P)	95	Replacement of Airspeed Indicators
212-12-74-1	Basic	8-29-74	I - (R)	5	100 Hour Inspection of Bleed Air Shutoff Valve, P/N 209-072-433-1
212-75-1	Basic	2-19-75	I - (S)	63	Inspection of Transmission Shaft Adapter Nut, P/N 212-040-631-1
212-75-2	Basic	3-14-75	I	52	One Time Inspection of Emergency Exit Decals and Betalight Emergency Exit Signs
212-75-3	Basic	3-27-75	I - (R)	S.I.	Internal Rescue Hoist Assembly, P/N 205-706-030-5, -15, or -21

212 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
212-75-4	Basic	4-14-75	I	S.I.	Manual Actuation of Emergency Flotation Valve, P/N 212-073-921-1
212-75-5	Basic	4-17-75	I - (R)	63	Inspection of Transmission Oil System
212-75-6	Basic Rev. C	9-12-75 4-25-79	I - (R)	62	Inspection, Sealing, and Refinishing of Main Rotor Blade, P/N 204-012-001 (All Dash Numbers) and P/N 212-015-501-5
212-75-7	Basic Rev. A	8-8-75 8-22-75	I - (S)	52	Replacement of Emergency Exit Decals and Escape Release Handle Covers
212-75-8	Basic Rev. A	8-18-75 10-7-75	I - (R)	67	Revised Tail Rotor Rigging Dimensions
212-75-9	Basic Rev. A	12-17-75 1-22-76	I	S.I.	Modification of Internal Rescue Hoist Assembly, P/N 205-706-030-21
212-76-1	Basic Rev. A	1-14-76 8-13-76	I - (S)	S.I.	Replacement of Emergency Flotation Inflation Equipment Aluminum Parts With Steel Parts
212-76-2	Basic	2-17-76	I - (R)	62	One Time Inspection of Main Rotor Blade Bolt Washer, P/N 204-011-152-1
212-76-3	Basic	3-5-76	I - (S)	4	A. Assignment of 500 Hour Service Life to Float Gear Crosstubes, P/N 205-050-114-1, -3, -5, -7, and -9, and Crosstube Assemblies, P/N 205-706-050-5 and -9 B. Removal From Service of Damper Assemblies, P/N 205-050-127-3 and -5 (Manufactured by Frisby)
212-76-4	Basic	3-17-76	I - (R)	5	Inspection of Stabilizer Bar Outer Tube, P/N 204-011-328-1/-11
212-76-5	Basic	5-17-76	I - (R)	4	Stabilizer Bar Tube Assembly, P/N 204-011-328-1

BHT-212-ASB INDEX**212 ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
212-76-6	Basic Rev. B	9-10-76 9-25-78	I - (R)	5	Flight Control Tubes and Bellcranks
212-76-7	Basic	9-10-76	I	29	Hydraulic Actuator, P/N 212-076-005-7, Moisture Seal Installation
212-76-8	Basic	9-16-76	I - (R)	4	Swashplate Support Assembly, P/N 204-011-404-9
212-76-9	Basic	9-29-76	I - (R)	52	Inspection and Adjustment of Latch System, Passenger Door Emergency Escape Panels
212-76-10	Basic Rev. B	9-29-76 12-9-76	I - (P)	62	Replacement of NAS Rotating Control Bolts With Bell Standard Bolts
212-76-11	Basic	10-11-76	I - (R)	4	Replacement of Tail Rotor Hanger Bearings, P/N 204-040-623-1, With P/N 204-040-623-5
212-76-12	Basic	10-28-76	I - (S)	5	Assignment of a 1000 Hours Overhaul Period to Rotor Brake Quill, P/N 205-040-300-1
212-76-13	Basic	11-10-76	I	28	One-Time Inspection of Fuel Boost Pumps, P/N 205-060-606-3 and -7
212-76-14	Basic Rev. A	11-19-76 12-1-76	I - (R)	62	Installation of Main Rotor Blade Inspection System Kit, P/N 212-704-116-1, on Main Rotor Blade, P/N 204-012-001-23
212-76-15	Basic Rev. A	12-2-76 1-10-77	I - (S)	63	Replacement of the Coupling Seals on the Main Driveshaft Assembly, P/N 212-040-005-11
212-76-16	Basic	12-8-76	I	63	Inspection of Transmission to Engine Driveshaft Adapter Nut, P/N 212-040-631-1
212-76-17	Basic	12-10-76	I - (S)	67	Installation of Cyclic SCAS Stops, P/N 212-001-190-7 and -8
212-76-18	Basic	12-22-76	I - (S)	62	Inspection of Steel Grip Pads on Main Rotor Blade, P/N 204-012-001 (All Dash Numbers)

212 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
212-76-19	Basic	12-22-76	I - (P)	63	Replacement of Transmission Accessory and Tail Rotor Drive Pinion Gear, P/N 212-040-202-1, With New Gear, P/N 212-040-202-3
212-77-1	Basic Rev. A	1-10-77 2-1-77	I - (S)	5	1000 Hour Special Insp. Requirements For Main Rotor Hub Fitting Assys, P/N 212-010-103-5, Pins, P/N 204-012-104-5, and Strap Assemblies
212-77-2	Basic	1-28-77	I - (S)	65	Model 212 Main Rotor Blades, P/N 204-012-001-23 and -29
212-77-3	Basic	2-4-77	I	S.I.	Installation of Cyclic SCAS Stops, P/N 212-001-190-7 and -8
212-77-4	Basic	2-16-77	I - (S)	4	Assignment of 600 Hr Service Life to the Rotor Brake Quill Bearings, P/N 204-040-424-1
212-77-5	Basic	3-8-77	A	71	Inspection of Engine Mount Bearing Assembly, P/N 212-061-101-1
212-77-6	Basic	3-8-77	I	S.I.	Hydraulic System Installation of AFCS Equipped Model 212 Helicopters
212-77-7	Basic	3-11-77	A	64	Tail Rotor Pitch Change Horn, P/N 212-010-716 (All Dash Numbers)
212-77-8	Basic Rev. A	3-17-77 11-15-78	I - (R)	4	Model 212 Main Rotor Blades, P/N 204-012-001-23 and -29 A. Reduction of Service Life, B. Inspection of Blades
212-77-9	Basic	3-23-77	I - (R)	52	Adding Additional Inspection Holes in the L/H and R/H Passenger Door Assemblies
212-77-10	Basic	4-28-77	I	62	Modification of Main Rotor Blade Inspection System Kit, P/N 212-704-116-1

BHT-212-ASB INDEX**212 ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
212-77-11	Basic	6-6-77	I	52	Replacement of Spacers Attaching the Emergency Escape Release Handle Covers
212-77-12	Basic	6-9-77	I	53	Inspection of T/R Driveshafts & Removal of Anti-Chafing Tape from the T/R Drive-Cover & the Fin Cover Door Assemblies
212-77-13	Basic Rev. A	6-15-77 2-20-79	I - (P)	63	Replacement of the Coupling Seals on the Main Driveshaft Assy, P/N 212-040-005-11
212-77-14	Basic	7-22-77	I	29	Inspection of Hydraulic Actuator, P/N 212-076-005-9
212-77-15	Basic	7-29-77	A	S.I.	Replacement of Emergency Flotation Inflation Equipment Aluminum Parts With Steel Parts
212-77-16	Basic	10-11-77	I - (S)	5	Changes to the 212 Maintenance Manual Overspeed Conditional Inspection Requirements
212-77-17	Basic	12-14-77	I - (R)	4	Assignment of 1000 Hour Service Life to Aft Crosstube Assemblies, P/N 205-040-400-7, -29, -35, and -705
212-78-1	Basic	1-23-78	I - (R)	4	Model 212 Main Rotor Blade, P/N 204-012-001-33, Reduction of Service Life
212-78-2	Basic	2-21-78	I - (S)	S.I.	External Cargo Suspension Kit, Decrease of Load Rating
212-78-3	Basic	4-19-78	I - (R)	4	Main Rotor Hub Inboard Fitting, P/N 212-010-103-5, Reduction of Service Life
212-78-4	Basic	4-19-78	I - (R)	4	Main Rotor Hub Strap Assys, P/N 204-012-112-5, Reduction of Service Life
212-78-5	Basic	5-8-78	I - (P)	S.I.	Installation of Deflector, P/N 212-030-699-101 L/H and -102 R/H, to Model 212 Passenger Doors, P/N 205-032-699-9 and -10

212 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
212-78-6	Basic	5-11-78	I	S.I.	Replacement of External Cargo Hook Link Assy, P/N 205-070-944-1 or -5, With New Link Assy, P/N 205-070-944-7
212-78-7	Basic	5-17-78	I	65	Replacement of Tail Rotor Driveshafts, P/N 204-040-620-3 and -7, With New Tail Rotor Driveshaft, P/N 204-040-620-11
212-78-8	Basic	7-28-78	I - (S)	63	Rotor Brake Quill Assembly, P/N 205-040-300-1, Removal of
212-78-9	Basic Rev. A	8-9-78 9-12-78	I	S.I.	Emergency Float Bag Assys, P/N's 212-050-207-1, -2, -3, and -4, or P/N 212-030-411-1, -2, -3, and -4, Installation of Girt Reinforcements on Inboard Corners of Girt Assemblies, In Accordance with B.F. Goodrich's Service Bulletin No. 1 and/Air Cruiser's Service Bulletin No. 120-78-1
212-78-10	Basic	10-13-78	I - (R)	4	Main Rotor Hub Strap Pin, P/N 204-012-104-5, Reduction of Service Life
212-78-11	Basic	10-23-78	A	63	Replacement of the Transmission Spiral Bevel Gear, P/N 204-040-701-1, -3, with Trans. Spiral Bevel Gear, P/N 204-040-701-101
212-78-12	Basic	11-17-78	I - (S)	63	Inspection of Spiral Bevel Gear, P/N 204-040-701-3 and -101, and Installation of Rotor Brake Quill P/N 204-040-300-1
212-79-13	Basic Rev. A	3-5-79 7-22-82	I	97	Avionic Equipment Wire Harness, Chafing/Rerouting of
212-79-14	Basic	5-22-79	I - (R)	62	Main Rotor Hub Assembly, P/N 204-012-101 (All Dash Numbers), Corrosion Protection of

BHT-212-ASB INDEX**212 ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
212-79-15	Basic Rev. A	8-7-79 4-28-80	I	63	Inspection and Replacement of Transmission Aluminum Oil Tubes, P/N 212-040-235-1, 212-040-236-1, 212-040-238-1, and Quick Disconnect Coupling Halves, P/N 375200-12 and 375504-12
212-79-16	Basic Rev. A	10-19-79 7-22-82	I	29	Hydraulic Cylinder Assemblies, P/N 212-076-005-001, -005, -007, -009 and -011, Inspection and Rework of Spanner Link Assembly, P/N 41000517
212-80-17	Basic	4-22-80	I - (R)	4	Reduction of Retirement Life of Tension/Torsion Straps, P/N 204-012-122-001 /-005
212-80-18	Basic Rev. A	2-20-80 9-12-80	I - (R)	S.I.	Float Landing Gear Crosstube, P/N's 205-050-114-001, -003, -005, -007, -009, -011, -013, and 205-706-050-005, -009, and -013, Mandatory Retirement and Mandatory Relocation of Forward Friction Damper
212-80-19	Basic Rev. A	12-8-80 3-25-81	I	63	Oil filter, P/N 204-040-760, V-Band Clamp T-Bolt, Replacement of
212-81-20	Basic Rev. A	2-3-81 7-22-82	I - (S)	63	Zinc Chromate, Thermal Limit Indicator, Addition of
212-81-21	Basic	2-3-81	I - (S)	62	Swashplate Support, P/N 204-011-404-017, Inspection of
212-81-22	Basic Rev. A	3-18-81 4-10-81	I	4	PART I: Swashplate Support Assembly, P/N 204-011-404-017, Retirement Life Reduction of PART II: Swashplate Support Assembly, P/N 204-011-404-017, Replacement of
212-81-23	Basic Rev. A	6-22-81 3-31-89	I - (S)	4	Main Rotor Yoke, P/N 204-011-102 (All Dash Numbers), Retirement Life of

212 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
212-81-24	Basic	10-8-81	I - (R)	S.I.	Emergency Flotation System, Kit P/N 212-706-042-(All), Manual Actuation System, Modification and Rerigging of
212-81-25	Basic	10-15-81	I	62	Swashplate Support Assembly, P/N 204-011-404-121, Inspection of
212-81-26	Basic Rev. A	10-28-81 7-22-82	I	29	Main Hydraulic Cylinder Assembly, P/N 212-076-005-101, Inspection of the Lower Servo Housing for Blocked Bypass Passage
212-81-27	Basic	11-7-81	I - (P)	63	Carbon Magnetic Input Quill Seal, P/N 412-040-111-101, Removal of
212-82-28	Basic	3-22-82	I - (R)	S.I.	Rotor Brake Master Cylinder, Maximum Pressure, Inspection of
212-82-29	Basic	6-22-82	I	S.I.	Float Kit, P/N 212-706-042 All, Unions, P/N MS21902J8, One-Time Special Inspection and Replacement of
212-82-30	Basic	7-26-82	I	S.I.	Internal Hoist, P/N 214-070-300-1, Western Gear Corp. P/N 42277R1, Inspection and Modification of
212-83-31	Basic Rev. A	7-29-83 12-20-88	I	71	Screen, P/N 212-060-538-103 and/or 212-060-536-001, Removal of
212-84-32	Basic	3-23-84	I - (P)	79	Decal, P/N 212-062-515-101 Installation of
212-84-33	Basic	7-27-84	I - (P)	96	Engine Fire Extinguisher Bottle, P/N 209-062-908-1, Squib Discharge Valve, Identification and Wiring Clarification of
212-84-34	Basic	8-30-84	I	S.I.	Reservoir, Emergency Flotation, P/N's 212-073-810-1, 212-073-812-3, 212-073-911-1, or 212-073-911-3, Installation of WARNING Decal, P/N 31-023-8B and Three CAUTION Decals, P/N 31-023-9B

BHT-212-ASB INDEX**212 ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
212-84-35	Basic	10-23-84	I	S.I.	Float Bag, P/N 212-050-207-009, -010, -011, and -012, Inspection of
212-84-36	Basic	11-2-84	I - (P)	53	Elevators, P/N 205-030-856-103 and -105 and Prior Dash Numbers, to Horn Assembly, P/N 205-001-914-029, Attachment, Modification of
212-85-37	Basic Rev. A	1-17-85 1-23-85	I	62	Main Rotor Grip/Blade Bolt Interference on Repaired Grips, P/N 204-011-121 Series, Inspection and Rework of
212-86-38	Basic Rev. A	6-26-86 10-14-86	I	53	Fin Spar Assembly, P/N 212-030-121-005/-107, Spar Cap Assembly, P/N 212-030-447-001/-101, Inspection and Repair of
212-86-39	Basic Rev. A	6-27-86 7-23-86	I	64	Tail Rotor Trunnion Bearing Housing, P/N 212-011-716-001, Inspection of
212-86-40	Basic	6-27-86	I - (S)	S.I.	Emergency Flotation System, and Squib Valve Assembly, P/N 212-073-912-(All), Inspection and Modification of
212-86-41	Basic Rev. A	8-4-86 10-21-93	I	62	Main Rotor Blade, P/N 204-012-001 (All Dash Numbers) and P/N 212-015-501 (All Dash Numbers), Inspection of
212-87-42	Basic	2-18-87	I	S.I.	Emergency Flotation System, Modification of, and Squib Valve Assembly, P/N 212-073-912-(All), Replacement of
212-87-43	Basic Rev. A	3-23-87 7-1-87	I - (S)	62	Main Rotor Pillow Block to Yoke Attachment Washer, P/N AN960-816, Replacement of
212-87-44	Basic Rev. A	8-4-87 8-21-87	I - (S)	4	Main Rotor Mast, P/N 204-011-450 Series, and Main Rotor Trunnion, P/N 204-011-105-001, Assignment of Retirement Life

212 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
212-87-45	Basic Rev. A	9-17-87 8-28-89	I	71	Gas Generator Case Seam Weld, Inspection Procedures
212-87-46	Basic	10-8-87	I	96	Engine Fuel Valve Electrical Connectors, P/N MS3456W14S-5S, One Time Inspection of
212-87-47	Basic Rev. A	11-11-87 1-14-88	I	9	Ground Handling Wheel Gear Assembly, P/N 212-050-200-005 and -101, Cradle Assembly, P/N 214-050-011-001, Pin Replacement of
212-87-48	Basic	12-15-87	I - (S)	62	Main Rotor Yoke, P/N 204-011-102 (All Dash Numbers), Inspection of
212-88-49	Basic	5-4-88	I - (R)	67	Flight Control Cylinder Assemblies, P/N 212-076-005 (All Dash Numbers) and 212-076-004 (All Dash Numbers) Cleaning of
212-88-50	Basic Rev. A	7-26-88 8-26-88	I	S.I.	Internal Hoist Assembly, P/N 205-072-260-15, -19 and -21, Inspection of Load Cable and Hook/Bumper Stowage
212-88-51	Basic	7-28-88	I	9	Ground Handling Wheel Gear Assembly, P/N 204-050-200-005 and -15 Forward Support Pin, Replacement of
212-88-52	Basic	8-16-88	I	96	Engine Fuel Switch, Inspection of
212-89-53	Basic Rev. B	1-10-89 8-1-89	I	71	Aeroquip 601 Hose Assemblies, One-Time Inspection and Replacement
212-89-54	Basic	4-6-89	I - (R)	63	Spiral Bevel Gear P/N 204-040-701-103, Inspection of
212-89-55	Basic Rev. A	8-29-89 8-29-89	I	62	Strap Assembly, Main Rotor Tension -Torsion P/N 204-012-122-5 and P/N 204-310-101-101, Removal from Service
212-89-56	Basic Rev. B	8-11-89 10-27-92	I - (R)	62	Main Rotor Flight Control System Bolts, Inspection of

BHT-212-ASB INDEX**212 ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
212-89-57	Basic Rev. A	10-25-89 3-8-90	I - (S)	S.I.	Breeze-Eastern Cargo Hooks P/N SP7109-12 and -62, Warning Plate, Addition of
212-89-58	Basic Rev. B	12-12-89 5-30-91	I	S.I.	Inspection of Float Bags P/N 212- 050-207-9, -10, -11, and -12
212-90-59	Basic	2-5-90	I - (R)	62	Drag Brace Assembly, P/N 204- 011-140-003, -005, Magnetic Particle Inspection
212-90-60	Basic Rev. A	3-23-90 8-31-90	I - (S)	62	Main Rotor Yoke P/N 204-011-102 (All Dash Numbers), Inspection of
212-90-61	Basic	3-26-90	I	62	Swashplate Outer Ring P/N 204- 011-403-001, S/N SC-000014, Removal From Service
212-90-62	Basic Rev. A	6-26-90 10-11-90	I - (S)	62	Main Rotor Pillow Block Attachment Bolt 204-011-171-003, Washer 140-007-33S28-3 and Nut EB080, One Time Use of
212-90-63	Basic Rev. A	7-20-90 8-10-90	I - (R/P)	53	Tailboom Upper Longeron Splice Inspection Provisions
212-90-64	Basic Rev. B	10-2-90 3-11-92	I - (S)	4	Method of Calculating Retirement Life on Subject Parts and Assignment of Retirement Lives 1) Main Rotor Yoke, P/N 204-011-102 All 2) Main Rotor Mast, P/N 204-011-105-450 All 3) Main Rotor Trunnion, P/N 204-011-105-001
212-90-65	Basic	12-5-90	I - (P)	52	Crew Door Hinge Pins (Jettison Pins) P/N 204-030-790-011/-013
212-91-66	Basic Rev. A	6-12-91 6-27-91	I - (R)	63	Lower Planetary Spider Gear, P/N 204-040-785-003, Assign- ment of a Special Inspection
212-91-67	Basic	6-24-91	I - (R)	63	Engine-To-Driveshaft Coupling Adapter Installation Procedures
212-91-68	Basic	9-26-91	I	62	Tension Torque Strap Retention Pins P/N 204-012-104-005

212 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
212-91-69	Basic Rev. B	10-4-91 11-21-91	I - (S)	65	Tail Rotor Driveshaft Hanger Bearing P/N 204-040-623-003/-005
212-91-70	Basic	10-10-91	I	71	Power Section Compressor Disc P/N 3018312 and 3017713, Inspection of
212-91-71	Basic	11-21-91	I	65	Tail Rotor Driveshaft Hanger Bearing P/N 204-040-623-003/-005
212-91-72	Basic	12-13-91	I	62	Swashplate Support P/N 204-011-404-125
212-92-73	Basic	2-6-92	I - (R)	62	Scissor Link to Swashplate Attachment Bolt, Inspection of
212-92-74	Basic	5-6-92	I	63	Oil Level Indicators P/N 204-040-508-005/-007/-013
212-92-75	Basic	5-15-92	I - (P)	67	Pilot Collective Stick P/N 212-001-164-105 (#2 Throttle Grip Anchor Pin) Modification of
212-92-76	Basic Rev. A	5-29-92 7-20-92	I - (P)	96	Co-Pilot Doorpost Wire Harness, Inspection/Modification of
212-92-77	Basic	7-28-92	I	52	Passenger Door Emergency Push-Out Windows
212-92-78	Basic	8-5-92	I	64	Tail Rotor Yoke 212-010-704-005/-107
212-92-79	Basic Rev. A	9-4-92 9-24-92	I - (P)	21	Pedestal Defrost Control Linkage, Inspection/Modification of
212-92-80	Basic	10-23-92	I - (R/P)	62	Main Rotor Yoke P/N 204-011-102 All Dash Numbers, Removal From Service
212-92-81	Basic	12-2-92	I	S.I.	Shear Link Assembly, P/N 212-001-262-001
212-93-82	Basic Rev. A	2-1-93 6-1-93	I	63	Rotor Brake Quill P/N 205-040-300-001, Removal From Service
212-93-83	Basic	6-18-93	I	63	Lower Spider P/N 412-040-785-101, Assignment of Retirement Life

BHT-212-ASB INDEX**212 ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
212-93-84	Basic Rev. A	6-21-93 6-20-94	I - (R)	S.I.	Cargo Hooks, Breeze Eastern Customer Advisory Bulletin O/H 3 Years
212-93-85	Basic Rev. A	6-21-93 7-1-94	I	53	Tailboom Doubler P/N 212-030- 099-089/-129
212-93-86	Basic	6-21-93	I	71	Hose Assembly Part Number 70-009K115C194A, 70-009K245W347A, 70-009K247W220A and 70-009K120W371A, One Time Inspection of
212-93-87	Basic	10-21-93	I	65	Intermediate Gearbox Mounting Bolts, One Time Inspection For Correct Part Number and Installation
212-93-88	Basic	11-10-93	I	65	Tail Rotor Driveshaft Hanger Bearing P/N 204-040-623-005 One Time Inspection of
212-93-89	Basic Rev. A	12-7-93 3-4-94	I - (R/P)	63/65	Main Driveshaft and Tail Rotor Drive System Grease Lubricated Couplings, Overtemperature Indicators, Installation of
212-94-90	Basic	4-13-94	I	96	Tarsyn-H Three Axis Gyro P/N 4020936-903/-904
212-94-91	Basic Rev. B	5-23-94 8-17-95	I	62	Blade Bolt 204-011-151-001, Removal From Service of Specific Serial Numbers
212-94-92	Basic Rev. A	10-14-94 3-13-95	I - (R)	62	Introduction of New Scheduled Inspection, Overhaul and Conditional Inspection Requirements, Main Rotor Grip P/N 204-011-121-009, -121 and Part Number Grips With Modified Suffix Characters
212-94-93	Basic	11-11-94	I	63	Main Driveshaft Boot Assy P/N 212-040-176-101 Inspection, Removal From Service
212-94-94	Basic	11-28-94	I - (R/P)	62	Main Rotor Yoke Inspection of

212 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
212-95-95	Basic Rev. C	5-8-95 10-9-95	I - (R)	5/65	Tail Rotor Hanger Bearings P/N 204-040-623-003/-005, Application of Witness Mark
212-95-96	Basic Rev. A	6-5-95 7-17-95	I	29	Elbow P/N 212-076-146-001, Removal From Service
212-95-97	Basic	6-30-95	I - (S)	4	Main Rotor Mast P/N 204-011- 450-007/-105/-113/-119, and Main Rotor Trunnion P/N 204-011-105- 001/-103, Change of Retirement Life and Method of Determination
212-95-98	Basic Rev. A	7-24-95 8-8-95	I	67	Main Rotor Hydraulic Servo Actuators P/N 212-076-005-007/ -009/-011/-101, One Time Inspection of Shoulder Bolts
212-95-99	Basic	11-27-95	I - (P)	71	Auxiliary Lower Engine Cowl Lock
212-96-100	Basic Rev A	8-1-96 5-18-98	I - (R/P)	5/64	Tail Rotor Yoke Assemblies P/N 212-010-704-All and P/N 212- 010-744-All Inspection of; and Trunnion Assemblies P/N 212- 010-738-001 Inspection of and Trunnion Assemblies P/N 205- 012-716-001 and P/N 212-010- 703-001 Removal From Service
212-96-101	Basic	9-3-96	I - (R/P)	5/64	Tail Rotor Yoke P/N 212-011-702- All Inspection of, and Tail Rotor Flapping Stop/Yield Indicator P/N 212-011-713-103 Installation of
212-98-102	Basic	6-12-98	I	S.I.	Cargo Hook Load Ring Decal
212-98-103	Basic Rev. B	8-3-98 10-22-98	I	67	HR Textron Inspection for Bogus Actuators
212-99-104	Basic	1-8-99	A	4	High Landing Gear Aft Crosstube Retirement Life
212-99-105	Basic	3-19-99	I	S.I.	BL 4807 Swivel Hook Reliability
212-00-106	Basic Rev. B	4-24-00 8-4-00	A	4	Main Rotor (M/R) Mast, P/N 204- 011-450-007/-105/-113/-119, Inspection and Retirement Index Number (RIN) Life Reduction

BHT-212-ASB INDEX**212 ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
212-00-107	Basic Rev. A	5-26-00 9-13-00	A	64	Tail Rotor Counterweight Bellcrank Retention Nut MS14145L6 and MS17826-6, Installation and One Time Use of
212-00-108	Basic Rev. A	8-1-00 9-9-02	I	S.I.	Cargo Hook, Onboard Systems P/N 528-002-00
212-00-109	Basic	10-19-00	A	67	Main Hydraulic Servo Actuator Rod End Lock Washer, Inspection and Replacement of
212-00-110	Basic Rev. A	11-6-00 1-19-01	A	5/53	Fin Spar Cap P/N 212-030-125-001, P/N 212-030-447-001/-101, Inspection of
212-00-111	Basic Rev. D	11-10-00 3-18-05	A	64	Tail Rotor (T/R) Blade 212-010-750-009/-105/-107, Tip Block Retention Modification
212-01-112	Basic	1-19-01	I	67	Magnetic Brake P/N 204-001-376-003 One Time Inspection of
212-01-113	Basic	3-30-01	I	63	Chip Detector Assembly, Tedeco B3703
212-01-114	Basic	4-19-01	A	4	Clutch Assembly P/N X134296, Assignment of Retirement Life
212-01-115	Basic	7-26-01	I	62	Pillow Block P/N 204-011-108-113, Tube Assembly, P/N 212-010-404-005, Inspection and Recall of Specific Serial Number Part
212-02-116	Basic Rev. A	5-3-02 10-30-02	A	62	Main Rotor Grips 204-011-121-009 and -121, Ultrasonic Inspection of
212-02-117	Basic	6-20-02	A	62	1200 Hour Special Inspection Requirements for Main Rotor Hub Pins P/N 204-012-104-003/-005
212-02-118	Basic	11-22-02	A	64	Tail Rotor Blade Assemblies P/N 212-010-750-113/-115 Inspection and Rework of

212 ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
212-04-119	Basic	2-17-04	I	71	Pratt Whitney Canada Service Information Letter (PT6T-040) Fuel Flow Transducer Kit Removal, Introduction of
212-04-120	Basic	12-3-04	I	64	Tail Rotor Pitch Horn Assembly P/N 212-011-708-105, Replacement of
212-05-121	Basic	2-18-05	I	64	Crosshead P/N 212-010-775-001, Inspection and Recall of Specific Serial Number Part
212-05-122	Basic	4-30-05	I	64	Tail Rotor Blade P/N 212-010-750-009 through -129, Inspection and Rework of
212-06-123	Basic	2-17-06	I	S.I.	Float Inflation Valve Squib 29022968, Misidentification of
212-07-124	Basic	3-26-07	I	71	Engine, P3 Filter and Pneumatic System – Inspection of
212-07-125	Basic Rev. A	9-11-07 9-19-07	I	64	Tail Rotor Blade Assembly, Inspection of
212-07-126	Basic	11-1-07	I	71	AGB Coupling – Shaft Bearing – Inspection/Replacement of
212-07-127	Basic	11-27-07	A	67	Cyclic Flight Control Bearing P/N MS27643-4 One Time Inspection and Replacement of

NOTICE

The following blank pages are provided for entry of additional bulletins when distributed. These additional bulletins will be included in this index at next revision.

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
---------------	--------------	-------------	---------------	--------------------------	----------------

BHT-212-ASB INDEX

NOTICE

The following blank pages are provided for entry of additional bulletins when distributed. These additional bulletins will be included in this index at next revision.

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
--------	-------	------	--------	------------------	---------