



ALERT SERVICE BULLETIN INDEX

NOTE

THIS INDEX IS A LIST OF ALERT SERVICE BULLETINS ISSUED. THIS INDEX DOES NOT IDENTIFY WHICH ALERT BULLETINS ARE ACTIVE OR INACTIVE.

THE ATA/CHAP. REF. COLUMN INDICATES THE MAINTENANCE AND/OR OVERHAUL MANUAL CHAPTER/S AFFECTED BY THE RESPECTIVE BULLETIN; OR, THE BULLETIN IS APPLICABLE TO A SERVICE INSTRUCTION (S.I.).

PROPRIETARY RIGHTS NOTICE

These data are proprietary to Bell Helicopter Textron, Inc. Disclosure, reproduction, or use of these data for any purpose other than helicopter operation is forbidden without prior written authorization from Bell Helicopter Textron, Inc.

Newly released Alert Service Bulletins can be viewed and printed by accessing our Service Directives website at www.bellcustomer.com. This publication supersedes BHT-222U-ASB INDEX dated 1 January 2007 in its entirety.

COPYRIGHT NOTICE
COPYRIGHT 2008
BELL® HELICOPTER TEXTRON INC.
AND BELL HELICOPTER TEXTRON
CANADA LTD.
ALL RIGHTS RESERVED

Bell Helicopter
A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

1 JANUARY 2008

222U ALERT SERVICE BULLETIN INDEX

STATUS CODE

A = Active

A- () = Active — (Additional Information)

└────────────────── P = Incorporated in Parts Catalog
R = Referenced in Maintenance Manual

I = Inactive

I- () = Inactive — (Reason)

└────────────────── I = Incorporated in Maintenance Manual
P = Incorporated in Parts Catalog
S = Superseded (New Bulletin Number)
R = Referenced in Maintenance Manual

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
222U-84-1	Basic	7-16-84		S.I.	Emergency Flotation Reservoir, P/N 222-325-021-101, Decal (WARNING), P/N 31-023-8B, and Decal (CAUTION), P/N 31-023-9B, Installation of
222U-85-2	Basic Rev A	2-13-85 6-12-85		S.I.	Dual Controls Auxiliary Equipment Kit, P/N 222-706-084-105, Installation of Spring Pin Assembly
222U-85-3	Basic	3-21-85		53	Tailboom, P/N 222-035-150-107, Inspection, Repair, and Modification of
222U-85-4	Basic	4-12-85		26	Fire Detector Element Ground Strap, Addition of
222U-85-5	Basic	6-13-85		96	Instrument Current Limiter, P/N 531-1, Reconfiguration of
222U-85-6	Basic Rev A	6-27-85 11-1-85		71	Engine, Lycoming LTS101-750C-1, Ng Operating Speed Restrictions
222U-85-7	Basic Rev A	9-5-85 11-3-86		27	Directional Hydraulic Actuator, P/N 222-382-002-101, Inspection of Rod End

BHT-222U-ASB INDEX**222U ALERT SERVICE BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	SUBJECT
				REF.	
222U-85-8	Basic	8-13-85		27	Directional Hydraulic Actuator, P/N 222-382-002-101, and Main Rotor Control Dual Servo Actuator, P/N 222-382-001-101, Inspection of Control Linkage Rivets
222U-85-9	Basic Rev B	9-30-85 10-13-86		25	Rescue Hoist Installation, Conversion of Hoist, P/N BL-16600-80, to P/N BL-16600-110
222U-85-10	Basic	11-20-85		53	Fin Assembly, P/N 222-035-220, Modification and Installation of
222U-86-11	Basic	6-27-86		S.I.	Emergency Flotation System, and Squib Valve Assembly, P/N 212-073-912-(All), Inspection and Modification of
222U-86-12	Basic	8-29-86		96	Rewiring of Engine Chip Detectors to Provide Early Warning of a No. 2 or No. 3 Bearing Failure
222U-86-13	Basic	10-28-86		25	Rescue Hoist Cable Cutter Circuit, Rewiring of in Accordance with Breeze Manufacturing Preferred Method
222U-86-14	Basic Rev A	10-31-86 1-14-87		65	Flapping Bearing, P/N 222-310-114-003/-105, Rework of
222U-87-15	Basic	1-26-87		65	Swashplate Pins, P/N 222-010-455-003, Inspection of
222U-87-16	Basic	2-18-87		S.I.	Emergency Flotation System, Modification of, and Squib Valve Assembly, P/N 212-073-912-103, Replacement of
222U-87-17	Basic	6-22-87		S.I.	Auxiliary Equipment Kit Emergency Flotation, P/N 222-706-093-117 and -123, Modification of
222U-87-18	Basic	10-12-87		52	Aft Passenger Windows (Emergency Exit), Replacement of
222U-87-19	Basic	11-11-87		32	Ground Handling Wheel Gear Assembly, P/N 212-050-200-005 and -103, Cradle Assembly, P/N 214-050-011-001, Pin Replacement of

222U ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
222U-88-20	Basic	1-14-88		65	Main Rotor Yoke, P/N 222-011-102-101, Inspection of
222U-88-21	Basic	3-2-88		96	Daily and Periodic Inspection of Engine Oil System Chip Detectors, Addition of a "Warning" Note to the Flight Manual, and Modification of the Chip Detector Electrical System
222U-88-22	Basic Rev A	7-26-88 8-26-88		-	External Hoist, P/N BL-16600-(All Dash Numbers), Inspection of Load Cable and Hook/Bumper Stowage
222U-88-23	Basic	9-1-88		53	Bulkhead P/N 222-031-309-103 Web to Angle Attach Rivets, One Time Inspection of
222U-88-24	Basic	9-1-88		53	Stabilizer Assembly, P/N 222-035-250-105, Inspection of
222U-88-25	Basic	11-14-88		65	Main Rotor Yoke Assembly P/N 222-011-102-101, Modification of
222U-89-26	Basic Rev A	1-10-89 8-1-89		79	Aeroquip 601 Hose Assemblies, One-Time Inspection and Replacement
222U-89-27	Basic Rev A	3-20-89 5-23-89		53	Stabilizer Assembly, P/N 222-035-250-105, Inspection and Replacement of
222U-89-28	Basic Rev A	8-9-89 9-27-89		65	Main Rotor Flight Control Bolts, Inspection of
222U-90-29	Basic	1-15-90		S.I.	Breeze-Eastern Cargo Hook P/N 17172-1 Warning Plate, Addition of
222U-90-30	Basic	12-21-90		96	Engine, Lycoming LTS 101-750 series Power Turbine Speed Restriction For Cast Turbine Wheels
222U-91-31	Basic	9-17-91		25	Crew Seat Restraint Assembly 222-320-823-107, -115, Improvement of

BHT-222U-ASB INDEX

222U ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	SUBJECT
				REF.	
222U-92-32	Basic	1-8-92		S.I.	Engine Overspeed Control System (OCS) Kit, Installation of
222U-92-33	Basic	12-16-92			Flapping Bearing, P/N 222-310-114-003/-105/-107/-109
222U-93-34	Basic Rev A	4-21-93 4-24-96			Engine Air Intake Duct Assembly, P/N 222-062-211, Inspection of
222U-93-35	Basic	6-2-93			Lycoming LT 101 Engine, Power Turbine Rotor Assembly P/N 4-141-290-01/-03, One Time Inspection of
222U-93-36	Basic Rev B	6-2-93 10-19-93			Lycoming LT 101 Engine, Power Turbine Rotor Assembly P/N 4-141-290-01/-03, Special Inspection of
222U-93-37	Basic Rev A	6-21-93 6-20-94			Cargo Hooks, Breeze Eastern Customer Advisory Bulletin No. CAB-100-41, Customer Service Bulletin No. CSB-147
222U-93-38	Basic	8-30-93			Flapping Bearings, P/N 222-310-114-003/-105/-107/-109, Replacement of
222U-93-39	Basic	10-19-93			Lycoming LT 101 Engine, Gas Producer Rotor Discs P/N 4-111-015-04/-09/-14, One Time Inspection of
222U-94-40	Basic Rev A	12-7-93 3-4-94			Main and Tail Rotor Drive Shaft Grease Lubricated Couplings, Over-temperature Indicators, Installation of
222U-94-41	Basic	4-4-94			Lycoming LT 101 Engine, Removal of No. 2 Winged Bearing, P/N 4-301-362-01, S/N 3-740 thru 3-839, S/N 3-1288 thru 3-1361 and S/N 4-534 thru 4-680
222U-94-42	Basic	8-12-94			Driveshaft P/N 222-044-685-101, Inspection of
222U-94-43	Basic	9-6-94			Pedal Assembly P/N 222-001-760-003/-105, Modification of

222U ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
222U-94-44	Basic	10-31-94			Emergency Exit, Passenger Door Windows
222U-94-45	Basic	11-14-94			Flapping Spring P/N 222-310-117-103, Inspection of
222U-95-46	Basic	1-18-95			Shaft Assembly P/N 222-044-685-101, Recall and Replacement of
222U-95-47	Basic Rev B	10-9-95 4-22-96			Tail Rotor Blades P/N 222-016-001-107/-111/-115
222U-95-48	Basic	10-16-95			Tail Rotor Pitch Link P/N 222-312-702-101, Replacement of
222U-95-49	Basic	12-4-95			Main Rotor Hub P/N 222-012-101-103/-107, Grip Retaining Bolt P/N 222-310-127-101, Retorque and Inspection of
222U-96-50	Basic	11-13-96			Tail Rotor Blade P/N 222-016-001-107/-111/-115, Removal from Service
222U-98-51	Basic	3-23-98			Power Trim Check Revised Procedure
222U-98-52	Basic	4-23-98			Main Rotor Hub Grip and Flapping Bearing Bolt Torque Check
222U-98-53	Basic Rev A	4-30-98 6-9-98			Vertical Fin Assembly, Inspection of
222U-98-54	Basic	10-12-98			Main Rotor Hub Trunnion Bolt, Inspection of
222U-99-55	Basic	2-15-99			Swashplate Assembly Drive Pin, Inspection of
222U-99-56	Basic	12-16-99			Tail Rotor (T/R) Pitch Change Bearings P/N 222-312-753-103, Inspection of; and Tail Rotor Blade Attaching Hardware, Replacement of
222U-00-57	Basic	5-19-00			Hydraulic Actuator Support P/N 222-040-125-001, Inspection of
222U-01-58	Basic	1-19-01			Magnetic Brake P/N 204-001-376-105 and -107, One Time Inspection of

BHT-222U-ASB INDEX

222U ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	SUBJECT
				REF.	
222U-01-59	Basic	1-16-01			Rescue Hoist BL-16600 Series, Breeze Eastern Customer Alert Bulletin CAB-100-58
222U-01-60	Basic	2-7-01			Upper Fuel Enclosure, Right Side, Addition of Drain Provision
222U-01-61	Basic Rev A	5-18-01 10-26-05			Rotating Ring Assembly P/N 222-010-403-005, -113 and -117, Inspection of
222U-01-62	Basic	5-18-01			Main Rotor Pendulum Weight Support P/N 222-011-114-103, Replacement of
222U-02-63	Basic	3-28-02			Main Rotor Pendulum Weight Support P/N 222-011-114-101 and -103, Rework of
222U-02-64	Basic Rev A	4-1-02 3-3-03			Main Rotor Hub Assemblies P/N 222-011-101-105/-107/-109 and P/N 222-012-101-103/-107, Inspection of
222U-02-65	Basic	4-9-02			Fuel System Check and Relief Valve P/N 222-366-687-101, Replacement of
222U-03-66	Basic	6-26-03			Honeywell LTS 101 Engine, Inspection of Fuel Pump Internal Drive Splines
222U-03-67	Basic	6-26-03			Honeywell LTS 101 Engine, Replacement of Fuel System Power Turbine Governor Spool Bearing Part No. 2523973
222U-03-68	Basic	9-23-03			Main Rotor Hub P/N 222-011-101-ALL and 222-012-101-ALL, Inspection of
222U-04-69	Basic	6-8-04			Honeywell LTS 101 Engine, Removal and Replacement of Fuel Control Spool Bearing P/N 2523973 Rev. M
222U-04-70	Basic Rev C	8-9-04 2-16-06			Tail Rotor Counterweight Bellcrank P/N 222-012-727-003, Removal from Service

222U ALERT SERVICE BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
222U-04-71	Basic Rev A	8-27-04 8-28-06			Tail Rotor Blade P/N 222-016-001-123 and -131, Inspection of
222U-04-72	Basic Rev B	10-12-04 3-15-06			Tail Rotor Counterweight Bellcrank P/N 222-012-727-105, Inspection of
222U-06-73	Basic	2-17-06			Float Inflation Valve Squib P/N 29022968, Misidentification of
222U-06-74	Basic	11-21-06			Engine — Gearbox — Removal and Replacement of Locking Cup Part No. 4-082-094-01
222U-07-75	Basic	1-9-07			Tail Rotor Pitch Change Mechanism, Revised Rigging Procedures
222U-07-76	Basic	3-28-07			Disc Assembly P/N 36300-1 and 37855-1, Inspection of
222U-07-77	Basic Rev C	9-11-07 9-20-07			Tail Rotor Blade Assembly, Inspection of

NOTICE

The following blank pages are provided for entry of additional bulletins when distributed. These additional bulletins will be included in this index at next revision.

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
---------------	--------------	-------------	---------------	--------------------------	----------------

BHT-222U-ASB INDEX

NOTICE

The following blank pages are provided for entry of additional bulletins when distributed. These additional bulletins will be included in this index at next revision.

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
--------	-------	------	--------	------------------	---------