

# **Bell Helicopter** **TEXTRON**

A Subsidiary of Textron, Inc.

September 30, 2003

**INFORMATION LETTER** 204B-03-19  
205-03-32  
205B-03-16  
212-03-51  
UH-1H-II-03-15

**TO: All Owners/Operators of Bell 204, 205, 212 and UH-1H-II series Helicopters**

**SUBJECT: MAIN ROTOR GRIP 204-011-121-005/-009/-117/-121  
ULTRASONIC INSPECTION COURSES**

Bell Helicopter has received requests on the availability of additional main rotor grip ultrasonic Inspection training courses. These courses were originally offered to support the ultrasonic inspection requirements per ASB 204-02-58, 205-02-88, 205B-02-39, 212-02-116 and UH-1H-II-02-04.

Future courses can be arranged at the Bell Helicopter Training Center located in Fort Worth, Texas on a, as needed basis, however there are certain guidelines that must be met in order for a course to take place.

A minimum of eight students must be enrolled prior to a course date being arranged. Once enrollment has reached eight individuals, they will be contacted and advised of the course date. There can only be a maximum of 12 students per course due to training equipment availability.

Student must be a certified A&P or equivalent, able to distinguish color (not color blind), and able to understand and read the English language.

The student will be responsible for accommodation, travel, expenses, and \$750 tuition for the course. The course is 16 hours (two days) in duration.

Offsite courses may also be arranged through the Customer Training Academy. For any further information and to sign up for this course please contact:

Bell Helicopter Customer Training  
Phone 817-280-8334  
Fax 817-278-8334  
e-mail [rbates@bellhelicopter.textron.com](mailto:rbates@bellhelicopter.textron.com)