

Bell Helicopter **TEXTRON**

A Subsidiary of Textron, Inc.

OCT 13, 2006

INFORMATION LETTER 206-06-94

TO: All Owners/Operators of Bell 206B Helicopters

SUBJECT: Improved Auto Relight Kits 206-706-038-003, 206-706-038-101, 206-706-038-105, and 206-706-038-107 Introduction of

The existing Auto-reignition control kit 23050521, 23052372, and 6877142 as used in the Rolls-Royce Installation Bulletin 1006 and Installation Bulletin 4003 are no longer procurable and/or repairable due to parts availability. To provide continued support for its auto relight kits 206-706-038-003, 206-706-038-105 for C-20 and C-20B/J engine and 206-706-038-101, 206-706-038-107 for C-20R engine, Bell Helicopter has acquired the rights for the Rolls-Royce kits P/N 23050521, 23052372, and 6877142.

This Information Letter introduces the release of an improved Bell Manufactured Control box P/N 206-375-017-101. That Control box is to be used as a direct replacement to the original Rolls-Royce Control box and it is available through Bell Spares. The Bell Helicopter Service Instruction BHT-206-SI-92 has been re-issued and now incorporates the Bell manufactured Control box as well as the installation instruction for complete kits on C-20 and C-20B/J and the C-20R engine.

Owners and Operators that have the original Control box available may still continue using it in accordance with the Rolls-Royce Installation Bulletin 1006 or Installation Bulletin 4003 as applicable.