

Bell Helicopter **TEXTRON**

A Subsidiary of Textron, Inc.

May 03, 2006

INFORMATION LETTER 206L-06-80

TO: All Owners/Operators of Bell 206L Helicopter

SUBJECT: IMPROVED AUTO RELIGHT KITS 206-706-044-001 AND 206-760-044-111, INTRODUCTION OF

The existing Auto-reignition control kit 23050522, 23052373, and 6892079 as used in the Rolls-Royce Installation Bulletin 1010 and Installation Bulletin 4003 are no longer procurable and/or repairable due to parts availability. To provide continued support for its auto relight kits 206-706-044-001 for C-20B/J engine and 206-706-044-111 for C-20R engine, Bell Helicopter has acquired the rights for the Rolls-Royce kits P/N 23050522, 23052373, and 6892079.

This Information Letter introduces the release of an improved Bell Manufactured Control box P/N 206-375-017-103. That Control box is to be used as a direct replacement to the original Rolls-Royce Control box and it is available through Bell Spares. The Bell Helicopter Service Instruction BHT-206-SI-2006 has been re-issued and now incorporates the Bell manufactured Control box as well as the installation instruction for complete kits on C-20B/J and the C-20R engine.

Owners and Operators that have the original Control box available may still continue using it in accordance with the Rolls-Royce Installation Bulletin 1010 or Installation Bulletin 4003 as applicable.