

# **Bell Helicopter** **TEXTRON**

A Subsidiary of Textron, Inc.

Apr 11, 2005

**TO: All Owners/Operators of Bell 206L Series Helicopters**

**SUBJECT: REVISION "A" TO TECHNICAL BULLETIN 206L-01-206:  
(TRANSMISSION OIL PUMP SEAL38-79004-1042-2,  
INTRODUCTION OF)**

Revision "A" is introduced to cancel this Technical Bulletin.

**TECHNICAL BULLETIN**  
**Bell Helicopter** **TEXTRON**

A Subsidiary of Textron Inc.

No. 206L-01-206

Date 04-30-01

Page 1 of 1

DATE: Apr 11, 2005

REV A

**MODEL AFFECTED:** 206L Series

**SUBJECT:** TRANSMISSION OIL PUMP SEAL 38-79004-1042-2, INTRODUCTION OF

**HELICOPTERS AFFECTED:** 206L, S/N 45004 through 45153;  
S/N 45601 through 45617  
206L1, S/N 45154 through 45790  
206L3, S/N 51001 through 51162  
206L4, S/N 52001 and subsequent

**COMPLIANCE:** Effective immediately

**DESCRIPTION:**

Technical Bulletin 206L-01-206 is cancelled and superceded by Technical Bulletin 206L-05-218.

A