

Bell Helicopter **TEXTRON**

A Subsidiary of Textron, Inc.

November 12, 2001

TO: All Bell 407 Helicopters Owners/Operators

**SUBJECT: REVISION "A" TO TECHNICAL BULLETIN 407-98-12:
(BEARING 407-340-339-101/-103 AND GREASE Royco 13 per
MIL-G-25013, INTRODUCTION OF)**

Technical Bulletin 407-98-12 is cancelled. Information contained in this bulletin is incorporated in the Maintenance Manual BHT-407-MM Rev. 12 dated May 8, 2001.

TECHNICAL BULLETIN
Bell Helicopter **TEXTRON**

A Subsidiary of Textron Inc.

No. 407-98-12

Date 12-16-98

Page 1 of 1

DATE 11-12-01

REV A

MODEL AFFECTED: 407

SUBJECT: BEARING 407-340-339-101/-103 AND GREASE ROYCO 13 PER MIL-G-25013, INTRODUCTION OF

HELICOPTERS AFFECTED: All model 407 helicopters.

COMPLIANCE: Effective immediately.

DESCRIPTION:

Technical Bulletin 407-98-12 is cancelled. Information contained in this bulletin is incorporated in the Maintenance Manual BHT-407-MM Rev. 12 dated May 8, 2001.

A