



November 24, 2009

TO: All Bell Owners/Operators of 206L Series

SUBJECT: REVISION A TO TECHNICAL BULLETIN 206L-79-38 (TAIL ROTOR HUB AND BLADE ASSEMBLIES, CONFIGURATION OF)

Remove Technical Bulletin 206L-79-38 and replace by TB 206L-09-239
November 24, 2009.