



TECHNICAL BULLETIN INDEX

THE ATA/CHAP. REF. COLUMN INDICATES THE MAINTENANCE AND/OR OVERHAUL MANUAL CHAPTER/S AFFECTED BY THE RESPECTIVE BULLETIN; OR, THE BULLETIN IS APPLICABLE TO A SERVICE INSTRUCTION (S.I.).

PROPRIETARY RIGHTS NOTICE

These data are proprietary to Bell Helicopter Textron, Inc. Disclosure, reproduction, or use of these data for any purpose other than helicopter operation is forbidden without prior written authorization from Bell Helicopter Textron, Inc.

Newly released Technical Bulletins can be viewed and printed by accessing our Service Directives website at www.bellcustomer.com. This publication supersedes BHT-204B-TB INDEX dated 1 January 2007 in its entirety.

COPYRIGHT NOTICE
COPYRIGHT 2008
BELL © HELICOPTER TEXTRON INC.
AND BELL HELICOPTER TEXTRON
CANADA LTD.
ALL RIGHTS RESERVED

Bell Helicopter
A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

1 JANUARY 2008

204B TECHNICAL BULLETIN INDEX

STATUS CODE

A = Active

A- () = Active — (Additional Information)

└────────── P = Incorporated in Parts Catalog
R = Referenced in Maintenance Manual

I = Inactive

I- () = Inactive — (Reason)

└────────── I = Incorporated in Maintenance Manual
P = Incorporated in Parts Catalog
S = Superseded (New Bulletin Number)
R = Referenced in Maintenance Manual

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
204-03-73-1	Basic	1-30-73		V	Engine Mount - Allowable Rod End Bearing Wear Limits
204-04-73-1	Basic	6-4-73		IV	Modification of Main Driveshaft Boot Assembly, P/N 204-040-176-3
204-04-73-2	Basic Rev A	4-30-73 6-8-73		IV	Tail Rotor Driveshaft, P/N 204-040-620-3 and -5
204-04-73-3	Basic	9-10-73		IV	Increase Torque of the Mast Lower Retainer Nut, P/N 204-040-309-1
204-04-73-4	Basic	9-10-73		IV	Special Tool, P/N T101586, Pusher Set
204-(04-2)-73-1	Basic	4-3-73		III	Scissors Assembly, P/N 204-011-406-15, and Tube Assembly (Mixing Lever to Scissors Assembly), P/N 212-010-404-5
204-06-73-1	Basic	8-2-73		VII	Alternate Hydraulic Pump, P/N PV3-044-8
204-13-73-1	Basic	1-2-73		-	Issuance of Technical Bulletin Will Replace Service Letter Publications Effective January 1973

BHT-204B-TB INDEX**204B TECHNICAL BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	SUBJECT
				REF.	
204-13-73-2	Basic	3-13-73		-	Component Exchange
204-13-73-3	Basic	3-27-73		I	Inspection of Airframe Dynamic Components
204-13-73-4	Basic	10-5-73		I	Announcements of Increase in Time-Between-Overhaul of Dynamic Helicopter Components
204-13-73-5	Basic	9-18-73		III	Fluorescent Penetrant Inspection
204-50-73-1	Basic	1-8-73		S.I.	Rotor Brake Assemblies (Goodyear)
204-(04-1)-74-1	Basic	8-27-74		II	Main Rotor Yoke Assembly, P/N 204-011-102-17, Spindle Replacement Dimension Change
204-05-74-1	Basic	11-27-74		VI	Dynamic Balance of Tail Rotor Hub and Blade Assembly, P/N 204-011-800 (All Dash Numbers)
204-011-74-1	Basic	6-25-74		VI	Lubrication of the Anti-Torque Silent Chain Assembly, P/N 205-001-721-1
204-13-74-1	Basic Rev A	3-8-74 9-19-74		-	Component Exchange
204-75-1	Basic	3-13-75		X	Ground Handling Gear Hydraulic Pump Repair Kit, P/N KH9000
204-76-1	Basic	3-5-76		-	To Provide Update Exchange Pricing Information Effective March 1, 1976
204-76-2	Basic	4-7-76		-	Warranty Claim Procedure and Return of Parts
204-76-3	Basic	7-8-76		VII	Flight Control Tubes and Bellcranks
204-77-1	Basic Rev A	4-6-77 6-21-77		II	Main Rotor Blade Splice Cover Assembly P/N 204-015-011-1

204B TECHNICAL BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
204-77-2	Basic Rev A	6-30-77 8-12-77		I	Assignment of 1000 Hour Service Life to Float Gear Forward Cross Tubes, P/N 204-706-053-3 and 204-706-053-75
204-77-3	Basic	10-10-77		VII	Inspection of Tail Rotor Servo Actuator, P/N 204-076-053-5, Vendor P/N 1660-17
204-77-4	Basic	10-11-77		IX	Transmission 42° and 90° Gearbox Assembly Electrical Chip Detector, P/N B752G and B7669B
204-77-5	Basic	10-18-77		S.I.	Rework Instructions for Cargo Hook Bumper Casting, P/N 204-072-901-1
204-78-1	Basic	2-28-78		X	Inspection and Maintenance of Emergency Exits
204-78-2	Basic	4-12-78		X	Replacement of Cargo Door Sliders, P/N 204-030-220-1
204-78-3	Basic	5-3-78		I	Announcement of Increase in Time-Between-Overhaul of Main Rotor Hub Assembly
204-78-4	Basic	5-17-78		II	Main Rotor Hub Assembly, P/N 204-012-101, Pillow Block Assembly Procedure
204-78-5	Basic	7-25-78		IV	Transmission Bevel Gear Attachment Bolts, P/N AN107607, Replacement of
204-78-6	Basic	11-27-78		V	Oil Cooler, P/N 204-060-594-5, Substitution
204-78-7	Basic	12-13-78		I	Forty-Two Degree Gearbox, P/N 204-040-003-37, Increase in Time-Between-Overhaul (T.B.O.)
204-78-8	Basic	12-21-78		IV	Transmission, P/N 204-040-009-61, Conversion to a 204-040-009-87 Transmission with a 2000 T.B.O. Interval

BHT-204B-TB INDEX**204B TECHNICAL BULLETIN INDEX**

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
204-79-9	Basic	1-23-79		I	Hydraulic Cylinder Assemblies, P/N 205-076-038 (All Dash Numbers), Removal of Mandatory Retirement Life
204-79-10	Basic	3-26-79		S.I.	High Skid Gear Forward and Aft Cross Tube Assemblies, P/N 205-050-403-31 and -33, Inspection and Rework
204-79-11	Basic	3-29-79		X	Structural Repair to Cabin Windshield Upper Longeron and Door Post, P/N 205-030-619
204-79-12	Basic	4-23-79		X	Repair of the Vertical Fin Forward Spar, P/N 205-030-846-49
204-79-13	Basic Rev A	7-30-79 9-5-79		I	M/R Mast Assembly, P/N 204-040-366-5, -7 and -9, TBO Increase, Mast Bearing, P/N 212-040-136-001, 1000 Hr. Retirement Deletion
204-80-14	Basic	2-18-80		III	Swashplate Support Assembly, P/N 204-011-404-017, and Inner Ring Assembly, P/N 204-011-402-021, Installation of
204-80-15	Basic	6-2-80		VII	Cyclic, Collective, and Tail Rotor Control Installations; Damage and Repair Limits of Bellcrank, Lever, and Support Assemblies Under the Cabin Floor Area
204-80-16	Basic	10-1-80		S.I.	High Skid Gear Kit, P/N 205-706-078-001, with Crosstubes, P/N 205-050-403-301 and -033, Provision for
204-81-17	Basic	2-12-81		VII	204B Elevators, P/N 204-030-858-053 and -054, and Elevator Horn, P/N 204-001-937-5, Installation of
204-81-18	Basic Rev B	6-10-81 3-14-84		V	Engine Driveshaft Adapter, P/N 204-040-812-003, Rework of
204-81-19	Basic	9-22-81		II	Main Rotor Hub Assembly, P/N 204-012-101 (All Dash Numbers), Modification of Grease Lubrication

204B TECHNICAL BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
204-82-20	Basic	7-19-82		S.I.	Suspension Assembly - Cargo, P/N 204-072-915-101 and Prior, Modification of
204-83-21	Basic	3-7-83			Kaflex ® Driveshaft P/N 204-040-433-101, Installation and Inspection of
204-83-22	Basic	12-1-83			3 Micron Transmission Oil Filter, P/N 204-040-433-101, Installation of
204-85-23	Basic	2-1-85			Gearbox Assembly, Intermediate and Tail Rotor, Modification of
204-85-24	Basic Rev A	11-1-85 6-25-86			Tail Rotor Blade, P/N 204-011-702 (All Dash Numbers), Improved Visibility Paint Scheme
204-86-25	Basic	4-28-86			Main Rotor Grip Seal, P/N S12561-341, Replacement
204-87-26	Basic	8-17-87			Markings Installation, P/N 204-072-693-1, -3, -9, and -11, Tail Rotor Hazard Warning Decals, Addition of
204-87-27	Basic	9-28-87			Rotor Brake Assembly, Modification of
204-88-28	Basic Rev A	2-8-88 2-17-88			Addition of Identification Decal on Aircraft Exterior
204-89-29	Basic Rev A	8-14-89 6-19-90			Airborne Canister Type Fuel Boost Pump Assembly P/N 206-062-687-101 Installation of
204-89-30	Basic	11-27-89			Mast Assembly P/N 204-040-366-007, -009, -013, -015, -017, -021, Configuration Change and Upgrade
204-90-31	Basic	2-7-90			Swashplate and Support Assembly P/N 204-011-400, Configuration Change and Upgrade

BHT-204B-TB INDEX

204B TECHNICAL BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	SUBJECT
				REF.	
204-90-32	Basic Rev A	4-12-90 5-22-90			Main Rotor Hub Assembly P/N 204-011-101 and 204-012-101, Configuration Change and Upgrade
204-90-33	Basic Rev A	5-17-90 8-3-90			MRC Duplex Bearings P/N 204-040-424-001, Inspection and Recall
204-91-34	Basic	2-5-91			Stablizer Bar Assembly P/N 204-011-326 and P/N 212-010-300, Configuration Change and Upgrade
204-91-35	Basic	3-5-91			Main Transmission Fuel Flow Debris Monitor
204-91-36	Basic	6-26-91			Transmission Oil Pump Key P/N 38-56007-1003-2 and MS35756-3 Which Were Supplied As Spares, Replacement of
204-92-37	Basic	1-27-92			Scissors and Sleeve Assembly P/N 204-011-401, Configuration Change and Upgrade
204-92-38	Basic	3-3-92			Sump Case Assembly P/N 204-040-355-005, Rework Procedures to Reduce the Size of the Chip Detector Boss Entry-Countersink
204-94-39	Basic	11-28-94			Rotor Brake Assembly, Introduction of Stainless Steel Piston
204-95-40	Basic	9-18-95			Pillow Block Bushing 204-011-135-105, Increase in Retirement Life
204B-98-41	Basic	4-22-98			Elevator Horn Rework
204-98-42	Basic	9-9-98			Breeze-Eastern Customer Service Bulletin: A60LT Cargo Hooks
204-99-43	Basic	2-10-99			Improved Pitch Horn to Main Rotor Grip Attachment Hardware
204-99-44	Basic	3-19-99			Tail Rotor (T/R) Gearbox Speedi-Sleeve P/N 99143 Addition of

204B TECHNICAL BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
204-00-45	Basic	6-30-00			Cyclic and Collective Jackshafts, Inspection and Modification of
204-00-46	Basic	4-14-00			Elevator Assy and Elevator Horn Assy, Increase in Retirement Life
204-03-47	Basic	10-20-03			Swashplate and Support Assembly, Bolt 204-011-463-107, Introduction of
204-03-48	Basic	10-29-03			Mast Assembly P/N 204-040-366-015 (With Bearing P/N 212-040-136-001 Installed) and Mast Assemblies 204-040-366-017, 021, Increase in Time-Between-Overhaul (TBO)
204-04-49	Basic	6-28-04			Transmission Oil Pump 212-040-184-001, Modification of
204-05-50	Basic	5-11-05			Bearing and Liner Assemblies P/N 204-010-433-001 and P/N 204-011-443-001: Installation Improvements

NOTICE

The following blank pages are provided for entry of additional bulletins when distributed. These additional bulletins will be included in this index at next revision.

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
---------------	--------------	-------------	---------------	--------------------------	----------------

BHT-204B-TB INDEX

NOTICE

The following blank pages are provided for entry of additional bulletins when distributed. These additional bulletins will be included in this index at next revision.

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
--------	-------	------	--------	------------------	---------