



TECHNICAL BULLETIN INDEX

THE ATA/CHAP. REF. COLUMN INDICATES THE MAINTENANCE AND/OR OVERHAUL MANUAL CHAPTER/S AFFECTED BY THE RESPECTIVE BULLETIN; OR, THE BULLETIN IS APPLICABLE TO A SERVICE INSTRUCTION (S.I.).

PROPRIETARY RIGHTS NOTICE

These data are proprietary to Bell Helicopter Textron, Inc. Disclosure, reproduction, or use of these data for any purpose other than helicopter operation is forbidden without prior written authorization from Bell Helicopter Textron, Inc.

Newly released Technical Bulletins can be viewed and printed by accessing our Service Directives website at www.bellcustomer.com. This publication supersedes BHT-222U-TB INDEX dated 1 January 2007 in its entirety.

COPYRIGHT NOTICE
COPYRIGHT 2008
BELL® HELICOPTER TEXTRON INC.
AND BELL HELICOPTER TEXTRON
CANADA LTD.
ALL RIGHTS RESERVED

Bell Helicopter
A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

1 JANUARY 2008

222U TECHNICAL BULLETIN INDEX

STATUS CODE

A = Active

A- () = Active — (Additional Information)

└────────────────── P = Incorporated in Parts Catalog
R = Referenced in Maintenance Manual

I = Inactive

I- () = Inactive — (Reason)

└────────────────── I = Incorporated in Maintenance Manual
P = Incorporated in Parts Catalog
S = Superseded (New Bulletin Number)
R = Referenced in Maintenance Manual

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
222-83-60	Basic	9-23-83		52	Door Hinge Fitting P/N 222-031-131-101 and -102, Installation, Inspection, and Modification of
222-83-62	Basic	10-24-83		65	Swashplate Drive Link, Load Reduction
222-83-63	Basic	12-9-83		66	Tail Rotor Gearbox Output Sleeve Lug Corrosion Protection, Increase of
222U-84-1	Basic	1-20-84		96	Engine MGT Trim Compensator, P/N 222-076-342, Rewiring of
222U-84-2	Basic	1-25-84		66	222 Main Input Shaft, Balance of
222U-84-3	Basic	4-12-84		95	Alternate Static Air Source Kit, P/N 222-706-019-103, Addition of
222U-84-4	Basic	5-1-84		96	Voltage Regulator, P/N 222-375-060-107, Replacement of
222U-84-5	Basic	6-8-84		96	Relay Coil Suppression Zener/ Diode Assemblies, P/N 30-126-5AA, Reversal of
222U-84-6	Basic	7-16-84		27	Directional Control Tube, P/N 222-001-088-101, Wear Sleeve Replacement
222U-84-7	Basic	7-27-84		96	Caution Annunciator Panel, P/N 222-375-010-123, Modification of

BHT-222U-TB INDEX

222U TECHNICAL BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
222U-84-8	Basic	8-10-84		66	Weight Arm, P/N 222-031-611-109 and -111, Cam Arm, P/N 222-031-639-105 and-107, Installation of
222U-84-9	Basic	9-5-84		66	Modification of Prevent Transmission Input Quill Assembly Seal Housing(s) From Draining Onto Nodal Beam Arm(s)
222U-84-10	Basic	11-5-84		96	Voltage Regulator, P/N 222-375-060-113, Replacement of
222U-84-11	Basic	12-13-84		29	Hydraulic System Modules, P/N 222-380-020-001, Bracing of
222U-85-12	Basic	1-17-85		65	Swashplate Boot, P/N 222-010-494-101, Replacement of
222U-85-13	Basic Rev A	1-22-85 6-6-85		21	Engine Bleed Air System, Modification of
222U-85-14	Basic	1-24-85		32	Ground Handling Gear, P/N 212-050-200-005, Modification of
222U-85-15	Basic	2-14-85		65	Swashplate Ball Sleeve Assembly, P/N 222-010-405-115, Added Inspection Criteria and Improvement of
222U-85-16	Basic	3-15-85		53	Main Rotor Tie-Down, Provisions for
222U-85-17	Basic	5-1-85		65	Tail Rotor Blade, P/N 222-016-001-107, Root Closure Repair
222U-85-18	Basic	11-1-85		65	Tail Rotor Blade, P/N 222-016-001-101/-107, Improved Visibility Paint Scheme
222U-85-19	Basic	11-11-85		71	Aft Fairing, P/N 222-061-824-133, and Ejector Assembly, P/N 222-062-216-101, Modification of
222U-86-20	Basic	3-26-86		52	Retainer Secured (Push Out) Passenger Compartment Windows
222U-86-21	Basic	5-22-86		29	Hydraulic System Installation, PCI and PCII, Replacement of 2014/2024 Aluminum Alloy Flareless Tube Fittings

222U TECHNICAL BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
222U-86-22	Basic	8-5-86		53	Roof Assembly, P/N 222-031-501, Inspection and Modification of
222U-86-23	Basic	11-6-86		65	Lever Assembly, P/N 222-012-715-001, Modification of
222U-86-24	Basic	11-25-86		27	Directional Hydraulic Actuator Support, P/N 222-001-730-005, Modification of
222U-86-25	Basic	12-9-86		27	Quick Disconnect Cyclic Control Stick Replacement of Pins, P/N NAS607-3-4P
222U-87-26	Basic	2-5-87		71	Engine Inlet Screen Assembly, P/N 222-062-215, Inspection of
222U-87-27	Basic	2-26-87		96	Caution Annunciator Panel, P/N 222-375-010-123, -131, Ref. Midland Ross/Division Service Bulletin 80-0500-33-0003, Rev A
222U-87-28	Basic	6-12-87		5	Main Driveshaft Assemblies, Calendar Inspection, Addition of
222U-87-29	Basic	6-17-87		5	Main Transmission, P/N 222-040-003-111, and Tail Rotor Gearbox, P/N 222-042-001-007, Increase in Time-Between-Overhaul
222U-87-30	Basic	6-25-87		26	Fire Detection System, Component Changes
222U-87-31	Basic	8-13-87		53	Wing to Fuselage Attach Bolts, Adding Washer to Improve Clamping
222U-87-32	Basic	8-14-87		21	Cyclic and Collective Control System Balance Springs, Adjustment Procedures
222U-87-33	Basic	8-17-87		11	Markings Installation, P/N 222-020-610-107, -113, -117, and -121, Tail Rotor Hazard Warning Decals, Addition of
222U-87-34	Basic	8-18-87		96	Voltage Regulator, P/N 222-375-060-113, Addition of Bonding Strap

BHT-222U-TB INDEX

222U TECHNICAL BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	SUBJECT
				REF.	
222U-87-35	Basic	9-3-87		29	Hydraulic System Reservoirs, Installation of Elbow with Filter Screen and Removal of Baffle
222U-87-36	Basic Rev A	9-14-87 10-20-87		66	Nodal Beam Weight Arm Cam Bearing, Provision for Lubrication
222U-87-37	Basic	9-18-87		29	Hydraulic System Modules, Installation of Bracing
222U-87-38	Basic	9-24-87		66	Rotor Brake Assembly, Modification of P/N 4000424-1
222U-87-39	Basic	10-20-87		52	Heated Birdproof Windshields, Interior Surface Waxing to Enhance Service Life
222U-87-40	Basic	12-9-87		65	Swashplate Drive Link Bolt, P/N 20-057-9-950, Torque Increase
222U-87-41	Basic	12-16-87		65	Main Rotor Trunnion Bolts, P/N NAS626-8, Installation and Retorque Inspection
222U-87-42	Basic	12-21-87		66	Transmission Stop Water Shield, Installation of
222U-88-43	Basic	2-8-88		11	Addition of Identification Decal on Aircraft Exterior
222U-88-44	Basic Rev A	5-27-88 11-18-91		53	Right Side Roof Beam, P/N 222-031-583-102 or 222-031-583-104 Removal and Replacement of
222U-88-45	Basic	6-27-88		29	Hydraulic Pump, P/N 222-380-009-103, (Abex Model AP1V-47, P/N 65132) Replacement of External Driveshaft
222U-88-46	Basic	9-29-88		27	Flight Control Actuators, P/N 222-382-001-101 and 222-382-002-101 Incorporation of Dual Retention of Servo Linkage Optional Low-Gain Control Valve Assembly for the 222-382-002-101
222U-89-47	Basic	5-2-89		29	Prevention of Hydraulic System Flexible Hose Chafing

222U TECHNICAL BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
222U-89-48	Basic Rev B	5-15-89 8-4-00		65	Main Rotor Hub Assembly, P/N 222-011-101-105/-107, Configuration Change and Upgrade
222U-89-49	Basic Rev A	6-2-89 2-22-94		65	Main Rotor Blade, P/N 222-015-600-101/-105 and -107 Retirement Life, Increase of
222U-89-50	Basic	6-6-89		66	Mast Assembly P/N 222-040-002, Configuration Change and Upgrade
222U-89-51	Basic Rev C	6-22-89 4-18-06		65	Swashplate and Levers Assemblies P/N 222-010-400, Configuration Change and Upgrade
222U-89-52	Basic	6-23-89		65	Main Rotor Pendulum Damper Shaft P/N 222-011-113-101, Modification of
222U-89-53	Basic	9-27-89		25	Ten Place Seating Configuration, Three Main Forward Facing-Passenger Seat Assembly, P/N 222-020-703-101, Seat Folding Instructions, Addition of
222U-89-54	Basic Rev A	10-5-89 8-10-90		5	Main Transmission P/N 222-040-003-111, and Tail Rotor Gearbox, P/N 222-042-001-007, Increase in Time-Between-Overhaul
222U-90-55	Basic	2-28-90		71	Inspection and Modification of Tailpipe Assembly P/N 222-063-307-107, -108, -141, and -142 to Accommodate LTS 101-750 Engine Power Turbine Rotor Mechanical Retention System
222U-91-56	Basic	1-15-91		53	Roof Installation P/N 222-031-501-ALL, Modification of
222U-91-57	Basic	2-5-91		66	Introduction of P/N 222-031-662-105/-107 Lift Link Rod End Bearing Assemblies
222U-91-58	Basic	9-27-91		53	Replacement of Horizontal Stabilizer Auxiliary Fin Attachment Screws, P/N AN525-10R7

BHT-222U-TB INDEX

222U TECHNICAL BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	SUBJECT
				REF.	
222U-92-59	Basic	5-6-92			Oil Cooler Blower Assembly, P/N 222-365-515-101/-103, Modification and Upgrade to the -105 Configuration (Torlon Drive)
222U-92-60	Basic	5-14-92			Collective Lever Assembly P/N 222-010-497-105 and Cyclic Lever Assembly P/N 222-010-408-109, Modification of
222U-92-61	Basic	5-14-92			Main Rotor Flight Control Actuators P/N 222-382-001-101/-103, Modification of
222U-92-62	Basic	8-27-92			Trunnion Shimming Procedure, Tail Rotor Hub, Alternate Methods
222U-93-63	Basic	11-24-93			Swashplate Cyclic Link P/N 222-010-419-101/-106, Upgrade
222U-93-64	Basic	11-24-93			Standby Attitude Indicator, Lighting Level, Decrease of
222U-94-65	Basic	2-17-94			Tailboom Reinforcement Doubler Installation
222U-94-66	Basic	3-14-94			Emergency Float Arm Annunciator Switch, P/N 10648BH1-19, Relocation of
222U-94-67	Basic	5-6-94			Maintenance Step Installation, Roof Right Hand Side
222U-94-68	Basic	5-11-94			Introduction of P/N 230-366-001-101 Drain Valve, Upper Auxiliary Fuel Kit Provisions P/N 222-706-204-123
222U-94-69	Basic Rev A	5-23-94 10-16-95			Tail Rotor Controls, Improvement
222U-94-70	Basic	5-23-94			Power Trim Check (Topping), 6 Percent Delta Topping Stop Assembly LTCT 12725-01, Introduction of
222U-94-71	Basic	9-29-94			Directional Control Tube P/N 222-001-088-101/-107/-109, Modification of
222U-94-72	Basic	11-4-94			Bulkhead Station 270 Reinforcement Doubler Installation

222U TECHNICAL BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	SUBJECT
				REF.	
222U-94-73	Basic	11-28-94			Rotor Brake Assembly, Introduction of Stainless Steel Piston
222U-94-74	Basic	12-12-94			Main Rotor Hub and Blade Assembly, Chordwise Balance Capability Increase
222U-94-75	Basic	12-23-94			Hydraulic System Reservoir, Installation of Baffle
222U-95-76	Basic	5-1-95			Baggage Compartment Door Handle, Modification of
222U-95-77	Basic	6-19-95			External Power (2K1), Bus Interconnect (2K2), No. 1 Generator (2K5) and No. 2 Generator (2K6) Contactors, Upgrade of
222U-95-78	Basic	8-28-95			Controllable Searchlight P/N 45-0128-3, and 930-500-25-1, Alternate Lamp, Authorization of
222U-95-79	Basic	9-11-95			Flapping Springs P/N 222-310-117-105, Introduction of
222U-95-80	Basic	10-30-95			BHT-222U-MM-2, Temporary Revision, 25 October 95
222U-95-81	Basic	11-20-95			Driveshaft Outer Coupling P/N 222-044-672-101, and Inner Coupling P/N 222-044-607-003, Corrosion Protection of
222U-96-82	Basic	8-5-96			Tail Rotor Driveshaft Hanger Assembly P/N 222-044-003-101/-103/-105/-107, Modification of
222U-96-83	Basic	8-30-96			Improved Passenger Door Lock Switch, Installation
222U-98-84	Basic Rev A	6-17-98 7-6-98			Vertical Fin Assembly, Installation Modification
222U-98-85	Basic	6-8-98			Horizontal Stabilizer Slat, Introduction of
222U-98-86	Basic	9-17-98			Swashplate Drive Assembly, Configuration Change and Upgrade of

BHT-222U-TB INDEX

222U TECHNICAL BULLETIN INDEX

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP	
				REF.	SUBJECT
222U-98-87	Basic	11-30-98			Main Rotor Flight Control Actuator, -107 Introduction of
222U-99-88	Basic	10-20-99			Tail Rotor Gearbox, P/N 222-042-001-007, -101 and -103, Configuration Change and Upgrade of
222U-00-89	Basic	5-1-00			Transmission Longitudinal Restraint Installation Retrofit
222U-00-90	Basic	5-1-00			Transmission Assembly P/N 222-040-003-111, -119 and -123, Configuration Change and Upgrade
222U-00-91	Basic	10-23-02			Honeywell LTS 101 Engine, Introduction of Flexible Fuel Manifold Assembly
222U-01-92	Basic	1-19-01			Main Driveshaft Assembly P/N 222-044-006-111, Introduction of
222U-01-93	Basic	4-16-01			Fuel Vent Assembly P/N 430-060-004-101, Introduction of
222U-02-94	Basic	3-25-02			Transmission Top Case Bushings P/N 222-040-326-101, Replacement of
222U-02-95	Basic	10-14-02			Improved Nose Frahm Bulkhead Support Assemblies, Installation of
222U-03-96	Basic	6-11-03			Fuel Valve Switch, Rewiring of
222U-03-97	Basic	6-18-03			Tail Rotor Guard Support, Improvement of
222U-04-98	Basic	10-28-04			Bulkhead STA.270, Improvement of
222U-06-99	Basic Rev A	5-23-06 2-13-07			Tail Rotor Blades 222-016-001-139 and Tail Rotor Yoke Assembly 222-012-702-113, Introduction of

NOTICE

The following blank pages are provided for entry of additional bulletins when distributed. These additional bulletins will be included in this index at next revision.

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
---------------	--------------	-------------	---------------	--------------------------	----------------

BHT-222U-TB INDEX

NOTICE

The following blank pages are provided for entry of additional bulletins when distributed. These additional bulletins will be included in this index at next revision.

NUMBER	ISSUE	DATE	STATUS	ATA/CHAP REF.	SUBJECT
--------	-------	------	--------	------------------	---------