



INFORMATION LETTER INDEX

COPYRIGHT NOTICE

COPYRIGHT 2011
BELL © HELICOPTER TEXTRON INC.
AND BELL HELICOPTER TEXTRON
CANADA LTD.
ALL RIGHTS RESERVED

Bell *helicopter*

A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

04 OCTOBER 2011

204B INFORMATION LETTER INDEX

NUMERICAL INDEX

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
IL 204-81-1	Basic	20-Apr-81	Swashplate Support Assembly P/N 204-011-404-017
IL 204-84-2	Basic	1-Aug-84	Tailboom Attachment
IL 204-86-3	Basic	9-Jan-86	Salvage Repair for Main Rotor Grips, P/N204-011-121-001, -005, AND -009
IL 204-87-4	Basic	28-Jan-87	Hydraulic Pump, P/N PV3-044-8A, Installation of
IL 204-88-5	Basic	10-Oct-88	Main Rotor Hub Retention Strap P/N 204-310-101-101
IL 204-90-6	Basic	28-Nov-90	Main Rotor Yoke Pillow Block Bushing Bore Repairs
IL 204-00-7	Basic	28-Feb-00	Inspection of Airborne Cartridge/Canister Fuel Boost Pumps for Presence of Check Valve
IL 204-00-8	Basic	20-Apr-00	Main Rotor Mast 204-011-450-001/-007/-105/-113/-119; Inspection and Retirement Index Number (RIN) life Reduction
IL 204B-00-9	Basic	2-Jun-00	Main Rotor Grip 204-011-121-121
IL 204B-00-10	Basic	3-Aug-00	Federal Aviation Administration (FAA) AD 2000-15-52
IL 204-00-11	Rev A	7-Aug-00	Federal Aviation Administration (FAA) AD 2000-15-52 Alternate Means of Compliance (AMOC) Statement for Trunnions 204-011-105-001 and 204-011-105-103
IL 204-00-12	Basic	18-Aug-00	Status Report on Medium Mast ASB 204-00-51
IL 204-00-13	Basic	1-Sep-00	Status Report on Medium Mast ASB 204-00-51
IL 204-01-14	Basic	8-Jan-01	Fin Spar Assembly Replacement
IL 204-01-15	Basic	20-Mar-01	Status Report on Medium Mast ASB 204-00-51
IL 204B-01-16	Basic	20-Jun-01	Improved Bearing with Silver-plated Steel Cage, Introduction of
IL 204-01-17	Basic	29-Nov-01	Status Report on Medium Helicopter Mast ASB 204-00-51
IL 204B-02-18	Basic	10-Dec-02	Improved Wiper Motors P/N 204-070-907-103/104
IL 204B-03-19	Basic	30-Sep-03	Main Rotor Grip 204-011-121-005/-009/-117/-121 Ultrasonic Inspection Courses
IL 204-04-20	Rev B	14-Sep-10	BLR FastFin and Strake Installation on All Bell 204, 205, 205B, and 212 Model Helicopters
IL 204-05-21	Basic	29-Mar-05	Main Rotor Drag Brace P/N 204-011-140-ALL
IL 204-06-22	Basic	13-Dec-06	Change to Recommended Intervals for Planned Maintenance of Breeze-Eastern Rescue Hoists and Cargo Winches
IL 204-08-23	Rev A	23-Jul-08	Grip Assembly P/N 204-011-121-125, Introduction of
IL 204-10-24	Rev A	1-Apr-10	Derived Empty Weight Clarifications

GENERAL INFORMATION LETTER INDEX

NUMERICAL INDEX

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
IL GEN-35:COA:ms-8833	Basic	6-Oct-77	Replacement of Grease P/N 204-040-755-3 (ANDEROL L786 OR R-508) with Grease P/N 204-040-755-5 (SYN TECH 3913-G1)
IL GEN-35:AJS:ms-9146	Basic	30-Jan-78	Cracked Main Rotor Yoke P/N 204-011-102
IL GEN-35:EAM:ms-9227	Basic	4-Mar-78	Inter Turbine Temperature Indicator Modification
IL GEN-35:GEH:ms-9379	Basic	17-Apr-78	AL-T3 Torque Ctrl Exchange Program
IL GEN-35:GEH:ms-9599	Basic	12-Jun-78	Idle Gear Failures
IL GEN-35:TKF:ms-9628	Basic	29-Jun-78	Gear Failure (-701) Referred to in OSN 212-78-1
IL GEN-35:COA:ms-9801	Basic	5-Oct-78	New Mast Bearing P/N 212-040-136-1
IL GEN-35:GAZ:oab-2102	Basic	11-Dec-78	New Bell Helicopter Textron Warranty for New Helicopters and Spares Delivered January 1, 1979 and Subsequent
IL GEN-35:COA:ms-9950	Basic	13-Dec-78	Inspection of Metal Contaminated Transmissions
IL GEN-35:CFB:ms-9963	Basic	20-Dec-78	(Idle Gear)
IL GEN-79-1	Basic	9-Feb-79	Agenda for 1979 Management, Flight & Maint Conf
IL GEN-79-2	Basic	29-Mar-79	Revised Main Rotor Hub Overhaul Procedures
IL GEN-79-3	Basic	14-May-79	Models 206, 206L, 212 Availability of Trial Micro-Fiche Publications
IL GEN-79-4	Basic	1-Jun-79	CANCELED
IL GEN-79-5	Basic	23-Jul-79	Lord Kinematics Refurbished Parts
IL GEN-79-6	Basic	20-Aug-79	Undersize 205-040-176-101 and 212-040-176-7 Boots
IL GEN-79-7	Basic	22-Aug-79	Lubrication Frequency (Superseded by GEN-79-9)
IL GEN-79-8	Basic	10-Sep-79	Imminent Bearing Shortages
IL GEN-79-9	Basic	9-Nov-79	Lubrication Frequency (Supersedes GEN-79-7)
IL GEN-79-10	Basic	13-Nov-79	Stabilizer Bar Assy Component Overhaul Schedule
IL GEN-80-11	Basic	21-Apr-80	New Discrepancy/Malfunction Report Form
IL GEN-80-12	Basic	23-Apr-80	Care and Handling of Electrical Wire and Cable
IL GEN-80-13	Basic	23-May-80	Dust Ingestion and Sulfur Contamination
IL GEN-80-14	Basic	16-Jun-80	Termination of the Trial Micro Fiche Publications Program
IL GEN-80-15	Basic	3-Oct-80	Terminal Junction System
IL GEN-80-16	Basic	16-Dec-80	New Location & Teletype Numbers for Product Supt Dept
IL GEN-81-17	Basic	21-Apr-81	Chadwick-Helmuth Rotor Balancer
IL GEN-81-18	Basic	5-Aug-81	Repair of Tailrotor driveshafts with Missing Weights
IL GEN-81-19	Basic	11-Aug-81	CSR Effectiveness Questionnaire
IL GEN-81-20	Basic	14-Aug-81	Use of Alternate Parts in 204/205/212 XMSNs
IL GEN-81-21	Basic	1-Sep-81	Compressor Wash - All Model Turbine Engines
IL GEN-81-22	Basic	29-Sep-81	BHT Announces New Round of M&O Conferences
IL GEN-81-23	Basic	9-Dec-81	Bell Helicopter Textron Announces the Continuance of Maintenance & Operations Conferences
IL GEN-81-24	Basic	14-Dec-81	Grease P/N 204-040-755-5 (SYN Tech 3913-G1) Shelf Life
IL GEN-82-25	Basic	7-Apr-82	The Discrepancy/Malfunction Rpt (D/MR)

GENERAL INFORMATION LETTER INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
IL GEN-82-26	Basic	15-Jan-82	Availability of Wire Strike Protection for Bell Helicopters
IL GEN-82-27	Basic	17-Mar-82	Bell Helicopter Textron, Inc. Training Center Telephone Number Changes
IL GEN-82-28	Basic	15-Nov-82	Trend Monitoring Vibrations
IL GEN-83-29	Basic	26-May-83	Daily Inspections/Airworthiness Checks
IL GEN-84-30	Rev A	31-May-84	Royal Lubricants Co., Royco Turbine Oil 500 Usage Of
IL GEN-84-31	Rev B	17-Nov-92	Inspection Rqmts for Reservoirs & Valve Operating Squibs Used in Emergency Float & Fire Extinguisher Systems (Superseded by IL GEN-93-52)
IL GEN-84-32	Basic	12-Jun-84	Driveshaft Coupling Lubricant, P/N 204-040-755-005
IL GEN-84-33	Basic	24-Jul-84	Electric ARC Etching, Unauthorized Procedure
IL GEN-84-34	Basic	9-Aug-84	Grease P/N 204-040-755-5 (SYN Tech 3913-G1) Unauthorized Sources
IL GEN-84-35	Basic	9-Aug-84	Failure of Main Rotor Pitch Change Link Clevis, P/N 204-011-136-001
IL GEN-84-36	Basic	28-Nov-84	Use of Pressing Tool (Work Aid) when Inst. 205-040-301-001 Pinion in 204-040-424-001 Dup. Brg. Of Rotor BK Quill
IL GEN-84-37	Basic	28-Nov-84	Use of Pressing Plug & Sleeve when Installing 204-040-102-017 Pin in Duplex BRG. Of Gen. Drive Quill
IL GEN-84-38	Basic	6-Dec-84	High Density Terminal Junction Modules
IL GEN-85-39	Basic	10-Jan-85	Simmonds Precision Information Letter No. 84-01 Describing Deterioration of Rubber in Fuel Transmitters
IL GEN-85-40	Rev A	9-Jan-86	Protection of Elastomeric Components with Silicone Elastomers
IL GEN-86-41	Basic	5-Feb-86	Availability of Alternate Cable Cutter Cartridge
IL GEN-86-42	Basic	17-Mar-86	1986 MF&M Conference (Avis)
IL GEN-86-43	Basic	10-Jun-86	New Rotor Brake Linings
IL GEN-87-44	Basic	18-Feb-87	Lord Corporation Refurbishment/Exchange Parts Program
IL GEN-87-45	Basic	7-Apr-87	Plastic Media Blasting (PMB)
IL GEN-87-46	Rev A	4-Jan-88	Use of Illustrated Parts Catalogs
IL GEN-88-47	Rev B	22-Apr-92	MS21042 Series Nuts, Approved Vendors for
IL GEN-90-48	Basic	8-Oct-90	Accelerometer Minimum Specifications for Main Rotor Balancing Applications
IL GEN-91-49	Basic	9-Oct-91	Refurbishment of Parts Manufactured with K1001 (BLUE) Epoxy Resin Coating
IL GEN-92-50	Basic	20-Jan-92	Lord Corporation Remanufactured/Exchange Parts Program
IL GEN-92-51	Basic	4-Dec-92	Magnolia Magnobond 6392 Adhesive

GENERAL INFORMATION LETTER INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
IL GEN-93-52	Basic	21-Jun-93	Insp Rqmts for Res. & Valve Operating Squibbs Used in Emergency Float & Eng. Fire Ext. Sys & for Rescue Hoist Cable Cutter Squibbs
IL GEN-94-53	Basic	4-Mar-94	Powertrain Component Corrosion Prevention
IL GEN-94-54	Basic	15-Apr-94	Retirement Index Number (RIN) for Cycle Lived Components (Superseded by IL GEN-03-94)
IL GEN-96-55	Rev A	19-Oct-99	Improved Tail Rotor 90/42 Degree Gearbox Oil Filler Caps
IL GEN-97-56	Basic	10-Mar-97	Bell Helicopter Part Numbering System
IL GEN-97-57	Basic	24-Mar-97	Use of Noise Cancelling Headsets in Bell Helicopters
IL GEN-97-58	Basic	13-Nov-97	Castrol Aero 5734
IL GEN-98-59	Rev A	8-May-98	Folding Step Electrical Actuators P/N 212-075-418-107
IL GEN-98-60	Basic	1-Jun-98	RADS-AT User Training
IL GEN-98-61	Basic	12-Jun-98	A/C Modification & New E-Mail Addresses for Bell Helicopter Textron Canada
IL GEN-98-62	Basic	16-Nov-98	Flexure Style Main Rotor & Tail Rotor Yokes
IL GEN-99-63	Basic	13-Jan-99	Pressure Vessels, used as Nitrogen Reservoirs for Emergency Floatation Systems, Service Life Of
IL GEN-99-64	Basic	18-Jan-99	Airframe Damage Descriptions
IL GEN-99-65	Rev A	2-Jun-06	Interchangeability of Agusta & Bell Manufactured Parts
IL GEN-99-66	Basic	21-Jan-99	RADS-AT User Training
IL GEN-99-67	Basic	19-Mar-99	RADS-AT Y2K Problems
IL GEN-99-68	Basic	7-Sep-99	Access to Commercial Helicopter Service Directives
IL GEN-99-69	Basic	17-Nov-99	Gimbal Arm Corrosion and Maximum Service Life of SX-16 Nightsun or SX-5 Starburst Searchlight
IL GEN-00-70	Basic	25-Jan-00	Damage to Aluminum Rigid Lines Caused by Identification Tape
IL GEN-00-71	Basic	26-May-00	Technical Publications Revision Status Website
IL GEN-00-72	Basic	18-Jul-00	Cold Expansion Tools and Sleeves
IL GEN-00-73	Basic	8-Sep-00	Breeze Eastern 300 LBS Rescue Hoist P/N BL-16600-110 and BL-16600-170, and Aeronautical Accessories Inc (AAI) 300 LBS Rescue Hoist P/N 407-979-100
IL GEN-00-74	Basic	13-Nov-00	Post Wiring Inspection After Customizing Modification
IL GEN-00-75	Basic	16-Nov-00	Rotor Analysis and Diagnostic Systems (RADS-AT) Training Course
IL GEN-01-76	Basic	20-Mar-01	Procedure for Requesting BHT-Approved Structural Repair
IL GEN-01-77	Basic	26-Apr-01	Fuel Cell Shelf Life & Storage
IL GEN-01-78	Basic	26-Apr-01	Helicopter External Noise Levels
IL GEN-01-79	Basic	19-Jun-01	Turnbuckle Part Number 204-011-137-001 (Pitch Link Barrel)
IL GEN-01-80	Basic	25-Jun-01	Replacement of Exxon Turbine Oils by Air BP Oils

GENERAL INFORMATION LETTER INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
IL GEN-01-81	Basic	5-Jul-01	Rotor Analysis and Diagnostic Systems (RADS-AT) Training Course
IL GEN-01-82	Basic	28-Aug-01	Use of Unapproved Parts from Surplus Military Inventory
IL GEN-01-83	Basic	8-Oct-01	Type MA-6/8 Inertia Reel Assemblies
IL GEN-01-84	Basic	11-Oct-01	Primer on Rotor Brake Disc Friction Surfaces
IL GEN-02-85	Basic	6-Mar-02	Rotor Analysis and Diagnostic Systems (RADS-AT) Manufacturing/Support Changes and Upcoming Training Course
IL GEN-02-86	Basic	4-Apr-02	New Internet Service Provided to Bell Customers
IL GEN-02-87	Basic	5-Sep-02	RADS-AT Training
IL GEN-03-88	Basic	31-Jan-03	Defective NAS516-1A Grease Fittings
IL GEN-03-89	Basic	28-Feb-03	Inspection and Surface Protection of Steel Parts
IL GEN-03-90	Basic	4-Mar-03	New Repair Angle Standard
IL GEN-03-91	Rev A	8-Apr-09	Receipt of Service Directives On-line
IL GEN-03-92	Basic	8-Aug-03	Expansion of Product Support Engineering Service
IL GEN-03-93	Basic	13-Aug-03	Bearing Grease Lubricant
IL GEN-03-94	Basic	10-Oct-03	Expanded Use of Retirement Index Numbers (RIN)
IL GEN-03-95	Basic	21-Nov-03	Use of High-pressure Washer Around Helicopters
IL GEN-04-96	Basic	6-Jan-04	Procedure for Requesting BHT-Approved Structural Repairs
IL GEN-04-97	Basic	14-Jun-04	Hand Held Fire Extinguisher, Replacement of
IL GEN-04-98	Rev C	3-Mar-11	Changes to BHT Customer Property Return (CPR) Process
IL GEN-04-99	Basic	3-Aug-04	Superseded Rivets
IL GEN-04-100	Basic	1-Dec-04	Information Regarding the Handling and Testing of Cartridges
IL GEN-04-101	Basic	20-Dec-04	Rolls-Royce Technical Publications Delivered with New Production Helicopters
IL GEN-05-102	Basic	7-Feb-05	Wet Installation Primer Application
IL GEN-05-103	Basic	28-Feb-05	Seat Belt and Shoulder Restraint Webbing, Inspection Guidelines
IL GEN-05-104	Basic	15-Dec-05	Temperature Indicator "TEMP-PLATE" Sealer, Introduction of
IL GEN-06-105	Basic	12-Jan-06	2006 Maintenance & Operations (M&O) Conferences
IL GEN-06-106	Reissue	11-Jan-10	Availability of Electronic Publications
IL GEN-06-107	Basic	23-Aug-06	Procedure for Providing Customer/Contact Information
IL GEN-07-108	Basic	15-Jan-07	Clarification of Proper Assembly Torque Technique When Using Conical Seal Washers on Flared End Fittings
IL GEN-07-109	Basic	9-Feb-07	Clarification on Part Numbers Identification
IL GEN-07-110	Basic	16-Feb-07	Continuing Qualification and Maintenance of Pressure Cylinders and Squibs

GENERAL INFORMATION LETTER INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
IL GEN-07-111	Basic	20-Apr-07	Risk of FOD of Fluid and Pneumatic Systems Malfunction Due to Cap Plugs
IL GEN-07-112	Basic	20-Apr-07	Shelf Life of Temp-Plates P/N 6000-1, 6000-2 and 6000-3
IL GEN-07-113	Basic	17-Jul-07	Compatibility of Newly Installed Equipment
IL GEN-08-114	Basic	25-Feb-08	Artex Service Bulletins SN019 and SN020
IL GEN-08-115	Basic	16-Jun-08	Aircraft Model Designations and Applicability to Bulletins
IL GEN-09-116	Basic	16-Feb-09	SkyBOOKS Electronic Log Books, Introduction of
IL GEN-09-117	Basic	17-Nov-09	psemil214@bellhelicopter.textron.com E-mail Address, Inactivation of
IL GEN-10-118	Basic	12-Aug-10	Breeze-Eastern Cargo Hook Maintenance Concept
IL GEN-10-119	Basic	12-Aug-10	Applicability of Bulletins After Incorporation into the Maintenance Manual
IL GEN-10-120	Basic	22-Dec-10	New Bulletin Format
IL GEN-11-121	Basic	4-Oct-11	Operation of Bell Aircraft Near Volcanic Activity

BHT-ALL-IL-INDEX

NOTICE

The following blank pages are provided for entry of additional notices when distributed. These additional notices will be included in this index at next revision

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
-------------	---------------	------	---------