



**OPERATIONS  
SAFETY  
NOTICE INDEX**

**COPYRIGHT NOTICE**

COPYRIGHT 2011  
BELL © HELICOPTER TEXTRON INC.  
AND BELL HELICOPTER TEXTRON  
CANADA LTD.  
ALL RIGHTS RESERVED



A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

**19 SEPTEMBER 2011**



## 204B OPERATIONS SAFETY NOTICE INDEX

## NUMERICAL INDEX

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
OSN 204B-75-1	Basic	6-Nov-75	25 Hour Inspection of 204-001-739-3 Tail RotorChain
OSN 204-80-1	Basic	15-Sep-80	Inspection of Drag Brace Assembly, P/N 204-011-140-001 and -005
OSN 204-80-2	Basic	27-Oct-80	Removal and Installation of Trunnion Bearings P/N 204-011-451-001 on Swashplate Assemblies, P/N 204-011-400 Series
OSN 204-81-3	Basic	4-Dec-81	Main Transmission Bevel Gear Tooth Damage
OSN 204-84-4	Basic	1-May-84	Main Rotor Blade Repair
OSN 204-85-5	Basic	8-Oct-85	Inspection for Defective Universals, P/N 204-011-128-001, Vendor P/N DW-6ZZ, Main Rotor PitchLink Assemblies
OSN 204-85-6	Basic	14-Nov-85	Cracked Main Rotor Blade Grip, P/N 204-011-121-009
OSN 204-86-7	Basic	6-Jun-86	Airworthiness Directive: 86-09-05 Applicable to Avco Lycoming Division T5313B and T5317ATurboshaft Engines
OSN 204-87-8	Basic	21-Apr-87	Ground Handling Wheels Kits, P/N 214-706-104-001 and -103, and Gear Assemblies, P/N 212-050-200-001, -003, and -005, Inspection
OSN 204-87-9	Basic	2-Sep-87	"Suspect Bogus" Non-FAA Certified Tail Rotor Grip,P/N 205-011-711-101
OSN 204-88-10	Basic	9-Mar-88	Availability of a Wire Strike Protection System forBell Helicopters
OSN 204-89-11	Rev A	6-Apr-89	Failure of Main Transmission Spiral Bevel Gear
OSN 204-89-12	Basic	27-Jun-89	Failure of Anti-Torque Control Chain, P/N 204-001-739-003
OSN 204-89-13	Basic	24-Jul-89	Time Expired Tail Rotor Grips, P/N 204-011-728-19Being Refurbished and Sold as New Parts
OSN 204-89-14	Basic	1-Aug-89	Defective Universals, P/N 204-011-128-001, Vendor Code 10083, Main Rotor Pitch LinkAssemblies
OSN 204-90-15	Basic	23-Feb-90	Failure of Main Rotor Yoke P/N 204-011-102-125
OSN 204-90-16	Basic	3-Mar-90	Investigation of Failed Main Rotor Yoke P/N 204-011-102-125
OSN 204-90-17	Basic	9-Oct-90	Stress Corrosion Cracking of Main Rotor GripAssemblies P/N 204-011-121 Series
OSN 204-91-18	Basic	30-Jan-91	Main Rotor Blade Doubler Cracks
OSN 204-91-19	Basic	3-Sep-91	Installation of Tail Rotor Driveshaft HangerAssemblies P/N 204-040-600 and 212-040-600
OSN 204-93-20	Basic	30-Apr-93	Main Rotor Blade Skin Cracks
OSN 204-93-21	Basic	27-Aug-93	Cargo Door Emergency Escape Panel
OSN 204B-93-22	Basic	8-Dec-93	Excessive Tail Rotor Drive System Use Caused byRepeated Heavy Lift Operations
OSN 204-94-23	Basic	16-May-94	Flight Limitations
OSN 204-98-24	Rev A	1-Jul-98	Allied Signal T53 Engine Spur Gear Failure
OSN 204-00-25	Basic	24-Mar-00	Main Rotor Mast 204-011-450-ALL RetirementIndex Number Calculation and Bell HelicopterRequest for Information

## 204B OPERATIONS SAFETY NOTICE INDEX

## NUMERICAL INDEX (Cont)

<b>PUBLICATION</b>	<b>ISSUE/ REV</b>	<b>DATE</b>	<b>SUBJECT</b>
OSN 204-03-26	Basic	4-Sep-03	Drive Link P/N 204-011-407-001, Inspection of
OSN 204-06-27	Basic	10-Jan-06	Rod End Bearing Assembly P/N 212-010-123-101, Inspection of
OSN 204-07-28	Basic	26-Mar-07	FAA Unapproved Parts Notification 2006-00097
OSN 204-07-29	Basic	5-Jul-07	FAA Unapproved parts notification 2007-00089

## GENERAL OPERATIONS SAFETY NOTICE INDEX

## NUMERICAL INDEX

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
OSN GEN-76-1	Basic	21-Jan-76	Use of Life Vests During Over-water Operations
OSN GEN-76-2	Basic	23-Jan-76	Helicopter Accidents Caused by Ground Handling Errors
OSN GEN-76-3	Basic	24-Sep-76	Use of Standard Hardware
OSN GEN-76-4	Basic	13-Sep-76	Heavy Lift, Aft Center of Gravity, Prolonged Hover, Cyclic Control Abuse
OSN GEN-76-5	Basic	13-Sep-76	Fuel Contamination
OSN GEN-76-6	Basic	18-Oct-76	Collective Minimum Friction
OSN GEN-76-7			NOT USED
OSN GEN-76-8	Basic	22-Dec-76	Operation of Helicopters in Salt Laden Atmosphere
OSN GEN-77-1	Rev A	3-Nov-77	Airworthiness of Aircraft Parts
OSN GEN-78-1	Basic	10-Jan-78	Maintenance of the Main Rotor Blade Inspection System (B.I.S.)
OSN GEN-78-2	Basic	5-May-78	Cracked Main Rotor Yoke P/N 204-011-102
OSN GEN-78-3	Basic	13-Sep-78	Chadwick C-47 Electronic Weighing System, Load Cell Link P/N 47-40200-19
OSN GEN-78-4	Basic	11-Dec-78	Chaffed Oil Lines
OSN GEN-79-1	Basic	2-May-79	Cracked Main Rotor Yoke P/N 204-011-102
OSN GEN-79-2	Basic	26-Nov-79	Cracked Main Rotor Yoke P/N 204-011-102
OSN GEN-80-3	Basic	13-Feb-80	Cracked Main Rotor Blade, P/N 204-011-250 Series
OSN GEN-80-4	Basic	19-Jun-80	Rotating Control Bolts
OSN GEN-80-5	Basic	27-Jun-80	Enhancement of Crew and Passenger Safety During High Impact Landings
OSN GEN-80-6	Basic	27-Jun-80	Daily Inspection of Main Input Driveshafts
OSN GEN-80-7	Basic	24-Jul-80	Transporting Flammable Cargo
OSN GEN-81-8	Basic	22-Sep-81	Inspection of Tail Rotor Pitch Links
OSN GEN-82-9	Basic	6-Oct-82	Tail Rotor Driveshaft Curvic Couplings, Inspection, Maintenance
OSN GEN-83-10	Basic	1-Sep-83	Engine Compressor Washing
OSN GEN-85-11	Basic	6-Nov-85	Beware of "Certificate of Manufacture, Inspection and Conformance"
OSN GEN-87-12	Basic	13-May-87	FAA Airworthiness Directive 87-06-09 (Mechanical Products, Inc.)
OSN GEN-88-13	Reissue	5-May-92	Lines Extending from the Helicopter
OSN GEN-89-14	Basic	6-Dec-89	Bogus P/N 212-073-905-1 Pressure Gage, Emergency Floats
OSN GEN-91-15	Basic	29-Jul-91	Electromagnetic Compatibility (EMC) of Aircraft Wiring with Pyrotechnic Device and Cargo Hooks
OSN GEN-91-16	Basic	21-Aug-91	Airframe Structural Repair
OSN GEN-91-17	Basic	1-Oct-91	Main Driveshaft Assembly, Inspection of
OSN GEN-92-18	Basic	19-Mar-92	Proper Stowage of Miscellaneous Items in and Around the Flight Crew Compartment
OSN GEN-92-19	Basic	5-May-92	MS21042 Series Nuts Approved Vendors
OSN GEN-92-20	Basic	25-Jun-92	Use of Non-Conforming Floatbag Assemblies
OSN GEN-92-21	Basic	25-Jun-92	Lubricant P/N 204-040-755-005

## GENERAL OPERATIONS SAFETY NOTICE INDEX

## NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
OSN GEN-93-22	Basic	29-Jan-93	Main Rotor Vibration; Emphasis on Timely Investigation
OSN GEN-93-23	Basic	29-Jan-93	Maintenance/Overhaul Procedures
OSN GEN-93-24	Basic	1-Mar-93	Parts Authenticity and Traceability
OSN GEN-93-25	Basic	15-Dec-93	"Slingshot" Maneuvers in Heavy Lift Operations
OSN GEN-95-26	Basic	19-Jan-95	Aircraft Cleaning
OSN GEN-95-27	Basic	24-Mar-95	Tail Rotor Yoke (Flexure Style) Failure
OSN GEN-96-28	Basic	21-May-96	Transmission Spiral Bevel Gear Cracks
OSN GEN-96-29	Basic	18-Oct-96	Unapproved Tail Rotor Driveshaft Hanger Bearings
OSN GEN-97-30	Basic	27-Jan-97	Breeze-Eastern Customer Advisory Bulletin Number CAB-100-54
OSN GEN-97-31	Basic	1-May-97	Tail Rotor Hanger Bearings Maintenance
OSN GEN-02-32	Basic	2-May-02	Bogus Parts Tail Rotor Grips
OSN GEN-02-33	Basic	10-Oct-02	Maintenance/Overhaul Procedures
OSN GEN-02-34	Basic	22-Nov-02	Correct Procedure for Torquing Fasteners
OSN GEN-04-35	Basic	21-Sep-04	Cyclic Stick Grip Assembly
OSN GEN-06-36	Basic	17-Apr-06	Paint Application on Helicopter Faying Surfaces
OSN GEN-06-37	Basic	20-Jul-06	NAS 1291-7 and -8 Nut, Confirmation of Condition Upon Installation
OSN GEN-09-38	Basic	7-Apr-09	Bearings in Flight Controls
OSN GEN-09-39			RESERVED
OSN GEN-09-40	Basic	16-Nov-09	Onboard Systems International Alert Service Letter Document no. 159-027-00.
OSN GEN-10-41	Basic	18-Jan-10	Honeywell Bendix/King Discrepant Databases for KLN35A/KLN 88/KLN 89/KLN 89B/KLN 90/KLN 90A/KLN90B/KLN 94/KLX 100/KLX 135/KLX 135A/KLN 900
OSN GEN-10-42	Basic	13-Dec-10	Use of Specified Hardware
OSN GEN-11-43	Rev A	16-Sep-11	NAS1291 Nuts and NAS626 Bolts
OSN GEN-11-44	Basic	10-May-11	Defective Grease Fittings NAS516-1A

**NOTICE**

The following blank pages are provided for entry of additional notices when distributed. These additional notices will be included in this index at next revision

<b>PUBLICATION</b>	<b>ISSUE/ REV</b>	<b>DATE</b>	<b>SUBJECT</b>
--------------------	-----------------------	-------------	----------------