

BHT-206A/B/B3-IL-INDEX

Bell *MODEL* **206A/B** *SERIES*

INFORMATION LETTER INDEX

COPYRIGHT NOTICE

COPYRIGHT 2011
BELL © HELICOPTER TEXTRON INC.
AND BELL HELICOPTER TEXTRON
CANADA LTD.
ALL RIGHTS RESERVED

Bell *helicopter*
A Textron Company

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

04 OCTOBER 2011

206A/B/B3 INFORMATION LETTER INDEX

NUMERICAL INDEX

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
IL 206-35:GAZ:cm-3214	Basic	30-Jul-68	Correct Location of the Auxiliary Position Lights
IL 206-35:WJD:ay-199	Basic	12-Sep-68	JetRanger Snow Winterization Kit
IL 206-35:WJD:ay-301	Basic	11-Oct-68	Sudden Transmission Oil Temperature Increase
IL 206-35:SDY:jl-46	Basic	7-Nov-68	Model 206A Memo to Operators Form
IL 206-35:BJM:jl-71	Basic	9-Dec-68	Allison Engine Publications
IL 206-35:WJD:paw-658	Basic	27-Dec-68	Maintenance and Overhaul Instructions establishing a 1200 Hour Retirement Life for the Swashplate Duplex Bearing Set
IL 206-35:FJZ:jl-100	Basic	27-Jan-69	Interim Revision to the Maintenance and Overhaul Instructions
IL 206-35:JWC:jl-170	Basic	23-Jun-69	Damaged Inboard Cages in the Freewheeling Clutch
IL 206-35:WJD:jl-225	Basic	22-Aug-69	Temporary Flight Manual Revision for Gear Box listed in Allison's Commercial Service Letter 250CSL-34
IL 206-35:DEG:jl-298	Basic	19-Nov-69	Exchange of Servo Actuators (Reference Service Bulletin No. 206A-12)
IL 206-35:HVK:jl-950	Basic	5-Dec-69	Failure of Transmission Spiders, P/N 206-040-041-1
IL 206-35:JWC:jl-351	Basic	12-Feb-70	Ordering of Improved Transmission Spider and Shafts
IL 206-35:DEG:jl-350	Basic	24-Feb-70	Cyclic Feed Back Forces
IL 206-35:SDY:jl-448	Basic	22-Jul-70	Anticipated 206A Component Overhaul Date(s)
IL 206-35:FJZ:jl-451	Basic	24-Jul-70	Fatigue tests to extend retirement life of Mast and Main Rotor Blades
IL 206-35:FJZ:jl-1451	Basic	20-Oct-70	Fatigue tests to extend retirement life of Mast and Main Rotor Blades
IL 206-35:DEG:sg-1444	Basic	30-Oct-70	Difference Between Induction System Particles Separator Kits
IL 206-35:WJD:sg-1567	Basic	18-Dec-70	Main Rotor Blade Crack
IL 206-35:FJZ:sg-1780	Basic	15-Mar-71	Main Rotor Blade, P/N 206-010-201-29, Improvements
IL 206-35:WJD:ay-920	Basic	5-Apr-71	Airworthiness Directive Concerning Particle Separator Kit
IL 206-35:BJM:paw-1885	Basic	28-Apr-71	Solenoid Valve Corrosion
IL 206-35:BJM:paw-1977	Basic	9-Jun-77	Modification of Torquemeter, P/N 206-070-399-1
IL 206-35:BJM:paw-1998	Basic	17-Jun-71	JetRanger-II Operational Survey
IL 206-35:BJM:paw-2275			Field Service Test for Modified Power Governor Lever on Models 206A and 206B Helicopters
IL 206-35:TKF:kn-3639	Basic	29-Sep-71	Operation of Model 206 Series Helicopters in Snow
IL 206-35:DEG:paw-2234	Basic	18-Oct-71	Operation of Model 206 Series Helicopters in Snow
IL 206-35:BJM:paw-2284	Basic	29-Oct-71	Model 250C20 Engine Shut Down Procedures
IL 206-35:DEG:paw-10	Basic	6-Jan-72	Inspection and/or Replacement of Induction Fairing Fasteners
IL 206-35:WJD:paw-540	Basic	30-Jun-72	Investigation of Recent 206A Accident in Progress
IL 206-35:DEG:saf-2471	Basic	15-Dec-72	Inlet Air Deflector Kit, P/N 206-706-136-1 for Model 206 Series Helicopters

206A/B/B3 INFORMATION LETTER INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
IL 206-35:WJD:ay-1541	Basic	12-Apr-73	Zyglo Inspection of the 206-031-508 Link
IL 206-35:WJD:oab-1150	Basic	8-May-73	Information Required for Shipment of 206-031-589 Links and 206-031-592 and -593 Fittings
IL 206-35:WJD:oab-1328	Basic	6-Aug-73	Accident in the East River, New York City
IL 206-35:WJD:oab-1540	Basic	6-Nov-73	Altimeter, P/N 206-070-263
IL 206-35:CJR:oab-1609	Basic	6-Dec-73	Battery Temperature Monitor System
IL 206-35:TKF:mjl-1118	Basic	14-May-74	Discontinue Bell JetRanger II (Model 206A) Flight Manual
IL 206-35:TKF:mjl-1119	Basic	14-May-74	Technical Publications Binders
IL 206-35:LAR:mjl-1225	Basic	5-Aug-74	Main Transmission, Main Case Overhaul Replacement Dimensions
IL 206-35:CJR:ia:1291	Basic	22-Aug-74	FAA Approval of Northrop Corporation
IL 206-35:WJD:mjl-1381	Basic	10-Oct-74	Details Concerning Shipment of 206 Grips to BHC
IL 206-35:DEG:mjl-1461	Basic	30-Oct-74	206-706-032-1 Rotor Brake
IL 206-35:CJR:cb-1536	Basic	9-Dec-74	Airworthiness Directive (AD-74-24-13) Concerning Altimeters
IL 206-35:LAR:cb-1566	Basic	20-Dec-74	Tail Rotor Drive Installation Incorporating Clamp Type Bearing Hangers with Springs
IL 206-35:LAR:cb-1567	Basic	6-Jan-75	Model 206A-206B IPB Correction
IL 206-35:DEG:eg-1030	Basic	30-Jan-75	Hoist Kit P/N 206-706-126-1
IL 206-35:LAR:saf-1623	Basic	7-Feb-75	Tail Rotor Drive Installation Incorporating Clamp Type Bearing Hangers with Springs
IL 206-35:WJD:ay-16	Basic	12-Feb-75	Main Rotor Pitch Link Clevis
IL 206-35:FJZ:cb-1640	Basic	15-Feb-75	Lubrication of Model 206 Main Rotor hubs
IL 206-35:FJZ:ay-058	Basic	15-Apr-75	P/N 206-010-710-1 and -3 Tail Rotor Pitch Links
IL 206-35:TKF:mjl-1804	Basic	30-Apr-75	Jet Ranger Boost Pump Operation
IL 206-35:JWC:mjl-1884	Basic	10-Jun-75	Use of Bell Standard Bolts in Lieu of Blue Dyed Head Bolts
IL 206-35:TKF:mjl-2021	Basic	15-Aug-75	Reconditioned Spare Parts
IL 206-35:FJZ:mjl-2108	Basic	29-Sep-75	Model 206 Main Rotor Pitch Link Assemblies
IL 206-35:WJD:ay-308	Basic	8-Dec-75	206-010-200-29 Main Rotor Blades - Special Warranty Credit
IL 206-35:WJD:je-3304	Basic	3-Jun-76	206B Accident
IL 206-35:TKF:je-4004	Basic	21-Jul-76	Accident near Carson City, Nevada
IL 206-35:MP:oab-1243	Basic	2-Dec-76	Component Exchange
IL 206-35:DLT:je-4356	Basic	12-Jan-77	Engine N2 Operating Speed Recommendation
IL 206-35:GG:je-4537	Basic	22-Mar-77	Accident in the Gulf of Mexico
IL 206-35:LAR:je-4560	Basic	1-Apr-77	Tapping Noise from Main Transmission
IL 206-35:DLT:je-4641	Basic	27-Apr-77	Temporary Revision to the Allison 250-C20 Series Operation and Maintenance Manual
IL 206-35:DLT:je-4673	Basic	6-May-77	Engine, Compressor Bleed Valve Strainer Assembly-Add
IL 206-35:LAR:je-4861	Basic	24-Jun-77	Model 206A/B Main Transmission Overhaul
IL 206-35:DLT:je-4932	Basic	8-Aug-77	Transitory Rotor RPM Droop

206A/B/B3 INFORMATION LETTER INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
IL 206-06:RVO:jj-423	Basic	15-Dec-77	Component Exchange
IL 206-35:JAS:jl-5962	Basic	26-Sep-78	Fan Driveshaft Bearing Hanger
IL 206-35:DEG:jl-5995	Basic	6-Oct-78	Service Instruction No. 206-112 Retrofit Kit Engine Assembly 250-C20B
IL 206-35:RTH:jl-6061	Basic	17-Nov-78	External Clamping on Hydraulic Servo Cylinder Barrels P/N 206-076-031-5
IL 206-35:GMP:ay-884	Basic	20-Nov-78	Allison C20 or C20B Inadvertent Deceleration
IL 206-79-1	Basic	5-Mar-79	Oversize Swashplate Sleeve Bearings P/N 206-010-459-001
IL 206-79-2	Basic	5-Mar-79	Increased Wear Limits for Tail Rotor Blade Bearings P/N 206-010-765-001
IL 206-79-3	Basic	16-Apr-79	Fatigue Test of the 206B Hydraulic Boost Cylinder Support, P/N 206-011-566-001
IL 206-79-4	Basic	27-Apr-79	Repair of Main Rotor Grips P/N 206-010-102 with Damaged Blade Bolt Bores
IL 206-79-5	Basic	8-May-79	New Tail Rotor Hub Trunnion Configuration for Hub Assemblies, P/N 206-010-810-003, -009 and -015
IL 206-79-6	Basic	8-May-79	Inspection of Swashplate Bearing Seals P/N 206-010-460-001
IL 206-79-7	Basic	30-Jul-79	Return of Delivery Notice Information to Airesearch Aviation Company
IL 206-79-8	Basic	17-Aug-79	Installation of Fuel Extender Devices
IL 206-79-9	Rev A	6-Dec-79	Possible Increase in Tension-Torsion Strap Retirement Life
IL 206-80-10	Basic	18-Feb-80	Ground Handling Wheels
IL 206-80-11	Basic	5-Mar-80	Announcement of Alternate Source for Bearings
IL 206-80-12	Basic	12-Mar-80	206B III Mast Assembly, 1200 Hour Inspection
IL 206-80-13	Basic	16-Apr-80	Engine External Scavenge Oil Filter
IL 206-80-14	Basic	24-Apr-80	Michigan Dynamics Fuel Filter Assemblies - Repair and Overhaul
IL 206-80-15	Basic	27-Jun-80	206A/B Tail Rotor Blades, P/N 206-010-750-005 and 206-010-750-007, Crack Inspection Results
IL 206-80-16	Basic	17-Oct-80	Tail Rotor Yoke, P/N 206-011-811 Modification
IL 206-80-17	Basic	4-Nov-80	Starter-Generator Applications
IL 206-81-18	Basic	10-Mar-81	206A/B Main Rotor Blade Retirement Life Extension Plan
IL 206-81-19	Basic	22-Apr-81	Correct Configuration of Tail Rotor Driveshaft Hangers on Oil Cooler Impeller Shafts by Model and Part Number
IL 206-81-20	Basic	7-May-81	Input Driveshaft Assembly, Main: New Design, P/N 206-040-015-103
IL 206-81-21	Basic	5-Aug-81	Main Rotor Pitch Link Inspection

206A/B/B3 INFORMATION LETTER INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
IL 206-82-22	Basic	7-Jan-82	Incorrect Information in Maintenance and Overhaul Instructions Manual, 206A/B
IL 206-82-23	Basic	25-Jan-82	Modification of Chadwick Model C-22 Auxiliary Fuel System
IL 206-82-24	Basic	7-Mar-82	Starter-Generator Applications
IL 206-82-25	Basic	28-Apr-82	Relocation of Airframe Fuel Filter to Reduce the Risk of Fire
IL 206-82-26	Basic	14-May-82	Allison Model 250-C20B and -C20J Engine Usage Model 206B Helicopters
IL 206-82-27	Basic	28-May-82	Michigan Dynamics Fuel Filter Assemblies - Repair and Overhaul
IL 206-82-28	Basic	17-Aug-82	Garrett Airesearch Environmental Control System (ECS) Maintenance and Flight Procedures
IL 206-82-29	Basic	31-Aug-82	Starter-Generator Service Bulletins, Manuals and Information Letters
IL 206-82-30	Basic	3-Sep-82	Main Rotor Hub Chordwise Balance Weights
IL 206-82-31	Basic	29-Nov-82	Boost Pump Cartridge Fuel Contamination
IL 206-83-32	Rev A	30-Mar-88	Particle Separator - Overhaul/Repair Facilities
IL 206-83-33	Basic	9-May-83	Wiggins Quick-Disconnect Hydraulic Fluid Coupling
IL 206-83-34	Basic	19-Jul-83	Service Instruction No. 206-112 Retrofit Kit, Engine Assembly 250-C20B/250-C20J
IL 206-83-35	Basic	17-Oct-83	100 Hour Inspection of Dry Spline Starter-Generator
IL 206-83-36	Basic	4-Nov-83	Allison Model 250-C20B, C20J, C28B and C30P Fuel Control/Starting Characteristics
IL 206-84-37	Basic	27-Mar-84	Freewheel Assembly Clutch Retirement Life
IL 206-84-38	Basic	30-Apr-84	Mast Assembly Increased Corrosion Protection
IL 206-84-39	Basic	21-May-84	Tail Rotor Hub Assembly Configuration - Weight and Balance Data
IL 206-84-40	Basic	29-May-84	Oil Cooler Blower Impellers P/N 206-061-432-031
IL 206-84-41	Basic	6-Jul-84	Low Speed Flight Characteristics Which Can Result in Unanticipated Right Yaw
IL 206-84-42	Basic	14-Aug-84	Announcement of Latest Model 206 Mast Repair Service
IL 206-84-43	Basic	12-Sep-84	Main Rotor Yoke, P/N 206-010-101 and 206-011-101 and 206-011-149, Repair of
IL 206-84-44	Basic	27-Sep-84	Model 206A and 206B Series Powertrain Components - Effectivity
IL 206-84-45	Basic	31-Oct-84	Introduction of New Freewheeling Clutch Assembly, P/N CL42250-1
IL 206-84-46	Basic	27-Nov-84	Improved 206 Powertrain Oil Seals
IL 206-85-47	Basic	17-Jan-85	Main/Tail Rotor Blades Improvement

206A/B/B3 INFORMATION LETTER INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
IL 206-85-48	Basic	25-Mar-85	Disassembly and Assembly Tool - Oil Cooler Blower/Tail Rotor Driveshaft
IL 206-85-49	Basic	1-May-85	Turbine Oil 555 in Powertrain Components
IL 206-85-50	Basic	2-May-85	Identifying Skid and Float Landing Gear Cross Tube Support Assemblies
IL 206-85-51	Basic	5-Sep-85	Upper Case Assembly, P/N 206-040-151-015
IL 206-85-52	Basic	4-Oct-85	Improved Fuel Pressure Transducer, P/N BSE 206-30G
IL 206-85-53	Basic	11-Nov-85	New Turbine Outlet Temperature (TOT) Indicator
IL 206-85-54	Basic	5-Dec-85	Main Rotor Blade Doubler Trimming
IL 206-86-55	Basic	23-Jul-86	Packing Part Numbers for Hydraulic Quick Disconnect Couplings
IL 206-86-56	Basic	27-Jul-86	Incorrect Information in Maintenance Manual Airworthiness Limitations Schedule, 206BJRIII
IL 206-86-57	Basic	29-Oct-86	Pinion Gear Improved Serviceability
IL 206-87-58	Basic	7-Jan-87	Corrosion Protection for Main Rotor Blade Retaining Bolt Area
IL 206-87-59	Basic	11-Dec-87	Float Inflation Valve P/N 30910
IL 206-88-60	Basic	21-Apr-88	Flight Operations in Falling or Blowing Snow
IL 206-89-61	Basic	25-Apr-89	Emergency Floation Kits P/N 206-706-211-101/-103 and 206-706-210-103/-105
IL 206-89-62	Basic	10-May-89	Discrepant Freewheel Housing Gaskets, P/N 206-040-229-001
IL 206-89-63	Basic	30-Nov-89	Emergency Float Squib Valve P/N 30910 Replacement of
IL 206-90-64	Basic	26-Jul-90	Lightweight Emergency Float Bag/Inflation Valve - Configuration of
IL 206-90-65	Basic	28-Sep-90	Fuel Pressure Transducer 206-061-535-007
IL 206-91-66	Basic	9-Apr-91	Support Assy 206-001-566-101 Historical Record
IL 206-92-67	Basic	6-Feb-92	Forged Tail Rotor Pith Links 206-010-795-101 and 206-010-795-105, Introduction of
IL 206-92-68	Basic	17-Mar-92	Main Rotor Yoke, P/N 206-010-101 and 206-011-101 and 206-011-149, Repair of
IL 206-92-69	Basic	10-Aug-92	Tail Rotor Yoke 206-011-819-105, Introduction of
IL 206-94-70	Basic	15-Feb-94	Main Rotor Hub Fitting 206-011-150-105
IL 206-95-71	Basic	27-Mar-95	Main Rotor Blade Leading Edge Erosion
IL 206-95-72	Basic	9-Oct-95	Model 206 Series, Transfer of Type Design Responsibility
IL 206-96-73	Basic	19-Apr-96	Spacer 206-040-420-101, New Surface Finish
IL 206-96-74	Basic	20-Aug-96	Fuselage Fittings P/N 206-030-104-All Dash Numbers
IL 206-97-75	Basic	9-Oct-97	Flight Operations in Falling or Blowing Snow
IL 206-99-76	Basic	25-Jan-99	206A/B and L Series Main Rotor Blade with High Visibility Paint Scheme

206A/B/B3 INFORMATION LETTER INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
IL 206-99-77	Basic	2-Feb-99	Use of Trim Tab Adjustment Tools on 206 Series Main Rotor Blades
IL 206-99-78	Basic	19-Mar-99	Number of Rollers in Main Rotor Grip Bearings
IL 206-99-79	Basic	4-Jun-99	Windows and Sightglasses
IL 206-00-80	Basic	12-Jan-00	Flight Operations in Falling or Blowing Snow
IL 206-00-81	Basic	28-Feb-00	Inspection of Airborne Cartridge/Canister Fuel Boost Pumps for Presence of Check Valve
IL 206-00-82	Rev A	13-Jun-11	Main Rotor Blades Usable on 206A/B (TH-67) Models
IL 206-00-83	Basic	26-May-00	Swashplate Duplex Bearing 206-010-443-001 & 406-310-402-103 Vee Mark
IL 206-00-84	Basic	28-Jul-00	Stolen Engines, Rolls Royce 250-C20B
IL 206-01-85	Basic	27-Feb-01	Hose Assemblies P/N AE1010354GO(*) (*) (*) as used in Emergency Lightweight Float Kits P/N 206-706-210-ALL (206L series) and 206-706-211-ALL (206A/B series)
IL 206-02-86	Basic	19-Feb-02	Main Rotor Flap Restraint Kit 206-706-013 Change in Installation Procedure
IL 206-03-87	Basic	13-Nov-03	206B Jet Ranger III Subsequent to S/N 4450 Delivered with TH-67 AFT Fuselage
IL 206-03-88	Basic	17-Nov-03	The Correct Orientation of Thrust Bearing 206-040-038-ALL and 406-040-038-ALL
IL 206-04-89	Rev A	17-Aug-04	Increased Maximum Take-Off Weight, Internal Load
IL 206-05-90	Basic	4-Mar-05	Transmission Adapter Packing
IL 206-05-91	Basic	14-Apr-05	206-033-426-001 and -003 Inspection of Tail Rotor Gearbox Support Assembly
IL 206-05-92	Basic	28-Nov-05	Filter 50-075-1, Inspection and Recall of
IL 206-06-93	Basic	7-Sep-06	Warning Concerning the Installation of STC Strakes from Boundry Layer Research
IL 206-06-94	Basic	13-Oct-06	Improved Auto Relight Kits 206-706-038-003, 206-706-038-101, 206-706-038-105, and 206-706-038-107 Introduction of
IL 206-06-95	Basic	13-Nov-06	FAA Unapproved Parts Notification
IL 206-06-96	Basic	11-Dec-06	Breeze-Eastern Rescue Hoist and Cargo Winches Maintenance Concept, Modification of
IL 206-08-97	Basic	6-Oct-08	Solenoid Drain Valve 206-360-503-103, Kit
IL 206-09-98	Basic	13-Apr-09	Suspect Flap Restraint Support 206-010-191-001
IL 206-10-99	Rev A	2-Sep-11	Kaiser/Ronson Hydraulic Servo Actuator Field Kit and Installation Instructions, Inactivation of
IL 206-10-100	Basic	14-Dec-10	Maintenance Manual Chapter 4 and 5, Revision of
IL 206-11-101	Basic	3-Feb-11	Cadmium Plating of Mast Threads

GENERAL INFORMATION LETTER INDEX

NUMERICAL INDEX

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
IL GEN-35:COA:ms-8833	Basic	6-Oct-77	Replacement of Grease P/N 204-040-755-3 (ANDEROL L786 OR R-508) with Grease P/N 204-040-755-5 (SYN TECH 3913-G1)
IL GEN-35:AJS:ms-9146	Basic	30-Jan-78	Cracked Main Rotor Yoke P/N 204-011-102
IL GEN-35:EAM:ms-9227	Basic	4-Mar-78	Inter Turbine Temperature Indicator Modification
IL GEN-35:GEH:ms-9379	Basic	17-Apr-78	AL-T3 Torque Ctrl Exchange Program
IL GEN-35:GEH:ms-9599	Basic	12-Jun-78	Idle Gear Failures
IL GEN-35:TKF:ms-9628	Basic	29-Jun-78	Gear Failure (-701) Referred to in OSN 212-78-1
IL GEN-35:COA:ms-9801	Basic	5-Oct-78	New Mast Bearing P/N 212-040-136-1
IL GEN-35:GAZ:oab-2102	Basic	11-Dec-78	New Bell Helicopter Textron Warranty for New Helicopters and Spares Delivered January 1, 1979 and Subsequent
IL GEN-35:COA:ms-9950	Basic	13-Dec-78	Inspection of Metal Contaminated Transmissions
IL GEN-35:CFB:ms-9963	Basic	20-Dec-78	(Idle Gear)
IL GEN-79-1	Basic	9-Feb-79	Agenda for 1979 Management, Flight & Maint Conf
IL GEN-79-2	Basic	29-Mar-79	Revised Main Rotor Hub Overhaul Procedures
IL GEN-79-3	Basic	14-May-79	Models 206, 206L, 212 Availability of Trial Micro-Fiche Publications
IL GEN-79-4	Basic	1-Jun-79	CANCELED
IL GEN-79-5	Basic	23-Jul-79	Lord Kinematics Refurbished Parts
IL GEN-79-6	Basic	20-Aug-79	Undersize 205-040-176-101 and 212-040-176-7 Boots
IL GEN-79-7	Basic	22-Aug-79	Lubrication Frequency (Superseded by GEN-79-9)
IL GEN-79-8	Basic	10-Sep-79	Imminent Bearing Shortages
IL GEN-79-9	Basic	9-Nov-79	Lubrication Frequency (Supersedes GEN-79-7)
IL GEN-79-10	Basic	13-Nov-79	Stabilizer Bar Assy Component Overhaul Schedule
IL GEN-80-11	Basic	21-Apr-80	New Discrepancy/Malfunction Report Form
IL GEN-80-12	Basic	23-Apr-80	Care and Handling of Electrical Wire and Cable
IL GEN-80-13	Basic	23-May-80	Dust Ingestion and Sulfur Contamination
IL GEN-80-14	Basic	16-Jun-80	Termination of the Trial Micro Fiche Publications Program
IL GEN-80-15	Basic	3-Oct-80	Terminal Junction System
IL GEN-80-16	Basic	16-Dec-80	New Location & Teletype Numbers for Product Supt Dept
IL GEN-81-17	Basic	21-Apr-81	Chadwick-Helmuth Rotor Balancer
IL GEN-81-18	Basic	5-Aug-81	Repair of Tailrotor driveshafts with Missing Weights
IL GEN-81-19	Basic	11-Aug-81	CSR Effectiveness Questionnaire
IL GEN-81-20	Basic	14-Aug-81	Use of Alternate Parts in 204/205/212 XMSNs
IL GEN-81-21	Basic	1-Sep-81	Compressor Wash - All Model Turbine Engines
IL GEN-81-22	Basic	29-Sep-81	BHT Announces New Round of M&O Conferences
IL GEN-81-23	Basic	9-Dec-81	Bell Helicopter Textron Announces the Continuance of Maintenance & Operations Conferences
IL GEN-81-24	Basic	14-Dec-81	Grease P/N 204-040-755-5 (SYN Tech 3913-G1) Shelf Life
IL GEN-82-25	Basic	7-Apr-82	The Discrepancy/Malfunction Rpt (D/MR)

GENERAL INFORMATION LETTER INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
IL GEN-82-26	Basic	15-Jan-82	Availability of Wire Strike Protection for Bell Helicopters
IL GEN-82-27	Basic	17-Mar-82	Bell Helicopter Textron, Inc. Training Center Telephone Number Changes
IL GEN-82-28	Basic	15-Nov-82	Trend Monitoring Vibrations
IL GEN-83-29	Basic	26-May-83	Daily Inspections/Airworthiness Checks
IL GEN-84-30	Rev A	31-May-84	Royal Lubricants Co., Royco Turbine Oil 500 Usage Of
IL GEN-84-31	Rev B	17-Nov-92	Inspection Rqmts for Reservoirs & Valve Operating Squibs Used in Emergency Float & Fire Extinguisher Systems (Superseded by IL GEN-93-52)
IL GEN-84-32	Basic	12-Jun-84	Driveshaft Coupling Lubricant, P/N 204-040-755-005
IL GEN-84-33	Basic	24-Jul-84	Electric ARC Etching, Unauthorized Procedure
IL GEN-84-34	Basic	9-Aug-84	Grease P/N 204-040-755-5 (SYN Tech 3913-G1) Unauthorized Sources
IL GEN-84-35	Basic	9-Aug-84	Failure of Main Rotor Pitch Change Link Clevis, P/N 204-011-136-001
IL GEN-84-36	Basic	28-Nov-84	Use of Pressing Tool (Work Aid) when Inst. 205-040-301-001 Pinion in 204-040-424-001 Dup. Brg. Of Rotor BK Quill
IL GEN-84-37	Basic	28-Nov-84	Use of Pressing Plug & Sleeve when Installing 204-040-102-017 Pin in Duplex BRG. Of Gen. Drive Quill
IL GEN-84-38	Basic	6-Dec-84	High Density Terminal Junction Modules
IL GEN-85-39	Basic	10-Jan-85	Simmonds Precision Information Letter No. 84-01 Describing Deterioration of Rubber in Fuel Transmitters
IL GEN-85-40	Rev A	9-Jan-86	Protection of Elastomeric Components with Silicone Elastomers
IL GEN-86-41	Basic	5-Feb-86	Availability of Alternate Cable Cutter Cartridge
IL GEN-86-42	Basic	17-Mar-86	1986 MF&M Conference (Avis)
IL GEN-86-43	Basic	10-Jun-86	New Rotor Brake Linings
IL GEN-87-44	Basic	18-Feb-87	Lord Corporation Refurbishment/Exchange Parts Program
IL GEN-87-45	Basic	7-Apr-87	Plastic Media Blasting (PMB)
IL GEN-87-46	Rev A	4-Jan-88	Use of Illustrated Parts Catalogs
IL GEN-88-47	Rev B	22-Apr-92	MS21042 Series Nuts, Approved Vendors for
IL GEN-90-48	Basic	8-Oct-90	Accelerometer Minimum Specifications for Main Rotor Balancing Applications
IL GEN-91-49	Basic	9-Oct-91	Refurbishment of Parts Manufactured with K1001 (BLUE) Epoxy Resin Coating
IL GEN-92-50	Basic	20-Jan-92	Lord Corporation Remanufactured/Exchange Parts Program
IL GEN-92-51	Basic	4-Dec-92	Magnolia Magnobond 6392 Adhesive

GENERAL INFORMATION LETTER INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
IL GEN-93-52	Basic	21-Jun-93	Insp Rqmts for Res. & Valve Operating Squibbs Used in Emergency Float & Eng. Fire Ext. Sys & for Rescue Hoist Cable Cutter Squibbs
IL GEN-94-53	Basic	4-Mar-94	Powertrain Component Corrosion Prevention
IL GEN-94-54	Basic	15-Apr-94	Retirement Index Number (RIN) for Cycle Lived Components (Superseded by IL GEN-03-94)
IL GEN-96-55	Rev A	19-Oct-99	Improved Tail Rotor 90/42 Degree Gearbox Oil Filler Caps
IL GEN-97-56	Basic	10-Mar-97	Bell Helicopter Part Numbering System
IL GEN-97-57	Basic	24-Mar-97	Use of Noise Cancelling Headsets in Bell Helicopters
IL GEN-97-58	Basic	13-Nov-97	Castrol Aero 5734
IL GEN-98-59	Rev A	8-May-98	Folding Step Electrical Actuators P/N 212-075-418-107
IL GEN-98-60	Basic	1-Jun-98	RADS-AT User Training
IL GEN-98-61	Basic	12-Jun-98	A/C Modification & New E-Mail Addresses for Bell Helicopter Textron Canada
IL GEN-98-62	Basic	16-Nov-98	Flexure Style Main Rotor & Tail Rotor Yokes
IL GEN-99-63	Basic	13-Jan-99	Pressure Vessels, used as Nitrogen Reservoirs for Emergency Floatation Systems, Service Life Of
IL GEN-99-64	Basic	18-Jan-99	Airframe Damage Descriptions
IL GEN-99-65	Rev A	2-Jun-06	Interchangeability of Agusta & Bell Manufactured Parts
IL GEN-99-66	Basic	21-Jan-99	RADS-AT User Training
IL GEN-99-67	Basic	19-Mar-99	RADS-AT Y2K Problems
IL GEN-99-68	Basic	7-Sep-99	Access to Commercial Helicopter Service Directives
IL GEN-99-69	Basic	17-Nov-99	Gimbal Arm Corrosion and Maximum Service Life of SX-16 Nightsun or SX-5 Starburst Searchlight
IL GEN-00-70	Basic	25-Jan-00	Damage to Aluminum Rigid Lines Caused by Identification Tape
IL GEN-00-71	Basic	26-May-00	Technical Publications Revision Status Website
IL GEN-00-72	Basic	18-Jul-00	Cold Expansion Tools and Sleeves
IL GEN-00-73	Basic	8-Sep-00	Breeze Eastern 300 LBS Rescue Hoist P/N BL-16600-110 and BL-16600-170, and Aeronautical Accessories Inc (AAI) 300 LBS Rescue Hoist P/N 407-979-100
IL GEN-00-74	Basic	13-Nov-00	Post Wiring Inspection After Customizing Modification
IL GEN-00-75	Basic	16-Nov-00	Rotor Analysis and Diagnostic Systems (RADS-AT) Training Course
IL GEN-01-76	Basic	20-Mar-01	Procedure for Requesting BHT-Approved Structural Repair
IL GEN-01-77	Basic	26-Apr-01	Fuel Cell Shelf Life & Storage
IL GEN-01-78	Basic	26-Apr-01	Helicopter External Noise Levels
IL GEN-01-79	Basic	19-Jun-01	Turnbuckle Part Number 204-011-137-001 (Pitch Link Barrel)
IL GEN-01-80	Basic	25-Jun-01	Replacement of Exxon Turbine Oils by Air BP Oils

GENERAL INFORMATION LETTER INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
IL GEN-01-81	Basic	5-Jul-01	Rotor Analysis and Diagnostic Systems (RADS-AT) Training Course
IL GEN-01-82	Basic	28-Aug-01	Use of Unapproved Parts from Surplus Military Inventory
IL GEN-01-83	Basic	8-Oct-01	Type MA-6/8 Inertia Reel Assemblies
IL GEN-01-84	Basic	11-Oct-01	Primer on Rotor Brake Disc Friction Surfaces
IL GEN-02-85	Basic	6-Mar-02	Rotor Analysis and Diagnostic Systems (RADS-AT) Manufacturing/Support Changes and Upcoming Training Course
IL GEN-02-86	Basic	4-Apr-02	New Internet Service Provided to Bell Customers
IL GEN-02-87	Basic	5-Sep-02	RADS-AT Training
IL GEN-03-88	Basic	31-Jan-03	Defective NAS516-1A Grease Fittings
IL GEN-03-89	Basic	28-Feb-03	Inspection and Surface Protection of Steel Parts
IL GEN-03-90	Basic	4-Mar-03	New Repair Angle Standard
IL GEN-03-91	Rev A	8-Apr-09	Receipt of Service Directives On-line
IL GEN-03-92	Basic	8-Aug-03	Expansion of Product Support Engineering Service
IL GEN-03-93	Basic	13-Aug-03	Bearing Grease Lubricant
IL GEN-03-94	Basic	10-Oct-03	Expanded Use of Retirement Index Numbers (RIN)
IL GEN-03-95	Basic	21-Nov-03	Use of High-pressure Washer Around Helicopters
IL GEN-04-96	Basic	6-Jan-04	Procedure for Requesting BHT-Approved Structural Repairs
IL GEN-04-97	Basic	14-Jun-04	Hand Held Fire Extinguisher, Replacement of
IL GEN-04-98	Rev C	3-Mar-11	Changes to BHT Customer Property Return (CPR) Process
IL GEN-04-99	Basic	3-Aug-04	Superseded Rivets
IL GEN-04-100	Basic	1-Dec-04	Information Regarding the Handling and Testing of Cartridges
IL GEN-04-101	Basic	20-Dec-04	Rolls-Royce Technical Publications Delivered with New Production Helicopters
IL GEN-05-102	Basic	7-Feb-05	Wet Installation Primer Application
IL GEN-05-103	Basic	28-Feb-05	Seat Belt and Shoulder Restraint Webbing, Inspection Guidelines
IL GEN-05-104	Basic	15-Dec-05	Temperature Indicator "TEMP-PLATE" Sealer, Introduction of
IL GEN-06-105	Basic	12-Jan-06	2006 Maintenance & Operations (M&O) Conferences
IL GEN-06-106	Reissue	11-Jan-10	Availability of Electronic Publications
IL GEN-06-107	Basic	23-Aug-06	Procedure for Providing Customer/Contact Information
IL GEN-07-108	Basic	15-Jan-07	Clarification of Proper Assembly Torque Technique When Using Conical Seal Washers on Flared End Fittings
IL GEN-07-109	Basic	9-Feb-07	Clarification on Part Numbers Identification
IL GEN-07-110	Basic	16-Feb-07	Continuing Qualification and Maintenance of Pressure Cylinders and Squibs

GENERAL INFORMATION LETTER INDEX

NUMERICAL INDEX (Cont)

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
IL GEN-07-111	Basic	20-Apr-07	Risk of FOD of Fluid and Pneumatic Systems Malfunction Due to Cap Plugs
IL GEN-07-112	Basic	20-Apr-07	Shelf Life of Temp-Plates P/N 6000-1, 6000-2 and 6000-3
IL GEN-07-113	Basic	17-Jul-07	Compatibility of Newly Installed Equipment
IL GEN-08-114	Basic	25-Feb-08	Artex Service Bulletins SN019 and SN020
IL GEN-08-115	Basic	16-Jun-08	Aircraft Model Designations and Applicability to Bulletins
IL GEN-09-116	Basic	16-Feb-09	SkyBOOKS Electronic Log Books, Introduction of
IL GEN-09-117	Basic	17-Nov-09	psemil214@bellhelicopter.textron.com E-mail Address, Inactivation of
IL GEN-10-118	Basic	12-Aug-10	Breeze-Eastern Cargo Hook Maintenance Concept
IL GEN-10-119	Basic	12-Aug-10	Applicability of Bulletins After Incorporation into the Maintenance Manual
IL GEN-10-120	Basic	22-Dec-10	New Bulletin Format
IL GEN-11-121	Basic	4-Oct-11	Operation of Bell Aircraft Near Volcanic Activity

BHT-ALL-IL-INDEX

NOTICE

The following blank pages are provided for entry of additional notices when distributed. These additional notices will be included in this index at next revision

PUBLICATION	ISSUE/ REV	DATE	SUBJECT
--------------------	-----------------------	-------------	----------------