

ALERT SERVICE BULLETIN

REVISION NOTICE

Bell Helicopter **TEXTRON**

A Subsidiary of Textron Inc.

DATE 11-12-01

TO: **All Bell 407 Helicopters Owners/Operators**

SUBJECT: **REVISION "A" TO ALERT SERVICE BULLETIN 407-00-35: (HANGER BEARINGS 406-040-339-ALL AND 407-340-339-103 INSPECTION AND LUBRICATION OF)**

Alert Service Bulletin 407-00-35 is cancelled and superseded by Alert Service Bulletin 407-01-47.

7851 60046 REV 1198

AN APPROPRIATE ENTRY SHOULD BE MADE IN THE AIRCRAFT LOG BOOK UPON ACCOMPLISHMENT
IF OWNERSHIP OF AIRCRAFT HAS CHANGED PLEASE FORWARD TO NEW OWNER

ALERT SERVICE BULLETIN

Bell Helicopter **TEXTRON**

A Subsidiary of Textron Inc.

NO. 407-00-35

DATE 03-20-00

PAGE 1 of 1

DATE 11-12-01

REV "A"

MODEL AFFECTED: 407

SUBJECT: HANGER BEARINGS 406-040-339-ALL AND 407-340-339-103 INSPECTION AND LUBRICATION OF

HELICOPTERS AFFECTED: All model 407 helicopters

COMPLIANCE: Effective immediately

DESCRIPTION:

Alert Service Bulletin 407-00-35 is cancelled and superceded by Alert Service Bulletin 407-01-47.

A.

7851 55192 REV 1198

AN APPROPRIATE ENTRY SHOULD BE MADE IN THE AIRCRAFT LOG BOOK UPON ACCOMPLISHMENT
IF OWNERSHIP OF AIRCRAFT HAS CHANGED PLEASE FORWARD TO NEW OWNER