

**ALERT SERVICE BULLETIN**  
REVISION NOTICE  
**Bell Helicopter** **TEXTRON**  
A Subsidiary of Textron Inc.

DATE June 8, 2005

TO: **All Owners/Operators of Bell 407 Helicopters**

SUBJECT: **REVISION "A" TO ALERT SERVICE BULLETIN 407-04-65:  
(POWER TURBINE RPM (Np) STEADY STATE OPERATION  
AVOIDANCE, INTRODUCTION OF)**

Revision "A" to this bulletin introduced to cancel this Alert Service Bulletin.

AN APPROPRIATE ENTRY SHOULD BE MADE IN THE AIRCRAFT LOGBOOK UPON ACCOMPLISHMENT  
IF OWNERSHIP OF AIRCRAFT HAS CHANGED PLEASE FORWARD TO NEW OWNER

**ALERT SERVICE BULLETIN**  
**Bell Helicopter** **TEXTRON**

A Subsidiary of Textron Inc.

**NO.** 407-04-65

**DATE** Mar 22, 2005

**PAGE** 1 of 1

<b>DATE</b>	June 8, 2005
<b>REV</b>	A

**MODEL AFFECTED:** 407

**SUBJECT:** POWER TURBINE RPM (Np) STEADY STATE OPERATION AVOIDANCE, INTRODUCTION OF

**HELICOPTERS AFFECTED:** Model 407 helicopters serial number 53000 through 53595.

**COMPLIANCE:** Effective immediately

**DESCRIPTION:**

Alert Service Bulletin 407-04-65 is cancelled and superceded by Alert Service Bulletin 407-05-67.

A