

November 03, 2008

INFORMATION LETTER 407-08-95

TO: All Owners/Operators of Bell 407 Helicopters

SUBJECT: DUAL TACHOMETER INDICATOR P/N 407-375-008-111 (BASIC SHIP) AND P/N 407-375-008-113 (QUIET MODE KIT), INTRODUCTION OF

This Information Letter is issued to advise that there is a new dual tachometer indicator being installed in production helicopters S/N 53863 through subsequent and being supplied through spares.

These new indicators P/N 407-375-008-111 (figure 1) and P/N 407-375-008-113 (figure 2) does not have the “power on” BIT check portion of the BIT check circuit and are marked with the “AHLERS” logo on the face. The earlier indicators P/N’s 407-375-008-101 and -107 are acceptable fielded substitutes for P/N 407-375-008-111. The P/N’s 407-375-008-105 and -109 are acceptable field substitutes for P/N 407-375-008-113.




Figure 1. P/N 407-375-008-111




Figure 2. P/N 407-375-008-113