

**Bell Helicopter** **TEXTRON**

A Subsidiary of Textron, Inc.

Apr 11, 2005

TO: **All Owners/Operators of Bell 206A/B Helicopters**

SUBJECT: **REVISION "B" TO TECHNICAL BULLETIN 206-01-176:  
(TRANSMISSION OIL PUMP SEAL38-79004-1042-2,  
INTRODUCTION OF)**

Revision "B" is introduced to cancel this Technical Bulletin.

**TECHNICAL BULLETIN**  
**Bell Helicopter** **TEXTRON**

A Subsidiary of Textron Inc.

No. 206-01-176

Date 04-30-01

Page 1 of 1

DATE: Apr 11, 2005
--------------------

REV B
-------

**MODEL AFFECTED:** 206A and 206B

**SUBJECT:** TRANSMISSION OIL PUMP SEAL 38-79004-1042-2, INTRODUCTION OF

**HELICOPTERS AFFECTED:** Model 206A, S/N 004 through 660;  
S/N 672 through 715,  
Model 206B, S/N 661 through 671;  
S/N 716 and subsequent.

**COMPLIANCE:** Effective immediately

**DESCRIPTION:**

Technical Bulletin 206-01-176 Rev "A" is cancelled and superceded by Technical Bulletin 206-05-184.

**B**