

# **Bell Helicopter** **TEXTRON**

A Subsidiary of Textron, Inc.

Apr 11, 2005

**TO: All Owners/Operators of Bell 407 Helicopters**

**SUBJECT: REVISION "A" TO TECHNICAL BULLETIN 407-00-23:  
(TRANSMISSION OIL PUMP SEAL38-79004-1042-2,  
INTRODUCTION OF)**

Revision "A" is introduced to cancel this Technical Bulletin.

**TECHNICAL BULLETIN**  
**Bell Helicopter** **TEXTRON**

A Subsidiary of Textron Inc.

No. 407-00-23

Date 03-10-00

Page 1 of 1

DATE: Apr 11, 2005

REV A

**MODEL AFFECTED:** 407 Series

**SUBJECT:** TRANSMISSION OIL PUMP SEAL 38-79004-1042-2, INTRODUCTION OF

**HELICOPTERS AFFECTED:** 407 serial number 53000 through subsequent.

**COMPLIANCE:** Effective immediately

**DESCRIPTION:**

Technical Bulletin 407-00-23 is cancelled and superceded by Technical Bulletin 407-05-65.

A